


	Substation	BERTAM VALLEY			Date: 02/06/2026
	Equipment	RMU SF6	Manufacturer	INDKOM	Time: 9:20 AM
	Model	INS24	Rating	12kV	Humidity: 79%
	Area	OVERVIEW		Panel No.	-
Panel Name	-				

IR IMAGE




VISUAL IMAGE



PARAMETER	VALUE
Spot Temp.1 (Sp1)	-
Spot Temp. 2 (Sp2)	-
Average Temp. (Ar1)	24.1 °C
Ambient Temp.	21.0 °C
Delta T (ΔT)	-
Load (A)	-
Defect	-

PARAMETER	VALUE
Serial No.	18072222340DE
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	-

ULTRASOUND IMAGE



Decibel (dB)	-
Sound characteristic	-
Severity	-
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	BERTAM VALLEY			Date: 02/06/2026
	Equipment	RMU SF6	Manufacturer	INDKOM	Time: 9:20 AM
	Model	INS24	Rating	12kV	Humidity: 79%
	Area	OVERVIEW TOP		Panel No.	-
Panel Name	-				

IR IMAGE




VISUAL IMAGE



PARAMETER	VALUE
Spot Temp.1 (Sp1)	-
Spot Temp. 2 (Sp2)	-
Average Temp. (Ar1)	23.5 °C
Ambient Temp.	21.0 °C
Delta T (ΔT)	-
Load (A)	-
Defect	-

PARAMETER	VALUE
Serial No.	18072222340DE
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	-

ULTRASOUND IMAGE



Decibel (dB)	-
Sound characteristic	-
Severity	-
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	BERTAM VALLEY			Date: 02/06/2026
	Equipment	RMU SF6	Manufacturer	INDKOM	Time: 9:20 AM
	Model	INS24	Rating	12kV	Humidity: 79%
	Area	CABLE COMPARTMENT		Panel No.	CCH00420
Panel Name	BERTAM MEWAH				

IR IMAGE




VISUAL IMAGE



PARAMETER	VALUE
Spot Temp.1 (Sp1)	24.1 °C
Spot Temp. 2 (Sp2)	24.0 °C
Average Temp. (Ar1)	24.1 °C
Ambient Temp.	21.0 °C
Delta T (Δ T)	0.1 °C
Load (A)	-
Defect	

PARAMETER	VALUE
Serial No.	18072222340DE
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	NOT ACCESSIBLE

ULTRASOUND IMAGE



Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	BERTAM VALLEY			Date: 02/06/2026
	Equipment	RMU SF6	Manufacturer	INDKOM	Time: 9:20 AM
	Model	INS24	Rating	12kV	Humidity: 79%
	Area	CABLE COMPARTMENT		Panel No.	CCH00423
Panel Name	CS JENSIN				

IR IMAGE




VISUAL IMAGE



PARAMETER	VALUE
Spot Temp.1 (Sp1)	23.9 °C
Spot Temp. 2 (Sp2)	23.6 °C
Average Temp. (Ar1)	23.8 °C
Ambient Temp.	21.0 °C
Delta T (Δ T)	0.3 °C
Load (A)	-
Defect	

PARAMETER	VALUE
Serial No.	18072222340DE
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	NOT ACCESSIBLE

ULTRASOUND IMAGE



Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	BERTAM VALLEY			Date: 02/06/2026
	Equipment	RMU SF6	Manufacturer	INDKOM	Time: 9:20 AM
	Model	INS24	Rating	12kV	Humidity: 79%
	Area	CABLE COMPARTMENT		Panel No.	CCH00422
Panel Name	OUF				

IR IMAGE




VISUAL IMAGE



PARAMETER	VALUE
Spot Temp.1 (Sp1)	23.9 °C
Spot Temp. 2 (Sp2)	23.8 °C
Average Temp. (Ar1)	23.8 °C
Ambient Temp.	21.0 °C
Delta T (Δ T)	0.1 °C
Load (A)	-
Defect	

PARAMETER	VALUE
Serial No.	18072222340DE
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	NOT ACCESSIBLE

ULTRASOUND IMAGE



Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	BERTAM VALLEY			Date: 02/06/2026
	Equipment	RMU SF6	Manufacturer	INDKOM	Time: 9:20 AM
	Model	INS24	Rating	12kV	Humidity: 79%
	Area	FUSE COMPARTMENT		Panel No.	CCH00421
Panel Name	TX				

IR IMAGE




VISUAL IMAGE



PARAMETER	VALUE
Spot Temp.1 (Sp1)	24.2 °C
Spot Temp. 2 (Sp2)	24.3 °C
Average Temp. (Ar1)	24.3 °C
Ambient Temp.	21.0 °C
Delta T (Δ T)	0.1 °C
Load (A)	-
Defect	

PARAMETER	VALUE
Serial No.	18072222340DE
Heater (A)	-
CB Position	CLOSE
Busbar Position	-
Cable Type	NOT ACCESSIBLE

ULTRASOUND IMAGE




Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	BERTAM VALLEY			Date: 02/06/2026
	Equipment	TRANSFORMER	Manufacturer	EWT	Time: 9:20 AM
	Model	HERMETICALLY SEAL	Rating	750kVA	Humidity: 79%
	Area	OVERVIEW			Tx No. 1
Location					

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	36.6 °C	Serial No.	EWT55674
Spot Temp. 2 (Sp2)	33.9 °C	Heater (A)	-
Average Temp. (Ar1)	33.2 °C	CB Position	-
Ambient Temp.	21.0 °C	Busbar Position	-
Delta T (Δ T)	2.7 °C	Cable Type	-
Load (A)	-		
Defect	-		

ULTRASOUND IMAGE	
	
Decibel (dB)	-
Sound characteristic	-
Defect	-
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	BERTAM VALLEY			Date: 02/06/2026
	Equipment	TRANSFORMER	Manufacturer	EWT	Time: 9:20 AM
	Model	HERMETICALLY SEAL	Rating	750kVA	Humidity: 79%
	Area	BUSHING		Tx No.	1
Location	HV SIDE				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	31.5 °C
Spot Temp. 2 (Sp2)	31.4 °C
Average Temp. (Ar1)	27.3 °C
Ambient Temp.	21.0 °C
Delta T (ΔT)	0.1 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	EWT55674
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE



Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	BERTAM VALLEY			Date: 02/06/2026
	Equipment	TRANSFORMER	Manufacturer	EWT	Time: 9:20 AM
	Model	HERMETICALLY SEAL	Rating	750kVA	Humidity: 79%
	Area	CABLE		Tx No.	1
Location	HV SIDE				

IR IMAGE




PARAMETER	VALUE
Spot Temp.1 (Sp1)	26.5 °C
Spot Temp. 2 (Sp2)	26.4 °C
Average Temp. (Ar1)	23.7 °C
Ambient Temp.	21.0 °C
Delta T (ΔT)	0.1 °C
Load (A)	-
Defect	

VISUAL IMAGE



PARAMETER	VALUE
Serial No.	EWT55674
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	XLPE

ULTRASOUND IMAGE



Decibel (dB)	0dB
Sound characteristic	Normal
Severity	
Sound clip	


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	BERTAM VALLEY			Date: 02/06/2026
	Equipment	TRANSFORMER	Manufacturer	EWT	Time: 9:20 AM
	Model	HERMETICALLY SEAL	Rating	750kVA	Humidity: 79%
	Area	BUSHING		Tx No.	1
Location	LV SIDE				

IR IMAGE



VISUAL IMAGE



PARAMETER	VALUE
Spot Temp.1 (Sp1)	27.5 °C
Spot Temp. 2 (Sp2)	27.7 °C
Average Temp. (Ar1)	-
Ambient Temp.	21.0 °C
Delta T (ΔT)	0.2 °C
Load (A)	-
Defect	

PARAMETER	VALUE
Serial No.	EWT55674
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	XLPE


Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

	Substation	BERTAM VALLEY			Date: 02/06/2026
	Equipment	TRANSFORMER	Manufacturer	EWT	Time: 9:20 AM
	Model	HERMETICALLY SEAL	Rating	750kVA	Humidity: 79%
	Area	CABLE		Tx No.	1
Location	LV SIDE				

IR IMAGE



VISUAL IMAGE



PARAMETER	VALUE
Spot Temp.1 (Sp1)	25.7 °C
Spot Temp. 2 (Sp2)	26.0 °C
Average Temp. (Ar1)	28.1 °C
Ambient Temp.	21.0 °C
Delta T (ΔT)	0.3 °C
Load (A)	-
Defect	


PARAMETER	VALUE
Serial No.	EWT55674
Heater (A)	-
CB Position	-
Busbar Position	-
Cable Type	XLPE

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -

TA 	Substation	BERTAM VALLEY			Date: 02/06/2026
	Equipment	FP TX1	Manufacturer	PSB	Time: 9:20 AM
	Model	DIN TYPE	Rating	1600A	Humidity: 79%
	Area	OVERVIEW		Feeder No.	-
Feeder Name		-			

IR IMAGE		VISUAL IMAGE	
			
PARAMETER	VALUE	PARAMETER	VALUE
Spot Temp.1 (Sp1)	-	Serial No.	RTLRL 642-045
Spot Temp. 2 (Sp2)	-	Heater (A)	-
Average Temp. (Ar1)	26.8 °C	CB Position	-
Ambient Temp.	21.0 °C	Busbar Position	-
Delta T (Δ T)	-	Cable Type	-
Load (A)	-		
Defect	-		

Analysis & Recommendations:

Analysis: No Anomaly.

Recommendation: -