



**CONDITION BASED ASSESSMENT  
FULL SCANNING REPORT  
SBUM DIAGNOSTIC PAHANG  
TNB BAHAGIAN PEMBAHAGIAN PAHANG**

|                            |   |                      |
|----------------------------|---|----------------------|
| FUNCTIONAL LOCATION (ERMS) | : | CRAU/PCE/J00260      |
| FUNCTIONAL LOCATION (SITE) | : | CRAU/PCE/J00260      |
| SUBSTATION NAME (ERMS)     | : | SS KG BENGALI        |
| SUBSTATION NAME (SITE)     | : | SS KG BENGALI        |
| COORDINATE                 | : | 3.812693, 101.844392 |
| SUBSTATION TYPE            | : | SS                   |
| AREA                       | : | RAUB                 |
| STATE                      | : | PAHANG               |
| PO                         | : | 42225439             |
| DATE                       | : | 06 MAR 2026          |

|                   |                                               |
|-------------------|-----------------------------------------------|
| <b>SCANNED BY</b> |                                               |
| THERMOGRAPHY      | : MUHAMMAD ADAM BIN SAFARUDDIN (2017MY34N004) |

|                        |                                                               |
|------------------------|---------------------------------------------------------------|
| <b>EQUIPMENT/TOOLS</b> |                                                               |
| THERMOGRAPHY           | : FLIR T640 (SN 55912229) (CALIBRATION DUE DATE: 26 DEC 2026) |

|                    |                                           |
|--------------------|-------------------------------------------|
| <b>PREPARED BY</b> |                                           |
| NAME OF CONTRACTOR | : <b>EET ENGINEERING SERVICES SDN BHD</b> |
| ADDRESS            | : NO.38, JALAN SS19/1D,                   |
|                    | : 47500, SUBANG JAYA, SELANGOR.           |

**SUBSTATION SIGNBOARD**




# EXECUTIVE SUMMARY

| NO. | EQUIPMENT                       | DEFECT AREA          | IR<br>(Abs T/ $\Delta$ T) | DEFECT |
|-----|---------------------------------|----------------------|---------------------------|--------|
| 1.  | RMU SF6, INDKOM                 | OVERVIEW             | -                         | -      |
|     |                                 | OVERVIEW TOP         | -                         | -      |
|     | PANEL CRB00770<br>SSU MUTIARA   | CABLE SWG/CABLE XLPE | 2.0 °C                    |        |
|     | PANEL CRB00771<br>SUNGAI LUI    | CABLE COMPARTMENT    | -                         |        |
|     | PANEL CRB00772<br>AUTO RECLOSER | CABLE COMPARTMENT    | -                         |        |

# VISUAL DEFECT SUMMARY

| NO. | EQUIPMENT  | DEFECT DESCRIPTION     | ADDITIONAL REMARKS                   |
|-----|------------|------------------------|--------------------------------------|
| 1   | SUBSTATION | CPR POSTER OLD VERSION | SWG BAY                              |
| 2   | SUBSTATION | BUSHES & CREEPERS      | CREEPERS AT SWG1 - CABLE COMPARTMENT |
| 3   | LIGHTING   | NOT OPERATED           | SWG BAY                              |
| 4   | CABLE PILC | CABLE PILC SWG         | CRB00771 - SUNGAI LUI                |

|                                                                                   |            |               |              |        |                  |
|-----------------------------------------------------------------------------------|------------|---------------|--------------|--------|------------------|
|  | Substation | SS KG BENGALI |              |        | Date: 06/03/2026 |
|                                                                                   | Equipment  | RMU SF6       | Manufacturer | INDKOM | Time: 09:24 AM   |
|                                                                                   | Model      | INS24         | Rating       | 12kV   | Humidity: 71%    |
|                                                                                   | Area       | OVERVIEW      |              |        | Panel No.        |
| Panel Name                                                                        | -          |               |              |        |                  |


| IR IMAGE                                                                          |         | VISUAL IMAGE                                                                       |            |
|-----------------------------------------------------------------------------------|---------|------------------------------------------------------------------------------------|------------|
|  |         |  |            |
| PARAMETER                                                                         | VALUE   | PARAMETER                                                                          | VALUE      |
| Spot Temp.1 (Sp1)                                                                 | -       | Serial No.                                                                         | 1205306965 |
| Spot Temp. 2 (Sp2)                                                                | -       | Heater (A)                                                                         | -          |
| Average Temp. (Ar1)                                                               | 29.3 °C | CB Position                                                                        | -          |
| Ambient Temp.                                                                     | 30.4 °C | Busbar Position                                                                    | -          |
| Delta T ( Δ T)                                                                    | -       | Cable Type                                                                         | -          |
| Load (A)                                                                          | -       |                                                                                    |            |
| Severity                                                                          | -       |                                                                                    |            |

Analysis & Recommendations:

**Analysis:** Please refer the following page for details defect.

**Recommendation:** N/A

|                                                                                   |            |               |              |           |                  |
|-----------------------------------------------------------------------------------|------------|---------------|--------------|-----------|------------------|
|  | Substation | SS KG BENGALI |              |           | Date: 06/03/2026 |
|                                                                                   | Equipment  | RMU SF6       | Manufacturer | INDKOM    | Time: 09:24 AM   |
|                                                                                   | Model      | INS24         | Rating       | 12kV      | Humidity: 71%    |
|                                                                                   | Area       | OVERVIEW TOP  |              | Panel No. | -                |
| Panel Name                                                                        | -          |               |              |           |                  |


| IR IMAGE                                                                          |         | VISUAL IMAGE                                                                       |            |
|-----------------------------------------------------------------------------------|---------|------------------------------------------------------------------------------------|------------|
|  |         |  |            |
| PARAMETER                                                                         | VALUE   | PARAMETER                                                                          | VALUE      |
| Spot Temp.1 (Sp1)                                                                 | -       | Serial No.                                                                         | 1205306965 |
| Spot Temp. 2 (Sp2)                                                                | -       | Heater (A)                                                                         | -          |
| Average Temp. (Ar1)                                                               | 28.5 °C | CB Position                                                                        | -          |
| Ambient Temp.                                                                     | 30.4 °C | Busbar Position                                                                    | -          |
| Delta T ( Δ T)                                                                    | -       | Cable Type                                                                         | -          |
| Load (A)                                                                          | -       |                                                                                    |            |
| Severity                                                                          | -       |                                                                                    |            |

Analysis & Recommendations:

**Analysis:** Please refer the following page for details defect.

**Recommendation:** N/A

|                                                                                   |            |                   |              |           |                  |
|-----------------------------------------------------------------------------------|------------|-------------------|--------------|-----------|------------------|
|  | Substation | SS KG BENGALI     |              |           | Date: 06/03/2026 |
|                                                                                   | Equipment  | RMU SF6           | Manufacturer | INDKOM    | Time: 09:24 AM   |
|                                                                                   | Model      | INS24             | Rating       | 12kV      | Humidity: 71%    |
|                                                                                   | Area       | CABLE COMPARTMENT |              | Panel No. | CRB00770         |
| Panel Name                                                                        |            | SSU MUTIARA       |              |           |                  |


| IR IMAGE                                                                          |         | VISUAL IMAGE                                                                       |            |
|-----------------------------------------------------------------------------------|---------|------------------------------------------------------------------------------------|------------|
|  |         |  |            |
| PARAMETER                                                                         | VALUE   | PARAMETER                                                                          | VALUE      |
| Spot Temp.1 (Sp1)                                                                 | 30.4 °C | Serial No.                                                                         | 1205306965 |
| Spot Temp. 2 (Sp2)                                                                | 28.4 °C | Heater (A)                                                                         | -          |
| Average Temp. (Ar1)                                                               | 28.9 °C | CB Position                                                                        | CLOSE      |
| Ambient Temp.                                                                     | 30.4 °C | Busbar Position                                                                    | -          |
| Delta T ( Δ T)                                                                    | 2.0 °C  | Cable Type                                                                         | XLPE       |
| Load (A)                                                                          | -       |                                                                                    |            |
| Severity                                                                          |         |                                                                                    |            |

#### Analysis & Recommendations:

**Analysis:** Thermal image above indicates hotspot detected at **CABLE XLPE – CABLE TERMINATION**.

**Recommendation:** To inspect and make a new termination or replace defective parts if necessary.

|                                                                                   |            |                   |              |           |                  |
|-----------------------------------------------------------------------------------|------------|-------------------|--------------|-----------|------------------|
|  | Substation | SS KG BENGALI     |              |           | Date: 06/03/2026 |
|                                                                                   | Equipment  | RMU SF6           | Manufacturer | INDKOM    | Time: 09:24 AM   |
|                                                                                   | Model      | INS24             | Rating       | 12kV      | Humidity: 71%    |
|                                                                                   | Area       | CABLE COMPARTMENT |              | Panel No. | CRB00771         |
| Panel Name                                                                        |            | SUNGAI LUI        |              |           |                  |

| IR IMAGE                                                                          |         | VISUAL IMAGE                                                                       |            |
|-----------------------------------------------------------------------------------|---------|------------------------------------------------------------------------------------|------------|
|  |         |  |            |
| PARAMETER                                                                         | VALUE   | PARAMETER                                                                          | VALUE      |
| Spot Temp.1 (Sp1)                                                                 | 29.6 °C | Serial No.                                                                         | 1205306965 |
| Spot Temp. 2 (Sp2)                                                                | 29.6 °C | Heater (A)                                                                         | -          |
| Average Temp. (Ar1)                                                               | 29.6 °C | CB Position                                                                        | TRIP       |
| Ambient Temp.                                                                     | 30.4 °C | Busbar Position                                                                    | -          |
| Delta T ( Δ T)                                                                    | -       | Cable Type                                                                         | XLPE       |
| Load (A)                                                                          | -       |                                                                                    |            |
| Defect                                                                            |         |                                                                                    |            |


Analysis & Recommendations:

**Analysis:** No Anomaly.

**Recommendation:** -



|                                                                                   |            |                   |              |           |                  |
|-----------------------------------------------------------------------------------|------------|-------------------|--------------|-----------|------------------|
|  | Substation | SS KG BENGALI     |              |           | Date: 06/03/2026 |
|                                                                                   | Equipment  | RMU SF6           | Manufacturer | INDKOM    | Time: 09:24 AM   |
|                                                                                   | Model      | INS24             | Rating       | 12kV      | Humidity: 71%    |
|                                                                                   | Area       | CABLE COMPARTMENT |              | Panel No. | CRB00772         |
| Panel Name                                                                        |            | AUTO RECLOSER     |              |           |                  |

| IR IMAGE                                                                          |         | VISUAL IMAGE                                                                       |            |
|-----------------------------------------------------------------------------------|---------|------------------------------------------------------------------------------------|------------|
|  |         |  |            |
| PARAMETER                                                                         | VALUE   | PARAMETER                                                                          | VALUE      |
| Spot Temp.1 (Sp1)                                                                 | 29.7 °C | Serial No.                                                                         | 1205306965 |
| Spot Temp. 2 (Sp2)                                                                | 30.2 °C | Heater (A)                                                                         | -          |
| Average Temp. (Ar1)                                                               | 29.8 °C | CB Position                                                                        | CLOSE      |
| Ambient Temp.                                                                     | 30.4 °C | Busbar Position                                                                    | -          |
| Delta T ( Δ T)                                                                    | 0.6 °C  | Cable Type                                                                         | XLPE       |
| Load (A)                                                                          | -       |                                                                                    |            |
| Defect                                                                            |         |                                                                                    |            |

Analysis & Recommendations:

**Analysis:** No Anomaly.

**Recommendation:** -



# SUBSTATION CONDITION

## SUBSTATION OVERVIEW



## SIGNBOARD



## SWITCHGEAR



## SWITCHGEAR NAMEPLATE



## EFI



## SF6 INDICATOR



## **VISUAL DEFECT**

### **SUBSTATION**



CPR POSTER OLD VERSION – SWG BAY

### **SUBSTATION**



BUSHES & CREEPERS – CREEPERS AT SWG1 - CABLE COMPARTMENT

### **LIGHTING**



NOT OPERATED – SWG BAY

### **CABLE PILC**



CABLE PILC SWG – CRB00771 - SUNGAI LUI



# NORMAL/DEFECT STICKER

## NORMAL STICKER

**CONDITION ASSESSMENT**

**DIAGNOSTIC UNIT SUBSTATION**

Cycle/Year : 1/2026

Testing Date : 06-03-2026

Defect : IR

Company/Team : EET ENGINEERING

TEV ☒

U/S ☒

IR ☒

## DEFECT STICKER PANEL CRB00770

**DEFECT NOTIFICATION**

**DIAGNOSTIC UNIT SUBSTATION**

Panel / TX No. : CRB 00770 -

Compartment : CABLE COMPARTMENT

Testing Date : 06-03-2026

Load (A) : -

Thermo:  $\Delta T$  1.5 °C

Abs. T °C

Remarks:

Ultrasound:

Mechanical Vib. dB

Corona dB

Tracking dB

Arcing dB

TEV: dB

Pulse / Cycle

Repair Date :

Repair By:

Rescan: OK ☐ NOT OK ☐

Rescan Date :

Company/Team

EET

181  
SS  
AIR

| STATE / AREA: PAHANG / KAU                                                                               |                   |                       |                       |            |                    |            |                                |           |           | DATE: 6/3/2026                       |            |           |           |                  |                                    |            |            |    |               | FUNCTIONAL LOCATION: KRAJ/PCE/300260 |        |    |            |         |  |  |  |  |  |
|----------------------------------------------------------------------------------------------------------|-------------------|-----------------------|-----------------------|------------|--------------------|------------|--------------------------------|-----------|-----------|--------------------------------------|------------|-----------|-----------|------------------|------------------------------------|------------|------------|----|---------------|--------------------------------------|--------|----|------------|---------|--|--|--|--|--|
| FE NAME: SS KG BENGALI                                                                                   |                   |                       |                       |            |                    |            |                                |           |           | TIME IN / OUT: 9:24 A.M. / 9:44 A.M. |            |           |           |                  |                                    |            |            |    |               | BACKGROUND TEMP: 30.4°C              |        |    |            |         |  |  |  |  |  |
| V.I. REF. NO:                                                                                            |                   |                       |                       |            |                    |            |                                |           |           | TEV BACK GROUND / HUMIDITY: 31 / 72  |            |           |           |                  |                                    |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
| DETAIL                                                                                                   |                   |                       |                       |            |                    |            |                                |           |           | TEMPERATURE                          |            |           |           |                  |                                    |            |            |    |               | ULTRASOUND                           |        |    |            |         |  |  |  |  |  |
| NO.                                                                                                      | FDR. NO.          | FEEDER NAME           | STATUS (TRIP / CLOSE) | LOAD (A)   | CABLE TYPE/SIZE    | HEATER (A) | SERIAL NO (ONLY BREAKER & OLU) | COMP      | Tmin (°C) | Tmax (°C)                            | AT         | Avg (°C)  | FILE      | REMARKS          | dB                                 | FILE       | TYPE CHAR. | dB | PULSE / CYCLE | TYPE CHAR.                           | REMARK |    |            |         |  |  |  |  |  |
| 1                                                                                                        | CRB 00770         | SSU MUTIARA           | TRIP / CLOSE          |            | XLPE P/LC N/A NACE |            |                                | CABLE     | 28.4      | 30.4                                 | 2.0        | 28.9      | 86        | FILE             | -6                                 | -          | -          | 27 | 0             | -                                    |        |    |            |         |  |  |  |  |  |
| 2                                                                                                        | CRB 00771         | SUNGAI LUI            | TRIP / CLOSE          |            | XLPE P/LC N/A NACE |            |                                | CABLE     | 29.1      | 29.5                                 | 0.4        | 29.4      | 82        |                  | -6                                 | -          | -          | 26 | 0             | -                                    |        |    |            |         |  |  |  |  |  |
| 3                                                                                                        | CRB 00772         | AUTO RECLOSER         | TRIP / CLOSE          |            | XLPE P/LC N/A NACE |            |                                | CABLE     | 29.4      | 29.9                                 | 0.5        | 29.7      | 83        |                  | -6                                 | -          | -          | 25 | 0             | -                                    |        |    |            |         |  |  |  |  |  |
| 4                                                                                                        |                   |                       | TRIP / CLOSE          |            | XLPE P/LC N/A NACE |            |                                | CABLE     |           |                                      |            |           |           |                  |                                    |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
| OVERVIEW                                                                                                 |                   |                       |                       |            |                    |            |                                |           |           | LOCAL TRANSFORMER                    |            |           |           |                  |                                    |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
| DETAILS                                                                                                  |                   |                       |                       |            |                    |            |                                |           |           | THERMOGRAPHY                         |            |           |           |                  |                                    |            |            |    |               | ULTRASOUND                           |        |    |            |         |  |  |  |  |  |
| TX ID                                                                                                    | SERIAL NO         | CABLE TYPE/ SIZE      | REMARK                | COMP.      | Tmin(°C)           | Tmax(°C)   | AT                             | Avg (°C)  | FILE      | dB                                   | TYPE CHAR. | TX ID     | SERIAL NO | CABLE TYPE/ SIZE | COMP.                              | Tmin(°C)   | Tmax(°C)   | AT | FILE          | Avg (°C)                             | FILE   | dB | TYPE CHAR. | REMARKS |  |  |  |  |  |
| TX1                                                                                                      |                   | XLPE/P/LC             |                       | HT CABLE   |                    |            |                                |           |           |                                      |            | TX3       |           | XLPE/P/LC        | HT CABLE                           |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          |                   | XLPE/P/LC             |                       | HT BUSHING |                    |            |                                |           |           |                                      |            |           |           | XLPE/P/LC        | HT BUSHING                         |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          |                   | XLPE/P/LC             |                       | LV CABLE   |                    |            |                                |           |           |                                      |            |           |           |                  | XLPE/P/LC                          | LV CABLE   |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          |                   | XLPE/P/LC             |                       | LV BUSHING |                    |            |                                |           |           |                                      |            |           |           |                  | XLPE/P/LC                          | LV BUSHING |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
| TX2                                                                                                      |                   | XLPE/P/LC             |                       | HT CABLE   |                    |            |                                |           |           |                                      |            | TX4       |           | XLPE/P/LC        | HT CABLE                           |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          |                   | XLPE/P/LC             |                       | HT BUSHING |                    |            |                                |           |           |                                      |            |           |           | XLPE/P/LC        | HT BUSHING                         |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          |                   | XLPE/P/LC             |                       | LV CABLE   |                    |            |                                |           |           |                                      |            |           |           |                  | XLPE/P/LC                          | LV CABLE   |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          |                   | XLPE/P/LC             |                       | LV BUSHING |                    |            |                                |           |           |                                      |            |           |           |                  | XLPE/P/LC                          | LV BUSHING |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
| LV DISTRIBUTION BOARD / FEEDER PILLAR / OTHERS                                                           |                   |                       |                       |            |                    |            |                                |           |           |                                      |            |           |           |                  |                                    |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
| 1                                                                                                        | LVDB / FP 1       | INC. 1                | INC. 2                | INC. 3     | F1                 | F2         | F3                             | F4        | F5        | F6                                   | F7         | F8        | F9        | F10              |                                    |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          | CABLE TYPE / SIZE | XLPE/P/LC             | XLPE/P/LC             | XLPE/P/LC  | XLPE/P/LC          | XLPE/P/LC  | XLPE/P/LC                      | XLPE/P/LC | XLPE/P/LC | XLPE/P/LC                            | XLPE/P/LC  | XLPE/P/LC | XLPE/P/LC | XLPE/P/LC        |                                    |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
| 2                                                                                                        | LVDB / FP 2       | INC. 1                | INC. 2                | INC. 3     | F1                 | F2         | F3                             | F4        | F5        | F6                                   | F7         | F8        | F9        | F10              |                                    |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          | CABLE TYPE / SIZE | XLPE/P/LC             | XLPE/P/LC             | XLPE/P/LC  | XLPE/P/LC          | XLPE/P/LC  | XLPE/P/LC                      | XLPE/P/LC | XLPE/P/LC | XLPE/P/LC                            | XLPE/P/LC  | XLPE/P/LC | XLPE/P/LC | XLPE/P/LC        |                                    |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
| NO                                                                                                       | LVDB / FP         | DEFECTIVE FEEDER NAME | Tmin(°C)              | Tmax(°C)   | AT                 | FILE       | Avg (°C)                       | REMARK    |           |                                      |            |           |           |                  | LVDB / FP 1 - 3-SLOTTED / DIN TYPE |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          | INC 1             |                       |                       |            |                    |            |                                |           |           |                                      |            |           |           |                  | Manufacturer:                      |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          | INC 2             |                       |                       |            |                    |            |                                |           |           |                                      |            |           |           |                  | Serial No.:                        |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          | F1                |                       |                       |            |                    |            |                                |           |           |                                      |            |           |           |                  | Rating: 1000A / 1000A / 800A       |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          | F2                |                       |                       |            |                    |            |                                |           |           |                                      |            |           |           |                  | LVDB / FP 2 - 3-SLOTTED / DIN TYPE |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          | F3                |                       |                       |            |                    |            |                                |           |           |                                      |            |           |           |                  | Manufacturer:                      |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          | F4                |                       |                       |            |                    |            |                                |           |           |                                      |            |           |           |                  | Serial No.:                        |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          | F5                |                       |                       |            |                    |            |                                |           |           |                                      |            |           |           |                  | Rating: 1600A / 1000A / 800A       |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          | F6                |                       |                       |            |                    |            |                                |           |           |                                      |            |           |           |                  |                                    |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          | F7                |                       |                       |            |                    |            |                                |           |           |                                      |            |           |           |                  |                                    |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
|                                                                                                          | F8                |                       |                       |            |                    |            |                                |           |           |                                      |            |           |           |                  |                                    |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |
| Battery Bank<br>Black Box 1<br>Black Box 2<br>Lightning Arrester<br>Dropout Fuse<br>Auto Recloser<br>LBS |                   |                       |                       |            |                    |            |                                |           |           |                                      |            |           |           |                  |                                    |            |            |    |               |                                      |        |    |            |         |  |  |  |  |  |

EET ENGINEERING SERVICES SDN BHD  
(53456-W)  
No. 98-2/2nd Floor, Jalan SS 19/1D  
47500 Subang Jaya, Selangor.  
Tel: 603-5636 6205 Fax: 603-5636 7205

MOHD AZZAD BIN OTHMAN (10059230)  
JURUTERNAK TINGKATAN 1  
DIAGNOSTIC SUBSTATION-PAHANG  
SBU MAINTENANCE EAST  
DISTRIBUTION NETWORK DIVISION



181

## VISUAL INSPECTION CHECKLIST FOR 11kV SUBSTATION

DATE:

P/E Name (ERMS):

P/E Name (SITE):

GPS Coordinate:

PCE Type:

PCE Area:

Switchgear Type 1:

Manufacturer/Model:

Switchgear Manufactured Date:

Switchgear Type 2:

Manufacturer/Model:

Switchgear Manufactured Date:

No. of Transformer:

Tx 1:

Tx 2:

Tx 3:

Tx 4:

## KEJANGGALAN

1. Signboard:

2. Earth connection:

3. EFI Functioning:

4. Heater Functioning:

5. Labelling @ Switchgear:

6. Labelling @ LVDB:

7. Gas Pressure:

8. Tx Guard:

9. Tx Oil Level (conservator tank):

10. Tx Oil Leak:

11. Tx Bushing:

12. Top Demand Indicator (@LVDB):

13. Link/fuse Holder:

14. LV Termination:

15. Rubber Mat:

16. Trenching:

17. Battery Voltage:

18. Lighting:

19. Roof Condition:

20. Fire Fighting:

21. Fence/door condition:

22. Cleanliness/Bushes:

23. Vandalism:

24. Other Findings:

6/3/2026

SS KG BENGALI

SS KG BENGALI

3.812693, 101.844392

INDOOR ☒ OUTDOOR ☒NORMAL ☒ INDUSTRIAL ☒RMU OIL ☒ RMU SF6 ☒

W0402 / W524

2012

RMU OIL ☒ RMU SF6 ☒

N/A

N/A

Type ☐ KVA ☐Type ☐ KVA ☐Type ☐ KVA ☐Type ☐ KVA ☐COMPACT ☐COASTAL ☐MRMU ☐

Switchgear Rating: 12 kV

MRMU ☐Switchgear Rating: ☐Construction Yr: ☐Construction Yr: ☐Construction Yr: ☐Construction Yr: ☐(recept (Sug),  
(cable-comp)

F/L NO (ERMS):

F/L NO (SITE):

CRAV/PCE/J00260

CRAV/PCE/J00260

ATTACH BUILDING ☐PAT ☐VCB ☐OCB ☐

RMU SF6 / OIL S/N: 1205306965

OCB ☐RMU SF6 / OIL S/N: ☐

S/N:

S/N:

S/N:

S/N:

|                                          |                                        |
|------------------------------------------|----------------------------------------|
| YES <input checked="" type="checkbox"/>  | NO <input type="checkbox"/>            |
| Good <input checked="" type="checkbox"/> | Not Good <input type="checkbox"/>      |
| Good <input checked="" type="checkbox"/> | Not Good <input type="checkbox"/>      |
| Good <input checked="" type="checkbox"/> | Not Good <input type="checkbox"/>      |
| Good <input checked="" type="checkbox"/> | Not Good <input type="checkbox"/>      |
| Good <input checked="" type="checkbox"/> | Not Good <input type="checkbox"/>      |
| Good <input checked="" type="checkbox"/> | Not Good <input type="checkbox"/>      |
| YES <input type="checkbox"/>             | NO <input type="checkbox"/>            |
| Good <input type="checkbox"/>            | Not Good <input type="checkbox"/>      |
| YES <input type="checkbox"/>             | NO <input type="checkbox"/>            |
| Good <input type="checkbox"/>            | Not Good <input type="checkbox"/>      |
| Good <input type="checkbox"/>            | Not Good <input type="checkbox"/>      |
| Good <input type="checkbox"/>            | Not Good <input type="checkbox"/>      |
| Good <input type="checkbox"/>            | Not Good <input type="checkbox"/>      |
| YES <input checked="" type="checkbox"/>  | NO <input type="checkbox"/>            |
| Good <input checked="" type="checkbox"/> | Not Good <input type="checkbox"/>      |
| Good <input type="checkbox"/>            | Not Good <input type="checkbox"/>      |
| Good <input type="checkbox"/>            | Not Good <input type="checkbox"/>      |
| Good <input type="checkbox"/>            | Not Good <input type="checkbox"/>      |
| Good <input checked="" type="checkbox"/> | Not Good <input type="checkbox"/>      |
| Good <input type="checkbox"/>            | Not Good <input type="checkbox"/>      |
| Valid <input type="checkbox"/>           | Expired <input type="checkbox"/>       |
| Good <input checked="" type="checkbox"/> | Not Good <input type="checkbox"/>      |
| Good <input checked="" type="checkbox"/> | Not Good <input type="checkbox"/>      |
| YES <input type="checkbox"/>             | NO <input checked="" type="checkbox"/> |

|         |                                                 |
|---------|-------------------------------------------------|
| Remarks |                                                 |
| Remarks |                                                 |
| Remarks |                                                 |
| Remarks | N/A                                             |
| Remarks |                                                 |
| Remarks | N/A                                             |
| Remarks |                                                 |
| Remarks | N/A                                             |
| Remarks | N/A                                             |
| Remarks | N/A                                             |
| Remarks | N/A                                             |
| Remarks | N/A                                             |
| Remarks | N/A                                             |
| Remarks |                                                 |
| Remarks |                                                 |
| Remarks | N/A                                             |
| Remarks | NOT OPERATED                                    |
| Remarks |                                                 |
| Remarks | Expiry Date: OUTDOOR No. of missing portable: - |
| Remarks |                                                 |
| Remarks |                                                 |
| Remarks |                                                 |

EET ENGINEERING SERVICES SDN BHD

(534556-W)

No. 38-2, 2nd Floor, Jalan SS 19/1D

47500 Subang Jaya, Selangor.

Tel: 603-5636 6205 Fax: 603-5636 7205

TESTED BY (NAME &amp; SIGNATURE):

TNB SUPERVISOR/ ENGINEER (NAME &amp; SIGNATURE):

MOHD AZZAD BIN OTHMAN (19058230)  
JURUTEKNIK TINGGI BIASA  
DIAGNOSTIC SUBSTATION PAHANG  
SBU MAINTENANCE EAST  
DISTRIBUTION NETWORK DIVISION