




Traffic Calming Study

City of Albuquerque

McDuffie/Twin Parks Neighborhood
Albuquerque, NM
5/7/2024

Traffic Calming Study

Prepared for

City of Albuquerque

McDuffie/Twin Parks Neighborhood
Albuquerque, NM

Prepared by



4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109
505-348-4000

© 2023 Wilson & Company, Inc., Engineers & Architects

Audra V. Gallegos
Audra Gallegos, PE

05.07.24
Date

Table of Contents

List of Tables	ii
List of Figures	iii
List of Abbreviations	iv
Executive Summary.....	v
Summary of Findings and Recommendations	v
1.0 Introduction.....	1
2.0 Project Area and Background	1
3.0 Existing Conditions	2
3.1 Roadways.....	2
3.2 Traffic Conditions	5
3.2 Safety.....	9
Crash Data.....	9
Crash Analysis.....	18
Washington Street and Aspen Avenue.....	18
Washington Street and Constitution Avenue.....	18
Washington Street and Lomas Boulevard	19
Washington Street and Avenida Del Sol.....	19
Morningside Drive and Constitution Avenue.....	19
Montclair Drive and Lomas Boulevard.....	19
3.3 Speed.....	19
3.5 Sight Distance.....	20
3.6 Lighting.....	23
4.0 NTMP Traffic Calming Criteria.....	24
4.1 NTMP Thresholds	24
5.0 Proposed Alternatives	28
5.1 Pedestrian Crossings	28
5.2 Striping.....	30
5.3 Traffic Circle.....	30
5.4 Neckdowns and/or Bulbouts	32
5.5 Speed Humps	33
6.0 Public Involvement	33

6.1 Public Meeting #1	33
6.1.1 Post Meeting Comments.....	33
6.2 Public Meeting #2	34
6.2.1 Post Meeting Comments.....	34
7.0 Summary of Findings and Recommendations.....	34
Appendix A – Traffic Data	A
Appendix B – Crash Data.....	B
Appendix C – Public Meeting Summary	C
Appendix D – Conceptual Cost Estimates.....	D

List of Tables

Table 1: Tube Count Data Summary	7
Table 2: Observed Pedestrian/Bicycle Crossing Counts	8
Table 3: Total Crash Data.....	9
Table 4: Morningside Drive/Marble Avenue – Crash Summary	11
Table 5: Washington Street – Crash Summary.....	11
Table 6: Constitution Avenue – Crash Summary	15
Table 7: Mackland Avenue – Crash Summary.....	16
Table 8: Montclair Drive – Crash Summary	16
Table 9: Washington Street and Constitution Avenue – Crash Severity	18
Table 10: Washington Street and Lomas Boulevard – Crash Severity.....	19
Table 11: Washington Street and Avenida Del Sol – Crash Severity.....	19
Table 12: Morningside Drive and Constitution Avenue – Crash Severity.....	19
Table 13: Montclair Drive and Lomas Boulevard – Crash Severity	19
Table 14: Percentage of Vehicles Exceeding Speed Limit	20
Table 15: Morningside Drive – Threshold Criteria Evaluation Results.....	25
Table 16: Washington Street – Threshold Criteria Evaluation Results	25
Table 17: Constitution Avenue – Threshold Criteria Evaluation Results.....	25
Table 18: Mackland Avenue – Threshold Criteria Evaluation Results	26
Table 19: Avenida Del Sol – Threshold Criteria Evaluation Results	26
Table 20: Montclair Drive – Threshold Criteria Evaluation Results.....	26
Table 21: Solano Drive – Threshold Criteria Evaluation Results.....	27
Table 22: Crossing Treatment Selection Matrix.....	28
Table 23: NTMP Criterion Results.....	34

List of Figures

Figure 1: Project Area	1
Figure 2: Washington Street from Marble Avenue to Constitution Avenue - Existing Typical Section	2
Figure 3: Washington Street from Constitution Avenue to Joe Dan Place - Existing Typical Section	2
Figure 4: Washington Street from Joe Dan Place to Indian School Road - Existing Typical Section	2
Figure 5: Constitution Avenue from Carlisle Avenue to Manana Avenue - Existing Typical Section	3
Figure 6: Constitution Avenue from Manana Avenue to Washington Street - Existing Typical Section	3
Figure 7: Morningside Drive - Existing Typical Section	3
Figure 8: Aspen Avenue - Existing Typical Section	3
Figure 9: Avenida Del Sol - Existing Typical Section	4
Figure 10: Montclair Drive - Existing Typical Section	4
Figure 11: Mackland Avenue - Existing Typical Section	4
Figure 12: Solano Drive - Existing Typical Section from Indian School Road to Mackland Avenue	4
Figure 13: Solano Drive - Existing Typical Section from Mackland Avenue to Lomas Boulevard	5
Figure 14: 2021 MRCOG AAWDT	5
Figure 15: Pedestrian Data Collection	8
Figure 16: Crash Heat Map	17
Figure 17: Washington Street and Constitution Avenue – Crash Types	18
Figure 18: Morningside Drive and Avenida la Resolana Sight Distance	21
Figure 19: Constitution Avenue and Washington Street Sight Distance	22
Figure 20: Street Lighting Locations	23
Figure 21: Washington Street and Sunningdale Avenue	29
Figure 22: Morningside Drive and Constitution Avenue	29
Figure 23: Washington Street and Constitution Avenue	30
Figure 24: Montclair Drive and Mackland Avenue – Proposed Traffic Circle	31
Figure 25: Avenida Del Sol and Avenida La Resolana – Proposed Traffic Circle	31
Figure 26: Avenida Del Sol and Morningside Drive – Proposed Bulbout	32
Figure 27: Avenida Del Sol – Proposed Speed Humps	33

List of Abbreviations

Abbreviation

Term/Phrase/Name

AAWDT

Average Annual Weekday Traffic

COA

City of Albuquerque

MPH

Miles Per Hour

MRCOG

Mid-Region Council of Governments

NTMP

Neighborhood Traffic Management Program

vpd

vehicles per day

Executive Summary

This report documents the traffic calming analysis conducted within the McDuffie and Twin Parks Neighborhoods, located north of Lomas Boulevard, south of Indian School Road, east of Carlisle Boulevard and west of Washington Street in Albuquerque, New Mexico. The purpose of this project was to collect and analyze traffic volumes, speeds, and conduct a safety analysis along Washington Street, Constitution Avenue, Morningside Drive, Aspen Avenue, Avenida Del Sol, Montclair Drive, Mackland Avenue, and Solano Drive to determine if they meet the traffic calming criterion described in the *City of Albuquerque (COA) Neighborhood Traffic Management Program (NTMP)*, October 2020.

Summary of Findings and Recommendations

An assessment was conducted in the McDuffie-Twin Parks neighborhoods, along Washington Street, Constitution Avenue, Morningside Drive, Avenida Del Sol, Montclair Drive, Mackland Avenue, and Solano Drive. These roadways were analyzed to determine if they meet the traffic calming criterion described in the *City of Albuquerque (COA) Neighborhood Traffic Management Program (NTMP)*, October 2020 results can be found in the table below.

NTMP Criterion Results

Roadway Name	NTMP Thresholds	# of NTMP Threshold Met	Meets Minimum
Washington Drive	9	6	YES
Constitution Avenue	9	2	YES
Morningside Drive	9	0	NO
Avenida Del Sol	9	1	YES
Montclair Drive	9	0	NO
Mackland Avenue	9	0	NO
Solano Drive	9	0	NO

From the results shown in [Table 23](#), only three of the roadways analyzed meet the minimum criterion needed to qualify for traffic calming. Therefore, different alternatives were analyzed along these roadways which include pedestrian crossings, striping, traffic circles, neckdowns/bulbouts, and speed bumps. The recommendations for each alternative analyzed are presented below, conceptual cost estimates are shown in the parentheses:

- Washington Street and Sunningdale Avenue (\$195,972)
 - **Pedestrian crossing.** Crosswalk marking and signage along the north and south legs. Complementary treatments are also recommended and can include stop or yield lines, in-street crossing sign, and a raised crosswalk.
 - **Striping.** A change in the existing lane roadway configuration to include bike lanes along Washington Street on both sides. The existing left-turn bays for northbound and southbound would be removed to shorten the pedestrian crossing distance. Add delineators between the bike lane and travel lane near intersection/pedestrian crossing.
 - **Neckdown/bulbout.** A bulbout is proposed at the southwest corner of the intersection to shorten the pedestrian crossing distances. A bulbout is proposed at the northeast corner of the intersection, on Sunningdale Avenue, in order to make the approach perpendicular to Washington Street.
- Morningside Drive and Constitution Avenue (\$139,913)
 - **Pedestrian crossing.** Crosswalk marking and signage along the east and west legs. Complementary treatments are also recommended and can include stop or yield lines, in-street crossing sign and raised crosswalk. Add delineators between the bike lane and travel lane near intersection/pedestrian crossing.
 - **Neckdown/bulbout.** A bulbout is proposed at the southeast corner of the intersection to shorten the pedestrian crossing distance and improve sight distances for the northbound approach.

- Washington Street and Constitution Avenue (\$58,614)
 - **Neckdown/bulbout.** A bulbout is proposed at the southwest corner of the intersection to shorten the pedestrian crossing distance and improve sight distances for the northbound approach. Add delineators between the bike lane and travel lane near intersection/pedestrian crossing.
- Constitution Avenue between Carlisle Boulevard and Morningside Drive
 - **Striping.** Addition of a striped buffered bike lane should be considered to narrow the driving lanes to 11-ft.
- Montclair Drive and Mackland Avenue (\$66,919)
 - **Traffic circle.** A change in the existing intersection control type from a two-way stop-controlled along Montclair Drive into a traffic circle with yield signs on all approaches.
- Avenida Del Sol (\$35,475)
 - **Speed humps/cushions.** Addition of speed humps or speed cushions along Avenida Del Sol between Morningside Drive and Washington Street.
- Hidden Park
 - **Striping.** Addition of no parking pavement markings at all access points to Hidden Park. Striping would include striped chevron markings and “NO PARKING” pavement markings.

1.0 Introduction

This report documents the traffic calming analysis conducted within the McDuffie and Twin Parks Neighborhoods, located north of Lomas Boulevard, south of Indian School Road, east of Carlisle Boulevard and west of Washington Street in Albuquerque, New Mexico. The purpose of this project was to collect and analyze traffic volumes, speeds, and conduct a safety analysis along Washington Street, Constitution Avenue, Morningside Drive, Aspen Avenue, Avenida Del Sol, Montclair Drive, Mackland Avenue, and Solano Drive to determine if they meet the traffic calming criterion described in the *City of Albuquerque (COA) Neighborhood Traffic Management Program (NTMP)*, October 2020.

2.0 Project Area and Background

The project is located in Albuquerque, New Mexico. The McDuffie and Twin Parks Neighborhoods are located near Washington Street and Constitution Avenue. City of Albuquerque Council Services staff met with individuals representing the neighborhoods to identify their concerns are regarding traffic. The main concerns are located along Washington Street, Constitution Avenue, Morningside Avenue, Marble Avenue, Avenida Del Sol, Mackland Avenue, Montclair Drive, Solano Drive, and the access points at Hidden Park (see [Figure 1](#)).




Figure 1: Project Area

3.0 Existing Conditions

3.1 Roadways

Washington Street. Washington Street is a two-lane, undivided major collector that runs north-south between Indian School Road and Lomas Boulevard. It intersects Constitution Avenue at a signalized intersection and has a posted speed limit of 30 mph. Washington Street from Marble Avenue to Constitution Avenue is a 28-ft wide roadway with 3-ft bike lanes, curb and gutter, and 4-ft wide sidewalks. Washington Street from Constitution Avenue to Joe Dan Place is a 36-ft wide roadway with a 4-ft bike lane on the west side of the roadway, a 5-ft bike lane on the east side of the roadway, 5-ft on-street parking on the east side of the roadway, curb and gutter, and 4-ft wide sidewalks. Washington Street from Joe Dan Place to Indian School Road is a 38-ft wide roadway with 4-ft bike lanes, 4-ft on-street parking lanes, curb and gutter, and 4-ft wide sidewalks. See [Figure 2](#) through [Figure 4](#) for the existing Washington Street typical sections.




Figure 2: Washington Street from Marble Avenue to Constitution Avenue - Existing Typical Section




Figure 3: Washington Street from Constitution Avenue to Joe Dan Place - Existing Typical Section




Figure 4: Washington Street from Joe Dan Place to Indian School Road - Existing Typical Section

Constitution Avenue. Constitution Avenue is a two-lane, undivided major collector that runs east-west between Carlisle Boulevard and Washington Street. It intersects Morningside Drive at a two-way stop-controlled intersection and has a posted speed limit of 30 mph. Constitution Avenue from Carlisle Avenue to Manana Avenue is a 44-ft wide roadway with 4-ft bike lanes, curb and gutter, and 4-ft wide sidewalks. Constitution Avenue from Manana Avenue to Washington Street is a 36-ft wide roadway with 7-ft bike lanes, curb and gutter, and 4-ft wide sidewalks. See [Figure 5](#) and [Figure 6](#) for the existing Constitution Avenue typical sections.




Figure 5: Constitution Avenue from Carlisle Avenue to Manana Avenue - Existing Typical Section




Figure 6: Constitution Avenue from Manana Avenue to Washington Street - Existing Typical Section

Morningside Drive. Morningside Drive is a north-south, two-way local roadway. It is a 28-ft wide roadway with curb and gutter, and 4-ft wide sidewalks. See [Figure 7](#) for the existing Morningside Drive typical section.




Figure 7: Morningside Drive - Existing Typical Section

Aspen Avenue. Aspen Avenue is an east-west, two-way local roadway. It is a 28-ft wide roadway with curb and gutter, and a 4-ft wide sidewalk on the southside of the roadway. See [Figure 8](#) for the existing Aspen Avenue typical section.




Figure 8: Aspen Avenue - Existing Typical Section

Avenida Del Sol. Avenida Del Sol is a two-way local roadway. It is a 28-ft wide roadway with curb and gutter, and 4-ft wide sidewalks. See [Figure 9](#) for the existing Avenida Del Sol typical section.




Figure 9: Avenida Del Sol - Existing Typical Section

Montclair Drive. Montclair Drive is an north-south, two-way local roadway. It is a 32-ft wide roadway with curb and gutter, and 4-ft wide sidewalks. See [Figure 10](#) for the existing Montclair Drive typical section.




Figure 10: Montclair Drive - Existing Typical Section

Mackland Avenue. Mackland Avenue is a east-west, two-way local roadway. It is a 32-ft wide roadway with curb and gutter, and 4-ft wide sidewalks. See [Figure 11](#) for the existing Mackland Avenue typical section.




Figure 11: Mackland Avenue - Existing Typical Section

Solano Drive. Solano Drive is a north-south, local roadway. It is a two-lane roadway with curb and gutter, and sidewalks on both sides. Solano Drive from Indian School Road to Aspen Avenue, from Aspen Avenue to Morningside Drive, and from La Hacienda Drive to Mackland Avenue is a 28-ft wide roadway with curb and gutter, and 4-ft wide sidewalks. Solano Drive from Mackland Avenue to Lomas Boulevard is a 32-ft wide roadway with curb and gutter, and 3-ft wide sidewalks. See [Figure 12](#) and [Figure 13](#) for the existing Solano Drive typical sections.




Figure 12: Solano Drive - Existing Typical Section from Indian School Road to Mackland Avenue




Figure 13: Solano Drive - Existing Typical Section from Mackland Avenue to Lomas Boulevard

3.2 Traffic Conditions

Historical traffic volumes were obtained from the Mid-Region Council of Governments (MRCOG) 2021 Traffic Flow Map for the Greater Albuquerque Area, see [Figure 14](#). The 2021 average annual weekday traffic (AAWDT) for Washington Street ranges from 5,800 vehicles per day (vpd) to 7,200 vpd within the study area. Constitution Avenue has an AAWDT of 6,600 vpd.



Figure 14: 2021 MRCOG AAWDT

Tube count data (volume, speed, classification) was collected for a 48-hour period on Wednesday, September 14, 2022, through Thursday, September 15, 2022, as well as, Wednesday, September 21, 2022, through Thursday, September 22, 2022. The tube counts were setup at multiple locations within the study area, which are shown in [Figure 1](#).

Table 1 provides a summary of the data collected from the tube counts, the full tube count data can be found in **Appendix A**. The average daily traffic on Washington Street ranged from 6,264 vpd to 6,805 vpd, which is similar to the 2021 MRCOG AAWDT data. Whereas Constitution Avenue, the average daily traffic was observed to drop from 6,600 vpd in the 2021 MRCOG AAWDT data to a range from 4,604 vpd to 5,264 vpd from the data collected.

Table 1: Tube Count Data Summary


Counter No.	Location	Direction	Volume (veh/day)	ADT (veh/day)	Posted Speed Limit (mph)	85 th Percentile Speed (mph)
1	Morningside Dr. between Indian School Rd. & Hannett Ave.	NB	189	365	25	30
		SB	176			29
2	Morningside Dr. between Hannett Ave. and Aspen Ave.	NB	259	454	25	22
		SB	195			21
3	Washington St. between Avenida Alturas NE & Sunningdale Ave. NE	NB	3,290	6,805	30	35
		SB	3,515			39
4	Washington St. between Royene Ave. NE & Chinlee Ave. NE	NB	3,327	6,405	30	38
		SB	3,078			34
5	Washington St. between Avenida Estrellita NE & Avenida Manana NE	NB	3,193	6,264	30	36
		SB	3,071			37
6	Washington St. between Mackland Ave. NE & Marble Ave.	NB	3,183	6,315	30	35
		SB	3,132			33
7	Constitution Ave. between Morningside Dr. & Avenida Manana NE	WB	2,519	5,264	30	44
		EB	2,745			37
8	Constitution Ave. between Morningside Dr. & Carlisle Blvd. NE	WB	2,570	4,604	30	38
		EB	2,034			38
9	Avenida Del Sol between Morningside Dr. & Avenida La Resolana	WB	148	275	25	26
		EB	127			32
10	Avenida Del Sol between Avenida La Resolana & Washington St.	WB	112	244	25	27
		EB	132			32
11	Morningside Dr. between Constitution Ave. & Mackland Ave.	NB	226	504	25	28
		SB	278			27
12	Marble Ave. between Calle Del Contento & Washington St.	WB	108	219	25	27
		EB	111			27
13	Mackland Ave. between Carlisle Blvd. & Montclair Dr.	WB	326	707	25	29
		EB	381			27
14	Mackland Ave. between Montclair Dr. & Morningside Dr.	WB	251	515	25	23
		EB	264			23
15	Montclair Dr. south of McDuffie Cir.	NB	252	528	25	30
		SB	276			29
16	Montclair Dr. north of Mesa Verde Ave.	NB	248	523	25	29
		SB	275			30
17	Solano Drive north of Aspen Avenue	NB	187	356	25	30
		SB	169			31
18	Solano Drive north of Lomas Boulevard	NB	80	167	25	26
		SB	87			25

Pedestrian and bicyclist crossings were collected at three intersections within the study area, shown in [Table 2](#). For the pedestrians crossing movements within the study area, the AM and PM Peak Hours were found to be 9:00 AM to 10:00 AM and 6:00 PM to 7:00 PM. For bicyclist the AM and PM Peak hours were found to be 7:45 AM to 8:45 AM and 2:00 PM to 3:00 PM.

Table 2: Observed Pedestrian/Bicycle Crossing Counts

Intersection	Time	Pedestrian 13-hr Volume				Bicyclist 13-hr Volume			
		South Leg	West Leg	North Leg	East Leg	NB	EB	SB	WB
Washington St. and Sunningdale Ave.	AM Peak	15	2	16	3	4	0	3	2
	PM Peak	1	2	9	1	8	3	3	0
	13 Hour Total	53	19	87	13	58	11	48	6
Washington St. and Constitution Ave.	AM Peak	2	2	1	3	0	2	2	4
	PM Peak	2	2	0	0	0	4	3	0
	13 Hour Total	9	8	3	4	17	39	18	36
Morningside Dr. and Constitution Ave.	AM Peak	4	5	1	10	0	2	2	6
	PM Peak	3	12	0	9	1	5	1	0
	13 Hour Total	16	71	12	57	22	37	15	37

The data collected provides pedestrian crossing information based on the approaching leg that they are crossing, see [Figure 15](#).



Source: Spack Solutions

Figure 15: Pedestrian Data Collection

3.2 Safety

Crash Data

Historical crash data was provided by MRCOG for the last five years available (2016-2020). The crash data requested was within the study area and at the specified roadways. There was a total of 158 reported crashes at the specified locations (see [Appendix B](#)). Out of the total crashes, 67% of crashes (106 crashes) were property damage only and 33% (52 crashes) were injury, see [Table 3](#). There were no fatalities that occurred during the five-year analysis period.

Table 3: Total Crash Data

Year	Crash Severity			Total
	Injury	Fatal	PDO*	
2016	9 (25%)	0 (0%)	27 (75%)	36 (100%)
2017	8 (27%)	0 (0%)	22 (73%)	30 (100%)
2018	11 (42%)	0 (0%)	15 (58%)	26 (100%)
2019	16 (39%)	0 (0%)	25 (61%)	41 (100%)
2020	8 (32%)	0 (0%)	17 (68%)	25 (100%)
Total	52 (33%)	0 (0%)	106 (67%)	158 (100%)

*PDO – Property Damage Only

The following observations were concluded from the crash data:

- Most of the crashes occurred in clear days 88% (116 crashes) of the total crashes and approximately 72% (95 crashes) occurred in daylight conditions.
- Single vehicles crashes made up 7% (12 crashes) of those reported at the specified locations, while 78% of crashes involved two-vehicles (123 crashes), 13% involved three-vehicles (20 crashes), 1% involved four-vehicles (2 crashes), and 1% involved five-vehicles (1 crash).
- Approximately 82% (130 crashes) of all the crashes involved another vehicle, and 5% (8 crashes) involved a fixed object.

Table 4 through **Table 8** present information related to the crash data by date, primary street, intersecting street, crash analysis, severity, top contributing factor and if the crash could be correctable with a traffic calming measure. A traffic calming measure consists of physical design or other strategies put in place on existing roads to reduce vehicle speeds and improve safety for pedestrians and cyclists. Hence, crashes that had excessive speed as a contributing factor were considered correctable. NMDOT no longer provides information such as top contributing factor for crash data that occurred in year 2020 and later. The 2020 police reports were requested from the Albuquerque Police Department in order to determine the top contributing factors. There were no reported crashes along Solano Drive as the primary street, only one reported crash at the intersection of Aspen Drive classified as head on with property damage.

Table 4: Morningside Drive/Marble Avenue – Crash Summary

Crash Date	Crash Primary Street	Crash Intersecting Street	Crash Analysis	Severity	Contributing Factors	Correctable with Traffic Calming
10/15/2016	Marble Ave NE		Invalid Code	Property Damage Only Crash	None	No
5/13/2017	Morningside Dr NE	Avenida La Resolana NE	Other Vehicle - All Others/Entering At Angle	Injury Crash	Failed to Yield Right of Way	No
11/12/2019	1822 Morningside Dr NE		Left Blank	Property Damage Only Crash	Missing Data	No
2/12/2020	Marble Rd In Front Of 700 Washington NE		Parked Vehicle - Unknown/Not Stated	Property Damage Only Crash	Driver Inattention	No

Table 5: Washington Street – Crash Summary

Crash Date	Crash Primary Street	Crash Intersecting Street	Crash Analysis	Severity	Contributing Factors	Correctable with Traffic Calming
3/10/2016	Washington	Constitution	Invalid Code	Property Damage Only Crash	Excessive Speed	Yes
5/5/2016	Washington St NE	Indian School Rd NE	Other Vehicle - From Same Direction/Rear End Collision	Property Damage Only Crash	Driver Inattention	No
6/21/2016	Washington NE	Constitution NE	Other Vehicle - From Opposite Direction	Property Damage Only Crash	Driver Inattention	No
7/16/2016	Washington St NE	Mountain Rd NE	Other Vehicle - From Opposite Direction	Property Damage Only Crash	Passed Stop Sign	No
8/25/2016	Washington	Indian School	Invalid Code	Property Damage Only Crash	Other Improper Driving	No
9/22/2016	Washington St NE	Lomas Blvd NE	Other Vehicle - All Others/Entering At Angle	Property Damage Only Crash	Driver Inattention	No
11/19/2016	Washington St NE	Constitution Ave NE	Other Vehicle - One Right Turn/Entering At Angle	Property Damage Only Crash	Avoid No Contact - Vehicle	No
12/3/2016	Washington St NE	Marble Ave NE	Other Vehicle - All Others/Entering At Angle	Property Damage Only Crash	Failed to Yield Right of Way	No
12/19/2016	Washington	Constitution	Left Blank	Injury Crash	Driver Inattention	No

Crash Date	Crash Primary Street	Crash Intersecting Street	Crash Analysis	Severity	Contributing Factors	Correctable with Traffic Calming
2/19/2017	Washington St NE	Sunningdale Ave NE	Other Vehicle - From Same Direction/Rear End Collision	Property Damage Only Crash	Following Too Closely	No
3/15/2017	Washington St NE	Lomas Blvd NE	Other Vehicle - All Others/Entering At Angle	Property Damage Only Crash	Made Improper Turn	No
4/15/2017	Washington NE	Indian School	Left Blank	Property Damage Only Crash	Missing Data	No
4/15/2017	Washington Pl NE	Indian School Rd NE	Left Blank	Property Damage Only Crash	Driver Inattention	No
4/15/2017	Washington St NE	Constitution Ave NE	Other Vehicle - Both Going Straight/Entering At Angle	Property Damage Only Crash	Driver Inattention	No
4/19/2017	Washington NE	Constitution NE	Left Blank	Property Damage Only Crash	Passed Stop Sign	No
5/6/2017	Washington St NE	Constitution Ave NE	Fixed Object - Fence (Wood, Brick, Stone)	Property Damage Only Crash	Disregarded Traffic Signal	No
5/11/2017	Washington	Lomas	Left Blank	Property Damage Only Crash	Missing Data	No
5/17/2017	Washington Ave	Avenida Del Sol NE	Other Vehicle - From Opposite Direction/One Left Turn	Injury Crash	Driver Inattention	No
7/14/2017	Washington St NE	Lomas Blvd NE	Other Vehicle - From Same Direction/Both Going Straight	Injury Crash	Driver Inattention	No
11/16/2017	Washington NE	Constitution	Left Blank	Property Damage Only Crash	Failed to Yield Right of Way	No
2/2/2018	Washington St NE	Indian School Rd NE	Overturn/Rollover - Right Side of Road	Property Damage Only Crash	Avoid No Contact - Vehicle	No
4/26/2018	Washington St NE	Indian School Rd NE	Other Vehicle - Both Going Straight/Entering At Angle	Injury Crash	Driver Inattention	No
5/9/2018	Washington St		Other Vehicle - From Same Direction/Rear End Collision	Injury Crash	Following Too Closely	No

Crash Date	Crash Primary Street	Crash Intersecting Street	Crash Analysis	Severity	Contributing Factors	Correctable with Traffic Calming
5/17/2018	Washington Ave	Constitution Ave NE	Other Vehicle - One Left Turn/Entering At Angle	Injury Crash	Failed to Yield Right of Way	No
6/8/2018	Washington St NE	Indian School Rd NE	Fixed Object - Median Raised Or Curb	Property Damage Only Crash	Alcohol/Drug Involved	No
7/6/2018	Lomas And Washington NE		Left Blank	Property Damage Only Crash	Missing Data	No
7/19/2018	Washington St NE	Constitution Ave NE	Fixed Object - Unknown/Not Stated	Property Damage Only Crash	Excessive Speed	Yes
7/19/2018	NB Washington and Constitution		Left Blank	Property Damage Only Crash	Driver Inattention	No
10/31/2018	Washington St NE		Other Vehicle - From Same Direction/Both Going Straight	Property Damage Only Crash	Driver Inattention	No
11/14/2018	Washington St NE	Avenida Del Sol NE	Other Vehicle - From Opposite Direction/One Right Turn	Property Damage Only Crash	Other Mechanical Defect	No
12/26/2018	Washington St NE	Indian School Rd NE	Other Vehicle - Both Going Straight/Entering At Angle	Injury Crash	Driver Inattention	No
2/6/2019	Washington St NE	Avenida Del Sol NE	Other Vehicle - Both Going Straight/Entering At Angle	Property Damage Only Crash	Other Mechanical Defect	No
3/15/2019	N - Washington & Lomas	Hit Coming N - In Front Of Starbucks	Left Blank	Property Damage Only Crash	Failed to Yield Right of Way	No
4/10/2019	Washington Street NE	Washington & Indian School	Left Blank	Property Damage Only Crash	Excessive Speed	Yes
4/13/2019	Washington St NE	Indian School NE	Left Blank	Property Damage Only Crash	Missing Data	No
5/16/2019	Lomas/ Washington	Lomas/ Washington	Other Vehicle - One Left Turn/Entering At Angle	Injury Crash	Disregarded Traffic Signal	No
6/14/2019	Washington	Indian School	Left Blank	Property Damage Only Crash	Missing Data	No

Crash Date	Crash Primary Street	Crash Intersecting Street	Crash Analysis	Severity	Contributing Factors	Correctable with Traffic Calming
6/21/2019	Washington Blvd NE	Constitution NE	Left Blank	Property Damage Only Crash	Passed Stop Sign	No
7/24/2019	Washington Pl NE	Indian School Rd NE	Left Blank	Property Damage Only Crash	Missing Data	No
7/30/2019	Washington Pl NE	Indian School Rd NE	Other Vehicle - From Same Direction/One Left Turn	Property Damage Only Crash	Made Improper Turn	No
8/2/2019	Washington St NE	Indian School Rd NE	Other Vehicle - From Same Direction/Rear End Collision	Property Damage Only Crash	Following Too Closely	No
9/4/2019	Washington St	Indian School Rd NE	Other Vehicle - From Same Direction/Both Going Straight	Property Damage Only Crash	Other - No Driver Error	No
9/10/2019	Washington St NE	Constitution Ave NE	Other Vehicle - From Same Direction/Rear End Collision	Injury Crash	Vehicle Skidded Before Brake	No
9/13/2019	Washington St NE	Constitution Ave NE	Other Vehicle - From Opposite Direction/Both Going Straight	Injury Crash	Alcohol/Drug Involved	No
10/7/2019	Washington and Indian School	Washington NE	Other Vehicle - From Same Direction/One Stopped	Property Damage Only Crash	Alcohol/Drug Involved	No
11/3/2019	Washington	Constitution	Left Blank	Property Damage Only Crash	Missing Data	No
11/21/2019	Washington NE	Mountain NE	Left Blank	Property Damage Only Crash	Passed Stop Sign	No
11/25/2019	Washington St NE	Lomas Blvd NE	Other Vehicle - One Left Turn/Entering At Angle	Injury Crash	Disregarded Traffic Signal	No
12/13/2019	Washington St NE	Indian School Rd NE	Other Vehicle - From Same Direction/Both Going Straight	Injury Crash	Driver Inattention	No
1/16/2020	Washington St NE	Mountain Rd NE	Other Vehicle - Both Going Straight/Entering At Angle	Injury Crash	Passed Stop Sign	No

Crash Date	Crash Primary Street	Crash Intersecting Street	Crash Analysis	Severity	Contributing Factors	Correctable with Traffic Calming
2/9/2020	Washington St NE	Constitution Ave NE	Other Vehicle - From Opposite Direction/Both Going Straight	Property Damage Only Crash	Driver Inattention	No
3/12/2020	Washington St NE	Constitution Ave NE	Other Vehicle - Both Going Straight/Entering At Angle	Injury Crash	Failed to Yield Right of Way	No
3/16/2020	Washington St NE	Indian School Rd NE	Other Vehicle - Both Going Straight/Entering At Angle	Property Damage Only Crash	Disregarded Traffic Signal	No
6/30/2020	Washington St NE	Constitution Ave NE	Other Vehicle - From Opposite Direction/Both Going Straight	Property Damage Only Crash	Passes Stop Sign	No
8/29/2020	Washington St NE	Lomas Blvd NE	Left Blank	Injury Crash	Driver Inattention	No
10/14/2020	Washington Ave	Constitution Ave NE	Left Blank	Property Damage Only Crash	Driver Inattention	No
11/26/2020	Washington St NE	Lomas Blvd NE	Left Blank	Injury Crash	Disregarded Traffic Signal	No
12/31/2020	Washington St NE	Constitution Ave NE	Left Blank	Injury Crash	Passed Stop Sign	No

Table 6: Constitution Avenue – Crash Summary

Crash Date	Crash Primary Street	Crash Intersecting Street	Crash Analysis	Severity	Contributing Factors	Correctable with Traffic Calming
2/12/2016	Constitution NE	Washington NE	Other Vehicle - From Opposite Direction	Property Damage Only Crash	Failed to Yield Right of Way	No
3/3/2016	Constitution Ave NE	Washington St NE	Other Vehicle - From Opposite Direction	Property Damage Only Crash	Failed to Yield Right of Way	No
7/29/2016	Constitution Ave NE	Washington St NE	Other Vehicle - From Same Direction/ Rear End Collision	Property Damage Only Crash	Driver Inattention	No
11/22/2016	Constitution Ave NE	Morningside Dr NE	Fixed Object - Fire Hydrant	Property Damage Only Crash	Other Improper Driving	No
5/12/2017	Intersection: Constitution/ Washington		Left Blank	Property Damage Only Crash	Passed Stop Sign	No
5/20/2017	Constitution Ave NE	Morningside Dr NE	Other Vehicle - One Right	Injury Crash	Improper Overtaking	No

Crash Date	Crash Primary Street	Crash Intersecting Street	Crash Analysis	Severity	Contributing Factors	Correctable with Traffic Calming
			Turn/ Entering At Angle			
8/28/2017	Constitution Ave NE	Washington Ave	Other Vehicle - Both Going Straight/ Entering At Angle	Property Damage Only Crash	Disregarded Traffic Signal	No
9/3/2017	Constitution Ave NE	Washington Ave	Other Vehicle - Both Going Straight/ Entering At Angle	Property Damage Only Crash	Passed Stop Sign	No
10/21/2017	Constitution Ave NE	Washington St NE	Left Blank	Property Damage Only Crash	Improper Backing	No
12/14/2017	Constitution NE	Washington NE	Left Blank	Property Damage Only Crash	Driver Inattention	No
2/21/2018	Constitution Ave NE	Morningside Dr NE	Other Vehicle - Both Going Straight/ Entering At Angle	Injury Crash	Failed to Yield Right of Way	No
11/21/2019	Constitution Ave NE	Morningside Dr NE	Other Vehicle - From Opposite Direction	Injury Crash	Failed to Yield Right of Way	No
3/4/2020	Constitution Ave NE	Washington St NE	Other Vehicle - One Left Turn/ Entering At Angle	Injury Crash	Failed to Yield Right of Way and Passed Stop Sign	No

Table 7: Mackland Avenue – Crash Summary

Crash Date	Crash Primary Street	Crash Intersecting Street	Crash Analysis	Severity	Contributing Factors	Correctable with Traffic Calming
9/22/2017	Carlisle / Mackland		Left Blank	Property Damage Only Crash	Speed Too Fast for Conditions	Yes

Table 8: Montclair Drive – Crash Summary

Crash Date	Crash Primary Street	Crash Intersecting Street	Crash Analysis	Severity	Contributing Factors	Correctable with Traffic Calming
1/2/2019	Monte Claire Se	Mesa Verde St	Left Blank	Property Damage Only Crash	Passed Stop Sign	No




Figure 16: Crash Heat Map

Crash Analysis

The crash data for following six intersections were further analyzed:

- Washington Street and Aspen Avenue
- Washington Street and Constitution Avenue
- Washington Street and Lomas Boulevard
- Washington Street and Avenida Del Sol
- Morningside Drive and Constitution Avenue
- Montclair Drive and Lomas Boulevard

Washington Street and Aspen Avenue

ONE crash was reported at the Washington Street and Aspen Avenue intersection, and it was classified as rear-end collision traveling north that resulted in property damage.

Washington Street and Constitution Avenue

The intersection of Washington Street and Constitution Avenue had a total of 30 reported crashes. From the crash data, it was observed that nine crashes involved another vehicle (left blank with no specified type of collision), seven were angle crashes and six crashes were head-on collisions. [Figure 17](#) summarizes the crash types.




Figure 17: Washington Street and Constitution Avenue – Crash Types

Table 9: Washington Street and Constitution Avenue – Crash Severity

Year	Crash Severity			Total
	Injury	Fatal	PDO*	
2016-2020	8 (26.7%)	0 (0.0%)	22 (73.3%)	30 (100%)

*PDO – Property Damage Only

Washington Street and Lomas Boulevard

Three crashes were reported at the Washington Street and Lomas Boulevard intersection, one crash was reported as an angle crash, one was a head-on, and one was unknown.

Table 10: Washington Street and Lomas Boulevard – Crash Severity

Year	Crash Severity			Total
	Injury	Fatal	PDO*	
2016-2020	1 (33.3%)	0 (0.0%)	2 (66.7%)	3 (100%)

*PDO – Property Damage Only

Washington Street and Avenida Del Sol

Seven crashes occurred at the Washington Street and Avenida Del Sol intersection, five crashes were classified as angle crashes, one as head-on, and one was with a collision with another vehicle (left blank with no specified type of collision).

Table 11: Washington Street and Avenida Del Sol – Crash Severity

Year	Crash Severity			Total
	Injury	Fatal	PDO*	
2016-2020	2 (28.6%)	0 (0.0%)	5 (71.4%)	7 (100%)

*PDO – Property Damage Only

Morningside Drive and Constitution Avenue

Four crashes occurred at the Morningside Drive and Constitution intersection, two crashes were classified as angle crashes, one crash as head-on, and one was with a fixed object.

Table 12: Morningside Drive and Constitution Avenue – Crash Severity

Year	Crash Severity			Total
	Injury	Fatal	PDO*	
2016-2020	3 (75.0%)	0 (0.0%)	1 (25.0%)	4 (100%)

*PDO – Property Damage Only

Montclair Drive and Lomas Boulevard

Three car crashes were reported at the Montclair Drive and Lomas Boulevard intersection, one crash was reported as an angle crash, one as head-on, and one was unknown.

Table 13: Montclair Drive and Lomas Boulevard – Crash Severity

Year	Crash Severity			Total
	Injury	Fatal	PDO*	
2016-2020	1 (33.3%)	0 (0.0%)	2 (66.7%)	3 (100%)

*PDO – Property Damage Only

3.3 Speed

Speed data was collected along the specified roadways for a 48-hour period on a Wednesday, either on September 14, 2022 or September 21, 2022 and on a Thursday, either on September 15, 2022 or September 22, 2022. See [Table 14](#) for the percentage of vehicles exceeding the posted speed limit by 5 mph and 7 mph. The COA NTMP Policy Manual has criteria that includes 15% of vehicles traveling in the study area exceeding 5 mph and 7 mph. The full speed data can be found in [Appendix A](#).

Table 14: Percentage of Vehicles Exceeding Speed Limit

Location	Speed	Percentage of Vehicles Exceeding Speed Limit			
		Wednesday		Thursday	
		Counter per Direction 1	Counter per Direction 2	Counter per Direction 1	Counter per Direction 2
Morningside Drive (North of Aspen Ave.)	5 mph	0%	0%	0%	0%
	7 mph	0%	0%	0%	0%
Morningside Drive (South of Aspen Ave.)	5 mph	15%	8%	15%	10%
	7 mph	8%	2%	10%	3%
Washington Street (North of Sunningdale Ave.)	5 mph	14%	41%	16%	45%
	7 mph	7%	24%	7%	27%
Washington Street (South of Sunningdale Ave.)	5 mph	8%	35%	10%	39%
	7 mph	3%	20%	5%	23%
Washington Street (South of Avenida Estrellita)	5 mph	18%	25%	24%	31%
	7 mph	9%	12%	12%	15%
Washington Street (South of Avenida Del Sol)	5 mph	6%	13%	6%	18%
	7 mph	2%	6%	3%	8%
Constitution Drive (West of Morningside Ave.)	5 mph	34%	39%	33%	39%
	7 mph	21%	22%	18%	23%
Constitution Drive (East of Morningside Ave.)	5 mph	73%	30%	73%	31%
	7 mph	61%	16%	60%	18%
Avenida Del Sol (West of Mackland Ave.)	5 mph	7%	25%	2%	20%
	7 mph	3%	19%	0%	11%
Avenida Del Sol (East of Mackland Ave.)	5 mph	2%	22%	4%	19%
	7 mph	1%	14%	2%	13%
Morningside Drive (North of Mackland Ave.)	5 mph	6%	7%	6%	9%
	7 mph	3%	2%	2%	6%
Marble Avenue (South of Mackland Ave.)	5 mph	7%	7%	6%	7%
	7 mph	4%	3%	4%	3%
Mackland Avenue (West of Montclair Dr.)	5 mph	5%	12%	6%	12%
	7 mph	3%	7%	2%	8%
Mackland Avenue (East of Montclair Dr.)	5 mph	0%	0%	0%	0%
	7 mph	0%	0%	0%	0%
Montclair Drive (South of McDuffie Cir.)	5 mph	13%	13%	6%	16%
	7 mph	5%	6%	2%	7%
Montclair Drive (North of Mesa Verde Ave.)	5 mph	14%	9%	12%	11%
	7 mph	8%	4%	7%	5%
Solano Drive (North of Aspen Ave.)	5 mph	21%	18%	17%	11%
	7 mph	14%	12%	10%	5%
Solano Drive (North of Lomas Blvd.)	5 mph	2%	5%	5%	5%
	7 mph	2%	2%	1%	2%

3.5 Sight Distance

City of Albuquerque Council Services staff met with individuals representing the neighborhoods to identify what their concerns are regarding traffic and sight distance. The intersections of Morningside Drive and Avenida la Resolana and Montclair Drive and Mackland Avenue were identified as an intersection with limited sight distance.

According to AASHTO *A Policy on Geometric Design of Highway and Streets*, 7th Edition, the stopping sight distance for a design speed of 30 mph is 200-ft. **Figure 18** shows the sight triangles using stopping sight distance at the intersection of Morningside Drive and Avenida la Resolana. There are existing obstructions within the sight triangles. **Figure 19** shows the sight triangles using stopping sight distance at the intersection of Montclair Drive and Mackland Avenue. There are existing obstructions within the sight triangles.



Figure 18: Morningside Drive and Avenida la Resolana Sight Distance



Figure 19: Montclair Drive and Mackland Avenue Sight Distance

3.6 Lighting

Figure 20 provides an aerial view of the street lighting locations provided within the study area.




Figure 20: Street Lighting Locations

4.0 NTMP Traffic Calming Criteria

In order to meet the traffic calming criterion described in the *City of Albuquerque Neighborhood Traffic Management Program Policy Manual (COA NTMP)*, one or more of the following threshold criteria must be met:

1. Over a twenty-four-hour period, 15% of the vehicles traveling in the study area exceeded 7 miles per hour over the speed limit.
2. Three reported crashes in a 5-year period where the police report identified speed as either a primary or contributing cause of the crash.
3. A crash involving a pedestrian or cyclist in a school zone in a five-year period.
4. Over a twenty-four-hour period more than 800 vehicles were counted traveling through the study area and 15% of the vehicles traveling in the study area exceeded 5 miles per hour over the speed limit.
5. Over a twenty-four-hour period, 15% of the vehicles traveling in the study area exceeded 5 miles per hour over the speed limit and there was at least one reported crash in a 5-year period where the police report identified speed as either a primary or contributing cause of the crash.
6. Over a twenty-four-hour period, 15% of the vehicles traveling in the study area exceeded 5 miles per hour over the speed limit and a field survey conducted by the Traffic Engineering Division determined that 25% of the peak hour traffic was cut-through traffic.
7. Over a twenty-four-hour period more than 800 vehicles were counted traveling through the study area and there was at least one reported crash in a 5-year period where the police report identified speed as either a primary or contributing cause of the crash.
8. Over a twenty-four-hour period more than 800 vehicles were counted traveling through the study area and a field survey conducted by the Traffic Engineering Division determined that 25% of the peak hour traffic was cut-through traffic.
9. A field survey conducted by the Traffic Engineering Division determined that 25% of the peak hour traffic was cut-through traffic and there was at least one reported crash in 5 years where the police report identified speed as either a primary or contributing cause of the crash.

4.1 NTMP Thresholds

From the data collected and the crash data provided, [Table 15](#) through [Table 21](#) summarizes the results for each of the roadways analyzed within the project area. Results indicate the following:

- Morningside Drive – None of the nine (9) thresholds meet the criteria; therefore, it **does not meet** the minimum traffic calming criterion as described in the *COA NTMP*.
- Washington Street – Six of the nine (9) thresholds meet the criteria; therefore, it **does meet** the minimum traffic calming criterion as described in the *COA NTMP*.
- Constitution Avenue – Two of the nine (9) thresholds meet the criteria; therefore, it **does meet** the minimum traffic calming criterion as described in the *COA NTMP*.
- Mackland Avenue – None of the nine (9) thresholds meets the criteria; therefore, it **does not meet** the minimum traffic calming criterion as described in the *COA NTMP*.
- Avenida Del Sol – One of the nine (9) thresholds meets the criteria; therefore, it **does meet** the minimum traffic calming criterion as described in the *COA NTMP*.
- Montclair Drive – None of the nine (9) thresholds meet the criteria; therefore, it **does not meet** the minimum traffic calming criterion as described in the *COA NTMP*.
- Solano Drive – None of the nine (9) thresholds meet the criteria; therefore, it **does not meet** the minimum traffic calming criterion as described in the *COA NTMP*.

Table 15: Morningside Drive – Threshold Criteria Evaluation Results

NTMP Threshold	Threshold Criteria Description	Criteria	Collected	Meets Threshold
1	Vehicles exceed 7 mph over the posted speed limit	15%	10%	NO
2	Crashes with speed as a contributing factor	3	0	NO
3	A crash involved a pedestrian or cyclist in a school zone	1	0	NO
4	Vehicle volume over 24-hr	800	504*	NO
	Vehicles exceed 5 mph over the posted speed limit	15%	15%	
5	Vehicles exceed 5 mph over the posted speed limit	15%	15%	NO
	A crash with speed as a contributing factor	1	0	
6	Vehicles exceed 5 mph over the posted speed limit	15%	15%	NO
	Percentage of cut-through traffic	25%		
7	Vehicle volume over 24-hr	800	504*	NO
	A crash with speed as a contributing factor	1	0	
8	Vehicle volume over 24-hr	800	504*	NO
	Percentage of cut-through traffic	25%		
9	Percentage of cut-through traffic	25%		NO
	A crash with speed as a contributing factor	1	0	

Note: * highest observed volume

Table 16: Washington Street – Threshold Criteria Evaluation Results

NTMP Threshold	Threshold Criteria Description	Criteria	Collected	Meets Threshold
1	Vehicles exceed 7 mph over the posted speed limit	15%	27%*	YES
2	Crashes with speed as a contributing factor	3	3	YES
3	A crash involved a pedestrian or cyclist in a school zone	1	1	YES
4	Vehicle volume over 24-hr	800	6,805*	YES
	Vehicles exceed 5 mph over the posted speed limit	15%	45%*	
5	Vehicles exceed 5 mph over the posted speed limit	15%	45%*	YES
	A crash with speed as a contributing factor	1	3	
6	Vehicles exceed 5 mph over the posted speed limit	15%	45%*	NO
	Percentage of cut-through traffic	25%		
7	Vehicle volume over 24-hr	800	6,805*	YES
	A crash with speed as a contributing factor	1	5	
8	Vehicle volume over 24-hr	800	6,805*	NO
	Percentage of cut-through traffic	25%		
9	Percentage of cut-through traffic	25%		NO
	A crash with speed as a contributing factor	1	3	

Note: * highest observed percentage of vehicles over the posted speed limit and/or highest observed volume

Table 17: Constitution Avenue – Threshold Criteria Evaluation Results

NTMP Threshold	Threshold Criteria Description	Criteria	Collected	Meets Threshold
1	Vehicles exceed 7 mph over the posted speed limit	15%	61%*	YES
2	Crashes with speed as a contributing factor	3	0	NO
3	A crash involved a pedestrian or cyclist in a school zone	1	0	NO
4	Vehicle volume over 24-hr	800	5,264*	YES
	Vehicles exceed 5 mph over the posted speed limit	15%	73%*	
5	Vehicles exceed 5 mph over the posted speed limit	15%	73%*	NO
	A crash with speed as a contributing factor	1	0	
6	Vehicles exceed 5 mph over the posted speed limit	15%	73%*	NO
	Percentage of cut-through traffic	25%		
7	Vehicle volume over 24-hr	800	5,264*	NO
	A crash with speed as a contributing factor	1	0	
8	Vehicle volume over 24-hr	800	5,264*	NO
	Percentage of cut-through traffic	25%		
9	Percentage of cut-through traffic	25%		NO

NTMP Threshold	Threshold Criteria Description	Criteria	Collected	Meets Threshold
	A crash with speed as a contributing factor	1	0	

Note: * highest observed percentage of vehicles over the posted speed limit and/or highest observed volume

Table 18: Mackland Avenue – Threshold Criteria Evaluation Results

NTMP Threshold	Threshold Criteria Description	Criteria	Collected	Meets Threshold
1	Vehicles exceed 7 mph over the posted speed limit	15%	8%*	NO
2	Crashes with speed as a contributing factor	3	1	NO
3	A crash involved a pedestrian or cyclist in a school zone	1	0	NO
4	Vehicle volume over 24-hr	800	707*	NO
	Vehicles exceed 5 mph over the posted speed limit	15%	12%*	
5	Vehicles exceed 5 mph over the posted speed limit	15%	12%*	NO
	A crash with speed as a contributing factor	1	1	
6	Vehicles exceed 5 mph over the posted speed limit	15%	12%*	NO
	Percentage of cut-through traffic	25%		
7	Vehicle volume over 24-hr	800	707*	NO
	A crash with speed as a contributing factor	1	1	
8	Vehicle volume over 24-hr	800	707*	NO
	Percentage of cut-through traffic	25%		
9	Percentage of cut-through traffic	25%		NO
	A crash with speed as a contributing factor	1	1	

Note: * highest observed percentage of vehicles over the posted speed limit and/or highest observed volume

Table 19: Avenida Del Sol – Threshold Criteria Evaluation Results

NTMP Threshold	Threshold Criteria Description	Criteria	Collected	Meets Threshold
1	Vehicles exceed 7 mph over the posted speed limit	15%	19%*	YES
2	Crashes with speed as a contributing factor	3	0	NO
3	A crash involved a pedestrian or cyclist in a school zone	1	0	NO
4	Vehicle volume over 24-hr	800	275*	NO
	Vehicles exceed 5 mph over the posted speed limit	15%	25%*	
5	Vehicles exceed 5 mph over the posted speed limit	15%	25%*	NO
	A crash with speed as a contributing factor	1	0	
6	Vehicles exceed 5 mph over the posted speed limit	15%	25%*	NO
	Percentage of cut-through traffic	25%		
7	Vehicle volume over 24-hr	800	275*	NO
	A crash with speed as a contributing factor	1	0	
8	Vehicle volume over 24-hr	800	275*	NO
	Percentage of cut-through traffic	25%		
9	Percentage of cut-through traffic	25%		NO
	A crash with speed as a contributing factor	1	0	

Note: * highest observed percentage of vehicles over the posted speed limit and/or highest observed volume

Table 20: Montclair Drive – Threshold Criteria Evaluation Results

NTMP Threshold	Threshold Criteria Description	Criteria	Collected	Meets Threshold
1	Vehicles exceed 7 mph over the posted speed limit	15%	8%*	NO
2	Crashes with speed as a contributing factor	3	0	NO
3	A crash involved a pedestrian or cyclist in a school zone	1	0	NO
4	Vehicle volume over 24-hr	800	528*	NO
	Vehicles exceed 5 mph over the posted speed limit	15%	16%*	
5	Vehicles exceed 5 mph over the posted speed limit	15%	16%*	NO
	A crash with speed as a contributing factor	1	0	
6	Vehicles exceed 5 mph over the posted speed limit	15%	16%*	NO
	Percentage of cut-through traffic	25%		

NTMP Threshold	Threshold Criteria Description	Criteria	Collected	Meets Threshold
7	Vehicle volume over 24-hr	800	528*	NO
	A crash with speed as a contributing factor	1	0	
8	Vehicle volume over 24-hr	800	528*	NO
	Percentage of cut-through traffic	25%		
9	Percentage of cut-through traffic	25%		NO
	A crash with speed as a contributing factor	1	0	

Note: * highest observed percentage of vehicles over the posted speed limit and/or highest observed volume

Table 21: Solano Drive – Threshold Criteria Evaluation Results

NTMP Threshold	Threshold Criteria Description	Criteria	Collected	Meets Threshold
1	Vehicles exceed 7 mph over the posted speed limit	15%	14%*	NO
2	Crashes with speed as a contributing factor	3	0	NO
3	A crash involved a pedestrian or cyclist in a school zone	1	0	NO
4	Vehicle volume over 24-hr	800	356*	NO
	Vehicles exceed 5 mph over the posted speed limit	15%	21%*	
5	Vehicles exceed 5 mph over the posted speed limit	15%	21%*	NO
	A crash with speed as a contributing factor	1	0	
6	Vehicles exceed 5 mph over the posted speed limit	15%	21%*	NO
	Percentage of cut-through traffic	25%		
7	Vehicle volume over 24-hr	800	356*	NO
	A crash with speed as a contributing factor	1	0	
8	Vehicle volume over 24-hr	800	356*	NO
	Percentage of cut-through traffic	25%		
9	Percentage of cut-through traffic	25%		NO
	A crash with speed as a contributing factor	1	0	

Note: * highest observed percentage of vehicles over the posted speed limit and/or highest observed volume

5.0 Proposed Alternatives

5.1 Pedestrian Crossings

For this alternative, pedestrian crossings were analyzed at the following intersections:

- Washington Street and Sunningdale Avenue
- Morningside Drive and Constitution Avenue

According to the *FHWA Safety Effects of Marked Versus Unmarked Crosswalks at Uncontrolled Locations*, published in 2005, it is recommended that the minimum pedestrian volume be 20 pedestrians crossing per peak hour or a minimum of 15 elderly and/or child pedestrians crossing per peak hour. The City of Albuquerque *Bicycle and Trail Crossing Guide*, published in 2022, provides recommendations for crossing designs based on roadway ADT, lanes configuration, and speed limit (shown below in [Table 22](#)). Based on [Table 22](#), the intersections should have the following treatments:

- Washington Street and Sunningdale Avenue (6,000 ADT; two lanes; 30 mph)
 - There were 31 pedestrians and two (2) bicyclists counted on the north and south legs during the AM peak hour.
 - Crosswalk marking and signage along the north and south legs. Complementary treatments are also recommended and can include stop or yield lines, in-street crossing sign, and a raised crosswalk, see [Figure 21](#) for proposed layout.
- Morningside Drive and Constitution Avenue (4,578 ADT; two lanes, 30 mph)
 - There were 21 pedestrians and five (5) bicyclists on the east and west legs during the PM peak hour.
 - Crosswalk marking and signage along the east and west legs. Complementary treatments are also recommended and can include stop or yield lines, in-street crossing sign and raised crosswalk, see [Figure 22](#) for proposed layout.

Table 22: Crossing Treatment Selection Matrix

Number of Crossing Lanes	Speed Limit	ADT Per Crossing Stage	Recommended Crossing Designs			Complementary Treatments		
			Crosswalk Markings and Signage	RRFB	PHB	Stop or Yield Lines	In-Street Crossing Sign	Raised Crosswalk
Two lanes	≤ 30 mph	<9,000	X			X	X	X
		9,000 to 15,000	X	X	X	X	X	
		>15,000	X	X	X	X	X	
	35 mph	<9,000	X	X	X	X		
		9,000 to 15,000		X	X	X		
		>15,000		X	X	X		
	≥ 40 mph	<9,000		X	X	X		
		9,000 to 15,000		X	X	X		
		>15,000		X	X	X		



Figure 21: Washington Street and Sunningdale Avenue



Figure 22: Morningside Drive and Constitution Avenue

5.2 Striping

This alternative takes into consideration changes in the existing lane configuration by re-striping the lanes to incorporate bike lanes and/or shift the roadway centerline. Some of the benefits for re-striping an existing roadway are it may slow traffic down, it is low cost to install and modify, and it does not slowdown emergency vehicles. As shown in [Figure 21](#) through [Figure 23](#), these changes are proposed at the following intersections:

- Washington Street and Sunningdale Avenue – A change in the existing lane roadway configuration to include bike lanes along Washington Street on both sides. The existing left-turn bays for northbound and southbound would be removed to shorten the pedestrian crossing distance, as shown in [Figure 21](#).
- Washington Street and Constitution Avenue – A change in the existing lane roadway configuration for the north leg of the intersection to relocate the existing on-street parking, shifting it from the east side to the west side. This would allow the centerline to shift east to reduce the offset roadway alignment connecting to the south leg, see [Figure 23](#).
- Washington Street between Carlisle Boulevard and Morningside Drive – Addition of a striped buffered bike lane should be considered to narrow the driving lanes to 11-ft.



Figure 23: Washington Street and Constitution Avenue

5.3 Traffic Circle

Traffic circles are a raised island creating a circular intersection, tend to reduce the vehicles traveling speeds, reduce the number of conflict points, improve safety, and increase access to main street from side street. For this alternative, traffic circles were evaluated at the following intersections:

- Montclair Drive and Mackland Avenue, see [Figure 24](#)
- Avenida Del Sol and Avenida La Resolana, see [Figure 25](#)



Figure 24: Montclair Drive and Mackland Avenue – Proposed Traffic Circle



Figure 25: Avenida Del Sol and Avenida La Resolana – Proposed Traffic Circle

5.4 Neckdowns and/or Bulbouts

Neckdowns consist of narrowing the roadway at an intersection to slow vehicles down and increase the safety of pedestrians by reducing their crossing distances. Bulbouts are similar to neckdowns, whereas the existing sidewalk or curb line is extended into the roadway centerline to shorten the pedestrian crossing distances. For this alternative, neckdowns and/or bulbouts were examined at the intersections of:

- Washington Street and Sunningdale Avenue – A bulbout is proposed at the southwest and northeast corners of the intersection to shorten the pedestrian crossing distances, see [Figure 21](#).
- Morningside Drive and Constitution Avenue - A bulbout is proposed at the southeast corner of the intersection to shorten the pedestrian crossing distance and improve sight distances for the northbound approach, see [Figure 23](#).
- Avenida Del Sol and Morningside Drive – Bulbouts are proposed to change Avenida Del Sol to a one-way roadway in the northbound direction, see [Figure 26](#). This would help improve operations at the existing Y-intersection and reduce traffic volumes on Avenida Del Sol.



Figure 26: Avenida Del Sol and Morningside Drive – Proposed Bulbout

5.5 Speed Humps

Speed humps help reduce vehicles speeds, do not restrict parking, and discourages cut-through traffic. However, speed humps can only be placed on non-emergency routes, such as Avenida Del Sol. Speed humps were evaluated at Avenida Del Sol between Morningside Drive and Washington Street, as shown in [Figure 27](#).



Figure 27: Avenida Del Sol – Proposed Speed Humps

6.0 Public Involvement

6.1 Public Meeting #1

The first public meeting to present the existing conditions and potential alternatives was held virtually on February 7, 2023, from 6:00 PM to 7:00 PM. The purpose of the meeting was to present the project and potential alternatives to the community and stakeholders. The meeting was held virtually via Zoom platform. The meeting consisted of a PowerPoint presentation by the project team, followed by a question-and-answer session.

Approximately 34 members attended the meeting. Questions from attendees covered topics such as pedestrian and bicyclist safety, speeding, and feedback on the potential alternatives that were presented. The full public meeting summary can be found in [Appendix C](#).

6.1.1 Post Meeting Comments

Public comments were accepted via email for two weeks after the February 7th meeting. There were 48 emails received. Comments covered topics such as feedback on potential alternatives and additional requests. The full comments can be found in [Appendix C](#).

6.2 Public Meeting #2

The second public meeting to present the alternatives was held virtually on September 7, 2023, from 6:00 PM to 7:00 PM. The purpose of the meeting was to present the project and alternatives to the community and stakeholders. The meeting was held virtually via Zoom platform. The meeting consisted of a PowerPoint presentation by the project team, followed by a question-and-answer session.

Approximately 38 members attended the meeting. Questions from attendees covered topics such as pedestrian and bicyclist safety, speeding, and feedback on the alternatives that were presented. The full public meeting summary can be found in [Appendix C](#).

6.2.1 Post Meeting Comments

Public comments were accepted via email for two weeks after the September 7th meeting. There were 60 emails received. Majority of emails received were for support of the alternatives that were presented. There were two (2) emails that were opposed to the traffic circle at Mackland and Montclair. The full comments can be found in [Appendix C](#).

7.0 Summary of Findings and Recommendations

An assessment was conducted in the McDuffie-Twin Parks neighborhoods, along Washington Street, Constitution Avenue, Morningside Drive, Avenida Del Sol, Montclair Drive, Mackland Avenue, and Solano Drive. These roadways were analyzed to determine if they meet the traffic calming criterion described in the *City of Albuquerque (COA) Neighborhood Traffic Management Program (NTMP)*, October 2020 results can be found in [Table 23](#).

Table 23: NTMP Criterion Results

Roadway Name	NTMP Thresholds	# of NTMP Threshold Met	Meets Minimum
Washington Drive	9	6	YES
Constitution Avenue	9	2	YES
Morningside Drive	9	0	NO
Avenida Del Sol	9	1	YES
Montclair Drive	9	0	NO
Mackland Avenue	9	0	NO
Solano Drive	9	0	NO

From the results shown in [Table 23](#), only three of the roadways analyzed meet the minimum criterion needed to qualify for traffic calming. Therefore, different alternatives were analyzed along these roadways which include pedestrian crossings, striping, traffic circles, neckdowns/bulbouts, and speed bumps. The recommendations for each alternative analyzed are presented below, conceptual cost estimates are shown in the parentheses:

- Washington Street and Sunningdale Avenue (\$195,972)
 - **Pedestrian crossing.** Crosswalk marking and signage along the north and south legs. Complementary treatments are also recommended and can include stop or yield lines, in-street crossing sign, and a raised crosswalk.
 - **Striping.** A change in the existing lane roadway configuration to include bike lanes along Washington Street on both sides. The existing left-turn bays for northbound and southbound would be removed to shorten the pedestrian crossing distance. Add delineators between the bike lane and travel lane near intersection/pedestrian crossing.

- **Neckdown/bulbout.** A bulbout is proposed at the southwest corner of the intersection to shorten the pedestrian crossing distances. A bulbout is proposed at the northeast corner of the intersection, on Sunningdale Avenue, in order to make the approach perpendicular to Washington Street.
- Morningside Drive and Constitution Avenue (\$139,913)
 - **Pedestrian crossing.** Crosswalk marking and signage along the east and west legs. Complementary treatments are also recommended and can include stop or yield lines, in-street crossing sign and raised crosswalk. Add delineators between the bike lane and travel lane near intersection/pedestrian crossing.
 - **Neckdown/bulbout.** A bulbout is proposed at the southeast corner of the intersection to shorten the pedestrian crossing distance and improve sight distances for the northbound approach.
- Washington Street and Constitution Avenue (\$58,614)
 - **Neckdown/bulbout.** A bulbout is proposed at the southwest corner of the intersection to shorten the pedestrian crossing distance and improve sight distances for the northbound approach. Add delineators between the bike lane and travel lane near intersection/pedestrian crossing.
- Constitution Avenue between Carlisle Boulevard and Morningside Drive
 - **Striping.** Addition of a striped buffered bike lane should be considered to narrow the driving lanes to 11-ft.
- Montclair Drive and Mackland Avenue (\$66,919)
 - **Traffic circle.** A change in the existing intersection control type from a two-way stop-controlled along Montclair Drive into a traffic circle with yield signs on all approaches.
- Avenida Del Sol (\$35,475)
 - **Speed humps/cushions.** Addition of speed humps or speed cushions along Avenida Del Sol between Morningside Drive and Washington Street.
- Hidden Park
 - **Striping.** Addition of no parking pavement markings at all access points to Hidden Park. Striping would include striped chevron markings and “NO PARKING” pavement markings.

Appendix A – Traffic Data

Washington St. & Hannett Ave. NE_Sunningdale Ave. NE
Albuquerque New Mexico
Thursday, September 15, 2022

Time	Southbound Washington St.						Westbound Sunningdale Ave. NE						Northbound Washington St.						Eastbound Hannett Ave. NE						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
12:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
12:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
12:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00 AM	0	1	7	0	0	8	0	0	1	1	0	2	0	0	8	1	0	9	0	0	0	0	0	0	19
6:15 AM	0	0	9	0	0	9	0	0	0	1	0	1	0	0	5	0	0	5	0	1	0	0	0	1	16
6:30 AM	0	2	14	0	1	16	0	0	0	5	1	5	0	1	12	0	0	13	0	5	0	0	0	5	39
6:45 AM	0	0	29	0	6	29	0	1	0	4	0	5	0	1	9	2	1	12	0	4	0	0	0	4	50
Hourly Total	0	3	59	0	7	62	0	1	1	11	1	13	0	2	34	3	1	39	0	10	0	0	0	10	124
7:00 AM	0	5	30	2	2	37	0	2	0	5	0	7	0	0	31	1	0	32	0	6	1	3	2	10	86
7:15 AM	0	0	32	0	1	32	0	4	3	3	0	10	0	2	25	2	1	29	0	4	0	3	2	7	78
7:30 AM	0	4	49	0	3	53	0	1	1	8	0	10	0	2	32	2	1	36	0	5	1	7	1	13	112
7:45 AM	0	3	60	1	4	64	0	1	0	6	0	7	0	5	28	4	3	37	0	5	0	2	1	7	115
Hourly Total	0	12	171	3	10	186	0	8	4	22	0	34	0	9	116	9	5	134	0	20	2	15	6	37	391

Washington St. & Hannett Ave. NE_Sunningdale Ave. NE
Albuquerque New Mexico
Thursday, September 15, 2022

Time	Southbound Washington St.						Westbound Sunningdale Ave. NE						Northbound Washington St.						Eastbound Hannett Ave. NE						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehicle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehicle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehicle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehicle Approach Total</i>	
8:00 AM	0	2	51	1	4	<i>54</i>	0	0	0	5	0	<i>5</i>	0	2	49	4	2	<i>55</i>	0	2	0	6	0	<i>8</i>	122
8:15 AM	0	1	30	0	2	<i>31</i>	0	2	1	2	0	<i>5</i>	0	2	47	4	1	<i>53</i>	0	6	2	3	0	<i>11</i>	100
8:30 AM	0	2	36	0	3	<i>38</i>	0	1	0	2	2	<i>3</i>	0	2	45	6	1	<i>53</i>	0	5	0	2	1	<i>7</i>	101
8:45 AM	0	3	59	1	3	<i>63</i>	0	1	4	3	0	<i>8</i>	0	2	40	8	5	<i>50</i>	0	3	1	6	0	<i>10</i>	131
Hourly Total	0	8	176	2	12	<i>186</i>	0	4	5	12	2	<i>21</i>	0	8	181	22	9	<i>211</i>	0	16	3	17	1	<i>36</i>	454
9:00 AM	0	3	59	0	3	<i>62</i>	0	0	1	2	1	<i>3</i>	0	0	38	2	3	<i>40</i>	0	7	1	3	0	<i>11</i>	116
9:15 AM	0	4	49	2	3	<i>55</i>	0	0	1	3	0	<i>4</i>	0	2	24	5	6	<i>31</i>	0	6	2	2	0	<i>10</i>	100
9:30 AM	0	2	48	1	6	<i>51</i>	0	0	1	3	2	<i>4</i>	0	0	35	7	2	<i>42</i>	0	4	1	4	1	<i>9</i>	106
9:45 AM	0	3	46	1	4	<i>50</i>	0	1	2	6	0	<i>9</i>	0	1	33	6	4	<i>40</i>	0	6	1	1	1	<i>8</i>	107
Hourly Total	0	12	202	4	16	<i>218</i>	0	1	5	14	3	<i>20</i>	0	3	130	20	15	<i>153</i>	0	23	5	10	2	<i>38</i>	429
10:00 AM	0	4	45	0	0	<i>49</i>	0	1	2	1	0	<i>4</i>	0	2	47	9	3	<i>58</i>	0	4	0	4	0	<i>8</i>	119
10:15 AM	0	1	40	3	2	<i>44</i>	0	0	1	6	1	<i>7</i>	0	0	36	3	4	<i>39</i>	0	3	2	6	0	<i>11</i>	101
10:30 AM	0	3	52	0	1	<i>55</i>	0	1	4	3	0	<i>8</i>	0	3	59	5	1	<i>67</i>	0	3	1	2	0	<i>6</i>	136
10:45 AM	0	3	41	1	1	<i>45</i>	0	0	0	4	1	<i>4</i>	0	2	50	8	1	<i>60</i>	0	5	1	4	0	<i>10</i>	119
Hourly Total	0	11	178	4	4	<i>193</i>	0	2	7	14	2	<i>23</i>	0	7	192	25	9	<i>224</i>	0	15	4	16	0	<i>35</i>	475
11:00 AM	0	1	60	2	1	<i>63</i>	0	2	1	6	0	<i>9</i>	0	2	54	4	0	<i>60</i>	0	6	2	4	0	<i>12</i>	144
11:15 AM	0	5	58	2	2	<i>65</i>	0	0	2	1	1	<i>3</i>	0	3	48	5	0	<i>56</i>	0	3	0	2	0	<i>5</i>	129
11:30 AM	0	3	56	1	1	<i>60</i>	0	3	0	3	0	<i>6</i>	0	6	49	5	0	<i>60</i>	0	10	2	2	1	<i>14</i>	140
11:45 AM	0	1	48	2	0	<i>51</i>	0	1	0	3	0	<i>4</i>	0	3	57	6	1	<i>66</i>	0	3	1	3	0	<i>7</i>	128
Hourly Total	0	10	222	7	4	<i>239</i>	0	6	3	13	1	<i>22</i>	0	14	208	20	1	<i>242</i>	0	22	5	11	1	<i>38</i>	541
12:00 PM	0	2	48	2	2	<i>52</i>	0	2	2	5	1	<i>9</i>	0	1	45	10	1	<i>56</i>	0	5	2	3	0	<i>10</i>	127
12:15 PM	0	4	56	3	1	<i>63</i>	0	3	3	1	0	<i>7</i>	0	2	63	10	0	<i>75</i>	0	2	0	2	1	<i>4</i>	149
12:30 PM	0	3	46	1	1	<i>50</i>	0	1	2	2	0	<i>5</i>	0	5	42	8	0	<i>55</i>	1	6	2	5	2	<i>14</i>	124
12:45 PM	0	1	58	2	1	<i>61</i>	0	1	1	8	0	<i>10</i>	0	1	61	9	0	<i>71</i>	0	5	5	1	0	<i>11</i>	153
Hourly Total	0	10	208	8	5	<i>226</i>	0	7	8	16	1	<i>31</i>	0	9	211	37	1	<i>257</i>	1	18	9	11	3	<i>39</i>	553
1:00 PM	0	2	60	0	1	<i>62</i>	0	0	2	1	0	<i>3</i>	0	0	33	5	1	<i>38</i>	0	3	1	2	0	<i>6</i>	109
1:15 PM	0	3	56	0	1	<i>59</i>	0	0	0	0	1	<i>0</i>	0	6	51	6	0	<i>63</i>	0	4	0	2	0	<i>6</i>	128
1:30 PM	0	0	69	0	2	<i>69</i>	0	1	2	0	1	<i>3</i>	0	4	49	5	1	<i>58</i>	0	2	2	2	0	<i>6</i>	136
1:45 PM	0	5	60	0	2	<i>65</i>	0	0	1	8	0	<i>9</i>	0	4	38	6	1	<i>48</i>	0	9	1	3	0	<i>13</i>	135
Hourly Total	0	10	245	0	6	<i>255</i>	0	1	5	9	2	<i>15</i>	0	14	171	22	3	<i>207</i>	0	18	4	9	0	<i>31</i>	508
2:00 PM	0	2	67	2	0	<i>71</i>	0	1	1	5	0	<i>7</i>	0	3	42	4	0	<i>49</i>	0	7	2	3	0	<i>12</i>	139
2:15 PM	0	2	75	1	0	<i>78</i>	0	2	0	2	0	<i>4</i>	0	1	57	4	0	<i>62</i>	0	5	0	3	0	<i>8</i>	152
2:30 PM	0	3	62	1	0	<i>66</i>	0	1	1	1	0	<i>3</i>	0	3	72	5	0	<i>80</i>	0	7	4	5	0	<i>16</i>	165
2:45 PM	0	5	65	0	0	<i>70</i>	0	2	0	1	0	<i>3</i>	0	1	74	10	0	<i>85</i>	0	5	0	4	0	<i>9</i>	167
Hourly Total	0	12	269	4	0	<i>285</i>	0	6	2	9	0	<i>17</i>	0	8	245	23	0	<i>276</i>	0	24	6	15	0	<i>45</i>	623
3:00 PM	0	5	75	2	0	<i>82</i>	0	2	1	5	0	<i>8</i>	0	4	69	5	0	<i>78</i>	0	10	2	12	0	<i>24</i>	192
3:15 PM	0	4	83	2	0	<i>89</i>	0	2	1	2	0	<i>5</i>	0	4	53	10	0	<i>67</i>	0	6	1	2	0	<i>9</i>	170
3:30 PM	0	7	75	4	0	<i>86</i>	0	0	1	4	0	<i>5</i>	0	4	66	8	1	<i>78</i>	0	4	0	4	0	<i>8</i>	177
3:45 PM	0	5	80	1	1	<i>86</i>	0	0	1	2	0	<i>3</i>	0	6	82	12	0	<i>100</i>	0	7	1	3	1	<i>11</i>	200
Hourly Total	0	21	313	9	1	<i>343</i>	0	4	4	13	0	<i>21</i>	0	18	270	35	1	<i>323</i>	0	27	4	21	1	<i>52</i>	739


Washington St. & Hannett Ave. NE_Sunningdale Ave. NE
Albuquerque New Mexico
Thursday, September 15, 2022

Time	Southbound Washington St.						Westbound Sunningdale Ave. NE						Northbound Washington St.						Eastbound Hannett Ave. NE						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehcle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehcle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehcle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehcle Approach Total</i>	
4:00 PM	0	4	105	2	0	111	0	0	1	7	0	8	0	2	85	8	2	95	0	6	3	0	0	9	223
4:15 PM	0	2	85	4	1	91	0	2	3	4	0	9	0	4	60	8	1	72	0	8	3	2	0	13	185
4:30 PM	0	2	57	4	3	63	0	1	0	4	0	5	0	2	65	5	0	72	0	4	2	2	0	8	148
4:45 PM	0	9	62	2	0	73	0	1	2	4	0	7	0	5	92	11	0	108	0	3	0	7	0	10	198
Hourly Total	0	17	309	12	4	338	0	4	6	19	0	29	0	13	302	32	3	347	0	21	8	11	0	40	754
5:00 PM	0	7	79	2	2	88	0	0	1	4	0	5	0	7	79	6	3	92	0	12	6	4	0	22	207
5:15 PM	0	8	67	0	0	75	0	1	1	5	0	7	0	6	63	8	0	77	0	3	4	6	1	13	172
5:30 PM	0	9	72	5	0	86	0	2	1	1	0	4	0	3	76	7	0	86	0	1	2	6	0	9	185
5:45 PM	0	3	61	1	7	65	0	0	1	2	0	3	0	3	52	6	1	61	0	6	0	3	2	9	138
Hourly Total	0	27	279	8	9	314	0	3	4	12	0	19	0	19	270	27	4	316	0	22	12	19	3	53	702
6:00 PM	0	7	60	1	2	68	0	0	1	4	0	5	0	1	51	9	0	61	0	7	2	5	0	14	148
6:15 PM	0	0	55	1	0	56	0	1	1	0	0	2	0	3	51	5	0	59	0	6	0	9	0	15	132
6:30 PM	0	6	42	2	5	50	0	3	0	3	0	6	0	8	42	3	0	53	0	6	0	3	1	9	118
6:45 PM	0	2	30	1	2	33	0	0	0	2	1	2	0	4	38	4	1	46	0	4	2	5	1	11	92
Hourly Total	0	15	187	5	9	207	0	4	2	9	1	15	0	16	182	21	1	219	0	23	4	22	2	49	490
7:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
8:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
8:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
8:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
8:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
DAILY TOTAL Cars	0	168	2818	66	87	3052	0	51	56	173	13	280	0	140	2512	296	53	2948	1	259	66	177	19	503	6783
Heavy Vehicles	0	3	26	0	6	29	0	1	0	4	1	5	0	5	17	4	2	26	0	2	0	4	1	6	66
Heavy Vehicle %	0.00%	1.79%	0.92%	0.00%	6.90%	0.95%	0.00%	1.96%	0.00%	2.31%	7.69%	1.79%	0.00%	3.57%	0.68%	1.35%	3.77%	0.88%	0.00%	0.77%	0.00%	2.26%	5.26%	1.19%	0.97%

Washington St. & Hannett Ave. NE_Sunningdale Ave. NE
Albuquerque New Mexico
Thursday, September 15, 2022

Time	Southbound						Westbound						Northbound						Eastbound						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	
11:00 AM	0	1	60	2	1	63	0	2	1	6	0	9	0	2	54	4	0	60	0	6	2	4	0	12	144
11:15 AM	0	5	58	2	2	65	0	0	2	1	1	3	0	3	48	5	0	56	0	3	0	2	0	5	129
11:30 AM	0	3	56	1	1	60	0	3	0	3	0	6	0	6	49	5	0	60	0	10	2	2	1	14	140
11:45 AM	0	1	48	2	0	51	0	1	0	3	0	4	0	3	57	6	1	66	0	3	1	3	0	7	128
Peak Hour Total	0	10	222	7	4	239	0	6	3	13	1	22	0	14	208	20	1	242	0	22	5	11	1	38	541
PHF	0.000	0.500	0.925	0.875	0.500	0.919	0.000	0.500	0.375	0.542	0.250	0.611	0.000	0.583	0.912	0.833	0.250	0.917	0.000	0.550	0.625	0.688	0.250	0.679	0.939

Time	Southbound						Westbound						Northbound						Eastbound						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	
3:30 PM	0	7	75	4	0	86	0	0	1	4	0	5	0	4	66	8	1	78	0	4	0	4	0	8	177
3:45 PM	0	5	80	1	1	86	0	0	1	2	0	3	0	6	82	12	0	100	0	7	1	3	1	11	200
4:00 PM	0	4	105	2	0	111	0	0	1	7	0	8	0	2	85	8	2	95	0	6	3	0	0	9	223
4:15 PM	0	2	85	4	1	91	0	2	3	4	0	9	0	4	60	8	1	72	0	8	3	2	0	13	185
Peak Hour Total	0	18	345	11	2	374	0	2	6	17	0	25	0	16	293	36	4	345	0	25	7	9	1	41	785
PHF	0.000	0.643	0.821	0.688	0.500	0.842	0.000	0.250	0.500	0.607	0.000	0.694	0.000	0.667	0.862	0.750	0.500	0.863	0.000	0.781	0.583	0.563	0.250	0.788	0.880



Washington St. & Constitution Ave. NE
Albuquerque New Mexico
Thursday, September 15, 2022

Time	Southbound Washington St.						Westbound Constitution Ave. NE						Northbound Washington St.						Eastbound Constitution Ave. NE						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
12:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
12:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
12:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00 AM	0	0	6	2	0	8	0	1	5	2	0	8	0	4	4	0	0	8	0	1	3	0	0	4	28
6:15 AM	0	1	1	2	0	4	0	0	4	2	0	6	0	1	6	1	0	8	0	1	4	2	0	7	25
6:30 AM	0	1	9	2	0	12	0	1	15	4	0	20	0	1	10	0	0	11	0	0	2	2	0	4	47
6:45 AM	0	1	9	1	0	11	0	1	11	4	0	16	0	10	18	2	0	30	0	4	10	7	0	21	78
Hourly Total	0	3	25	7	0	35	0	3	35	12	0	50	0	16	38	3	0	57	0	6	19	11	0	36	178
7:00 AM	0	0	27	6	0	33	0	4	12	5	0	21	0	1	24	0	0	25	0	5	10	4	0	19	98
7:15 AM	0	3	19	9	0	31	0	7	27	5	0	39	0	2	24	6	0	32	0	4	11	7	0	22	124
7:30 AM	0	3	29	8	0	40	0	4	25	7	0	36	0	4	36	2	0	42	0	2	24	4	0	30	148
7:45 AM	0	0	20	7	0	27	0	3	42	6	0	51	0	3	45	6	0	54	0	8	20	11	0	39	171
Hourly Total	0	6	95	30	0	131	0	18	106	23	0	147	0	10	129	14	0	153	0	19	65	26	0	110	541

Washington St. & Constitution Ave. NE
Albuquerque New Mexico
Thursday, September 15, 2022

Time	Southbound Washington St.						Westbound Constitution Ave. NE						Northbound Washington St.						Eastbound Constitution Ave. NE						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehicle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehicle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehicle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehicle Approach Total</i>	
8:00 AM	0	5	37	14	0	56	0	5	24	6	0	35	0	5	40	8	0	53	0	5	30	3	0	38	182
8:15 AM	0	5	33	12	0	50	0	5	30	1	0	36	0	6	25	2	0	33	0	2	19	4	0	25	144
8:30 AM	0	4	32	8	0	44	0	6	35	3	0	44	0	3	28	5	0	36	0	4	24	5	0	33	157
8:45 AM	0	3	34	6	1	43	0	6	23	7	1	36	0	9	42	5	0	56	0	11	17	8	0	36	171
Hourly Total	0	17	136	40	1	193	0	22	112	17	1	151	0	23	135	20	0	178	0	22	90	20	0	132	654
9:00 AM	0	2	34	4	0	40	0	2	17	4	0	23	0	4	51	7	1	62	0	7	19	8	0	34	159
9:15 AM	0	4	18	4	1	26	0	4	23	1	0	28	0	8	41	9	0	58	0	11	18	3	0	32	144
9:30 AM	0	4	28	5	0	37	0	2	27	2	3	31	0	4	32	4	1	40	0	13	16	5	1	34	142
9:45 AM	0	8	19	4	0	31	0	3	12	5	0	20	0	5	36	3	0	44	0	4	23	2	1	29	124
Hourly Total	0	18	99	17	1	134	0	11	79	12	3	102	0	21	160	23	2	204	0	35	76	18	2	129	569
10:00 AM	0	1	39	8	0	48	0	2	22	6	0	30	0	3	38	3	2	44	0	5	17	12	1	34	156
10:15 AM	0	4	27	4	0	35	0	4	22	3	0	29	0	6	31	3	0	40	0	3	27	4	0	34	138
10:30 AM	0	7	45	9	0	61	0	1	22	8	0	31	0	9	36	4	0	49	0	7	24	8	0	39	180
10:45 AM	0	8	38	5	0	51	0	3	21	6	0	30	0	9	31	4	0	44	0	7	22	6	0	35	160
Hourly Total	0	20	149	26	0	195	0	10	87	23	0	120	0	27	136	14	2	177	0	22	90	30	1	142	634
11:00 AM	0	4	41	11	0	56	0	2	18	7	0	27	0	3	45	3	0	51	0	7	24	9	0	40	174
11:15 AM	0	4	29	9	0	42	0	2	21	7	0	30	0	8	44	7	0	59	0	11	20	7	0	38	169
11:30 AM	0	4	43	10	1	57	0	3	23	6	0	32	0	13	37	5	0	55	0	8	30	8	0	46	190
11:45 AM	0	4	47	6	0	57	0	4	31	5	0	40	0	9	35	10	0	54	0	7	19	10	0	36	187
Hourly Total	0	16	160	36	1	212	0	11	93	25	0	129	0	33	161	25	0	219	0	33	93	34	0	160	720
12:00 PM	0	3	41	7	0	51	0	6	21	6	0	33	0	9	38	3	0	50	0	8	21	8	0	37	171
12:15 PM	0	5	52	7	0	64	0	2	20	11	0	33	0	6	38	8	0	52	0	8	20	15	1	43	192
12:30 PM	0	5	33	10	0	48	0	1	22	9	0	32	0	11	33	4	0	48	0	9	23	8	0	40	168
12:45 PM	0	2	45	13	0	60	0	2	27	6	0	35	0	9	40	4	0	53	0	11	20	12	0	43	191
Hourly Total	0	15	171	37	0	223	0	11	90	32	0	133	0	35	149	19	0	203	0	36	84	43	1	163	722
1:00 PM	0	6	26	6	0	38	0	5	27	5	0	37	0	8	50	8	0	66	0	7	23	10	0	40	181
1:15 PM	0	5	30	15	0	50	0	3	34	8	0	45	0	10	45	10	1	65	0	5	24	12	0	41	201
1:30 PM	0	5	30	9	0	44	0	2	25	5	0	32	0	6	49	2	1	57	0	6	25	7	0	38	171
1:45 PM	0	3	30	16	0	49	0	2	23	8	0	33	0	7	46	3	0	56	0	8	20	10	0	38	176
Hourly Total	0	19	116	46	0	181	0	12	109	26	0	147	0	31	190	23	2	244	0	26	92	39	0	157	729
2:00 PM	0	10	28	7	0	45	0	4	16	4	0	24	0	5	46	6	0	57	0	11	19	15	0	45	171
2:15 PM	0	1	40	11	0	52	0	4	28	8	0	40	0	7	58	6	1	71	0	10	26	10	0	46	209
2:30 PM	0	9	51	11	0	71	0	5	21	8	0	34	0	7	44	4	0	55	0	12	30	11	0	53	213
2:45 PM	0	4	55	16	0	75	0	5	29	9	0	43	0	4	59	6	0	69	0	7	37	7	0	51	238
Hourly Total	0	24	174	45	0	243	0	18	94	29	0	141	0	23	207	22	1	252	0	40	112	43	0	195	831
3:00 PM	0	6	57	19	0	82	0	4	23	7	0	34	0	13	59	5	0	77	0	10	30	10	0	50	243
3:15 PM	0	4	38	11	0	53	0	4	35	5	0	44	0	7	68	15	0	90	0	15	37	16	0	68	255
3:30 PM	0	6	51	10	0	67	0	9	40	11	0	60	0	8	53	12	0	73	0	16	37	11	0	64	264
3:45 PM	0	8	60	11	0	79	0	6	30	6	0	42	0	5	64	7	0	76	0	14	39	13	0	66	263
Hourly Total	0	24	206	51	0	281	0	23	128	29	0	180	0	33	244	39	0	316	0	55	143	50	0	248	1025

Washington St. & Constitution Ave. NE
Albuquerque New Mexico
Thursday, September 15, 2022

Time	Southbound Washington St.						Westbound Constitution Ave. NE						Northbound Washington St.						Eastbound Constitution Ave. NE						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehicle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehicle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehicle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehicle Approach Total</i>	
4:00 PM	0	5	56	19	0	80	0	6	31	11	0	48	0	10	81	11	0	102	0	17	36	15	1	68	298
4:15 PM	0	5	44	11	0	60	0	7	28	4	0	39	0	12	74	4	0	90	0	8	37	9	1	54	243
4:30 PM	0	6	48	11	0	65	0	5	41	10	0	56	0	9	36	10	2	55	0	17	54	12	0	83	259
4:45 PM	0	10	63	19	0	92	0	12	34	5	0	51	0	4	49	9	0	62	0	13	31	10	0	54	259
Hourly Total	0	26	211	60	0	297	0	30	134	30	0	194	0	35	240	34	2	309	0	55	158	46	2	259	1059
5:00 PM	0	6	59	14	0	79	0	4	36	7	0	47	0	11	62	9	0	82	0	14	51	7	0	72	280
5:15 PM	0	4	50	11	0	65	0	7	38	10	0	55	0	5	47	11	0	63	0	10	55	20	0	85	268
5:30 PM	0	12	51	12	0	75	0	7	34	8	0	49	0	10	62	10	0	82	0	11	42	16	1	69	275
5:45 PM	0	5	36	8	0	49	0	6	31	6	0	43	0	13	45	3	0	61	0	11	28	13	1	52	205
Hourly Total	0	27	196	45	0	268	0	24	139	31	0	194	0	39	216	33	0	288	0	46	176	56	2	278	1028
6:00 PM	0	4	38	9	0	51	0	3	15	5	0	23	0	15	52	6	0	73	0	8	36	15	0	59	206
6:15 PM	0	6	41	10	0	57	0	9	27	8	0	44	0	7	36	3	0	46	0	6	25	15	0	46	193
6:30 PM	0	5	35	7	0	47	0	6	18	7	0	31	0	8	35	6	0	49	0	2	25	12	0	39	166
6:45 PM	0	5	31	6	0	42	0	6	14	6	0	26	0	7	25	5	0	37	0	4	22	13	0	39	144
Hourly Total	0	20	145	32	0	197	0	24	74	26	0	124	0	37	148	20	0	205	0	20	108	55	0	183	709
7:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
8:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
8:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
8:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
8:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
DAILY TOTAL Cars	0	235	1883	472	3	2590	0	217	1280	315	4	1812	0	363	2153	289	9	2805	0	415	1306	471	8	2192	9399
Heavy Vehicles	0	3	1872	470	3	2574	0	216	1274	310	4	1800	0	362	2132	289	9	2783	0	414	1297	470	7	2181	9338
Heavy Vehicle %	0.00%	1.28%	0.58%	0.42%	0.00%	0.62%	0.00%	0.46%	0.47%	1.59%	0.00%	0.66%	0.00%	0.28%	0.98%	0.00%	0.00%	0.78%	0.00%	0.24%	0.69%	0.21%	12.50%	0.50%	0.65%

Washington St. & Constitution Ave. NE
Albuquerque New Mexico
Thursday, September 15, 2022

AM Peak Hour

Time	Southbound						Westbound						Northbound						Eastbound						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	
11:00 AM	0	4	41	11	0	56	0	2	18	7	0	27	0	3	45	3	0	51	0	7	24	9	0	40	174
11:15 AM	0	4	29	9	0	42	0	2	21	7	0	30	0	8	44	7	0	59	0	11	20	7	0	38	169
11:30 AM	0	4	43	10	1	57	0	3	23	6	0	32	0	13	37	5	0	55	0	8	30	8	0	46	190
11:45 AM	0	4	47	6	0	57	0	4	31	5	0	40	0	9	35	10	0	54	0	7	19	10	0	36	187
Peak Hour Total	0	16	160	36	1	212	0	11	93	25	0	129	0	33	161	25	0	219	0	33	93	34	0	160	720
PHF	0.000	1.000	0.851	0.818	0.250	0.930	0.000	0.688	0.750	0.893	0.000	0.806	0.000	0.635	0.894	0.625	0.000	0.928	0.000	0.750	0.775	0.850	0.000	0.870	0.947

PM Peak Hour

Time	Southbound						Westbound						Northbound						Eastbound						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	
4:45 PM	0	10	63	19	0	92	0	12	34	5	0	51	0	4	49	9	0	62	0	13	31	10	0	54	259
5:00 PM	0	6	59	14	0	79	0	4	36	7	0	47	0	11	62	9	0	82	0	14	51	7	0	72	280
5:15 PM	0	4	50	11	0	65	0	7	38	10	0	55	0	5	47	11	0	63	0	10	55	20	0	85	268
5:30 PM	0	12	51	12	0	75	0	7	34	8	0	49	0	10	62	10	0	82	0	11	42	16	1	69	275
Peak Hour Total	0	32	223	56	0	311	0	30	142	30	0	202	0	30	220	39	0	289	0	48	179	53	1	280	1082
PHF	0.000	0.667	0.885	0.737	0.000	0.845	0.000	0.625	0.934	0.750	0.000	0.918	0.000	0.682	0.887	0.886	0.000	0.881	0.000	0.857	0.814	0.663	0.250	0.824	0.966

Total Vehicles On Leg			5473		
Vehicles Entering Intersection 2590			Vehicles Exiting Intersection 2883		
Southbound					
Cars	470	1872	232	0	3
Heavy	2	11	3	0	0
Total	472	1883	235	0	3



Total Vehicles on Leg 4307	Vehicles Entering Intersection 2192	Eastbound	Cars	Heavy	Total
	Vehicles Exiting Intersection 2115		7	1	8
			0	0	0
			414	1	415
			1297	9	1306
			470	1	471



Daily Volumes

Cars	Heavy	Total	Westbound	Vehicles Entering Intersection 1812	Total Vehicles on Leg 3642
310	5	315		Vehicles Exiting Intersection 1830	
1274	6	1280			
216	1	217			
0	0	0			
4	0	4			



Cars	9	0	362	2132	289
Heavy	0	0	1	21	0
Total	9	0	363	2153	289
Northbound					
Vehicles Entering Intersection			2805	Vehicles Exiting Intersection 2571	
Total Vehicles On Leg			5376		

Constitution Ave. NE & Morningside Dr. NE
Albuquerque New Mexico
Thursday, September 15, 2022

Time	Southbound Morningside Dr. NE						Westbound Constitution Ave. NE						Northbound Morningside Dr. NE						Eastbound Constitution Ave. NE						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
12:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
12:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
12:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:15 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:30 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:45 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00 AM	0	0	0	0	0	0	0	0	11	0	0	11	0	1	1	1	0	3	0	0	0	4	0	4	18
6:15 AM	0	0	1	0	0	1	0	2	7	2	0	11	0	3	0	1	0	4	0	0	7	2	0	9	25
6:30 AM	0	0	0	1	0	1	0	0	16	0	1	16	0	3	1	1	0	5	0	0	5	1	0	6	28
6:45 AM	0	0	0	0	1	0	0	0	21	0	5	21	0	3	1	3	0	7	0	0	16	4	4	20	48
Hourly Total	0	0	1	1	1	2	0	2	55	2	6	59	0	10	3	6	0	19	0	0	32	7	4	39	119
7:00 AM	0	2	0	2	2	4	0	2	16	0	1	18	0	5	2	5	0	12	0	1	15	1	4	17	51
7:15 AM	0	2	5	6	1	13	0	2	38	0	3	40	0	7	0	2	1	9	0	1	23	5	2	29	91
7:30 AM	0	2	2	3	0	7	0	2	37	0	3	39	0	7	0	1	0	8	0	1	26	1	2	28	82
7:45 AM	0	0	0	2	0	2	0	2	59	2	2	63	0	3	0	3	0	6	0	2	37	0	2	39	110
Hourly Total	0	6	7	13	3	26	0	8	150	2	9	160	0	22	2	11	1	35	0	5	101	7	10	113	334

Constitution Ave. NE & Morningside Dr. NE
Albuquerque New Mexico
Thursday, September 15, 2022

Time	Southbound Morningside Dr. NE						Westbound Constitution Ave. NE						Northbound Morningside Dr. NE						Eastbound Constitution Ave. NE						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	
8:00 AM	0	1	1	1	1	3	0	1	45	2	1	48	0	7	4	0	0	11	0	1	36	2	5	39	101
8:15 AM	0	0	1	3	0	4	0	3	43	1	4	47	0	3	1	0	0	4	0	0	27	0	3	27	82
8:30 AM	0	1	1	4	1	6	0	2	52	1	1	55	0	7	1	4	1	12	0	0	30	5	3	35	108
8:45 AM	0	1	1	2	0	4	0	1	40	1	1	42	0	4	2	3	1	9	0	4	33	1	4	38	93
Hourly Total	0	3	4	10	2	17	0	7	180	5	7	192	0	21	8	7	2	36	0	5	126	8	15	139	384
9:00 AM	0	3	0	0	0	3	0	3	23	1	5	27	0	9	0	5	1	14	0	4	33	4	3	41	85
9:15 AM	0	1	1	1	1	3	0	1	38	1	3	40	0	4	3	2	0	9	0	1	27	2	1	30	82
9:30 AM	0	0	1	2	0	3	0	2	33	1	2	36	0	5	4	2	2	11	0	0	30	2	1	32	82
9:45 AM	0	2	4	1	0	7	0	0	23	0	0	23	0	3	3	3	1	9	0	0	27	5	0	32	71
Hourly Total	0	6	6	4	1	16	0	6	117	3	10	126	0	21	10	12	4	43	0	5	117	13	5	135	320
10:00 AM	0	1	3	2	0	6	0	2	37	0	1	39	0	1	1	1	0	3	0	3	31	3	0	37	85
10:15 AM	0	1	1	1	0	3	0	3	33	0	1	36	0	7	2	5	0	14	0	0	30	3	2	33	86
10:30 AM	0	1	1	0	0	2	0	3	37	1	2	41	0	3	2	3	0	8	0	2	38	3	0	43	94
10:45 AM	0	1	0	3	0	4	0	0	35	2	0	37	0	3	0	4	1	7	0	1	32	3	1	36	84
Hourly Total	0	4	5	6	0	15	0	8	142	3	4	153	0	14	5	13	1	32	0	6	131	12	3	149	349
11:00 AM	0	1	2	1	1	4	0	3	31	0	1	34	0	3	4	6	0	13	0	2	37	2	1	41	92
11:15 AM	0	1	0	0	0	1	0	3	39	0	2	42	0	2	1	2	0	5	0	1	35	4	0	40	88
11:30 AM	0	2	2	0	0	4	0	3	41	1	1	45	0	5	1	1	0	7	0	1	44	4	1	49	105
11:45 AM	0	0	1	2	0	3	0	2	42	1	1	45	1	3	0	1	0	5	0	1	26	6	1	33	86
Hourly Total	0	4	5	3	1	12	0	11	153	2	5	166	1	13	6	10	0	30	0	5	142	16	3	163	371
12:00 PM	0	1	4	1	0	6	0	6	31	1	0	38	0	3	2	5	0	10	0	5	38	5	2	48	102
12:15 PM	0	0	1	1	0	2	0	2	31	3	0	36	0	1	3	3	0	7	0	1	38	1	0	40	85
12:30 PM	0	2	1	1	0	4	0	5	42	1	0	48	0	4	0	1	0	5	0	1	43	3	3	47	104
12:45 PM	0	0	3	3	0	6	0	3	44	1	0	48	0	2	5	2	0	9	0	5	49	2	4	56	119
Hourly Total	0	3	9	6	0	18	0	16	148	6	0	170	0	10	10	11	0	31	0	12	168	11	9	191	410
1:00 PM	0	1	1	1	0	3	0	3	40	1	0	44	0	3	0	3	0	6	0	2	34	4	0	40	93
1:15 PM	0	0	1	1	0	2	0	4	54	0	2	58	0	0	0	3	0	3	0	0	36	6	0	42	105
1:30 PM	0	0	1	3	1	4	0	3	43	1	0	47	0	3	0	5	1	8	0	1	34	4	0	39	98
1:45 PM	0	1	1	1	0	3	0	1	49	1	0	51	0	4	1	2	0	7	0	0	36	3	0	39	100
Hourly Total	0	2	4	6	1	12	0	11	186	3	2	200	0	10	1	13	1	24	0	3	140	17	0	160	396
2:00 PM	0	1	0	1	0	2	0	0	27	0	0	27	0	3	1	1	0	5	0	0	42	4	0	46	80
2:15 PM	0	1	2	2	0	5	0	5	43	0	0	48	0	0	1	8	1	9	0	2	43	4	0	49	111
2:30 PM	0	1	2	3	0	6	0	2	36	1	1	39	0	4	1	4	1	9	0	1	38	2	1	41	95
2:45 PM	0	1	2	2	0	5	0	3	48	1	0	52	0	2	3	4	0	9	0	3	54	5	0	62	128
Hourly Total	0	4	6	8	0	18	0	10	154	2	1	166	0	9	6	17	2	32	0	6	177	15	1	198	414
3:00 PM	0	0	4	3	0	7	0	6	52	3	0	61	0	4	0	5	0	9	0	1	48	3	0	52	129
3:15 PM	0	0	0	2	0	2	0	2	52	2	0	56	0	6	1	3	0	10	0	2	70	0	0	72	140
3:30 PM	0	1	1	1	0	3	0	9	56	0	0	65	0	4	1	5	0	10	0	1	65	9	0	75	153
3:45 PM	0	0	1	4	0	5	0	4	42	1	0	47	0	4	2	4	1	10	0	2	65	4	0	71	133
Hourly Total	0	1	6	10	0	17	0	21	202	6	0	229	0	18	4	17	1	39	0	6	248	16	0	270	555

Constitution Ave. NE & Morningside Dr. NE
Albuquerque New Mexico
Thursday, September 15, 2022

Time	Southbound Morningside Dr. NE						Westbound Constitution Ave. NE						Northbound Morningside Dr. NE						Eastbound Constitution Ave. NE						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehcle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehcle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehcle Approach Total</i>	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	<i>Vehcle Approach Total</i>	
4:00 PM	0	1	1	3	0	5	0	5	56	2	0	63	0	5	2	6	0	13	0	1	63	4	1	68	149
4:15 PM	0	1	4	2	0	7	0	2	45	3	1	50	0	4	0	3	0	7	0	1	53	6	1	60	124
4:30 PM	0	0	3	2	0	5	0	8	54	1	0	63	0	3	3	7	0	13	0	1	75	2	0	78	159
4:45 PM	0	3	3	2	2	8	0	6	54	1	2	61	0	1	0	5	0	6	0	2	50	5	1	57	132
Hourly Total	0	5	11	9	2	25	0	21	209	7	3	237	0	13	5	21	0	39	0	5	241	17	3	263	564
5:00 PM	0	0	5	3	0	8	0	5	57	3	0	65	0	6	4	4	0	14	0	7	74	2	0	83	170
5:15 PM	0	3	3	5	0	11	0	5	43	2	1	50	0	7	3	4	0	14	0	2	80	13	3	95	170
5:30 PM	0	1	5	2	0	8	0	3	50	2	0	55	0	4	1	3	1	8	0	5	65	7	2	77	148
5:45 PM	0	1	1	5	1	7	0	9	51	1	0	61	0	5	1	2	0	8	0	5	51	4	1	60	136
Hourly Total	0	5	14	15	1	34	0	22	201	8	1	231	0	22	9	13	1	44	0	19	270	26	6	315	624
6:00 PM	0	4	2	0	0	6	0	2	38	0	2	40	0	1	3	1	2	5	0	0	55	5	3	60	111
6:15 PM	0	2	1	1	0	4	0	5	39	1	0	45	0	1	2	0	0	3	0	0	44	4	2	48	100
6:30 PM	0	0	2	2	0	4	0	0	36	1	2	37	0	5	1	2	0	8	0	1	44	8	6	53	102
6:45 PM	0	1	0	0	0	1	0	3	28	0	5	31	0	2	3	1	1	6	0	1	34	5	1	40	78
Hourly Total	0	7	5	3	0	15	0	10	141	2	9	153	0	9	9	4	3	22	0	2	177	22	12	201	391
7:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
8:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
8:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
8:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
8:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:00 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:15 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:30 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:45 PM	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Hourly Total	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
DAILY TOTAL Cars	0	50	83	94	12	227	0	153	2038	51	57	2242	1	192	78	155	16	426	0	79	2070	187	71	2336	5231
Heavy Vehicles	0	47	83	92	10	222	0	152	2032	49	53	2233	1	189	77	155	15	422	0	79	2063	187	69	2329	5206
Heavy Vehicle %	0	3	0	2	2	5	0	1	6	2	4	9	0	3	1	0	1	4	0	0	7	0	2	7	25
Heavy Vehicle %	0.00%	6.00%	0.00%	2.13%	16.67%	2.20%	0.00%	0.65%	0.29%	3.92%	7.02%	0.40%	0.00%	1.56%	1.28%	0.00%	6.25%	0.94%	0.00%	0.00%	0.34%	0.00%	2.82%	0.30%	0.48%

Constitution Ave. NE & Morningside Dr. NE

Albuquerque New Mexico

Thursday, September 15, 2022

AM Peak Hour

Time	Southbound						Westbound						Northbound						Eastbound						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	
7:45 AM	0	0	0	2	0	2	0	2	59	2	2	63	0	3	0	3	0	6	0	2	37	0	2	39	110
8:00 AM	0	1	1	1	1	3	0	1	45	2	1	48	0	7	4	0	0	11	0	1	36	2	5	39	101
8:15 AM	0	0	1	3	0	4	0	3	43	1	4	47	0	3	1	0	0	4	0	0	27	0	3	27	82
8:30 AM	0	1	1	4	1	6	0	2	52	1	1	55	0	7	1	4	1	12	0	0	30	5	3	35	108
Peak Hour Total	0	2	3	10	2	15	0	8	199	6	8	213	0	20	6	7	1	33	0	3	130	7	13	140	401
PHF	0.000	0.500	0.750	0.625	0.500	0.625	0.000	0.667	0.843	0.750	0.500	0.845	0.000	0.714	0.375	0.438	0.250	0.688	0.000	0.375	0.878	0.350	0.650	0.897	0.911

PM Peak Hour

Time	Southbound						Westbound						Northbound						Eastbound						VEHICLE TOTAL
	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	U Turns	Left Turns	Straight Through	Right Turns	Crosswalk Crossings	Vehicle Approach Total	
4:30 PM	0	0	3	2	0	5	0	8	54	1	0	63	0	3	3	7	0	13	0	1	75	2	0	78	159
4:45 PM	0	3	3	2	2	8	0	6	54	1	2	61	0	1	0	5	0	6	0	2	50	5	1	57	132
5:00 PM	0	0	5	3	0	8	0	5	57	3	0	65	0	6	4	4	0	14	0	7	74	2	0	83	170
5:15 PM	0	3	3	5	0	11	0	5	43	2	1	50	0	7	3	4	0	14	0	2	80	13	3	95	170
Peak Hour Total	0	6	14	12	2	32	0	24	208	7	3	239	0	17	10	20	0	47	0	12	279	22	4	313	631
PHF	0.000	0.500	0.700	0.600	0.250	0.727	0.000	0.750	0.912	0.583	0.375	0.919	0.000	0.607	0.625	0.714	0.000	0.839	0.000	0.429	0.872	0.423	0.333	0.824	0.928

Total Vehicles On Leg			435		
Vehicles Entering Intersection 227			Vehicles Exiting Intersection 208		
Southbound					
Cars	92	83	47	0	10
Heavy	2	0	3	0	2
Total	94	83	50	0	12



Total Vehicles on Leg 4660	Vehicles Entering Intersection 2336	Eastbound	Cars	Heavy	Total
	Vehicles Exiting Intersection 2324		69	2	71
			0	0	0
			79	0	79
			2063	7	2070
			187	0	187



Daily Volumes

Cars	Heavy	Total	Westbound	Vehicles Entering Intersection 2242	Total Vehicles on Leg 4517
49	2	51			
2032	6	2038			
152	1	153			
0	0	0			
53	4	57			
				Vehicles Exiting Intersection 2275	



Cars	15	1	189	77	155
Heavy	1	0	3	1	0
Total	16	1	192	78	155
Northbound					
Vehicles Entering Intersection			Vehicles Exiting Intersection		
426			424		
Total Vehicles On Leg			850		





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter #1

Date Printed: 9/19/2022

Start Date: 9/14/2022

End Date: 9/15/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.100587
Longitude: -106.600283

9/12/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB
12:00 AM	*	*	*	*	1	0	2	1	*	*	*	*	*	*	2	0
1:00	*	*	*	*	0	0	0	0	*	*	*	*	*	*	0	0
2:00	*	*	*	*	0	0	1	0	*	*	*	*	*	*	0	0
3:00	*	*	*	*	0	0	1	1	*	*	*	*	*	*	0	0
4:00	*	*	*	*	0	0	2	3	*	*	*	*	*	*	1	2
5:00	*	*	*	*	3	2	2	0	*	*	*	*	*	*	2	1
6:00	*	*	*	*	5	4	4	4	*	*	*	*	*	*	4	4
7:00	*	*	*	*	14	5	21	8	*	*	*	*	*	*	18	6
8:00	*	*	*	*	13	5	15	14	*	*	*	*	*	*	14	10
9:00	*	*	*	*	14	7	15	8	*	*	*	*	*	*	14	8
10:00	*	*	*	*	19	15	11	11	*	*	*	*	*	*	15	13
11:00	*	*	*	*	12	18	11	14	*	*	*	*	*	*	12	16
12:00 PM	*	*	*	*	15	20	18	19	*	*	*	*	*	*	16	20
1:00	*	*	*	*	14	14	12	9	*	*	*	*	*	*	13	12
2:00	*	*	*	*	12	10	12	9	*	*	*	*	*	*	12	10
3:00	*	*	*	*	13	14	12	18	*	*	*	*	*	*	12	16
4:00	*	*	*	*	18	7	11	10	*	*	*	*	*	*	14	8
5:00	*	*	*	*	14	19	19	22	*	*	*	*	*	*	16	20
6:00	*	*	*	*	15	7	9	16	*	*	*	*	*	*	12	12
7:00	*	*	*	*	8	9	5	8	*	*	*	*	*	*	6	8
8:00	*	*	*	*	1	4	4	6	*	*	*	*	*	*	2	5
9:00	*	*	*	*	2	1	0	4	*	*	*	*	*	*	1	2
10:00	*	*	*	*	2	3	2	3	*	*	*	*	*	*	2	3
11:00	*	*	*	*	1	0	1	0	*	*	*	*	*	*	1	0
Total	0	0	0	0	196	164	190	188	0	0	0	0	0	0	189	176
Day	0		0		360		378		0		0		0		365	
AM Peak					10:00	11:00	7:00	8:00							7:00	11:00
Volume					19	18	21	14							18	16
PM Peak					4:00	12:00 PM	5:00	5:00							12:00 PM	12:00 PM
Volume					18	20	19	22							16	20
Comb Total	0		0		360		378		0		0		0		365	
ADT	ADT: 369		AADT: 369													



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.100587
Longitude: -106.600283

File Name: Morningside Dr Counter #1
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter

#1

Station ID:
Location 1:
Location 2:
Latitude: 35.100587
Longitude: -106.600283
Direction: A to B, NB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	1	0	0	0	0	0	0	0	0	0	1
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	0	2	1	0	0	0	0	0	0	0	0	0	3
6:00	0	0	2	3	0	0	0	0	0	0	0	0	0	5
7:00	3	1	2	5	2	1	0	0	0	0	0	0	0	14
8:00	0	2	3	5	2	1	0	0	0	0	0	0	0	13
9:00	0	2	2	8	2	0	0	0	0	0	0	0	0	14
10:00	1	4	4	6	4	0	0	0	0	0	0	0	0	19
11:00	1	3	4	3	1	0	0	0	0	0	0	0	0	12
12:00 PM	0	5	2	6	2	0	0	0	0	0	0	0	0	15
1:00	2	0	6	4	2	0	0	0	0	0	0	0	0	14
2:00	0	1	5	3	3	0	0	0	0	0	0	0	0	12
3:00	2	4	4	2	1	0	0	0	0	0	0	0	0	13
4:00	0	3	7	4	4	0	0	0	0	0	0	0	0	18
5:00	0	3	4	5	1	1	0	0	0	0	0	0	0	14
6:00	2	2	3	6	2	0	0	0	0	0	0	0	0	15
7:00	0	1	3	4	0	0	0	0	0	0	0	0	0	8
8:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
9:00	0	0	0	2	0	0	0	0	0	0	0	0	0	2
10:00	0	1	1	0	0	0	0	0	0	0	0	0	0	2
11:00	0	0	0	0	1	0	0	0	0	0	0	0	0	1
Total	11	32	54	69	27	3	0	0	0	0	0	0	0	196



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.100587
Longitude: -106.600283
Direction: A to B, NB

#1
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	1	1	0	0	0	0	0	0	0	0	0	0	2
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
3:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
4:00	0	0	1	1	0	0	0	0	0	0	0	0	0	2
5:00	0	0	2	0	0	0	0	0	0	0	0	0	0	2
6:00	0	0	3	1	0	0	0	0	0	0	0	0	0	4
7:00	0	2	10	6	1	2	0	0	0	0	0	0	0	21
8:00	0	0	8	6	1	0	0	0	0	0	0	0	0	15
9:00	1	3	4	6	0	1	0	0	0	0	0	0	0	15
10:00	0	1	6	2	1	1	0	0	0	0	0	0	0	11
11:00	0	0	6	2	3	0	0	0	0	0	0	0	0	11
12:00 PM	3	0	3	9	3	0	0	0	0	0	0	0	0	18
1:00	0	2	3	6	1	0	0	0	0	0	0	0	0	12
2:00	1	0	4	3	2	1	1	0	0	0	0	0	0	12
3:00	1	2	4	3	2	0	0	0	0	0	0	0	0	12
4:00	0	2	8	1	0	0	0	0	0	0	0	0	0	11
5:00	0	0	5	8	5	1	0	0	0	0	0	0	0	19
6:00	0	1	3	2	2	1	0	0	0	0	0	0	0	9
7:00	0	2	1	2	0	0	0	0	0	0	0	0	0	5
8:00	1	1	1	1	0	0	0	0	0	0	0	0	0	4
9:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:00	0	1	0	1	0	0	0	0	0	0	0	0	0	2
11:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Total	7	19	75	60	21	7	1	0	0	0	0	0	0	190
Grand Total	18	51	129	129	48	10	1	0	0	0	0	0	0	386

Stats	Percentile	15th	50th	85th	95th
Speed		19	25	30	33
Mean Speed (Average)		24.5			
10 MPH Pace Speed		20-29			
Number in Pace		256			
Percent in Pace		66.3%			
Number > 25 MPH		188			
Percent > 25 MPH		48.7%			



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter

#1

Station ID:
Location 1:
Location 2:
Latitude: 35.100587
Longitude: -106.600283
Direction: B to A, SB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	1	1	0	0	0	0	0	0	0	0	0	0	2
6:00	1	0	1	1	1	0	0	0	0	0	0	0	0	4
7:00	0	0	3	1	1	0	0	0	0	0	0	0	0	5
8:00	0	0	4	1	0	0	0	0	0	0	0	0	0	5
9:00	0	1	3	3	0	0	0	0	0	0	0	0	0	7
10:00	0	2	5	7	1	0	0	0	0	0	0	0	0	15
11:00	4	3	8	3	0	0	0	0	0	0	0	0	0	18
12:00 PM	1	3	7	7	2	0	0	0	0	0	0	0	0	20
1:00	1	3	6	2	2	0	0	0	0	0	0	0	0	14
2:00	0	1	3	5	1	0	0	0	0	0	0	0	0	10
3:00	1	3	4	4	2	0	0	0	0	0	0	0	0	14
4:00	0	0	3	4	0	0	0	0	0	0	0	0	0	7
5:00	0	2	5	10	1	1	0	0	0	0	0	0	0	19
6:00	1	0	2	4	0	0	0	0	0	0	0	0	0	7
7:00	0	2	4	2	1	0	0	0	0	0	0	0	0	9
8:00	0	3	0	1	0	0	0	0	0	0	0	0	0	4
9:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
10:00	1	0	1	1	0	0	0	0	0	0	0	0	0	3
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	10	24	60	57	12	1	0	0	0	0	0	0	0	164



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.100587
Longitude: -106.600283
Direction: B to A, SB

#1
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	1	0	0	0	0	0	0	0	0	0	1
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
4:00	0	1	0	2	0	0	0	0	0	0	0	0	0	3
5:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00	1	1	2	0	0	0	0	0	0	0	0	0	0	4
7:00	1	2	3	1	1	0	0	0	0	0	0	0	0	8
8:00	0	4	5	4	1	0	0	0	0	0	0	0	0	14
9:00	1	1	3	3	0	0	0	0	0	0	0	0	0	8
10:00	0	4	6	1	0	0	0	0	0	0	0	0	0	11
11:00	1	1	5	5	1	1	0	0	0	0	0	0	0	14
12:00 PM	2	0	7	7	2	1	0	0	0	0	0	0	0	19
1:00	2	1	2	3	1	0	0	0	0	0	0	0	0	9
2:00	4	1	1	3	0	0	0	0	0	0	0	0	0	9
3:00	0	4	5	8	1	0	0	0	0	0	0	0	0	18
4:00	2	1	2	3	2	0	0	0	0	0	0	0	0	10
5:00	0	2	8	8	4	0	0	0	0	0	0	0	0	22
6:00	2	4	4	4	2	0	0	0	0	0	0	0	0	16
7:00	1	2	2	3	0	0	0	0	0	0	0	0	0	8
8:00	1	1	3	1	0	0	0	0	0	0	0	0	0	6
9:00	0	0	1	2	1	0	0	0	0	0	0	0	0	4
10:00	0	0	3	0	0	0	0	0	0	0	0	0	0	3
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	18	30	62	60	16	2	0	0	0	0	0	0	0	188
Grand Total	28	54	122	117	28	3	0	0	0	0	0	0	0	352

Stats	Percentile	15th	50th	85th	95th
Speed		18	24	29	31
Mean Speed (Average)		23.2			
10 MPH Pace Speed		20-29			
Number in Pace		238			
Percent in Pace		67.6%			
Number > 25 MPH		148			
Percent > 25 MPH		42.0%			



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter
#1

Station ID:
Location 1:
Location 2:
Latitude: 35.100587
Longitude: -106.600283

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No



85th Percentile: 28.3

85th Percentile: 28.8



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter #2

Date Printed: 9/19/2022

Start Date: 9/14/2022

End Date: 9/15/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.097980
Longitude: -106.600294

9/12/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB
12:00 AM	*	*	*	*	2	0	2	0	*	*	*	*	*	*	2	0
1:00	*	*	*	*	0	0	0	0	*	*	*	*	*	*	0	0
2:00	*	*	*	*	0	0	1	1	*	*	*	*	*	*	0	0
3:00	*	*	*	*	0	0	0	0	*	*	*	*	*	*	0	0
4:00	*	*	*	*	0	0	0	1	*	*	*	*	*	*	0	0
5:00	*	*	*	*	2	1	2	1	*	*	*	*	*	*	2	1
6:00	*	*	*	*	4	0	3	0	*	*	*	*	*	*	4	0
7:00	*	*	*	*	14	5	18	13	*	*	*	*	*	*	16	9
8:00	*	*	*	*	14	11	20	13	*	*	*	*	*	*	17	12
9:00	*	*	*	*	18	7	20	12	*	*	*	*	*	*	19	10
10:00	*	*	*	*	22	16	18	8	*	*	*	*	*	*	20	12
11:00	*	*	*	*	19	21	16	11	*	*	*	*	*	*	18	16
12:00 PM	*	*	*	*	20	19	28	10	*	*	*	*	*	*	24	14
1:00	*	*	*	*	17	11	12	9	*	*	*	*	*	*	14	10
2:00	*	*	*	*	20	12	13	7	*	*	*	*	*	*	16	10
3:00	*	*	*	*	21	23	19	16	*	*	*	*	*	*	20	20
4:00	*	*	*	*	22	13	9	13	*	*	*	*	*	*	16	13
5:00	*	*	*	*	34	25	26	33	*	*	*	*	*	*	30	29
6:00	*	*	*	*	27	13	18	21	*	*	*	*	*	*	22	17
7:00	*	*	*	*	8	9	10	11	*	*	*	*	*	*	9	10
8:00	*	*	*	*	1	6	7	5	*	*	*	*	*	*	4	6
9:00	*	*	*	*	4	3	4	5	*	*	*	*	*	*	4	4
10:00	*	*	*	*	2	2	2	3	*	*	*	*	*	*	2	2
11:00	*	*	*	*	0	0	1	1	*	*	*	*	*	*	0	0
Total	0	0	0	0	271	197	249	194	0	0	0	0	0	0	259	195
Day	0		0		468		443		0		0		0		454	
AM Peak					10:00	11:00	8:00	7:00							10:00	11:00
Volume					22	21	20	13							20	16
PM Peak					5:00	5:00	12:00 PM	5:00							5:00	5:00
Volume					34	25	28	33							30	29
Comb Total	0		0		468		443		0		0		0		454	
ADT	ADT: 456		AADT: 456													




Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.097980
Longitude: -106.600294

File Name: Morningside Dr Counter #2
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter

#2

Station ID:
Location 1:
Location 2:
Latitude: 35.097980
Longitude: -106.600294
Direction: A to B, NB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	1	0	1	0	0	0	0	0	0	0	0	0	0	2
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	1	0	1	0	0	0	0	0	0	0	0	0	2
6:00	1	1	2	0	0	0	0	0	0	0	0	0	0	4
7:00	4	8	1	1	0	0	0	0	0	0	0	0	0	14
8:00	3	9	2	0	0	0	0	0	0	0	0	0	0	14
9:00	6	8	3	1	0	0	0	0	0	0	0	0	0	18
10:00	9	7	6	0	0	0	0	0	0	0	0	0	0	22
11:00	6	9	4	0	0	0	0	0	0	0	0	0	0	19
12:00 PM	5	6	8	1	0	0	0	0	0	0	0	0	0	20
1:00	2	9	5	1	0	0	0	0	0	0	0	0	0	17
2:00	3	9	7	1	0	0	0	0	0	0	0	0	0	20
3:00	5	14	2	0	0	0	0	0	0	0	0	0	0	21
4:00	4	11	6	1	0	0	0	0	0	0	0	0	0	22
5:00	20	13	1	0	0	0	0	0	0	0	0	0	0	34
6:00	17	9	1	0	0	0	0	0	0	0	0	0	0	27
7:00	3	4	0	1	0	0	0	0	0	0	0	0	0	8
8:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
9:00	0	2	1	1	0	0	0	0	0	0	0	0	0	4
10:00	1	1	0	0	0	0	0	0	0	0	0	0	0	2
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	90	121	51	9	0	0	0	0	0	0	0	0	0	271



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter

#2

Station ID:
Location 1:
Location 2:
Latitude: 35.097980
Longitude: -106.600294
Direction: A to B, NB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	2	0	0	0	0	0	0	0	0	0	0	2
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	2	0	0	0	0	0	0	0	0	0	0	0	2
6:00	1	0	2	0	0	0	0	0	0	0	0	0	0	3
7:00	5	8	4	1	0	0	0	0	0	0	0	0	0	18
8:00	6	5	8	1	0	0	0	0	0	0	0	0	0	20
9:00	12	4	4	0	0	0	0	0	0	0	0	0	0	20
10:00	16	2	0	0	0	0	0	0	0	0	0	0	0	18
11:00	6	7	3	0	0	0	0	0	0	0	0	0	0	16
12:00 PM	4	16	8	0	0	0	0	0	0	0	0	0	0	28
1:00	4	2	6	0	0	0	0	0	0	0	0	0	0	12
2:00	2	7	2	2	0	0	0	0	0	0	0	0	0	13
3:00	7	9	1	2	0	0	0	0	0	0	0	0	0	19
4:00	0	8	1	0	0	0	0	0	0	0	0	0	0	9
5:00	7	13	5	1	0	0	0	0	0	0	0	0	0	26
6:00	11	6	0	1	0	0	0	0	0	0	0	0	0	18
7:00	2	3	5	0	0	0	0	0	0	0	0	0	0	10
8:00	2	1	4	0	0	0	0	0	0	0	0	0	0	7
9:00	1	1	1	1	0	0	0	0	0	0	0	0	0	4
10:00	1	1	0	0	0	0	0	0	0	0	0	0	0	2
11:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Total	87	96	57	9	0	0	0	0	0	0	0	0	0	249
Grand Total	177	217	108	18	0	0	0	0	0	0	0	0	0	520

Stats	Percentile	15th	50th	85th	95th
Speed	11	17	22	24	
Mean Speed (Average)	15.5				
10 MPH Pace Speed	15-24				
Number in Pace	324				
Percent in Pace	62.3%				
Number > 25 MPH	18				
Percent > 25 MPH	3.5%				



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter

#2

Station ID:
Location 1:
Location 2:
Latitude: 35.097980
Longitude: -106.600294
Direction: B to A, SB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
6:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7:00	1	4	0	0	0	0	0	0	0	0	0	0	0	5
8:00	0	7	4	0	0	0	0	0	0	0	0	0	0	11
9:00	0	5	2	0	0	0	0	0	0	0	0	0	0	7
10:00	7	6	3	0	0	0	0	0	0	0	0	0	0	16
11:00	6	11	4	0	0	0	0	0	0	0	0	0	0	21
12:00 PM	4	6	9	0	0	0	0	0	0	0	0	0	0	19
1:00	4	4	3	0	0	0	0	0	0	0	0	0	0	11
2:00	5	6	1	0	0	0	0	0	0	0	0	0	0	12
3:00	3	12	7	1	0	0	0	0	0	0	0	0	0	23
4:00	3	3	7	0	0	0	0	0	0	0	0	0	0	13
5:00	14	8	3	0	0	0	0	0	0	0	0	0	0	25
6:00	8	2	3	0	0	0	0	0	0	0	0	0	0	13
7:00	1	6	1	1	0	0	0	0	0	0	0	0	0	9
8:00	3	2	1	0	0	0	0	0	0	0	0	0	0	6
9:00	1	0	1	1	0	0	0	0	0	0	0	0	0	3
10:00	0	2	0	0	0	0	0	0	0	0	0	0	0	2
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	60	84	50	3	0	0	0	0	0	0	0	0	0	197



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.097980
Longitude: -106.600294
Direction: B to A, SB

#2
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
5:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
6:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7:00	0	9	4	0	0	0	0	0	0	0	0	0	0	13
8:00	0	7	5	1	0	0	0	0	0	0	0	0	0	13
9:00	4	8	0	0	0	0	0	0	0	0	0	0	0	12
10:00	7	1	0	0	0	0	0	0	0	0	0	0	0	8
11:00	3	7	0	1	0	0	0	0	0	0	0	0	0	11
12:00 PM	2	6	2	0	0	0	0	0	0	0	0	0	0	10
1:00	3	5	1	0	0	0	0	0	0	0	0	0	0	9
2:00	1	3	3	0	0	0	0	0	0	0	0	0	0	7
3:00	2	8	6	0	0	0	0	0	0	0	0	0	0	16
4:00	3	7	2	1	0	0	0	0	0	0	0	0	0	13
5:00	10	14	9	0	0	0	0	0	0	0	0	0	0	33
6:00	9	8	3	1	0	0	0	0	0	0	0	0	0	21
7:00	1	7	3	0	0	0	0	0	0	0	0	0	0	11
8:00	2	2	1	0	0	0	0	0	0	0	0	0	0	5
9:00	1	3	1	0	0	0	0	0	0	0	0	0	0	5
10:00	0	2	1	0	0	0	0	0	0	0	0	0	0	3
11:00	1	0	0	0	0	0	0	0	0	0	0	0	0	1
Total	49	99	42	4	0	0	0	0	0	0	0	0	0	194
Grand Total	109	183	92	7	0	0	0	0	0	0	0	0	0	391

Stats	Percentile	15th	50th	85th	95th
Speed		13	17	21	24
Mean Speed (Average)		16.1			
10 MPH Pace Speed		15-24			
Number in Pace		274			
Percent in Pace		70.1%			
Number > 25 MPH		7			
Percent > 25 MPH		1.8%			



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter

#2

Date Printed: 9/19/2022

Start Date: 9/14/2022

End Date: 9/15/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.097980
Longitude: -106.600294





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter #3

Date Printed: 9/19/2022

Start Date: 9/14/2022

End Date: 9/15/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.099326
Longitude: -106.595302

9/12/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB
12:00 AM	*	*	*	*	4	10	3	9	*	*	*	*	*	*	4	10
1:00	*	*	*	*	4	7	6	6	*	*	*	*	*	*	5	6
2:00	*	*	*	*	4	3	4	3	*	*	*	*	*	*	4	3
3:00	*	*	*	*	0	4	2	4	*	*	*	*	*	*	1	4
4:00	*	*	*	*	3	11	6	11	*	*	*	*	*	*	4	11
5:00	*	*	*	*	18	33	14	29	*	*	*	*	*	*	16	31
6:00	*	*	*	*	52	79	40	85	*	*	*	*	*	*	46	82
7:00	*	*	*	*	140	231	127	213	*	*	*	*	*	*	134	222
8:00	*	*	*	*	188	199	194	202	*	*	*	*	*	*	191	200
9:00	*	*	*	*	191	216	156	232	*	*	*	*	*	*	174	224
10:00	*	*	*	*	190	217	217	205	*	*	*	*	*	*	204	211
11:00	*	*	*	*	224	285	227	245	*	*	*	*	*	*	226	265
12:00 PM	*	*	*	*	266	243	245	234	*	*	*	*	*	*	256	238
1:00	*	*	*	*	209	279	200	267	*	*	*	*	*	*	204	273
2:00	*	*	*	*	239	235	265	299	*	*	*	*	*	*	252	267
3:00	*	*	*	*	302	302	311	340	*	*	*	*	*	*	306	321
4:00	*	*	*	*	314	363	332	337	*	*	*	*	*	*	323	350
5:00	*	*	*	*	326	370	295	292	*	*	*	*	*	*	310	331
6:00	*	*	*	*	236	194	216	212	*	*	*	*	*	*	226	203
7:00	*	*	*	*	195	118	139	100	*	*	*	*	*	*	167	109
8:00	*	*	*	*	126	73	124	67	*	*	*	*	*	*	125	70
9:00	*	*	*	*	65	46	62	48	*	*	*	*	*	*	64	47
10:00	*	*	*	*	29	20	34	24	*	*	*	*	*	*	32	22
11:00	*	*	*	*	17	12	14	18	*	*	*	*	*	*	16	15
Total	0	0	0	0	3342	3550	3233	3482	0	0	0	0	0	0	3290	3515
Day	0		0		6892		6715		0		0		0		6805	
AM Peak					11:00	11:00	11:00	11:00							11:00	11:00
Volume					224	285	227	245							226	265
PM Peak					5:00	5:00	4:00	3:00							4:00	4:00
Volume					326	370	332	340							323	350
Comb Total	0		0		6892		6715		0		0		0		6805	
ADT	ADT: 6,804		AADT: 6,804													



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.099326
Longitude: -106.595302

File Name: Washington St Counter #3
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

#3

Station ID:
Location 1:
Location 2:
Latitude: 35.099326
Longitude: -106.595302
Direction: A to B, NB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	2	2	0	0	0	0	0	0	0	0	4
1:00	0	0	0	0	4	0	0	0	0	0	0	0	0	4
2:00	0	0	0	0	1	3	0	0	0	0	0	0	0	4
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	1	2	0	0	0	0	0	0	0	3
5:00	0	0	1	8	6	3	0	0	0	0	0	0	0	18
6:00	0	0	1	19	26	4	1	1	0	0	0	0	0	52
7:00	1	1	6	51	65	10	6	0	0	0	0	0	0	140
8:00	1	3	13	51	77	36	4	2	1	0	0	0	0	188
9:00	0	1	8	70	85	20	7	0	0	0	0	0	0	191
10:00	0	2	6	67	92	20	3	0	0	0	0	0	0	190
11:00	0	0	7	87	110	20	0	0	0	0	0	0	0	224
12:00 PM	1	3	12	79	133	34	4	0	0	0	0	0	0	266
1:00	0	2	7	73	98	27	2	0	0	0	0	0	0	209
2:00	4	0	15	80	105	31	4	0	0	0	0	0	0	239
3:00	1	1	10	125	127	32	5	0	1	0	0	0	0	302
4:00	3	1	12	93	153	43	9	0	0	0	0	0	0	314
5:00	0	3	5	116	164	37	1	0	0	0	0	0	0	326
6:00	0	2	15	79	99	38	3	0	0	0	0	0	0	236
7:00	1	4	14	70	83	21	2	0	0	0	0	0	0	195
8:00	1	1	6	40	67	10	1	0	0	0	0	0	0	126
9:00	0	0	1	25	28	7	2	2	0	0	0	0	0	65
10:00	0	0	1	10	15	1	2	0	0	0	0	0	0	29
11:00	0	0	0	5	6	4	2	0	0	0	0	0	0	17
Total	13	24	140	1150	1547	403	58	5	2	0	0	0	0	3342



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

#3

Station ID:
Location 1:
Location 2:
Latitude: 35.099326
Longitude: -106.595302
Direction: A to B, NB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	1	2	0	0	0	0	0	0	0	0	3
1:00	0	0	0	2	4	0	0	0	0	0	0	0	0	6
2:00	0	0	0	1	3	0	0	0	0	0	0	0	0	4
3:00	0	0	0	1	0	0	1	0	0	0	0	0	0	2
4:00	0	0	0	2	2	2	0	0	0	0	0	0	0	6
5:00	0	0	1	4	5	4	0	0	0	0	0	0	0	14
6:00	0	0	1	6	20	11	1	0	1	0	0	0	0	40
7:00	0	2	6	41	52	25	1	0	0	0	0	0	0	127
8:00	1	1	6	64	88	30	4	0	0	0	0	0	0	194
9:00	1	2	5	45	64	31	6	2	0	0	0	0	0	156
10:00	1	0	2	39	121	41	10	2	1	0	0	0	0	217
11:00	2	2	16	66	107	30	2	1	1	0	0	0	0	227
12:00 PM	2	4	2	98	107	30	2	0	0	0	0	0	0	245
1:00	1	0	8	54	101	32	3	0	1	0	0	0	0	200
2:00	1	7	5	108	121	22	0	1	0	0	0	0	0	265
3:00	3	4	19	110	139	31	5	0	0	0	0	0	0	311
4:00	3	3	25	88	175	33	3	1	1	0	0	0	0	332
5:00	0	3	4	75	158	45	7	2	1	0	0	0	0	295
6:00	2	0	8	61	112	31	2	0	0	0	0	0	0	216
7:00	1	3	11	43	62	17	2	0	0	0	0	0	0	139
8:00	0	0	4	30	72	17	0	1	0	0	0	0	0	124
9:00	0	0	3	26	24	5	1	2	0	1	0	0	0	62
10:00	0	0	5	10	16	2	1	0	0	0	0	0	0	34
11:00	0	0	0	5	6	3	0	0	0	0	0	0	0	14
Total	18	31	131	980	1561	442	51	12	6	1	0	0	0	3233
Grand Total	31	55	271	2130	3108	845	109	17	8	1	0	0	0	6575

Stats	Percentile	15th	50th	85th	95th
Speed	27	31	35	38	
Mean Speed (Average)	31.1				
10 MPH Pace Speed	25-34				
Number in Pace	5181				
Percent in Pace	78.8%				
Number > 30 MPH	4088				
Percent > 30 MPH	62.2%				



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

#3

Station ID:
Location 1:
Location 2:
Latitude: 35.099326
Longitude: -106.595302
Direction: B to A, SB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	1	2	2	4	1	0	0	0	0	0	0	10
1:00	0	0	0	1	4	2	0	0	0	0	0	0	0	7
2:00	0	0	0	0	1	0	2	0	0	0	0	0	0	3
3:00	0	0	0	0	1	0	1	2	0	0	0	0	0	4
4:00	0	0	0	1	4	3	3	0	0	0	0	0	0	11
5:00	0	1	2	5	10	9	5	0	1	0	0	0	0	33
6:00	0	0	1	3	32	28	14	1	0	0	0	0	0	79
7:00	1	2	0	25	101	87	15	0	0	0	0	0	0	231
8:00	0	0	5	22	85	71	14	1	1	0	0	0	0	199
9:00	4	3	4	22	93	71	16	3	0	0	0	0	0	216
10:00	1	2	5	22	104	69	11	3	0	0	0	0	0	217
11:00	1	2	6	24	128	88	34	1	0	1	0	0	0	285
12:00 PM	1	1	8	25	107	82	16	3	0	0	0	0	0	243
1:00	0	3	4	24	142	90	16	0	0	0	0	0	0	279
2:00	0	0	2	24	110	82	15	2	0	0	0	0	0	235
3:00	2	2	3	35	130	100	28	1	1	0	0	0	0	302
4:00	1	2	8	47	169	115	21	0	0	0	0	0	0	363
5:00	2	0	7	36	177	120	24	3	1	0	0	0	0	370
6:00	0	3	0	25	85	66	13	2	0	0	0	0	0	194
7:00	1	1	3	21	51	36	5	0	0	0	0	0	0	118
8:00	0	0	2	17	38	14	2	0	0	0	0	0	0	73
9:00	1	0	2	9	17	9	6	1	0	0	0	1	0	46
10:00	0	0	0	1	6	12	0	1	0	0	0	0	0	20
11:00	0	0	0	0	6	3	3	0	0	0	0	0	0	12
Total	15	22	63	391	1603	1161	265	24	4	1	0	1	0	3550



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.099326
Longitude: -106.595302
Direction: B to A, SB

#3
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	1	4	3	1	0	0	0	0	0	0	9
1:00	0	0	0	2	2	1	1	0	0	0	0	0	0	6
2:00	0	0	0	0	1	2	0	0	0	0	0	0	0	3
3:00	0	0	0	0	3	1	0	0	0	0	0	0	0	4
4:00	0	0	1	0	3	4	3	0	0	0	0	0	0	11
5:00	0	1	1	4	10	9	2	2	0	0	0	0	0	29
6:00	2	0	2	12	38	22	7	2	0	0	0	0	0	85
7:00	1	1	2	30	97	65	16	0	1	0	0	0	0	213
8:00	1	1	5	22	97	61	15	0	0	0	0	0	0	202
9:00	2	1	2	21	107	77	21	1	0	0	0	0	0	232
10:00	0	0	0	21	86	81	15	2	0	0	0	0	0	205
11:00	0	0	3	22	110	80	28	2	0	0	0	0	0	245
12:00 PM	1	1	5	21	100	88	14	4	0	0	0	0	0	234
1:00	0	1	2	19	118	111	12	3	1	0	0	0	0	267
2:00	1	1	5	33	129	109	16	4	1	0	0	0	0	299
3:00	1	0	6	26	145	131	30	1	0	0	0	0	0	340
4:00	1	0	6	12	131	147	34	6	0	0	0	0	0	337
5:00	1	2	3	15	116	117	34	2	0	0	0	2	0	292
6:00	0	0	2	21	100	69	18	2	0	0	0	0	0	212
7:00	1	4	2	9	56	18	8	1	0	1	0	0	0	100
8:00	0	0	3	21	22	15	6	0	0	0	0	0	0	67
9:00	1	0	1	4	23	14	5	0	0	0	0	0	0	48
10:00	0	1	2	1	11	5	2	2	0	0	0	0	0	24
11:00	0	0	2	5	6	2	3	0	0	0	0	0	0	18
Total	13	14	55	322	1515	1232	291	34	3	1	0	2	0	3482
Grand Total	28	36	118	713	3118	2393	556	58	7	2	0	3	0	7032

Stats	Percentile	15th	50th	85th	95th
Speed		30	34	39	41
Mean Speed (Average)		34.4			
10 MPH Pace Speed		30-39			
Number in Pace		5477			
Percent in Pace		77.9%			
Number > 30 MPH		6137			
Percent > 30 MPH		87.3%			



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter
#3

Station ID:
Location 1:
Location 2:
Latitude: 35.099326
Longitude: -106.595302

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter #4

Date Printed: 9/19/2022

Start Date: 9/14/2022

End Date: 9/15/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.096956
Longitude: -106.595302

9/12/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB
12:00 AM	*	*	*	*	5	13	3	9	*	*	*	*	*	*	4	11
1:00	*	*	*	*	4	7	4	4	*	*	*	*	*	*	4	6
2:00	*	*	*	*	3	3	2	6	*	*	*	*	*	*	2	4
3:00	*	*	*	*	1	6	3	4	*	*	*	*	*	*	2	5
4:00	*	*	*	*	3	11	4	8	*	*	*	*	*	*	4	10
5:00	*	*	*	*	16	25	11	22	*	*	*	*	*	*	14	24
6:00	*	*	*	*	46	68	35	61	*	*	*	*	*	*	40	64
7:00	*	*	*	*	152	207	131	180	*	*	*	*	*	*	142	194
8:00	*	*	*	*	195	188	199	178	*	*	*	*	*	*	197	183
9:00	*	*	*	*	174	207	135	208	*	*	*	*	*	*	154	208
10:00	*	*	*	*	182	195	199	184	*	*	*	*	*	*	190	190
11:00	*	*	*	*	206	235	222	222	*	*	*	*	*	*	214	228
12:00 PM	*	*	*	*	241	230	226	217	*	*	*	*	*	*	234	224
1:00	*	*	*	*	182	260	180	252	*	*	*	*	*	*	181	256
2:00	*	*	*	*	235	229	257	288	*	*	*	*	*	*	246	258
3:00	*	*	*	*	292	302	280	336	*	*	*	*	*	*	286	319
4:00	*	*	*	*	283	359	297	326	*	*	*	*	*	*	290	342
5:00	*	*	*	*	305	368	270	294	*	*	*	*	*	*	288	331
6:00	*	*	*	*	228	190	201	194	*	*	*	*	*	*	214	192
7:00	*	*	*	*	188	119	130	99	*	*	*	*	*	*	159	109
8:00	*	*	*	*	107	75	112	78	*	*	*	*	*	*	110	76
9:00	*	*	*	*	61	47	50	53	*	*	*	*	*	*	56	50
10:00	*	*	*	*	27	23	34	27	*	*	*	*	*	*	30	25
11:00	*	*	*	*	18	14	16	22	*	*	*	*	*	*	17	18
Total	0	0	0	0	3154	3381	3001	3272	0	0	0	0	0	0	3078	3327
Day	0		0		6535		6273		0		0		0		6405	
AM Peak					11:00	11:00	11:00	11:00							11:00	11:00
Volume					206	235	222	222							214	228
PM Peak					5:00	5:00	4:00	3:00							4:00	4:00
Volume					305	368	297	336							290	342
Comb Total	0		0		6535		6273		0		0		0		6405	
ADT	ADT: 6,404		AADT: 6,404													



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.096956
Longitude: -106.595302

File Name: Washington St Counter #4
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

#4

Station ID:
Location 1:
Location 2:
Latitude: 35.096956
Longitude: -106.595302
Direction: A to B, SB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	1	1	1	1	1	0	0	0	0	0	0	0	5
1:00	0	0	0	2	2	0	0	0	0	0	0	0	0	4
2:00	0	0	0	0	0	3	0	0	0	0	0	0	0	3
3:00	1	0	0	0	0	0	0	0	0	0	0	0	0	1
4:00	0	0	0	0	2	0	1	0	0	0	0	0	0	3
5:00	0	0	3	6	6	1	0	0	0	0	0	0	0	16
6:00	0	2	1	22	18	2	1	0	0	0	0	0	0	46
7:00	0	3	10	68	63	7	0	1	0	0	0	0	0	152
8:00	4	9	13	58	86	21	3	0	1	0	0	0	0	195
9:00	0	5	8	76	73	10	1	0	0	1	0	0	0	174
10:00	1	2	8	76	80	13	2	0	0	0	0	0	0	182
11:00	1	4	16	97	79	8	1	0	0	0	0	0	0	206
12:00 PM	1	6	14	112	91	16	1	0	0	0	0	0	0	241
1:00	0	7	10	76	74	14	1	0	0	0	0	0	0	182
2:00	1	5	14	85	98	31	1	0	0	0	0	0	0	235
3:00	1	1	32	100	134	23	1	0	0	0	0	0	0	292
4:00	0	11	12	108	135	15	2	0	0	0	0	0	0	283
5:00	3	1	9	150	123	17	2	0	0	0	0	0	0	305
6:00	1	3	18	95	91	18	2	0	0	0	0	0	0	228
7:00	1	5	21	90	62	8	1	0	0	0	0	0	0	188
8:00	0	0	5	58	38	6	0	0	0	0	0	0	0	107
9:00	1	1	5	30	20	2	1	1	0	0	0	0	0	61
10:00	0	0	2	12	10	3	0	0	0	0	0	0	0	27
11:00	0	0	3	4	4	5	2	0	0	0	0	0	0	18
Total	16	66	205	1326	1290	224	23	2	1	1	0	0	0	3154



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

#4

Station ID:
Location 1:
Location 2:
Latitude: 35.096956
Longitude: -106.595302
Direction: A to B, SB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	1	2	0	0	0	0	0	0	0	0	3
1:00	0	0	0	0	3	1	0	0	0	0	0	0	0	4
2:00	1	0	0	1	0	0	0	0	0	0	0	0	0	2
3:00	0	0	0	1	1	1	0	0	0	0	0	0	0	3
4:00	0	0	1	0	3	0	0	0	0	0	0	0	0	4
5:00	0	0	1	6	4	0	0	0	0	0	0	0	0	11
6:00	0	1	2	7	19	5	1	0	0	0	0	0	0	35
7:00	0	1	4	49	59	15	2	0	1	0	0	0	0	131
8:00	0	3	9	76	90	18	3	0	0	0	0	0	0	199
9:00	1	1	7	45	60	18	3	0	0	0	0	0	0	135
10:00	2	3	3	45	122	19	5	0	0	0	0	0	0	199
11:00	3	7	9	88	97	17	1	0	0	0	0	0	0	222
12:00 PM	1	2	17	98	93	15	0	0	0	0	0	0	0	226
1:00	0	8	7	70	77	15	3	0	0	0	0	0	0	180
2:00	0	1	15	113	107	19	1	0	0	0	0	0	1	257
3:00	1	4	13	83	145	26	8	0	0	0	0	0	0	280
4:00	1	3	19	119	123	25	6	1	0	0	0	0	0	297
5:00	3	4	13	101	125	21	1	2	0	0	0	0	0	270
6:00	1	1	12	82	87	16	2	0	0	0	0	0	0	201
7:00	1	4	9	46	57	9	4	0	0	0	0	0	0	130
8:00	2	0	8	56	37	6	2	1	0	0	0	0	0	112
9:00	0	1	4	20	18	5	1	1	0	0	0	0	0	50
10:00	0	0	6	11	15	2	0	0	0	0	0	0	0	34
11:00	0	1	0	5	8	2	0	0	0	0	0	0	0	16
Total	17	45	159	1123	1352	255	43	5	1	0	0	0	1	3001
Grand Total	33	111	364	2449	2642	479	66	7	2	1	0	0	1	6155

Stats	Percentile	15th	50th	85th	95th
Speed	27	30	34	36	
Mean Speed (Average)	30.1				
10 MPH Pace Speed	25-34				
Number in Pace	5045				
Percent in Pace	82.0%				
Number > 30 MPH	3198				
Percent > 30 MPH	52.0%				



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

#4

Station ID:
Location 1:
Location 2:
Latitude: 35.096956
Longitude: -106.595302
Direction: B to A, NB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	3	4	4	2	0	0	0	0	0	0	13
1:00	0	0	2	2	3	0	0	0	0	0	0	0	0	7
2:00	0	0	0	1	0	0	2	0	0	0	0	0	0	3
3:00	0	0	0	1	2	1	0	1	1	0	0	0	0	6
4:00	0	0	0	2	5	3	1	0	0	0	0	0	0	11
5:00	0	0	1	8	5	9	0	2	0	0	0	0	0	25
6:00	0	0	1	6	32	18	10	1	0	0	0	0	0	68
7:00	0	0	8	35	92	58	12	1	1	0	0	0	0	207
8:00	0	2	5	25	96	50	10	0	0	0	0	0	0	188
9:00	0	4	8	20	113	52	8	1	1	0	0	0	0	207
10:00	1	1	6	33	87	50	13	2	1	1	0	0	0	195
11:00	2	1	4	24	98	81	19	4	1	1	0	0	0	235
12:00 PM	2	4	8	28	101	69	15	2	0	1	0	0	0	230
1:00	0	2	5	39	114	79	18	2	1	0	0	0	0	260
2:00	0	1	3	38	109	68	9	0	1	0	0	0	0	229
3:00	0	1	7	55	133	79	24	2	0	1	0	0	0	302
4:00	1	0	7	46	175	103	24	3	0	0	0	0	0	359
5:00	0	2	4	54	200	84	20	1	2	0	1	0	0	368
6:00	0	2	7	39	86	44	9	3	0	0	0	0	0	190
7:00	0	1	2	14	60	33	9	0	0	0	0	0	0	119
8:00	0	2	1	17	44	9	2	0	0	0	0	0	0	75
9:00	1	0	1	9	16	12	6	1	0	0	0	0	1	47
10:00	0	2	0	1	11	8	1	0	0	0	0	0	0	23
11:00	0	0	1	0	9	3	1	0	0	0	0	0	0	14
Total	7	25	81	500	1595	917	215	26	9	4	1	0	1	3381



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.096956
Longitude: -106.595302
Direction: B to A, NB

#4
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	2	0	4	3	0	0	0	0	0	0	9
1:00	0	0	0	0	1	2	1	0	0	0	0	0	0	4
2:00	0	0	0	1	3	1	1	0	0	0	0	0	0	6
3:00	0	0	0	1	2	1	0	0	0	0	0	0	0	4
4:00	0	0	0	1	1	4	1	0	1	0	0	0	0	8
5:00	0	0	0	3	9	7	1	1	1	0	0	0	0	22
6:00	0	0	2	10	23	18	6	2	0	0	0	0	0	61
7:00	0	0	4	21	77	57	16	4	1	0	0	0	0	180
8:00	1	1	3	18	84	53	16	2	0	0	0	0	0	178
9:00	0	3	2	27	101	62	12	0	1	0	0	0	0	208
10:00	0	0	3	29	69	59	21	2	1	0	0	0	0	184
11:00	1	4	8	21	90	75	20	3	0	0	0	0	0	222
12:00 PM	0	1	3	33	104	62	9	5	0	0	0	0	0	217
1:00	0	1	5	27	125	74	17	2	0	1	0	0	0	252
2:00	1	3	7	42	126	83	16	8	1	0	1	0	0	288
3:00	2	0	9	27	153	108	35	2	0	0	0	0	0	336
4:00	7	1	3	28	146	109	27	5	0	0	0	0	0	326
5:00	3	0	5	50	138	78	15	5	0	0	0	0	0	294
6:00	1	3	3	41	84	54	7	1	0	0	0	0	0	194
7:00	0	0	3	19	47	23	7	0	0	0	0	0	0	99
8:00	0	0	2	15	32	23	6	0	0	0	0	0	0	78
9:00	0	0	2	9	24	15	3	0	0	0	0	0	0	53
10:00	0	0	1	1	14	9	2	0	0	0	0	0	0	27
11:00	0	0	2	6	8	4	2	0	0	0	0	0	0	22
Total	16	17	67	432	1461	985	244	42	6	1	1	0	0	3272
Grand Total	23	42	148	932	3056	1902	459	68	15	5	2	0	1	6653

Stats	Percentile	15th	50th	85th	95th
Speed		30	34	38	41
Mean Speed (Average)		33.8			
10 MPH Pace Speed		30-39			
Number in Pace		4939			
Percent in Pace		74.2%			
Number > 30 MPH		5508			
Percent > 30 MPH		82.8%			



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

#4

Station ID:
Location 1:
Location 2:
Latitude: 35.096956
Longitude: -106.595302

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No



Keyboard shortcuts | Map Data | Terms of Use | Report a map error



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator

Location

Washington St Counter #4


Analysis Dates

Start: 9/15/2022

End: 9/15/2022


Total Percentage of Enforceable Violations

Posted Speed Limit 30 MPH
Enforcement Tolerance 5 MPH
Enforcement Limit Greater than 35 MPH



Percent Speeding: 25%

Rating: Medium Low



Percent Speeding: 10%

Rating: Medium Low



Percent Speeding: 39%

Rating: Medium

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
33	62	226	1555	2813	1240	287	47	7	1	1	0	1

85th Percentile: 36.7

Vehicle Totals - A to B, SB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
17	45	159	1123	1352	255	43	5	1	0	0	0	1

85th Percentile: 34

Vehicle Totals - B to A, NB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
16	17	67	432	1461	985	244	42	6	1	1	0	0

85th Percentile: 38.3



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter #5

Date Printed: 9/19/2022

Start Date: 9/14/2022

End Date: 9/15/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.092514
Longitude: -106.595227

9/12/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB
12:00 AM	*	*	*	*	12	7	8	7	*	*	*	*	*	*	10	7
1:00	*	*	*	*	8	4	4	4	*	*	*	*	*	*	6	4
2:00	*	*	*	*	3	2	6	0	*	*	*	*	*	*	4	1
3:00	*	*	*	*	6	1	4	4	*	*	*	*	*	*	5	2
4:00	*	*	*	*	14	4	10	6	*	*	*	*	*	*	12	5
5:00	*	*	*	*	27	15	25	19	*	*	*	*	*	*	26	17
6:00	*	*	*	*	61	51	56	41	*	*	*	*	*	*	58	46
7:00	*	*	*	*	165	160	144	141	*	*	*	*	*	*	154	150
8:00	*	*	*	*	188	199	184	195	*	*	*	*	*	*	186	197
9:00	*	*	*	*	186	192	204	131	*	*	*	*	*	*	195	162
10:00	*	*	*	*	175	192	177	187	*	*	*	*	*	*	176	190
11:00	*	*	*	*	221	195	213	204	*	*	*	*	*	*	217	200
12:00 PM	*	*	*	*	218	210	205	226	*	*	*	*	*	*	212	218
1:00	*	*	*	*	242	191	242	161	*	*	*	*	*	*	242	176
2:00	*	*	*	*	205	230	246	232	*	*	*	*	*	*	226	231
3:00	*	*	*	*	298	286	316	284	*	*	*	*	*	*	307	285
4:00	*	*	*	*	355	275	301	282	*	*	*	*	*	*	328	278
5:00	*	*	*	*	328	311	277	283	*	*	*	*	*	*	302	297
6:00	*	*	*	*	199	226	205	222	*	*	*	*	*	*	202	224
7:00	*	*	*	*	131	200	135	131	*	*	*	*	*	*	133	166
8:00	*	*	*	*	82	107	85	100	*	*	*	*	*	*	84	104
9:00	*	*	*	*	48	57	57	61	*	*	*	*	*	*	52	59
10:00	*	*	*	*	25	31	34	33	*	*	*	*	*	*	30	32
11:00	*	*	*	*	20	18	31	22	*	*	*	*	*	*	26	20
Total	0	0	0	0	3217	3164	3169	2976	0	0	0	0	0	0	3193	3071
Day	0		0		6381		6145		0		0		0		6264	
AM Peak					11:00	8:00	11:00	11:00							11:00	11:00
Volume					221	199	213	204							217	200
PM Peak					4:00	5:00	3:00	3:00							4:00	5:00
Volume					355	311	316	284							328	297
Comb Total	0		0		6381		6145		0		0		0		6264	
ADT	ADT: 6,263		AADT: 6,263													



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.092514
Longitude: -106.595227

File Name: Washington St Counter #5
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

#5

Station ID:
Location 1:
Location 2:
Latitude: 35.092514
Longitude: -106.595227
Direction: A to B, NB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	3	2	6	1	0	0	0	0	0	0	0	12
1:00	0	0	1	2	4	1	0	0	0	0	0	0	0	8
2:00	0	0	0	1	1	1	0	0	0	0	0	0	0	3
3:00	0	0	0	1	1	1	2	1	0	0	0	0	0	6
4:00	0	0	0	2	7	4	1	0	0	0	0	0	0	14
5:00	1	2	1	3	15	5	0	0	0	0	0	0	0	27
6:00	0	1	1	12	28	15	4	0	0	0	0	0	0	61
7:00	0	1	1	27	102	32	2	0	0	0	0	0	0	165
8:00	2	0	7	45	99	31	3	1	0	0	0	0	0	188
9:00	4	0	5	43	103	28	2	1	0	0	0	0	0	186
10:00	3	1	6	51	92	16	5	1	0	0	0	0	0	175
11:00	1	0	5	53	112	41	6	3	0	0	0	0	0	221
12:00 PM	2	3	4	54	93	51	10	1	0	0	0	0	0	218
1:00	0	1	7	72	126	30	6	0	0	0	0	0	0	242
2:00	0	2	1	36	114	46	5	1	0	0	0	0	0	205
3:00	3	3	12	102	133	36	8	0	1	0	0	0	0	298
4:00	3	3	25	143	146	29	6	0	0	0	0	0	0	355
5:00	4	0	6	106	165	41	4	1	1	0	0	0	0	328
6:00	3	4	2	54	101	31	4	0	0	0	0	0	0	199
7:00	3	3	9	42	54	19	1	0	0	0	0	0	0	131
8:00	0	0	11	36	27	6	2	0	0	0	0	0	0	82
9:00	3	1	3	11	19	7	4	0	0	0	0	0	0	48
10:00	0	0	2	9	8	6	0	0	0	0	0	0	0	25
11:00	0	0	0	5	9	3	2	1	0	0	0	0	0	20
Total	32	25	112	912	1565	481	77	11	2	0	0	0	0	3217



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.092514
Longitude: -106.595227
Direction: A to B, NB

#5
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	1	0	5	1	0	0	1	0	0	0	0	8
1:00	0	0	0	1	2	1	0	0	0	0	0	0	0	4
2:00	0	0	1	0	5	0	0	0	0	0	0	0	0	6
3:00	0	0	0	1	1	1	1	0	0	0	0	0	0	4
4:00	0	0	0	1	4	5	0	0	0	0	0	0	0	10
5:00	1	2	4	5	8	5	0	0	0	0	0	0	0	25
6:00	0	1	2	12	20	18	2	1	0	0	0	0	0	56
7:00	0	0	2	42	68	30	2	0	0	0	0	0	0	144
8:00	1	2	3	42	98	35	3	0	0	0	0	0	0	184
9:00	1	5	11	49	93	38	7	0	0	0	0	0	0	204
10:00	0	2	1	31	89	46	8	0	0	0	0	0	0	177
11:00	2	2	7	34	115	44	7	2	0	0	0	0	0	213
12:00 PM	0	3	6	37	110	42	6	1	0	0	0	0	0	205
1:00	1	1	7	66	115	47	5	0	0	0	0	0	0	242
2:00	0	0	3	45	121	67	8	1	0	1	0	0	0	246
3:00	0	2	2	68	167	64	11	1	0	1	0	0	0	316
4:00	2	0	3	53	152	81	8	2	0	0	0	0	0	301
5:00	4	2	3	54	159	46	7	0	0	1	0	1	0	277
6:00	2	1	9	67	101	22	3	0	0	0	0	0	0	205
7:00	3	8	6	38	58	18	3	0	1	0	0	0	0	135
8:00	1	1	6	22	40	10	4	1	0	0	0	0	0	85
9:00	0	1	1	16	26	12	1	0	0	0	0	0	0	57
10:00	0	2	1	5	17	6	3	0	0	0	0	0	0	34
11:00	1	1	2	6	16	5	0	0	0	0	0	0	0	31
Total	19	36	81	695	1590	644	89	9	2	3	0	1	0	3169
Grand Total	51	61	193	1607	3155	1125	166	20	4	3	0	1	0	6386

Stats	Percentile	15th	50th	85th	95th
Speed	28	32	36	39	
Mean Speed (Average)	31.9				
10 MPH Pace Speed	25-34				
Number in Pace	4703				
Percent in Pace	73.6%				
Number > 30 MPH	4474				
Percent > 30 MPH	70.1%				



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

#5

Station ID:
Location 1:
Location 2:
Latitude: 35.092514
Longitude: -106.595227
Direction: B to A, SB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	1	2	2	2	0	0	0	0	0	0	0	7
1:00	0	0	0	3	1	0	0	0	0	0	0	0	0	4
2:00	0	0	0	0	0	2	0	0	0	0	0	0	0	2
3:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
4:00	0	0	0	1	0	3	0	0	0	0	0	0	0	4
5:00	0	0	1	4	4	5	1	0	0	0	0	0	0	15
6:00	1	0	2	8	29	8	3	0	0	0	0	0	0	51
7:00	2	0	4	45	59	44	5	1	0	0	0	0	0	160
8:00	6	0	2	47	108	29	7	0	0	0	0	0	0	199
9:00	3	0	1	41	98	41	8	0	0	0	0	0	0	192
10:00	7	0	7	39	98	32	8	1	0	0	0	0	0	192
11:00	1	1	3	46	105	36	3	0	0	0	0	0	0	195
12:00 PM	2	5	2	42	95	56	4	3	0	1	0	0	0	210
1:00	5	1	5	38	81	55	4	1	0	1	0	0	0	191
2:00	0	1	6	35	122	56	10	0	0	0	0	0	0	230
3:00	6	3	10	50	135	71	7	4	0	0	0	0	0	286
4:00	4	0	2	66	139	53	10	1	0	0	0	0	0	275
5:00	4	1	5	43	187	65	5	0	0	0	0	0	1	311
6:00	4	4	1	46	107	55	7	2	0	0	0	0	0	226
7:00	0	3	2	71	96	24	3	1	0	0	0	0	0	200
8:00	1	0	4	29	59	12	2	0	0	0	0	0	0	107
9:00	1	1	2	10	29	6	5	2	1	0	0	0	0	57
10:00	1	0	0	9	13	6	1	1	0	0	0	0	0	31
11:00	0	1	1	3	7	2	3	1	0	0	0	0	0	18
Total	48	21	62	678	1574	663	96	18	1	2	0	0	1	3164



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.092514
Longitude: -106.595227
Direction: B to A, SB

#5
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	1	3	3	0	0	0	0	0	0	0	7
1:00	0	0	0	0	1	3	0	0	0	0	0	0	0	4
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	3	1	0	0	0	0	0	0	0	4
4:00	0	0	0	0	3	1	1	1	0	0	0	0	0	6
5:00	0	0	1	5	4	8	1	0	0	0	0	0	0	19
6:00	0	0	0	11	20	8	1	1	0	0	0	0	0	41
7:00	0	0	1	22	66	40	10	2	0	0	0	0	0	141
8:00	3	4	1	25	98	53	11	0	0	0	0	0	0	195
9:00	3	2	2	18	62	35	7	2	0	0	0	0	0	131
10:00	0	2	2	15	105	49	13	1	0	0	0	0	0	187
11:00	0	1	1	34	100	59	8	1	0	0	0	0	0	204
12:00 PM	3	2	2	40	116	52	10	1	0	0	0	0	0	226
1:00	0	3	1	21	83	44	7	1	1	0	0	0	0	161
2:00	0	2	1	34	123	65	7	0	0	0	0	0	0	232
3:00	2	0	2	17	143	103	17	0	0	0	0	0	0	284
4:00	7	1	3	22	148	90	11	0	0	0	0	0	0	282
5:00	6	2	2	41	152	66	11	2	1	0	0	0	0	283
6:00	1	5	3	36	132	40	5	0	0	0	0	0	0	222
7:00	2	1	2	37	65	18	6	0	0	0	0	0	0	131
8:00	0	1	5	17	56	19	1	1	0	0	0	0	0	100
9:00	2	1	1	13	30	8	2	3	0	0	1	0	0	61
10:00	0	0	4	7	13	7	2	0	0	0	0	0	0	33
11:00	0	0	0	5	9	7	0	1	0	0	0	0	0	22
Total	29	27	34	421	1535	779	131	17	2	0	1	0	0	2976
Grand Total	77	48	96	1099	3109	1442	227	35	3	2	1	0	1	6140

Stats	Percentile	15th	50th	85th	95th
Speed		29	33	37	40
Mean Speed (Average)		32.7			
10 MPH Pace Speed		30-39			
Number in Pace		4544			
Percent in Pace		74.0%			
Number > 30 MPH		4820			
Percent > 30 MPH		78.5%			



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

#5

Station ID:
Location 1:
Location 2:
Latitude: 35.092514
Longitude: -106.595227

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter #6

Date Printed: 9/19/2022

Start Date: 9/14/2022

End Date: 9/15/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.089591
Longitude: -106.595249

9/12/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB
12:00 AM	*	*	*	*	7	12	7	9	*	*	*	*	*	*	7	10
1:00	*	*	*	*	6	8	4	4	*	*	*	*	*	*	5	6
2:00	*	*	*	*	2	2	0	6	*	*	*	*	*	*	1	4
3:00	*	*	*	*	1	6	4	4	*	*	*	*	*	*	2	5
4:00	*	*	*	*	4	13	6	9	*	*	*	*	*	*	5	11
5:00	*	*	*	*	16	25	20	22	*	*	*	*	*	*	18	24
6:00	*	*	*	*	56	56	49	52	*	*	*	*	*	*	52	54
7:00	*	*	*	*	165	166	154	145	*	*	*	*	*	*	160	156
8:00	*	*	*	*	217	188	209	184	*	*	*	*	*	*	213	186
9:00	*	*	*	*	201	184	139	217	*	*	*	*	*	*	170	200
10:00	*	*	*	*	190	170	192	194	*	*	*	*	*	*	191	182
11:00	*	*	*	*	198	214	211	208	*	*	*	*	*	*	204	211
12:00 PM	*	*	*	*	205	208	225	208	*	*	*	*	*	*	215	208
1:00	*	*	*	*	194	246	164	236	*	*	*	*	*	*	179	241
2:00	*	*	*	*	239	212	231	252	*	*	*	*	*	*	235	232
3:00	*	*	*	*	288	289	279	300	*	*	*	*	*	*	284	294
4:00	*	*	*	*	279	350	282	311	*	*	*	*	*	*	280	330
5:00	*	*	*	*	313	319	297	287	*	*	*	*	*	*	305	303
6:00	*	*	*	*	231	192	220	197	*	*	*	*	*	*	226	194
7:00	*	*	*	*	198	135	138	137	*	*	*	*	*	*	168	136
8:00	*	*	*	*	106	89	100	86	*	*	*	*	*	*	103	88
9:00	*	*	*	*	61	45	57	58	*	*	*	*	*	*	59	52
10:00	*	*	*	*	28	24	31	37	*	*	*	*	*	*	30	30
11:00	*	*	*	*	20	22	21	31	*	*	*	*	*	*	20	26
Total	0	0	0	0	3225	3175	3040	3194	0	0	0	0	0	0	3132	3183
Day	0		0		6400		6234		0		0		0		6315	
AM Peak					8:00	11:00	11:00	9:00							8:00	11:00
Volume					217	214	211	217							213	211
PM Peak					5:00	4:00	5:00	4:00							5:00	4:00
Volume					313	350	297	311							305	330
Comb Total	0		0		6400		6234		0		0		0		6315	
ADT	ADT: 6,317		AADT: 6,317													



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.089591
Longitude: -106.595249

File Name: Washington St Counter #6
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

#6

Station ID:
Location 1:
Location 2:
Latitude: 35.089591
Longitude: -106.595249
Direction: A to B, SB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	1	3	1	2	0	0	0	0	0	0	0	0	7
1:00	1	0	1	2	2	0	0	0	0	0	0	0	0	6
2:00	0	0	0	0	2	0	0	0	0	0	0	0	0	2
3:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
4:00	0	0	0	1	2	1	0	0	0	0	0	0	0	4
5:00	0	0	3	8	4	1	0	0	0	0	0	0	0	16
6:00	0	0	8	24	20	1	1	2	0	0	0	0	0	56
7:00	1	2	18	81	49	12	2	0	0	0	0	0	0	165
8:00	0	2	17	106	73	18	0	1	0	0	0	0	0	217
9:00	0	1	21	92	75	11	1	0	0	0	0	0	0	201
10:00	1	2	22	80	70	12	2	1	0	0	0	0	0	190
11:00	0	1	20	121	53	3	0	0	0	0	0	0	0	198
12:00 PM	1	5	17	113	57	11	1	0	0	0	0	0	0	205
1:00	0	1	26	98	60	9	0	0	0	0	0	0	0	194
2:00	0	1	23	129	71	14	1	0	0	0	0	0	0	239
3:00	3	2	38	145	85	12	1	2	0	0	0	0	0	288
4:00	1	5	39	138	82	11	2	1	0	0	0	0	0	279
5:00	0	3	43	160	93	13	1	0	0	0	0	0	0	313
6:00	5	1	26	119	66	11	3	0	0	0	0	0	0	231
7:00	0	8	44	107	38	1	0	0	0	0	0	0	0	198
8:00	0	0	24	59	21	2	0	0	0	0	0	0	0	106
9:00	0	0	10	30	14	4	2	1	0	0	0	0	0	61
10:00	0	0	8	11	7	1	1	0	0	0	0	0	0	28
11:00	0	0	4	3	6	5	2	0	0	0	0	0	0	20
Total	13	36	415	1628	952	153	20	8	0	0	0	0	0	3225



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.089591
Longitude: -106.595249
Direction: A to B, SB

#6
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	1	1	5	0	0	0	0	0	0	0	0	7
1:00	0	0	0	0	4	0	0	0	0	0	0	0	0	4
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	2	1	1	0	0	0	0	0	0	0	4
4:00	0	0	0	2	3	0	1	0	0	0	0	0	0	6
5:00	0	2	3	5	8	2	0	0	0	0	0	0	0	20
6:00	0	1	6	22	18	2	0	0	0	0	0	0	0	49
7:00	1	2	15	71	53	12	0	0	0	0	0	0	0	154
8:00	0	4	17	84	89	12	3	0	0	0	0	0	0	209
9:00	0	0	9	62	48	16	4	0	0	0	0	0	0	139
10:00	0	3	10	71	88	19	0	1	0	0	0	0	0	192
11:00	1	1	16	99	80	13	1	0	0	0	0	0	0	211
12:00 PM	0	1	22	118	75	8	1	0	0	0	0	0	0	225
1:00	1	0	13	93	45	10	1	0	1	0	0	0	0	164
2:00	3	1	31	102	85	8	1	0	0	0	0	0	0	231
3:00	2	0	21	127	108	20	1	0	0	0	0	0	0	279
4:00	0	0	25	123	116	17	1	0	0	0	0	0	0	282
5:00	3	4	32	130	114	11	2	0	0	1	0	0	0	297
6:00	1	3	24	119	66	6	1	0	0	0	0	0	0	220
7:00	1	3	22	71	37	4	0	0	0	0	0	0	0	138
8:00	0	1	12	51	32	3	0	1	0	0	0	0	0	100
9:00	0	0	12	31	9	3	2	0	0	0	0	0	0	57
10:00	0	0	7	12	10	2	0	0	0	0	0	0	0	31
11:00	0	0	5	5	9	2	0	0	0	0	0	0	0	21
Total	13	26	303	1401	1103	171	19	2	1	1	0	0	0	3040
Grand Total	26	62	718	3029	2055	324	39	10	1	1	0	0	0	6265

Stats	Percentile	15th	50th	85th	95th
Speed	25	29	33	35	
Mean Speed (Average)	29.1				
10 MPH Pace Speed	25-34				
Number in Pace	5057				
Percent in Pace	80.7%				
Number > 30 MPH	2430				
Percent > 30 MPH	38.8%				



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

#6

Station ID:
Location 1:
Location 2:
Latitude: 35.089591
Longitude: -106.595249
Direction: B to A, NB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	5	6	1	0	0	0	0	0	0	0	12
1:00	1	0	1	3	2	0	1	0	0	0	0	0	0	8
2:00	0	0	0	1	0	1	0	0	0	0	0	0	0	2
3:00	0	0	0	1	2	0	2	1	0	0	0	0	0	6
4:00	0	0	1	2	7	3	0	0	0	0	0	0	0	13
5:00	0	1	2	7	8	7	0	0	0	0	0	0	0	25
6:00	0	0	0	11	30	12	3	0	0	0	0	0	0	56
7:00	0	0	6	40	96	23	0	0	0	0	1	0	0	166
8:00	3	1	14	65	88	15	2	0	0	0	0	0	0	188
9:00	1	1	14	64	84	19	1	0	0	0	0	0	0	184
10:00	0	1	11	65	71	20	2	0	0	0	0	0	0	170
11:00	1	2	11	63	103	28	5	1	0	0	0	0	0	214
12:00 PM	2	2	8	66	85	38	6	1	0	0	0	0	0	208
1:00	1	4	11	79	113	36	2	0	0	0	0	0	0	246
2:00	0	0	2	41	134	30	5	0	0	0	0	0	0	212
3:00	3	0	12	124	120	27	3	0	0	0	0	0	0	289
4:00	1	2	27	144	133	40	2	1	0	0	0	0	0	350
5:00	0	0	16	136	137	25	4	1	0	0	0	0	0	319
6:00	1	1	12	69	92	15	2	0	0	0	0	0	0	192
7:00	0	1	17	51	57	7	1	0	1	0	0	0	0	135
8:00	1	2	22	41	15	5	3	0	0	0	0	0	0	89
9:00	0	0	5	18	14	6	2	0	0	0	0	0	0	45
10:00	0	0	5	8	8	2	1	0	0	0	0	0	0	24
11:00	0	0	0	8	9	5	0	0	0	0	0	0	0	22
Total	15	18	197	1112	1414	365	47	5	1	0	1	0	0	3175



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.089591
Longitude: -106.595249
Direction: B to A, NB

#6
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	2	4	2	0	0	0	1	0	0	0	9
1:00	0	0	0	1	3	0	0	0	0	0	0	0	0	4
2:00	0	0	1	1	3	1	0	0	0	0	0	0	0	6
3:00	0	0	0	0	3	1	0	0	0	0	0	0	0	4
4:00	0	1	0	2	3	3	0	0	0	0	0	0	0	9
5:00	0	0	2	7	9	4	0	0	0	0	0	0	0	22
6:00	0	0	3	13	21	12	3	0	0	0	0	0	0	52
7:00	0	1	11	35	68	27	1	2	0	0	0	0	0	145
8:00	1	1	13	62	86	19	2	0	0	0	0	0	0	184
9:00	0	3	21	51	114	26	2	0	0	0	0	0	0	217
10:00	0	0	9	53	97	26	9	0	0	0	0	0	0	194
11:00	0	0	10	57	105	28	6	2	0	0	0	0	0	208
12:00 PM	2	3	18	39	109	32	4	1	0	0	0	0	0	208
1:00	1	0	13	75	116	30	1	0	0	0	0	0	0	236
2:00	1	0	12	44	137	48	7	3	0	0	0	0	0	252
3:00	2	7	20	58	141	64	8	0	0	0	0	0	0	300
4:00	0	0	16	73	155	61	6	0	0	0	0	0	0	311
5:00	2	4	14	83	137	41	6	0	0	0	0	0	0	287
6:00	4	0	14	61	96	22	0	0	0	0	0	0	0	197
7:00	1	1	17	46	54	16	1	0	0	1	0	0	0	137
8:00	0	0	6	32	34	11	3	0	0	0	0	0	0	86
9:00	0	2	2	19	28	7	0	0	0	0	0	0	0	58
10:00	0	0	5	10	14	8	0	0	0	0	0	0	0	37
11:00	0	0	3	10	17	1	0	0	0	0	0	0	0	31
Total	14	23	210	834	1554	490	59	8	0	2	0	0	0	3194
Grand Total	29	41	407	1946	2968	855	106	13	1	2	1	0	0	6369

Stats	Percentile	15th	50th	85th	95th
Speed		27	31	35	38
Mean Speed (Average)		31.1			
10 MPH Pace Speed		25-34			
Number in Pace		4863			
Percent in Pace		76.4%			
Number > 30 MPH		3946			
Percent > 30 MPH		62.0%			



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Washington St Counter
#6

Station ID:
Location 1:
Location 2:
Latitude: 35.089591
Longitude: -106.595249

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator

Location

Washington St Counter #6

Analysis Dates

Start: 9/15/2022


End: 9/15/2022

Total Percentage of Enforceable Violations

Posted Speed Limit	30 MPH
--------------------	--------


Enforcement Tolerance 7 MPH

Enforcement Limit	Greater than 37 MPH
-------------------	---------------------



Percent Speeding: 6%

Rating: Low



Percent Speeding: 3%

Rating: Low

Percent Speeding: 8%

Rating: Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
27	49	513	2235	2657	661	78	10	1	3	0	0	0
85th Percentile: 34.3												

Vehicle Totals - A to B, SB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
13	26	303	1401	1103	171	19	2	1	1	0	0	0
85th Percentile: 32.9												

Vehicle Totals - B to A, NB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
14	23	210	834	1554	490	59	8	0	2	0	0	0
85th Percentile: 35.3												



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Constitution Ave Counter #7

Date Printed: 9/19/2022

Start Date: 9/14/2022

End Date: 9/15/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.094728
Longitude: -106.599191

9/12/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB
12:00 AM	*	*	*	*	2	12	10	9	*	*	*	*	*	*	6	10
1:00	*	*	*	*	4	1	5	2	*	*	*	*	*	*	4	2
2:00	*	*	*	*	4	3	5	3	*	*	*	*	*	*	4	3
3:00	*	*	*	*	6	1	6	4	*	*	*	*	*	*	6	2
4:00	*	*	*	*	6	4	5	2	*	*	*	*	*	*	6	3
5:00	*	*	*	*	17	15	8	15	*	*	*	*	*	*	12	15
6:00	*	*	*	*	54	34	57	36	*	*	*	*	*	*	56	35
7:00	*	*	*	*	160	114	159	115	*	*	*	*	*	*	160	114
8:00	*	*	*	*	175	139	193	136	*	*	*	*	*	*	184	138
9:00	*	*	*	*	124	154	123	133	*	*	*	*	*	*	124	144
10:00	*	*	*	*	143	163	150	150	*	*	*	*	*	*	146	156
11:00	*	*	*	*	163	164	164	158	*	*	*	*	*	*	164	161
12:00 PM	*	*	*	*	189	184	168	180	*	*	*	*	*	*	178	182
1:00	*	*	*	*	173	193	199	158	*	*	*	*	*	*	186	176
2:00	*	*	*	*	174	176	163	196	*	*	*	*	*	*	168	186
3:00	*	*	*	*	229	259	224	264	*	*	*	*	*	*	226	262
4:00	*	*	*	*	234	280	226	267	*	*	*	*	*	*	230	274
5:00	*	*	*	*	215	281	228	283	*	*	*	*	*	*	222	282
6:00	*	*	*	*	160	248	146	188	*	*	*	*	*	*	153	218
7:00	*	*	*	*	130	233	117	145	*	*	*	*	*	*	124	189
8:00	*	*	*	*	66	85	77	85	*	*	*	*	*	*	72	85
9:00	*	*	*	*	50	63	58	66	*	*	*	*	*	*	54	64
10:00	*	*	*	*	19	30	22	26	*	*	*	*	*	*	20	28
11:00	*	*	*	*	14	16	14	16	*	*	*	*	*	*	14	16
Total	0	0	0	0	2511	2852	2527	2637	0	0	0	0	0	0	2519	2745
Day	0		0		5363		5164		0		0		0		5264	
AM Peak					8:00	11:00	8:00	11:00							8:00	11:00
Volume					175	164	193	158							184	161
PM Peak					4:00	5:00	5:00	5:00							4:00	5:00
Volume					234	281	228	283							230	282
Comb Total	0		0		5363		5164		0		0		0		5264	
ADT	ADT: 5,264		AADT: 5,264													



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.094728
Longitude: -106.599191

File Name: Constitution Ave Counter #7
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Constitution Ave Counter
#7

Station ID:
Location 1:
Location 2:
Latitude: 35.094728
Longitude: -106.599191
Direction: A to B, WB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	1	0	0	1	0	0	0	0	0	0	0	2
1:00	1	0	0	0	1	0	0	1	1	0	0	0	0	4
2:00	0	0	0	1	0	2	0	1	0	0	0	0	0	4
3:00	0	0	1	0	0	3	1	0	1	0	0	0	0	6
4:00	0	0	0	1	0	1	1	2	0	0	1	0	0	6
5:00	0	0	0	0	6	4	4	2	1	0	0	0	0	17
6:00	0	1	0	3	12	18	14	6	0	0	0	0	0	54
7:00	0	0	8	12	24	56	44	10	6	0	0	0	0	160
8:00	2	1	6	10	16	66	55	14	5	0	0	0	0	175
9:00	1	2	4	7	11	44	38	15	2	0	0	0	0	124
10:00	0	0	5	12	20	50	39	14	2	0	0	0	1	143
11:00	0	2	2	10	19	64	49	13	2	2	0	0	0	163
12:00 PM	0	1	2	13	25	65	64	16	3	0	0	0	0	189
1:00	1	0	8	9	29	60	51	11	4	0	0	0	0	173
2:00	0	1	4	9	28	60	48	23	1	0	0	0	0	174
3:00	1	1	7	15	44	76	62	18	4	1	0	0	0	229
4:00	2	2	6	17	34	90	62	18	2	0	0	0	1	234
5:00	1	1	5	14	31	79	61	17	5	1	0	0	0	215
6:00	0	0	6	14	31	48	36	19	2	2	2	0	0	160
7:00	0	1	6	17	32	44	25	3	2	0	0	0	0	130
8:00	0	0	6	8	19	24	7	1	0	0	1	0	0	66
9:00	0	0	0	5	8	24	5	6	2	0	0	0	0	50
10:00	0	1	0	2	4	7	2	0	2	1	0	0	0	19
11:00	0	0	1	0	2	7	3	0	1	0	0	0	0	14
Total	9	14	78	179	396	893	671	210	48	7	4	0	2	2511



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Constitution Ave Counter

#7

Station ID:
Location 1:
Location 2:
Latitude: 35.094728
Longitude: -106.599191
Direction: A to B, WB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	1	0	0	3	1	4	1	0	0	0	0	0	10
1:00	0	0	0	2	1	1	1	0	0	0	0	0	0	5
2:00	0	0	1	1	0	3	0	0	0	0	0	0	0	5
3:00	0	1	0	0	0	1	3	1	0	0	0	0	0	6
4:00	0	0	0	0	0	4	1	0	0	0	0	0	0	5
5:00	0	0	2	0	1	2	1	1	1	0	0	0	0	8
6:00	0	1	4	0	8	17	18	6	2	1	0	0	0	57
7:00	0	0	6	11	22	56	47	14	3	0	0	0	0	159
8:00	0	0	9	10	28	68	59	18	1	0	0	0	0	193
9:00	0	0	3	9	18	43	38	11	0	1	0	0	0	123
10:00	0	1	2	10	30	55	36	11	4	1	0	0	0	150
11:00	0	0	5	9	21	69	44	13	3	0	0	0	0	164
12:00 PM	0	1	4	13	31	53	50	13	3	0	0	0	0	168
1:00	0	1	3	15	41	67	56	12	3	1	0	0	0	199
2:00	1	0	3	12	24	56	50	16	1	0	0	0	0	163
3:00	0	0	10	12	36	86	55	18	6	1	0	0	0	224
4:00	2	0	9	11	32	72	68	23	6	2	0	0	1	226
5:00	1	1	6	15	38	85	62	15	4	1	0	0	0	228
6:00	0	1	5	5	23	51	44	11	6	0	0	0	0	146
7:00	0	0	5	10	30	46	21	3	1	1	0	0	0	117
8:00	1	0	2	12	18	27	10	4	2	1	0	0	0	77
9:00	0	0	3	2	22	17	10	2	2	0	0	0	0	58
10:00	0	0	1	0	6	8	4	3	0	0	0	0	0	22
11:00	0	0	1	0	4	5	3	1	0	0	0	0	0	14
Total	5	8	84	159	437	893	685	197	48	10	0	0	1	2527
Grand Total	14	22	162	338	833	1786	1356	407	96	17	4	0	3	5038

Stats	Percentile	15th	50th	85th	95th
Speed	32	38	44	48	
Mean Speed (Average)	38.0				
10 MPH Pace Speed	35-44				
Number in Pace	3132				
Percent in Pace	62.2%				
Number > 30 MPH	4502				
Percent > 30 MPH	89.4%				



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Constitution Ave Counter
#7

Station ID:
Location 1:
Location 2:
Latitude: 35.094728
Longitude: -106.599191
Direction: B to A, EB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	3	2	3	2	1	1	0	0	0	0	0	12
1:00	0	0	0	0	0	1	0	0	0	0	0	0	0	1
2:00	0	0	1	1	1	0	0	0	0	0	0	0	0	3
3:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
4:00	0	0	1	2	0	0	0	1	0	0	0	0	0	4
5:00	0	0	2	2	8	1	1	1	0	0	0	0	0	15
6:00	0	0	2	11	12	7	2	0	0	0	0	0	0	34
7:00	0	0	13	29	47	21	4	0	0	0	0	0	0	114
8:00	1	2	10	21	55	39	10	1	0	0	0	0	0	139
9:00	2	4	16	27	54	40	9	1	1	0	0	0	0	154
10:00	0	3	12	36	66	38	6	1	0	1	0	0	0	163
11:00	0	2	10	23	80	42	6	1	0	0	0	0	0	164
12:00 PM	1	6	12	39	74	39	11	1	0	1	0	0	0	184
1:00	2	1	10	26	89	47	17	0	1	0	0	0	0	193
2:00	0	2	20	29	74	45	4	2	0	0	0	0	0	176
3:00	3	1	18	49	110	67	9	1	1	0	0	0	0	259
4:00	1	1	19	55	129	63	11	1	0	0	0	0	0	280
5:00	1	6	12	68	118	68	7	1	0	0	0	0	0	281
6:00	1	3	15	47	86	69	21	5	1	0	0	0	0	248
7:00	0	0	7	56	104	49	15	1	0	0	0	0	1	233
8:00	1	1	10	25	28	17	2	0	1	0	0	0	0	85
9:00	0	2	8	15	18	14	6	0	0	0	0	0	0	63
10:00	0	0	3	8	12	6	0	0	1	0	0	0	0	30
11:00	0	0	1	4	5	3	0	1	1	1	0	0	0	16
Total	13	34	206	575	1173	678	142	20	7	3	0	0	1	2852



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Constitution Ave Counter

#7

Station ID:
Location 1:
Location 2:
Latitude: 35.094728
Longitude: -106.599191
Direction: B to A, EB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	1	0	2	5	1	0	0	0	0	0	0	0	9
1:00	0	0	0	0	1	1	0	0	0	0	0	0	0	2
2:00	0	0	1	1	0	0	1	0	0	0	0	0	0	3
3:00	0	0	0	2	0	1	0	1	0	0	0	0	0	4
4:00	0	0	0	0	0	1	1	0	0	0	0	0	0	2
5:00	0	0	2	7	3	1	2	0	0	0	0	0	0	15
6:00	0	0	2	12	14	6	2	0	0	0	0	0	0	36
7:00	0	2	15	15	50	28	4	1	0	0	0	0	0	115
8:00	0	0	10	19	56	38	9	4	0	0	0	0	0	136
9:00	3	4	16	24	41	38	5	1	1	0	0	0	0	133
10:00	0	2	14	18	68	40	6	1	1	0	0	0	0	150
11:00	1	2	11	19	61	49	12	3	0	0	0	0	0	158
12:00 PM	1	1	11	33	67	53	13	1	0	0	0	0	0	180
1:00	2	3	10	23	68	43	8	1	0	0	0	0	0	158
2:00	2	1	20	34	73	54	10	1	0	1	0	0	0	196
3:00	0	4	12	43	132	59	10	3	0	1	0	0	0	264
4:00	2	3	18	36	129	56	22	1	0	0	0	0	0	267
5:00	3	3	12	56	134	62	11	1	0	0	0	0	1	283
6:00	0	2	10	34	90	44	6	2	0	0	0	0	0	188
7:00	1	2	13	40	53	25	10	1	0	0	0	0	0	145
8:00	0	0	5	23	32	19	4	1	1	0	0	0	0	85
9:00	0	1	5	19	28	11	2	0	0	0	0	0	0	66
10:00	0	0	2	5	10	8	1	0	0	0	0	0	0	26
11:00	0	0	2	4	5	5	0	0	0	0	0	0	0	16
Total	15	31	191	469	1120	643	139	23	3	2	0	0	1	2637
Grand Total	28	65	397	1044	2293	1321	281	43	10	5	0	0	2	5489

Stats	Percentile	15th	50th	85th	95th
Speed	27	33	37	41	
Mean Speed (Average)	32.5				
10 MPH Pace Speed	30-39				
Number in Pace	3608				
Percent in Pace	65.7%				
Number > 30 MPH	3955				
Percent > 30 MPH	72.1%				



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Constitution Ave Counter
#7

Station ID:
Location 1:
Location 2:
Latitude: 35.094728
Longitude: -106.599191

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator

Location

Constitution Ave Counter #7


Analysis Dates

Start: 9/14/2022

End: 9/14/2022


Total Percentage of Enforceable Violations

Posted Speed Limit 30 MPH
Enforcement Tolerance 5 MPH
Enforcement Limit Greater than 35 MPH



Percent Speeding: 50%

Rating: Severe



Percent Speeding: 73%

Rating: Severe



Percent Speeding: 30%

Rating: Medium

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
22	48	284	754	1569	1571	813	230	55	10	4	0	3

85th Percentile: 41.3

Vehicle Totals - A to B, WB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
9	14	78	179	396	893	671	210	48	7	4	0	2

85th Percentile: 43.7

Vehicle Totals - B to A, EB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
13	34	206	575	1173	678	142	20	7	3	0	0	1

85th Percentile: 37.2



Speed Enforcement Evaluator

Constitution Ave Counter #7

Start: 9/15/2022

End: 9/15/2022

Posted Speed Limit	30 MPH
Enforcement Tolerance	5 MPH
Enforcement Limit	Greater than 35 MPH



Rating: Severe



Rating: Severe



Rating: Medium

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
20	39	275	628	1557	1536	824	220	51	12	0	0	2
85th Percentile: 41.4												

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
5	8	84	159	437	893	685	197	48	10	0	0	1
85th Percentile: 43.6												

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
15	31	191	469	1120	643	139	23	3	2	0	0	1
85th Percentile: 37.4												



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator

Location

Constitution Ave Counter #7

Analysis Dates

Start: 9/14/2022

End: 9/14/2022


Total Percentage of Enforceable Violations

Posted Speed Limit 30 MPH
Enforcement Tolerance 7 MPH
Enforcement Limit Greater than 37 MPH



Percent Speeding: 37%

Rating: Medium



Percent Speeding: 61%

Rating: Severe



Percent Speeding: 16%

Rating: Medium Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
22	48	284	754	1569	1571	813	230	55	10	4	0	3

85th Percentile: 41.3

Vehicle Totals - A to B, WB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
9	14	78	179	396	893	671	210	48	7	4	0	2

85th Percentile: 43.7

Vehicle Totals - B to A, EB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
13	34	206	575	1173	678	142	20	7	3	0	0	1

85th Percentile: 37.2

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
15	31	191	469	1120	643	139	23	3	2	0	0	1
85th Percentile: 37.4												



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Constitution Ave Counter #8

Date Printed: 9/19/2022

Start Date: 9/14/2022

End Date: 9/15/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.094799
Longitude: -106.600671

9/12/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB
12:00 AM	*	*	*	*	13	1	11	10	*	*	*	*	*	*	12	6
1:00	*	*	*	*	1	4	2	3	*	*	*	*	*	*	2	4
2:00	*	*	*	*	3	3	3	3	*	*	*	*	*	*	3	3
3:00	*	*	*	*	0	6	4	6	*	*	*	*	*	*	2	6
4:00	*	*	*	*	3	5	2	7	*	*	*	*	*	*	2	6
5:00	*	*	*	*	13	20	10	9	*	*	*	*	*	*	12	14
6:00	*	*	*	*	34	58	38	66	*	*	*	*	*	*	36	62
7:00	*	*	*	*	111	194	111	182	*	*	*	*	*	*	111	188
8:00	*	*	*	*	134	199	139	210	*	*	*	*	*	*	136	204
9:00	*	*	*	*	149	141	128	146	*	*	*	*	*	*	138	144
10:00	*	*	*	*	142	146	93	159	*	*	*	*	*	*	118	152
11:00	*	*	*	*	107	172	53	159	*	*	*	*	*	*	80	166
12:00 PM	*	*	*	*	87	177	42	157	*	*	*	*	*	*	64	167
1:00	*	*	*	*	67	169	21	193	*	*	*	*	*	*	44	181
2:00	*	*	*	*	57	170	42	165	*	*	*	*	*	*	50	168
3:00	*	*	*	*	145	213	80	203	*	*	*	*	*	*	112	208
4:00	*	*	*	*	292	222	119	220	*	*	*	*	*	*	206	221
5:00	*	*	*	*	302	237	236	230	*	*	*	*	*	*	269	234
6:00	*	*	*	*	257	167	191	148	*	*	*	*	*	*	224	158
7:00	*	*	*	*	243	119	163	121	*	*	*	*	*	*	203	120
8:00	*	*	*	*	96	69	90	71	*	*	*	*	*	*	93	70
9:00	*	*	*	*	67	53	68	56	*	*	*	*	*	*	68	54
10:00	*	*	*	*	33	19	31	22	*	*	*	*	*	*	32	20
11:00	*	*	*	*	17	14	17	15	*	*	*	*	*	*	17	14
Total	0	0	0	0	2373	2578	1694	2561	0	0	0	0	0	0	2034	2570
Day	0		0		4951		4255		0		0		0		4604	
AM Peak					9:00	8:00	8:00	8:00							9:00	8:00
Volume					149	199	139	210							138	204
PM Peak					5:00	5:00	5:00	5:00							5:00	5:00
Volume					302	237	236	230							269	234
Comb Total	0		0		4951		4255		0		0		0		4604	
ADT	ADT: 4,603		AADT: 4,603													




Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.094799
Longitude: -106.600671

File Name: Constitution Ave Counter #8
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Constitution Ave Counter

#8

Station ID:
Location 1:
Location 2:
Latitude: 35.094799
Longitude: -106.600671
Direction: A to B, EB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	1	3	5	0	3	0	1	0	0	0	0	13
1:00	0	0	0	0	0	1	0	0	0	0	0	0	0	1
2:00	0	0	0	2	0	1	0	0	0	0	0	0	0	3
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	1	1	0	1	0	0	0	0	0	0	3
5:00	0	0	0	0	7	3	1	1	1	0	0	0	0	13
6:00	0	0	0	4	14	9	7	0	0	0	0	0	0	34
7:00	1	0	1	24	40	32	12	1	0	0	0	0	0	111
8:00	1	0	1	19	47	45	18	3	0	0	0	0	0	134
9:00	0	1	1	24	66	45	10	1	1	0	0	0	0	149
10:00	1	0	5	25	72	30	8	0	1	0	0	0	0	142
11:00	2	0	1	21	59	22	1	1	0	0	0	0	0	107
12:00 PM	3	0	2	20	38	18	6	0	0	0	0	0	0	87
1:00	4	1	1	11	39	9	2	0	0	0	0	0	0	67
2:00	1	1	1	13	31	7	3	0	0	0	0	0	0	57
3:00	3	0	2	35	67	32	5	0	1	0	0	0	0	145
4:00	2	1	7	66	131	75	9	1	0	0	0	0	0	292
5:00	0	1	3	62	140	83	12	1	0	0	0	0	0	302
6:00	2	0	6	28	99	78	36	7	1	0	0	0	0	257
7:00	0	0	3	25	123	63	27	1	1	0	0	0	0	243
8:00	0	0	4	17	44	24	6	0	0	1	0	0	0	96
9:00	0	0	2	16	24	13	10	2	0	0	0	0	0	67
10:00	0	0	3	1	18	7	3	0	0	1	0	0	0	33
11:00	0	1	1	2	4	5	1	1	1	0	0	1	0	17
Total	20	6	45	419	1069	602	181	20	8	2	0	1	0	2373



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Constitution Ave Counter

#8

Station ID:
Location 1:
Location 2:
Latitude: 35.094799
Longitude: -106.600671
Direction: A to B, EB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	2	3	6	0	0	0	0	0	0	0	11
1:00	0	0	0	0	1	1	0	0	0	0	0	0	0	2
2:00	1	0	0	0	1	0	0	1	0	0	0	0	0	3
3:00	0	0	0	1	1	1	0	0	1	0	0	0	0	4
4:00	0	0	0	0	0	1	1	0	0	0	0	0	0	2
5:00	0	0	0	2	5	1	2	0	0	0	0	0	0	10
6:00	0	0	0	7	10	16	4	0	1	0	0	0	0	38
7:00	0	1	1	8	45	39	16	1	0	0	0	0	0	111
8:00	1	1	0	20	59	46	7	4	1	0	0	0	0	139
9:00	0	0	6	15	55	49	1	2	0	0	0	0	0	128
10:00	0	0	1	21	43	25	2	1	0	0	0	0	0	93
11:00	3	0	1	14	16	16	3	0	0	0	0	0	0	53
12:00 PM	0	0	1	14	22	5	0	0	0	0	0	0	0	42
1:00	2	0	0	5	6	8	0	0	0	0	0	0	0	21
2:00	0	0	1	15	15	10	1	0	0	0	0	0	0	42
3:00	5	0	2	19	38	16	0	0	0	0	0	0	0	80
4:00	3	0	0	21	52	33	10	0	0	0	0	0	0	119
5:00	1	2	2	61	115	49	6	0	0	0	0	0	0	236
6:00	0	1	3	38	95	42	10	2	0	0	0	0	0	191
7:00	0	0	4	50	72	27	9	1	0	0	0	0	0	163
8:00	0	0	2	16	36	26	7	2	0	0	1	0	0	90
9:00	0	0	0	16	26	19	5	2	0	0	0	0	0	68
10:00	0	0	1	7	12	8	2	0	1	0	0	0	0	31
11:00	0	0	1	4	4	6	2	0	0	0	0	0	0	17
Total	16	5	26	356	732	450	88	16	4	0	1	0	0	1694
Grand Total	36	11	71	775	1801	1052	269	36	12	2	1	1	0	4067

Stats	Percentile	15th	50th	85th	95th
Speed	29	33	38	41	
Mean Speed (Average)	33.3				
10 MPH Pace Speed	30-39				
Number in Pace	2847				
Percent in Pace	70.0%				
Number > 30 MPH	3174				
Percent > 30 MPH	78.0%				



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Constitution Ave Counter
#8

Station ID:
Location 1:
Location 2:
Latitude: 35.094799
Longitude: -106.600671
Direction: B to A, WB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/14/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	0	1	0	0	0	0	0	0	0	0	1
1:00	0	0	0	2	0	1	1	0	0	0	0	0	0	4
2:00	0	0	0	0	2	1	0	0	0	0	0	0	0	3
3:00	0	0	0	1	2	2	0	1	0	0	0	0	0	6
4:00	0	0	0	0	1	2	1	0	1	0	0	0	0	5
5:00	1	0	1	4	6	4	3	1	0	0	0	0	0	20
6:00	0	0	1	8	31	14	3	1	0	0	0	0	0	58
7:00	2	1	5	42	90	42	12	0	0	0	0	0	0	194
8:00	1	1	3	29	95	55	13	2	0	0	0	0	0	199
9:00	0	0	2	23	63	43	7	3	0	0	0	0	0	141
10:00	0	0	2	26	65	39	12	2	0	0	0	0	0	146
11:00	0	0	2	22	79	56	11	2	0	0	0	0	0	172
12:00 PM	0	0	0	16	81	68	9	3	0	0	0	0	0	177
1:00	0	1	1	20	74	62	10	1	0	0	0	0	0	169
2:00	0	0	0	19	68	67	14	2	0	0	0	0	0	170
3:00	0	0	3	19	104	74	7	6	0	0	0	0	0	213
4:00	0	1	4	19	93	87	18	0	0	0	0	0	0	222
5:00	0	0	3	33	106	75	18	2	0	0	0	0	0	237
6:00	0	1	5	32	68	47	11	3	0	0	0	0	0	167
7:00	0	0	6	17	67	24	5	0	0	0	0	0	0	119
8:00	0	0	3	21	30	12	2	1	0	0	0	0	0	69
9:00	0	0	1	6	25	14	7	0	0	0	0	0	0	53
10:00	0	0	1	3	8	4	1	2	0	0	0	0	0	19
11:00	0	0	1	2	6	4	0	1	0	0	0	0	0	14
Total	4	5	44	364	1165	797	165	33	1	0	0	0	0	2578



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Constitution Ave Counter

#8

Station ID:
Location 1:
Location 2:
Latitude: 35.094799
Longitude: -106.600671
Direction: B to A, WB

Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No

9/15/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	1	0	5	4	0	0	0	0	0	0	0	10
1:00	0	0	0	0	2	1	0	0	0	0	0	0	0	3
2:00	0	0	0	0	3	0	0	0	0	0	0	0	0	3
3:00	0	0	1	0	0	5	0	0	0	0	0	0	0	6
4:00	0	0	0	1	2	4	0	0	0	0	0	0	0	7
5:00	0	0	0	2	4	2	1	0	0	0	0	0	0	9
6:00	0	0	2	10	25	19	9	1	0	0	0	0	0	66
7:00	0	1	4	32	88	50	6	1	0	0	0	0	0	182
8:00	1	0	5	27	99	64	14	0	0	0	0	0	0	210
9:00	1	0	2	27	49	58	7	2	0	0	0	0	0	146
10:00	0	0	1	21	77	45	13	2	0	0	0	0	0	159
11:00	0	0	0	18	80	47	11	3	0	0	0	0	0	159
12:00 PM	0	0	3	20	66	53	15	0	0	0	0	0	0	157
1:00	0	0	1	38	79	60	14	1	0	0	0	0	0	193
2:00	0	0	1	22	79	52	10	1	0	0	0	0	0	165
3:00	0	1	2	23	98	63	13	2	1	0	0	0	0	203
4:00	0	0	2	21	85	83	24	5	0	0	0	0	0	220
5:00	0	0	3	27	105	81	12	2	0	0	0	0	0	230
6:00	0	0	1	10	71	47	17	2	0	0	0	0	0	148
7:00	0	0	2	20	64	31	3	0	1	0	0	0	0	121
8:00	0	0	2	11	37	16	3	1	1	0	0	0	0	71
9:00	0	0	1	11	31	10	2	1	0	0	0	0	0	56
10:00	0	0	2	3	9	7	1	0	0	0	0	0	0	22
11:00	0	0	0	3	5	6	1	0	0	0	0	0	0	15
Total	2	2	36	347	1163	808	176	24	3	0	0	0	0	2561
Grand Total	6	7	80	711	2328	1605	341	57	4	0	0	0	0	5139

Stats	Percentile	15th	50th	85th	95th
Speed	30	34	38	41	
Mean Speed (Average)	34.1				
10 MPH Pace Speed	30-39				
Number in Pace	3915				
Percent in Pace	76.2%				
Number > 30 MPH	4335				
Percent > 30 MPH	84.4%				



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.094799
Longitude: -106.600671

File Name: Constitution Ave Counter
#8
Date Printed: 9/19/2022
Start Date: 9/14/2022
End Date: 9/15/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator

Location

Constitution Ave Counter #8


Analysis Dates

Start: 9/15/2022

End: 9/15/2022

Total Percentage of Enforceable Violations

Posted Speed Limit 30 MPH
Enforcement Tolerance 5 MPH
Enforcement Limit Greater than 35 MPH



Percent Speeding: 37%

Rating: Medium



Percent Speeding: 33%

Rating: Medium



Percent Speeding: 39%

Rating: Medium

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
18	7	62	703	1895	1258	264	40	7	0	1	0	0

85th Percentile: 38

Vehicle Totals - A to B, EB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
16	5	26	356	732	450	88	16	4	0	1	0	0

85th Percentile: 37.7

Vehicle Totals - B to A, WB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
2	2	36	347	1163	808	176	24	3	0	0	0	0

85th Percentile: 38.2

Speed Enforcement Evaluator

Location

Constitution Ave Counter #8

Analysis Dates

Start: 9/14/2022


End: 9/14/2022

Total Percentage of Enforceable Violations

Posted Speed Limit	30 MPH
--------------------	--------


Enforcement Tolerance 7 MPH

Enforcement Limit	Greater than 37 MPH
-------------------	---------------------



Percent Speeding: 21%

Rating: Medium Low



Percent Speeding: 21%

Rating: Medium Low

Percent Speeding: 22%

Rating: Medium Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
24	11	89	783	2234	1399	346	53	9	2	0	1	0
85th Percentile: 38.1												

Vehicle Totals - A to B, EB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
20	6	45	419	1069	602	181	20	8	2	0	1	0
85th Percentile: 38.3												

Vehicle Totals - B to A, WB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
4	5	44	364	1165	797	165	33	1	0	0	0	0
85th Percentile: 38												



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Avenida Del Sol Counter #5

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.092603
Longitude: -106.599114

9/19/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB
12:00 AM	*	*	*	*	0	0	0	1	*	*	*	*	*	*	0	0
1:00	*	*	*	*	0	0	0	0	*	*	*	*	*	*	0	0
2:00	*	*	*	*	1	0	1	0	*	*	*	*	*	*	1	0
3:00	*	*	*	*	0	0	0	0	*	*	*	*	*	*	0	0
4:00	*	*	*	*	1	0	1	0	*	*	*	*	*	*	1	0
5:00	*	*	*	*	5	0	3	1	*	*	*	*	*	*	4	0
6:00	*	*	*	*	4	3	7	7	*	*	*	*	*	*	6	5
7:00	*	*	*	*	11	7	4	2	*	*	*	*	*	*	8	4
8:00	*	*	*	*	12	13	9	8	*	*	*	*	*	*	10	10
9:00	*	*	*	*	12	9	12	8	*	*	*	*	*	*	12	8
10:00	*	*	*	*	12	6	7	7	*	*	*	*	*	*	10	6
11:00	*	*	*	*	11	8	14	13	*	*	*	*	*	*	12	10
12:00 PM	*	*	*	*	10	11	6	8	*	*	*	*	*	*	8	10
1:00	*	*	*	*	7	7	12	3	*	*	*	*	*	*	10	5
2:00	*	*	*	*	12	10	11	13	*	*	*	*	*	*	12	12
3:00	*	*	*	*	8	10	14	13	*	*	*	*	*	*	11	12
4:00	*	*	*	*	16	11	13	8	*	*	*	*	*	*	14	10
5:00	*	*	*	*	9	15	9	14	*	*	*	*	*	*	9	14
6:00	*	*	*	*	8	8	11	7	*	*	*	*	*	*	10	8
7:00	*	*	*	*	4	7	4	5	*	*	*	*	*	*	4	6
8:00	*	*	*	*	4	3	5	6	*	*	*	*	*	*	4	4
9:00	*	*	*	*	1	1	4	4	*	*	*	*	*	*	2	2
10:00	*	*	*	*	0	1	0	1	*	*	*	*	*	*	0	1
11:00	*	*	*	*	0	0	0	0	*	*	*	*	*	*	0	0
Total	0	0	0	0	148	130	147	129	0	0	0	0	0	0	148	127
Day	0		0		278		276		0		0		0		275	
AM Peak					8:00	8:00	11:00	11:00							9:00	8:00
Volume					12	13	14	13							12	10
PM Peak					4:00	5:00	3:00	5:00							4:00	5:00
Volume					16	15	14	14							14	14
Comb Total	0		0		278		276		0		0		0		275	
ADT	ADT: 277		AADT: 277													



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.092603
Longitude: -106.599114

File Name: Avenida Del Sol Counter #5
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Avenida Del Sol Counter

#5

Station ID:
Location 1:
Location 2:
Latitude: 35.092603
Longitude: -106.599114
Direction: A to B, WB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	1	0	0	0	0	0	0	0	0	1
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
5:00	2	0	3	0	0	0	0	0	0	0	0	0	0	5
6:00	0	2	2	0	0	0	0	0	0	0	0	0	0	4
7:00	0	4	5	1	1	0	0	0	0	0	0	0	0	11
8:00	1	2	7	2	0	0	0	0	0	0	0	0	0	12
9:00	3	3	3	3	0	0	0	0	0	0	0	0	0	12
10:00	3	2	3	4	0	0	0	0	0	0	0	0	0	12
11:00	0	3	4	4	0	0	0	0	0	0	0	0	0	11
12:00 PM	0	5	4	1	0	0	0	0	0	0	0	0	0	10
1:00	0	1	2	3	1	0	0	0	0	0	0	0	0	7
2:00	1	3	6	2	0	0	0	0	0	0	0	0	0	12
3:00	0	4	3	1	0	0	0	0	0	0	0	0	0	8
4:00	2	4	5	5	0	0	0	0	0	0	0	0	0	16
5:00	1	3	3	2	0	0	0	0	0	0	0	0	0	9
6:00	0	4	1	3	0	0	0	0	0	0	0	0	0	8
7:00	0	2	2	0	0	0	0	0	0	0	0	0	0	4
8:00	0	3	1	0	0	0	0	0	0	0	0	0	0	4
9:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
10:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	13	47	54	31	3	0	0	0	0	0	0	0	0	148



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Avenida Del Sol Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.092603
Longitude: -106.599114
Direction: A to B, WB

#5
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	1	0	0	0	0	0	0	0	0	1
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
5:00	1	0	0	2	0	0	0	0	0	0	0	0	0	3
6:00	1	3	2	1	0	0	0	0	0	0	0	0	0	7
7:00	1	0	2	1	0	0	0	0	0	0	0	0	0	4
8:00	0	3	4	2	0	0	0	0	0	0	0	0	0	9
9:00	1	5	3	2	1	0	0	0	0	0	0	0	0	12
10:00	0	4	3	0	0	0	0	0	0	0	0	0	0	7
11:00	2	1	8	2	1	0	0	0	0	0	0	0	0	14
12:00 PM	0	2	2	2	0	0	0	0	0	0	0	0	0	6
1:00	1	1	8	2	0	0	0	0	0	0	0	0	0	12
2:00	0	3	4	2	2	0	0	0	0	0	0	0	0	11
3:00	3	5	5	1	0	0	0	0	0	0	0	0	0	14
4:00	1	8	3	1	0	0	0	0	0	0	0	0	0	13
5:00	1	4	2	2	0	0	0	0	0	0	0	0	0	9
6:00	0	4	5	1	1	0	0	0	0	0	0	0	0	11
7:00	1	2	0	1	0	0	0	0	0	0	0	0	0	4
8:00	1	2	2	0	0	0	0	0	0	0	0	0	0	5
9:00	0	2	2	0	0	0	0	0	0	0	0	0	0	4
10:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	14	49	56	22	6	0	0	0	0	0	0	0	0	147
Grand Total	27	96	110	53	9	0	0	0	0	0	0	0	0	295

Stats	Percentile	15th	50th	85th	95th
Speed		16	21	26	29
Mean Speed (Average)		20.7			
10 MPH Pace Speed		15-24			
Number in Pace		204			
Percent in Pace		69.2%			
Number > 25 MPH		62			
Percent > 25 MPH		21.0%			



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Avenida Del Sol Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.092603
Longitude: -106.599114
Direction: B to A, EB

#5
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00	0	2	1	0	0	0	0	0	0	0	0	0	0	3
7:00	1	0	1	5	0	0	0	0	0	0	0	0	0	7
8:00	1	3	5	3	1	0	0	0	0	0	0	0	0	13
9:00	0	2	1	3	2	1	0	0	0	0	0	0	0	9
10:00	0	0	1	2	2	1	0	0	0	0	0	0	0	6
11:00	0	2	1	3	2	0	0	0	0	0	0	0	0	8
12:00 PM	1	2	3	3	1	1	0	0	0	0	0	0	0	11
1:00	0	0	2	3	1	1	0	0	0	0	0	0	0	7
2:00	0	2	2	4	0	2	0	0	0	0	0	0	0	10
3:00	0	2	2	3	3	0	0	0	0	0	0	0	0	10
4:00	0	1	2	5	3	0	0	0	0	0	0	0	0	11
5:00	0	0	4	9	2	0	0	0	0	0	0	0	0	15
6:00	0	0	1	4	2	0	1	0	0	0	0	0	0	8
7:00	1	2	0	3	0	1	0	0	0	0	0	0	0	7
8:00	0	0	0	1	0	2	0	0	0	0	0	0	0	3
9:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
10:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	4	18	27	52	19	9	1	0	0	0	0	0	0	130



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Avenida Del Sol Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.092603
Longitude: -106.599114
Direction: B to A, EB

#5
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	0	1	0	0	0	0	0	0	0	0	1
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
6:00	0	4	1	0	1	1	0	0	0	0	0	0	0	7
7:00	0	1	0	1	0	0	0	0	0	0	0	0	0	2
8:00	1	1	2	3	1	0	0	0	0	0	0	0	0	8
9:00	0	1	3	4	0	0	0	0	0	0	0	0	0	8
10:00	1	2	1	3	0	0	0	0	0	0	0	0	0	7
11:00	0	1	5	5	1	1	0	0	0	0	0	0	0	13
12:00 PM	0	0	1	3	4	0	0	0	0	0	0	0	0	8
1:00	0	0	2	1	0	0	0	0	0	0	0	0	0	3
2:00	1	1	4	5	1	1	0	0	0	0	0	0	0	13
3:00	3	2	1	1	4	2	0	0	0	0	0	0	0	13
4:00	0	2	0	2	3	1	0	0	0	0	0	0	0	8
5:00	1	4	3	6	0	0	0	0	0	0	0	0	0	14
6:00	0	1	6	0	0	0	0	0	0	0	0	0	0	7
7:00	0	2	2	1	0	0	0	0	0	0	0	0	0	5
8:00	0	1	2	1	2	0	0	0	0	0	0	0	0	6
9:00	0	2	0	1	1	0	0	0	0	0	0	0	0	4
10:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	7	25	34	38	19	6	0	0	0	0	0	0	0	129
Grand Total	11	43	61	90	38	15	1	0	0	0	0	0	0	259

Stats	Percentile	15th	50th	85th	95th
Speed		18	26	32	35
Mean Speed (Average)		25.2			
10 MPH Pace Speed		20-29			
Number in Pace		150			
Percent in Pace		57.9%			
Number > 25 MPH		144			
Percent > 25 MPH		55.6%			



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Avenida Del Sol Counter

#5

Station ID:
Location 1:
Location 2:
Latitude: 35.092603
Longitude: -106.599114

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No



85th Percentile: 30.7



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Avenida Del Sol Counter #6

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.091190
Longitude: -106.596839

9/19/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB
12:00 AM	*	*	*	*	0	0	0	1	*	*	*	*	*	*	0	0
1:00	*	*	*	*	0	0	0	0	*	*	*	*	*	*	0	0
2:00	*	*	*	*	0	0	0	0	*	*	*	*	*	*	0	0
3:00	*	*	*	*	0	0	0	1	*	*	*	*	*	*	0	0
4:00	*	*	*	*	0	0	0	1	*	*	*	*	*	*	0	0
5:00	*	*	*	*	2	2	1	0	*	*	*	*	*	*	2	1
6:00	*	*	*	*	2	3	2	3	*	*	*	*	*	*	2	3
7:00	*	*	*	*	10	7	3	6	*	*	*	*	*	*	6	6
8:00	*	*	*	*	11	13	9	12	*	*	*	*	*	*	10	12
9:00	*	*	*	*	5	6	9	8	*	*	*	*	*	*	7	7
10:00	*	*	*	*	8	9	7	8	*	*	*	*	*	*	8	8
11:00	*	*	*	*	6	8	9	12	*	*	*	*	*	*	8	10
12:00 PM	*	*	*	*	8	12	12	8	*	*	*	*	*	*	10	10
1:00	*	*	*	*	6	9	3	11	*	*	*	*	*	*	4	10
2:00	*	*	*	*	8	9	10	10	*	*	*	*	*	*	9	10
3:00	*	*	*	*	8	15	11	15	*	*	*	*	*	*	10	15
4:00	*	*	*	*	12	7	9	13	*	*	*	*	*	*	10	10
5:00	*	*	*	*	12	9	11	7	*	*	*	*	*	*	12	8
6:00	*	*	*	*	4	9	8	7	*	*	*	*	*	*	6	8
7:00	*	*	*	*	5	10	4	4	*	*	*	*	*	*	4	7
8:00	*	*	*	*	5	4	4	4	*	*	*	*	*	*	4	4
9:00	*	*	*	*	0	1	1	4	*	*	*	*	*	*	0	2
10:00	*	*	*	*	1	1	0	1	*	*	*	*	*	*	0	1
11:00	*	*	*	*	0	0	0	0	*	*	*	*	*	*	0	0
Total	0	0	0	0	113	134	113	136	0	0	0	0	0	0	112	132
Day	0		0		247		249		0		0		0		244	
AM Peak					8:00	8:00	8:00	8:00							8:00	8:00
Volume					11	13	9	12							10	12
PM Peak					4:00	3:00	12:00 PM	3:00							5:00	3:00
Volume					12	15	12	15							12	15
Comb Total	0		0		247		249		0		0		0		244	
ADT	ADT: 248		AADT: 248													




Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.091190
Longitude: -106.596839

File Name: Avenida Del Sol Counter #6
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Avenida Del Sol Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.091190
Longitude: -106.596839
Direction: A to B, WB

#6
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	1	1	0	0	0	0	0	0	0	0	0	0	2
6:00	0	1	1	0	0	0	0	0	0	0	0	0	0	2
7:00	1	4	3	2	0	0	0	0	0	0	0	0	0	10
8:00	1	4	5	1	0	0	0	0	0	0	0	0	0	11
9:00	1	0	2	1	1	0	0	0	0	0	0	0	0	5
10:00	1	1	3	3	0	0	0	0	0	0	0	0	0	8
11:00	0	2	1	2	1	0	0	0	0	0	0	0	0	6
12:00 PM	0	3	2	3	0	0	0	0	0	0	0	0	0	8
1:00	0	2	1	1	2	0	0	0	0	0	0	0	0	6
2:00	0	0	5	3	0	0	0	0	0	0	0	0	0	8
3:00	1	1	3	1	1	1	0	0	0	0	0	0	0	8
4:00	0	2	6	2	2	0	0	0	0	0	0	0	0	12
5:00	0	2	7	3	0	0	0	0	0	0	0	0	0	12
6:00	0	1	2	1	0	0	0	0	0	0	0	0	0	4
7:00	1	2	1	1	0	0	0	0	0	0	0	0	0	5
8:00	1	2	2	0	0	0	0	0	0	0	0	0	0	5
9:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	7	28	46	24	7	1	0	0	0	0	0	0	0	113



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Avenida Del Sol Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.091190
Longitude: -106.596839
Direction: A to B, WB

#6
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
6:00	0	0	2	0	0	0	0	0	0	0	0	0	0	2
7:00	0	0	2	1	0	0	0	0	0	0	0	0	0	3
8:00	0	1	4	4	0	0	0	0	0	0	0	0	0	9
9:00	0	0	7	2	0	0	0	0	0	0	0	0	0	9
10:00	1	3	3	0	0	0	0	0	0	0	0	0	0	7
11:00	0	1	7	1	0	0	0	0	0	0	0	0	0	9
12:00 PM	1	0	4	6	1	0	0	0	0	0	0	0	0	12
1:00	0	0	3	0	0	0	0	0	0	0	0	0	0	3
2:00	0	3	3	3	1	0	0	0	0	0	0	0	0	10
3:00	1	5	3	2	0	0	0	0	0	0	0	0	0	11
4:00	0	1	6	2	0	0	0	0	0	0	0	0	0	9
5:00	1	2	5	3	0	0	0	0	0	0	0	0	0	11
6:00	0	1	2	5	0	0	0	0	0	0	0	0	0	8
7:00	0	1	3	0	0	0	0	0	0	0	0	0	0	4
8:00	1	2	1	0	0	0	0	0	0	0	0	0	0	4
9:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
10:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	5	22	55	29	2	0	0	0	0	0	0	0	0	113
Grand Total	12	50	101	53	9	1	0	0	0	0	0	0	0	226

Stats	Percentile	15th	50th	85th	95th
Speed		18	23	27	30
Mean Speed (Average)		22.3			
10 MPH Pace Speed		20-29			
Number in Pace		154			
Percent in Pace		68.1%			
Number > 25 MPH		63			
Percent > 25 MPH		27.9%			



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Avenida Del Sol Counter

#6

Station ID:
Location 1:
Location 2:
Latitude: 35.091190
Longitude: -106.596839
Direction: B to A, EB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	2	0	0	0	0	0	0	0	0	0	0	0	2
6:00	0	2	0	1	0	0	0	0	0	0	0	0	0	3
7:00	1	2	3	1	0	0	0	0	0	0	0	0	0	7
8:00	1	1	5	4	2	0	0	0	0	0	0	0	0	13
9:00	0	1	2	1	2	0	0	0	0	0	0	0	0	6
10:00	2	1	1	3	0	2	0	0	0	0	0	0	0	9
11:00	1	1	2	2	0	2	0	0	0	0	0	0	0	8
12:00 PM	0	3	4	3	2	0	0	0	0	0	0	0	0	12
1:00	1	0	2	2	3	1	0	0	0	0	0	0	0	9
2:00	0	2	1	4	2	0	0	0	0	0	0	0	0	9
3:00	3	1	2	4	3	2	0	0	0	0	0	0	0	15
4:00	0	0	1	2	2	2	0	0	0	0	0	0	0	7
5:00	0	1	0	6	2	0	0	0	0	0	0	0	0	9
6:00	0	0	4	2	2	0	1	0	0	0	0	0	0	9
7:00	2	1	4	1	1	1	0	0	0	0	0	0	0	10
8:00	0	2	0	0	0	2	0	0	0	0	0	0	0	4
9:00	1	0	0	0	0	0	0	0	0	0	0	0	0	1
10:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	12	20	32	36	21	12	1	0	0	0	0	0	0	134



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Avenida Del Sol Counter

Station ID:
Location 1:
Location 2:
Latitude: 35.091190
Longitude: -106.596839
Direction: B to A, EB

#6
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	1	0	0	0	0	0	0	0	0	0	1
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
4:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
5:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00	0	0	2	0	1	0	0	0	0	0	0	0	0	3
7:00	0	1	3	1	0	1	0	0	0	0	0	0	0	6
8:00	1	3	5	2	1	0	0	0	0	0	0	0	0	12
9:00	0	1	2	1	4	0	0	0	0	0	0	0	0	8
10:00	2	0	4	1	0	1	0	0	0	0	0	0	0	8
11:00	1	1	2	5	1	2	0	0	0	0	0	0	0	12
12:00 PM	0	0	2	3	2	1	0	0	0	0	0	0	0	8
1:00	2	2	3	1	3	0	0	0	0	0	0	0	0	11
2:00	0	0	4	4	2	0	0	0	0	0	0	0	0	10
3:00	2	1	4	6	0	2	0	0	0	0	0	0	0	15
4:00	2	1	2	5	2	0	1	0	0	0	0	0	0	13
5:00	0	0	3	3	1	0	0	0	0	0	0	0	0	7
6:00	0	2	3	2	0	0	0	0	0	0	0	0	0	7
7:00	2	1	1	0	0	0	0	0	0	0	0	0	0	4
8:00	1	1	0	1	1	0	0	0	0	0	0	0	0	4
9:00	0	0	3	0	1	0	0	0	0	0	0	0	0	4
10:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	13	16	43	37	19	7	1	0	0	0	0	0	0	136
Grand Total	25	36	75	73	40	19	2	0	0	0	0	0	0	270

Stats	Percentile	15th	50th	85th	95th
Speed		18	25	32	35
Mean Speed (Average)		24.5			
10 MPH Pace Speed		20-29			
Number in Pace		147			
Percent in Pace		54.4%			
Number > 25 MPH		134			
Percent > 25 MPH		49.6%			




Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Avenida Del Sol Counter
#6

Station ID:
Location 1:
Location 2:
Latitude: 35.091190
Longitude: -106.596839

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No



Speed Enforcement Evaluator

Location

Avenida Del Sol Counter #6

Analysis Dates

Start: 9/22/2022


End: 9/22/2022

Total Percentage of Enforceable Violations

Posted Speed Limit	25 MPH
--------------------	--------


Enforcement Tolerance 5 MPH

Enforcement Limit	Greater than 30 MPH
-------------------	---------------------



Percent Speeding: 12%

Rating: Medium Low



Percent Speeding: 2%

Rating: Low

Percent Speeding: 20%

Rating: Medium Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
18	38	98	66	21	7	1	0	0	0	0	0	0
85th Percentile: 29.2												

Vehicle Totals - A to B, WB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
5	22	55	29	2	0	0	0	0	0	0	0	0
85th Percentile: 26.7												

Vehicle Totals - B to A, EB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
13	16	43	37	19	7	1	0	0	0	0	0	0
85th Percentile: 31.2												



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator

Location

Avenida Del Sol Counter #6


Analysis Dates

Start: 9/21/2022

End: 9/21/2022


Total Percentage of Enforceable Violations

Posted Speed Limit 25 MPH
Enforcement Tolerance 7 MPH
Enforcement Limit Greater than 32 MPH



Percent Speeding: 11%

Rating: Medium Low



Percent Speeding: 3%

Rating: Low



Percent Speeding: 19%

Rating: Medium Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
19	48	78	60	28	13	1	0	0	0	0	0	0

85th Percentile: 30.6

Vehicle Totals - A to B, WB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
7	28	46	24	7	1	0	0	0	0	0	0	0

85th Percentile: 27.4

Vehicle Totals - B to A, EB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
12	20	32	36	21	12	1	0	0	0	0	0	0

85th Percentile: 32.3



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter #7

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.091461
Longitude: -106.599726

9/19/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB
12:00 AM	*	*	*	*	1	0	2	1	*	*	*	*	*	*	2	0
1:00	*	*	*	*	1	0	0	0	*	*	*	*	*	*	0	0
2:00	*	*	*	*	2	0	0	0	*	*	*	*	*	*	1	0
3:00	*	*	*	*	1	1	0	0	*	*	*	*	*	*	0	0
4:00	*	*	*	*	0	0	1	1	*	*	*	*	*	*	0	0
5:00	*	*	*	*	1	3	1	2	*	*	*	*	*	*	1	2
6:00	*	*	*	*	7	10	2	9	*	*	*	*	*	*	4	10
7:00	*	*	*	*	13	18	13	10	*	*	*	*	*	*	13	14
8:00	*	*	*	*	20	24	8	13	*	*	*	*	*	*	14	18
9:00	*	*	*	*	14	15	18	16	*	*	*	*	*	*	16	16
10:00	*	*	*	*	21	11	15	13	*	*	*	*	*	*	18	12
11:00	*	*	*	*	18	15	14	11	*	*	*	*	*	*	16	13
12:00 PM	*	*	*	*	19	18	23	15	*	*	*	*	*	*	21	16
1:00	*	*	*	*	14	10	17	10	*	*	*	*	*	*	16	10
2:00	*	*	*	*	14	12	12	20	*	*	*	*	*	*	13	16
3:00	*	*	*	*	19	13	24	24	*	*	*	*	*	*	22	18
4:00	*	*	*	*	28	17	34	30	*	*	*	*	*	*	31	24
5:00	*	*	*	*	24	21	26	18	*	*	*	*	*	*	25	20
6:00	*	*	*	*	18	13	25	16	*	*	*	*	*	*	22	14
7:00	*	*	*	*	18	11	28	11	*	*	*	*	*	*	23	11
8:00	*	*	*	*	10	4	13	8	*	*	*	*	*	*	12	6
9:00	*	*	*	*	3	3	5	4	*	*	*	*	*	*	4	4
10:00	*	*	*	*	2	1	3	0	*	*	*	*	*	*	2	0
11:00	*	*	*	*	0	0	5	3	*	*	*	*	*	*	2	2
Total	0	0	0	0	268	220	289	235	0	0	0	0	0	0	278	226
Day	0		0		488		524		0		0		0		504	
AM Peak					10:00	8:00	9:00	9:00							10:00	8:00
Volume					21	24	18	16							18	18
PM Peak					4:00	5:00	4:00	4:00							4:00	4:00
Volume					28	21	34	30							31	24
Comb Total	0		0		488		524		0		0		0		504	
ADT	ADT: 506		AADT: 506													



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.091461
Longitude: -106.599726

File Name: Morningside Dr Counter #7
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter

#7

Station ID:
Location 1:
Location 2:
Latitude: 35.091461
Longitude: -106.599726
Direction: A to B, SB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	1
1:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
2:00	0	1	0	1	0	0	0	0	0	0	0	0	0	2
3:00	1	0	0	0	0	0	0	0	0	0	0	0	0	1
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
6:00	0	2	5	0	0	0	0	0	0	0	0	0	0	7
7:00	1	1	7	2	2	0	0	0	0	0	0	0	0	13
8:00	1	4	7	7	1	0	0	0	0	0	0	0	0	20
9:00	1	3	8	2	0	0	0	0	0	0	0	0	0	14
10:00	1	6	11	2	0	1	0	0	0	0	0	0	0	21
11:00	2	3	8	3	1	1	0	0	0	0	0	0	0	18
12:00 PM	5	3	9	2	0	0	0	0	0	0	0	0	0	19
1:00	0	4	7	2	0	1	0	0	0	0	0	0	0	14
2:00	1	2	7	3	1	0	0	0	0	0	0	0	0	14
3:00	1	3	8	6	1	0	0	0	0	0	0	0	0	19
4:00	1	4	7	12	4	0	0	0	0	0	0	0	0	28
5:00	1	5	11	5	2	0	0	0	0	0	0	0	0	24
6:00	0	4	10	3	0	0	1	0	0	0	0	0	0	18
7:00	0	3	10	4	1	0	0	0	0	0	0	0	0	18
8:00	0	2	6	2	0	0	0	0	0	0	0	0	0	10
9:00	0	0	2	1	0	0	0	0	0	0	0	0	0	3
10:00	0	0	0	2	0	0	0	0	0	0	0	0	0	2
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	16	52	124	59	13	3	1	0	0	0	0	0	0	268



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter

#7

Station ID:
Location 1:
Location 2:
Latitude: 35.091461
Longitude: -106.599726
Direction: A to B, SB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	1	1	0	0	0	0	0	0	0	0	0	2
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
5:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
6:00	0	1	0	1	0	0	0	0	0	0	0	0	0	2
7:00	1	4	2	6	0	0	0	0	0	0	0	0	0	13
8:00	0	2	5	1	0	0	0	0	0	0	0	0	0	8
9:00	0	3	9	4	2	0	0	0	0	0	0	0	0	18
10:00	1	1	8	4	0	1	0	0	0	0	0	0	0	15
11:00	0	1	4	8	1	0	0	0	0	0	0	0	0	14
12:00 PM	0	3	9	11	0	0	0	0	0	0	0	0	0	23
1:00	0	1	8	7	1	0	0	0	0	0	0	0	0	17
2:00	1	3	3	3	2	0	0	0	0	0	0	0	0	12
3:00	0	5	13	6	0	0	0	0	0	0	0	0	0	24
4:00	0	1	18	11	4	0	0	0	0	0	0	0	0	34
5:00	2	3	11	6	4	0	0	0	0	0	0	0	0	26
6:00	2	3	12	7	0	1	0	0	0	0	0	0	0	25
7:00	2	6	11	9	0	0	0	0	0	0	0	0	0	28
8:00	1	2	6	3	1	0	0	0	0	0	0	0	0	13
9:00	0	1	3	1	0	0	0	0	0	0	0	0	0	5
10:00	0	0	2	1	0	0	0	0	0	0	0	0	0	3
11:00	2	1	0	1	1	0	0	0	0	0	0	0	0	5
Total	12	41	126	92	16	2	0	0	0	0	0	0	0	289
Grand Total	28	93	250	151	29	5	1	0	0	0	0	0	0	557

Stats	Percentile	15th	50th	85th	95th
Speed		18	23	27	30
Mean Speed (Average)		23.0			
10 MPH Pace Speed		20-29			
Number in Pace		400			
Percent in Pace		71.8%			
Number > 25 MPH		186			
Percent > 25 MPH		33.4%			



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter
#7

Station ID:
Location 1:
Location 2:
Latitude: 35.091461
Longitude: -106.599726
Direction: B to A, NB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	1	0	0	0	0	0	0	1
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	0	2	0	1	0	0	0	0	0	0	0	0	3
6:00	0	0	4	3	3	0	0	0	0	0	0	0	0	10
7:00	0	5	6	5	2	0	0	0	0	0	0	0	0	18
8:00	2	1	12	9	0	0	0	0	0	0	0	0	0	24
9:00	1	4	3	7	0	0	0	0	0	0	0	0	0	15
10:00	0	1	6	4	0	0	0	0	0	0	0	0	0	11
11:00	1	2	7	5	0	0	0	0	0	0	0	0	0	15
12:00 PM	1	2	8	6	1	0	0	0	0	0	0	0	0	18
1:00	0	2	4	3	1	0	0	0	0	0	0	0	0	10
2:00	0	1	5	6	0	0	0	0	0	0	0	0	0	12
3:00	0	0	7	5	1	0	0	0	0	0	0	0	0	13
4:00	0	1	5	9	2	0	0	0	0	0	0	0	0	17
5:00	0	1	8	10	2	0	0	0	0	0	0	0	0	21
6:00	0	1	5	5	1	1	0	0	0	0	0	0	0	13
7:00	0	2	8	1	0	0	0	0	0	0	0	0	0	11
8:00	0	0	1	3	0	0	0	0	0	0	0	0	0	4
9:00	0	0	2	1	0	0	0	0	0	0	0	0	0	3
10:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	5	23	93	83	14	1	1	0	0	0	0	0	0	220



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter
#7

Station ID:
Location 1:
Location 2:
Latitude: 35.091461
Longitude: -106.599726
Direction: B to A, NB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	1	0	0	0	0	0	1
5:00	0	0	1	1	0	0	0	0	0	0	0	0	0	2
6:00	0	0	3	5	1	0	0	0	0	0	0	0	0	9
7:00	0	1	6	3	0	0	0	0	0	0	0	0	0	10
8:00	1	3	4	4	1	0	0	0	0	0	0	0	0	13
9:00	0	1	9	4	2	0	0	0	0	0	0	0	0	16
10:00	1	1	5	5	1	0	0	0	0	0	0	0	0	13
11:00	0	1	4	2	4	0	0	0	0	0	0	0	0	11
12:00 PM	0	1	7	6	1	0	0	0	0	0	0	0	0	15
1:00	1	0	6	3	0	0	0	0	0	0	0	0	0	10
2:00	0	1	7	10	2	0	0	0	0	0	0	0	0	20
3:00	0	3	10	10	1	0	0	0	0	0	0	0	0	24
4:00	2	5	15	6	2	0	0	0	0	0	0	0	0	30
5:00	1	1	6	8	2	0	0	0	0	0	0	0	0	18
6:00	1	3	4	4	2	1	0	1	0	0	0	0	0	16
7:00	0	1	9	1	0	0	0	0	0	0	0	0	0	11
8:00	0	0	3	5	0	0	0	0	0	0	0	0	0	8
9:00	0	1	2	1	0	0	0	0	0	0	0	0	0	4
10:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:00	2	1	0	0	0	0	0	0	0	0	0	0	0	3
Total	9	25	101	78	19	1	0	2	0	0	0	0	0	235
Grand Total	14	48	194	161	33	2	1	2	0	0	0	0	0	455

Stats	Percentile	15th	50th	85th	95th
Speed	20	24	28	31	
Mean Speed (Average)	24.3				
10 MPH Pace Speed	20-29				
Number in Pace	353				
Percent in Pace	77.6%				
Number > 25 MPH	199				
Percent > 25 MPH	43.7%				



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Morningside Dr Counter
#7

Station ID:
Location 1:
Location 2:
Latitude: 35.091461
Longitude: -106.599726

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No



85th Percentile: 28.1



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Marble Ave Counter #8

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.089236
Longitude: -106.597141

9/19/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB	A to B, WB	B to A, EB
12:00 AM	*	*	*	*	1	0	1	1	*	*	*	*	*	*	1	0
1:00	*	*	*	*	1	0	1	0	*	*	*	*	*	*	1	0
2:00	*	*	*	*	0	1	0	0	*	*	*	*	*	*	0	0
3:00	*	*	*	*	1	1	0	0	*	*	*	*	*	*	0	0
4:00	*	*	*	*	0	0	1	1	*	*	*	*	*	*	0	0
5:00	*	*	*	*	0	1	0	2	*	*	*	*	*	*	0	2
6:00	*	*	*	*	2	4	1	2	*	*	*	*	*	*	2	3
7:00	*	*	*	*	6	5	3	11	*	*	*	*	*	*	4	8
8:00	*	*	*	*	1	12	10	6	*	*	*	*	*	*	6	9
9:00	*	*	*	*	6	12	5	10	*	*	*	*	*	*	6	11
10:00	*	*	*	*	9	9	7	7	*	*	*	*	*	*	8	8
11:00	*	*	*	*	9	8	5	0	*	*	*	*	*	*	7	4
12:00 PM	*	*	*	*	8	7	12	14	*	*	*	*	*	*	10	10
1:00	*	*	*	*	3	8	4	7	*	*	*	*	*	*	4	8
2:00	*	*	*	*	8	5	8	8	*	*	*	*	*	*	8	6
3:00	*	*	*	*	9	9	11	12	*	*	*	*	*	*	10	10
4:00	*	*	*	*	10	9	6	12	*	*	*	*	*	*	8	10
5:00	*	*	*	*	8	10	10	10	*	*	*	*	*	*	9	10
6:00	*	*	*	*	8	3	11	3	*	*	*	*	*	*	10	3
7:00	*	*	*	*	6	5	8	4	*	*	*	*	*	*	7	4
8:00	*	*	*	*	5	2	3	3	*	*	*	*	*	*	4	2
9:00	*	*	*	*	4	2	0	2	*	*	*	*	*	*	2	2
10:00	*	*	*	*	0	1	1	1	*	*	*	*	*	*	0	1
11:00	*	*	*	*	2	0	0	0	*	*	*	*	*	*	1	0
Total	0	0	0	0	107	114	108	116	0	0	0	0	0	0	108	111
Day	0		0		221		224		0		0		0		219	
AM Peak					10:00	8:00	8:00	7:00							10:00	9:00
Volume					9	12	10	11							8	11
PM Peak					4:00	5:00	12:00 PM	12:00 PM							12:00 PM	12:00 PM
Volume					10	10	12	14							10	10
Comb Total	0		0		221		224		0		0		0		219	
ADT	ADT: 222		AADT: 222													




Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.089236
Longitude: -106.597141

File Name: Marble Ave Counter #8
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Marble Ave Counter #8

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.089236
Longitude: -106.597141
Direction: A to B, WB

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
1:00	1	0	0	0	0	0	0	0	0	0	0	0	0	1
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	1	0	0	0	0	0	0	0	0	1
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00	1	0	0	1	0	0	0	0	0	0	0	0	0	2
7:00	0	1	1	4	0	0	0	0	0	0	0	0	0	6
8:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
9:00	0	0	4	2	0	0	0	0	0	0	0	0	0	6
10:00	1	5	1	0	2	0	0	0	0	0	0	0	0	9
11:00	3	3	2	1	0	0	0	0	0	0	0	0	0	9
12:00 PM	0	1	4	2	0	1	0	0	0	0	0	0	0	8
1:00	0	1	1	1	0	0	0	0	0	0	0	0	0	3
2:00	1	0	4	3	0	0	0	0	0	0	0	0	0	8
3:00	3	1	2	2	1	0	0	0	0	0	0	0	0	9
4:00	1	0	7	2	0	0	0	0	0	0	0	0	0	10
5:00	0	2	2	2	2	0	0	0	0	0	0	0	0	8
6:00	2	1	3	2	0	0	0	0	0	0	0	0	0	8
7:00	1	2	1	2	0	0	0	0	0	0	0	0	0	6
8:00	0	1	3	1	0	0	0	0	0	0	0	0	0	5
9:00	1	0	2	1	0	0	0	0	0	0	0	0	0	4
10:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:00	0	0	1	0	0	1	0	0	0	0	0	0	0	2
Total	15	19	39	26	6	2	0	0	0	0	0	0	0	107



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Marble Ave Counter #8

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.089236
Longitude: -106.597141
Direction: A to B, WB

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	1	0	0	0	0	0	0	0	0	0	1
1:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	1	0	0	0	0	0	0	0	0	1
5:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
7:00	0	0	2	0	1	0	0	0	0	0	0	0	0	3
8:00	1	0	5	3	1	0	0	0	0	0	0	0	0	10
9:00	1	1	1	2	0	0	0	0	0	0	0	0	0	5
10:00	0	3	2	1	1	0	0	0	0	0	0	0	0	7
11:00	0	1	4	0	0	0	0	0	0	0	0	0	0	5
12:00 PM	0	1	8	3	0	0	0	0	0	0	0	0	0	12
1:00	0	0	3	0	0	1	0	0	0	0	0	0	0	4
2:00	0	2	4	1	1	0	0	0	0	0	0	0	0	8
3:00	1	2	5	3	0	0	0	0	0	0	0	0	0	11
4:00	1	1	4	0	0	0	0	0	0	0	0	0	0	6
5:00	1	4	3	1	1	0	0	0	0	0	0	0	0	10
6:00	2	3	5	1	0	0	0	0	0	0	0	0	0	11
7:00	1	6	1	0	0	0	0	0	0	0	0	0	0	8
8:00	1	0	2	0	0	0	0	0	0	0	0	0	0	3
9:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
10:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	9	24	51	17	6	1	0	0	0	0	0	0	0	108
Grand Total	24	43	90	43	12	3	0	0	0	0	0	0	0	215

Stats	Percentile	15th	50th	85th	95th
	Speed	16	22	27	31
Mean Speed (Average)		21.6			
10 MPH Pace Speed		16-25			
Number in Pace		133			
Percent in Pace		61.9%			
Number > 25 MPH		58			
Percent > 25 MPH		27.0%			



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Marble Ave Counter #8

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.089236
Longitude: -106.597141
Direction: B to A, EB

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
3:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
6:00	0	1	2	0	1	0	0	0	0	0	0	0	0	4
7:00	1	1	2	0	1	0	0	0	0	0	0	0	0	5
8:00	1	1	8	2	0	0	0	0	0	0	0	0	0	12
9:00	1	2	3	4	1	1	0	0	0	0	0	0	0	12
10:00	2	1	4	1	1	0	0	0	0	0	0	0	0	9
11:00	1	2	3	2	0	0	0	0	0	0	0	0	0	8
12:00 PM	1	1	2	3	0	0	0	0	0	0	0	0	0	7
1:00	0	2	4	1	1	0	0	0	0	0	0	0	0	8
2:00	2	2	1	0	0	0	0	0	0	0	0	0	0	5
3:00	1	2	3	1	2	0	0	0	0	0	0	0	0	9
4:00	0	1	6	2	0	0	0	0	0	0	0	0	0	9
5:00	3	1	5	1	0	0	0	0	0	0	0	0	0	10
6:00	0	0	2	1	0	0	0	0	0	0	0	0	0	3
7:00	0	3	2	0	0	0	0	0	0	0	0	0	0	5
8:00	1	0	1	0	0	0	0	0	0	0	0	0	0	2
9:00	0	1	1	0	0	0	0	0	0	0	0	0	0	2
10:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	14	24	49	19	7	1	0	0	0	0	0	0	0	114



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Marble Ave Counter #8

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.089236
Longitude: -106.597141
Direction: B to A, EB

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	1
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
5:00	1	1	0	0	0	0	0	0	0	0	0	0	0	2
6:00	0	0	0	1	1	0	0	0	0	0	0	0	0	2
7:00	0	6	4	1	0	0	0	0	0	0	0	0	0	11
8:00	1	1	3	1	0	0	0	0	0	0	0	0	0	6
9:00	1	3	3	3	0	0	0	0	0	0	0	0	0	10
10:00	1	0	4	2	0	0	0	0	0	0	0	0	0	7
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
12:00 PM	1	1	3	6	3	0	0	0	0	0	0	0	0	14
1:00	0	2	0	5	0	0	0	0	0	0	0	0	0	7
2:00	3	1	4	0	0	0	0	0	0	0	0	0	0	8
3:00	2	1	5	2	2	0	0	0	0	0	0	0	0	12
4:00	1	3	5	3	0	0	0	0	0	0	0	0	0	12
5:00	1	0	5	4	0	0	0	0	0	0	0	0	0	10
6:00	0	0	2	0	1	0	0	0	0	0	0	0	0	3
7:00	0	1	2	1	0	0	0	0	0	0	0	0	0	4
8:00	0	1	1	0	1	0	0	0	0	0	0	0	0	3
9:00	1	0	1	0	0	0	0	0	0	0	0	0	0	2
10:00	1	0	0	0	0	0	0	0	0	0	0	0	0	1
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	14	21	44	29	8	0	0	0	0	0	0	0	0	116
Grand Total	28	45	93	48	15	1	0	0	0	0	0	0	0	230
Stats														
	Percentile			15th	50th	85th	95th							
	Speed			16	23	27	30							
	Mean Speed (Average)			21.5										
	10 MPH Pace Speed			20-29										
	Number in Pace			141										
	Percent in Pace			61.3%										
	Number > 25 MPH			64										
	Percent > 25 MPH			27.8%										




Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.089236
Longitude: -106.597141

File Name: Marble Ave Counter #8
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator

Location

Marble Ave Counter #8


Total Percentage of Enforceable Violations

Analysis Dates

Start: 9/21/2022


End: 9/21/2022

Posted Speed Limit 25 MPH
Enforcement Tolerance 5 MPH
Enforcement Limit Greater than 30 MPH



Percent Speeding: 7%

Rating: Low



Percent Speeding: 7%

Rating: Low



Percent Speeding: 7%

Rating: Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
29	43	88	45	13	3	0	0	0	0	0	0	0

85th Percentile: 26.9

Vehicle Totals - A to B, WB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
15	19	39	26	6	2	0	0	0	0	0	0	0

85th Percentile: 27.2

Vehicle Totals - B to A, EB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
14	24	49	19	7	1	0	0	0	0	0	0	0

85th Percentile: 26.6

85th Percentile: 27.7



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Mackland Ave Counter #3

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.091142
Longitude: -106.602260

9/19/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB
12:00 AM	*	*	*	*	1	1	1	1	*	*	*	*	*	*	1	1
1:00	*	*	*	*	1	0	1	1	*	*	*	*	*	*	1	0
2:00	*	*	*	*	0	1	0	0	*	*	*	*	*	*	0	0
3:00	*	*	*	*	3	1	2	0	*	*	*	*	*	*	2	0
4:00	*	*	*	*	3	0	2	1	*	*	*	*	*	*	2	0
5:00	*	*	*	*	2	5	1	3	*	*	*	*	*	*	2	4
6:00	*	*	*	*	5	14	4	13	*	*	*	*	*	*	4	14
7:00	*	*	*	*	14	21	15	19	*	*	*	*	*	*	14	20
8:00	*	*	*	*	27	22	23	20	*	*	*	*	*	*	25	21
9:00	*	*	*	*	20	26	21	15	*	*	*	*	*	*	20	20
10:00	*	*	*	*	19	11	24	23	*	*	*	*	*	*	22	17
11:00	*	*	*	*	26	13	21	30	*	*	*	*	*	*	24	22
12:00 PM	*	*	*	*	25	23	27	29	*	*	*	*	*	*	26	26
1:00	*	*	*	*	22	26	22	16	*	*	*	*	*	*	22	21
2:00	*	*	*	*	22	21	22	13	*	*	*	*	*	*	22	17
3:00	*	*	*	*	29	24	38	32	*	*	*	*	*	*	34	28
4:00	*	*	*	*	33	27	38	32	*	*	*	*	*	*	36	30
5:00	*	*	*	*	35	24	42	34	*	*	*	*	*	*	38	29
6:00	*	*	*	*	23	26	26	13	*	*	*	*	*	*	24	20
7:00	*	*	*	*	33	18	17	14	*	*	*	*	*	*	25	16
8:00	*	*	*	*	13	10	16	8	*	*	*	*	*	*	14	9
9:00	*	*	*	*	15	7	5	5	*	*	*	*	*	*	10	6
10:00	*	*	*	*	9	3	9	3	*	*	*	*	*	*	9	3
11:00	*	*	*	*	3	1	4	3	*	*	*	*	*	*	4	2
Total	0	0	0	0	383	325	381	328	0	0	0	0	0	0	381	326
Day	0		0		708		709		0		0		0		707	
AM Peak					8:00	9:00	10:00	11:00							8:00	11:00
Volume					27	26	24	30							25	22
PM Peak					5:00	4:00	5:00	5:00							5:00	4:00
Volume					35	27	42	34							38	30
Comb Total	0		0		708		709		0		0		0		707	
ADT	ADT: 708		AADT: 708													



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.091142
Longitude: -106.602260

File Name: Mackland Ave Counter #3
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Mackland Ave Counter
#3

Station ID:
Location 1:
Location 2:
Latitude: 35.091142
Longitude: -106.602260
Direction: A to B, EB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	1	0	0	0	0	0	0	0	0	0	1
1:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	1	1	1	0	0	0	0	0	0	0	0	0	3
4:00	0	2	0	0	1	0	0	0	0	0	0	0	0	3
5:00	1	0	1	0	0	0	0	0	0	0	0	0	0	2
6:00	1	2	0	2	0	0	0	0	0	0	0	0	0	5
7:00	1	4	3	4	1	0	1	0	0	0	0	0	0	14
8:00	4	10	10	3	0	0	0	0	0	0	0	0	0	27
9:00	8	6	4	1	1	0	0	0	0	0	0	0	0	20
10:00	2	3	11	3	0	0	0	0	0	0	0	0	0	19
11:00	4	6	9	7	0	0	0	0	0	0	0	0	0	26
12:00 PM	3	3	10	9	0	0	0	0	0	0	0	0	0	25
1:00	2	3	10	6	0	1	0	0	0	0	0	0	0	22
2:00	2	9	5	5	1	0	0	0	0	0	0	0	0	22
3:00	4	9	8	7	0	1	0	0	0	0	0	0	0	29
4:00	2	7	9	10	5	0	0	0	0	0	0	0	0	33
5:00	1	9	15	7	3	0	0	0	0	0	0	0	0	35
6:00	1	7	10	4	1	0	0	0	0	0	0	0	0	23
7:00	6	10	12	4	1	0	0	0	0	0	0	0	0	33
8:00	1	1	7	4	0	0	0	0	0	0	0	0	0	13
9:00	1	2	8	3	1	0	0	0	0	0	0	0	0	15
10:00	0	2	3	3	1	0	0	0	0	0	0	0	0	9
11:00	1	1	1	0	0	0	0	0	0	0	0	0	0	3
Total	45	97	138	84	16	2	1	0	0	0	0	0	0	383



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Mackland Ave Counter
#3

Station ID:
Location 1:
Location 2:
Latitude: 35.091142
Longitude: -106.602260
Direction: A to B, EB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	1	0	0	0	0	0	0	0	0	0	1
1:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	2	0	0	0	0	0	0	0	0	0	0	0	2
4:00	0	0	1	0	1	0	0	0	0	0	0	0	0	2
5:00	1	0	0	0	0	0	0	0	0	0	0	0	0	1
6:00	0	3	1	0	0	0	0	0	0	0	0	0	0	4
7:00	1	3	7	2	2	0	0	0	0	0	0	0	0	15
8:00	4	4	10	5	0	0	0	0	0	0	0	0	0	23
9:00	3	5	8	5	0	0	0	0	0	0	0	0	0	21
10:00	3	8	11	1	1	0	0	0	0	0	0	0	0	24
11:00	5	2	4	7	3	0	0	0	0	0	0	0	0	21
12:00 PM	2	6	12	6	1	0	0	0	0	0	0	0	0	27
1:00	1	4	7	8	2	0	0	0	0	0	0	0	0	22
2:00	4	3	7	6	0	2	0	0	0	0	0	0	0	22
3:00	1	11	18	7	1	0	0	0	0	0	0	0	0	38
4:00	6	11	12	9	0	0	0	0	0	0	0	0	0	38
5:00	4	13	14	8	3	0	0	0	0	0	0	0	0	42
6:00	1	9	12	3	1	0	0	0	0	0	0	0	0	26
7:00	4	4	6	3	0	0	0	0	0	0	0	0	0	17
8:00	0	6	5	3	1	1	0	0	0	0	0	0	0	16
9:00	2	2	1	0	0	0	0	0	0	0	0	0	0	5
10:00	0	2	2	3	2	0	0	0	0	0	0	0	0	9
11:00	1	0	2	1	0	0	0	0	0	0	0	0	0	4
Total	43	99	140	78	18	3	0	0	0	0	0	0	0	381
Grand Total	88	196	278	162	34	5	1	0	0	0	0	0	0	764

Stats	Percentile	15th	50th	85th	95th
Speed		16	22	27	30
Mean Speed (Average)		21.2			
10 MPH Pace Speed		15-24			
Number in Pace		469			
Percent in Pace		61.4%			
Number > 25 MPH		202			
Percent > 25 MPH		26.4%			



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Mackland Ave Counter
#3

Station ID:
Location 1:
Location 2:
Latitude: 35.091142
Longitude: -106.602260
Direction: B to A, WB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	1	0	0	0	0	0	0	0	0	0	1
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
3:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	2	2	0	0	0	0	0	1	0	0	0	0	5
6:00	2	0	4	7	1	0	0	0	0	0	0	0	0	14
7:00	0	2	9	7	3	0	0	0	0	0	0	0	0	21
8:00	3	4	5	8	2	0	0	0	0	0	0	0	0	22
9:00	5	8	7	4	2	0	0	0	0	0	0	0	0	26
10:00	1	2	5	3	0	0	0	0	0	0	0	0	0	11
11:00	0	3	3	1	4	2	0	0	0	0	0	0	0	13
12:00 PM	3	4	8	3	4	0	0	1	0	0	0	0	0	23
1:00	3	5	10	7	1	0	0	0	0	0	0	0	0	26
2:00	2	2	12	4	1	0	0	0	0	0	0	0	0	21
3:00	3	3	10	5	2	0	0	1	0	0	0	0	0	24
4:00	3	2	11	6	4	1	0	0	0	0	0	0	0	27
5:00	1	4	6	9	4	0	0	0	0	0	0	0	0	24
6:00	7	4	8	4	2	1	0	0	0	0	0	0	0	26
7:00	5	7	5	1	0	0	0	0	0	0	0	0	0	18
8:00	0	0	4	5	1	0	0	0	0	0	0	0	0	10
9:00	1	1	2	1	2	0	0	0	0	0	0	0	0	7
10:00	0	0	2	1	0	0	0	0	0	0	0	0	0	3
11:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Total	39	53	115	78	33	4	0	2	1	0	0	0	0	325



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Mackland Ave Counter

#3

Station ID:
Location 1:
Location 2:
Latitude: 35.091142
Longitude: -106.602260
Direction: B to A, WB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	1	0	0	0	0	0	0	0	0	0	0	1
1:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	1	0	0	0	0	0	0	0	0	0	0	0	0	1
5:00	0	0	1	1	1	0	0	0	0	0	0	0	0	3
6:00	0	2	7	4	0	0	0	0	0	0	0	0	0	13
7:00	0	3	8	5	3	0	0	0	0	0	0	0	0	19
8:00	0	5	10	3	2	0	0	0	0	0	0	0	0	20
9:00	0	3	7	3	2	0	0	0	0	0	0	0	0	15
10:00	1	3	10	8	1	0	0	0	0	0	0	0	0	23
11:00	2	4	11	10	1	2	0	0	0	0	0	0	0	30
12:00 PM	5	4	10	5	3	2	0	0	0	0	0	0	0	29
1:00	1	3	6	2	2	2	0	0	0	0	0	0	0	16
2:00	0	2	7	1	3	0	0	0	0	0	0	0	0	13
3:00	6	8	12	5	0	1	0	0	0	0	0	0	0	32
4:00	3	6	11	8	3	1	0	0	0	0	0	0	0	32
5:00	1	7	11	10	4	1	0	0	0	0	0	0	0	34
6:00	0	5	5	1	2	0	0	0	0	0	0	0	0	13
7:00	1	4	7	1	1	0	0	0	0	0	0	0	0	14
8:00	1	2	4	1	0	0	0	0	0	0	0	0	0	8
9:00	1	2	1	1	0	0	0	0	0	0	0	0	0	5
10:00	1	1	0	1	0	0	0	0	0	0	0	0	0	3
11:00	0	0	2	0	1	0	0	0	0	0	0	0	0	3
Total	24	64	132	70	29	9	0	0	0	0	0	0	0	328
Grand Total	63	117	247	148	62	13	0	2	1	0	0	0	0	653

Stats	Percentile	15th	50th	85th	95th
Speed	17	23	29	33	
Mean Speed (Average)	22.7				
10 MPH Pace Speed	20-29				
Number in Pace	394				
Percent in Pace	60.3%				
Number > 25 MPH	226				
Percent > 25 MPH	34.6%				



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Mackland Ave Counter
#3

Station ID:
Location 1:
Location 2:
Latitude: 35.091142
Longitude: -106.602260

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator

Location

Mackland Ave Counter #3

Analysis Dates

Start: 9/22/2022


End: 9/22/2022

Total Percentage of Enforceable Violations

Posted Speed Limit	25 MPH
--------------------	--------


Enforcement Tolerance 5 MPH

Enforcement Limit	Greater than 30 MPH
-------------------	---------------------



Percent Speeding: 8%

Rating: Low



Percent Speeding: 6%

Rating: Low

Percent Speeding: 12%

Rating: Medium Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
67	163	272	148	47	12	0	0	0	0	0	0	0
85th Percentile: 27.9												

Vehicle Totals - A to B, EB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
43	99	140	78	18	3	0	0	0	0	0	0	0
85th Percentile: 27.2												

Vehicle Totals - B to A, WB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
24	64	132	70	29	9	0	0	0	0	0	0	0
85th Percentile: 28.6												

85th Percentile: 28.6



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Mackland Ave Counter #4

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.090800
Longitude: -106.600270

9/19/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB	A to B, EB	B to A, WB
12:00 AM	*	*	*	*	2	0	0	1	*	*	*	*	*	*	1	0
1:00	*	*	*	*	0	0	2	1	*	*	*	*	*	*	1	0
2:00	*	*	*	*	0	1	0	0	*	*	*	*	*	*	0	0
3:00	*	*	*	*	0	0	1	0	*	*	*	*	*	*	0	0
4:00	*	*	*	*	1	0	0	1	*	*	*	*	*	*	0	0
5:00	*	*	*	*	0	1	1	1	*	*	*	*	*	*	0	1
6:00	*	*	*	*	4	4	3	4	*	*	*	*	*	*	4	4
7:00	*	*	*	*	12	14	9	11	*	*	*	*	*	*	10	12
8:00	*	*	*	*	23	23	14	16	*	*	*	*	*	*	18	20
9:00	*	*	*	*	14	16	17	19	*	*	*	*	*	*	16	18
10:00	*	*	*	*	12	14	19	14	*	*	*	*	*	*	16	14
11:00	*	*	*	*	17	17	12	18	*	*	*	*	*	*	14	18
12:00 PM	*	*	*	*	23	21	14	23	*	*	*	*	*	*	18	22
1:00	*	*	*	*	18	17	18	9	*	*	*	*	*	*	18	13
2:00	*	*	*	*	12	21	30	14	*	*	*	*	*	*	21	18
3:00	*	*	*	*	16	17	27	22	*	*	*	*	*	*	22	20
4:00	*	*	*	*	25	18	41	32	*	*	*	*	*	*	33	25
5:00	*	*	*	*	22	13	29	22	*	*	*	*	*	*	26	18
6:00	*	*	*	*	20	19	16	22	*	*	*	*	*	*	18	20
7:00	*	*	*	*	18	17	11	15	*	*	*	*	*	*	14	16
8:00	*	*	*	*	4	8	7	6	*	*	*	*	*	*	6	7
9:00	*	*	*	*	4	1	5	5	*	*	*	*	*	*	4	3
10:00	*	*	*	*	2	2	3	0	*	*	*	*	*	*	2	1
11:00	*	*	*	*	3	1	2	1	*	*	*	*	*	*	2	1
Total	0	0	0	0	252	245	281	257	0	0	0	0	0	0	264	251
Day	0		0		497		538		0		0		0		515	
AM Peak					8:00	8:00	10:00	9:00							8:00	8:00
Volume					23	23	19	19							18	20
PM Peak					4:00	12:00 PM	4:00	4:00							4:00	4:00
Volume					25	21	41	32							33	25
Comb Total	0		0		497		538		0		0		0		515	
ADT	ADT: 518		AADT: 518													



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.090800
Longitude: -106.600270

File Name: Mackland Ave Counter #4
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Mackland Ave Counter
#4

Station ID:
Location 1:
Location 2:
Latitude: 35.090800
Longitude: -106.600270
Direction: A to B, EB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	1	0	1	0	0	0	0	0	0	0	0	0	2
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
5:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00	0	4	0	0	0	0	0	0	0	0	0	0	0	4
7:00	1	5	6	0	0	0	0	0	0	0	0	0	0	12
8:00	1	12	10	0	0	0	0	0	0	0	0	0	0	23
9:00	4	4	5	1	0	0	0	0	0	0	0	0	0	14
10:00	1	3	8	0	0	0	0	0	0	0	0	0	0	12
11:00	0	8	8	1	0	0	0	0	0	0	0	0	0	17
12:00 PM	2	9	7	5	0	0	0	0	0	0	0	0	0	23
1:00	0	6	11	1	0	0	0	0	0	0	0	0	0	18
2:00	1	4	5	2	0	0	0	0	0	0	0	0	0	12
3:00	1	6	8	1	0	0	0	0	0	0	0	0	0	16
4:00	1	7	15	2	0	0	0	0	0	0	0	0	0	25
5:00	2	10	9	1	0	0	0	0	0	0	0	0	0	22
6:00	0	9	9	2	0	0	0	0	0	0	0	0	0	20
7:00	3	10	5	0	0	0	0	0	0	0	0	0	0	18
8:00	1	1	2	0	0	0	0	0	0	0	0	0	0	4
9:00	0	3	0	1	0	0	0	0	0	0	0	0	0	4
10:00	0	1	1	0	0	0	0	0	0	0	0	0	0	2
11:00	1	1	1	0	0	0	0	0	0	0	0	0	0	3
Total	19	104	111	18	0	0	0	0	0	0	0	0	0	252



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Mackland Ave Counter

#4

Station ID:
Location 1:
Location 2:
Latitude: 35.090800
Longitude: -106.600270
Direction: A to B, EB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	2	0	0	0	0	0	0	0	0	0	0	0	2
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
6:00	0	1	2	0	0	0	0	0	0	0	0	0	0	3
7:00	2	3	4	0	0	0	0	0	0	0	0	0	0	9
8:00	0	8	5	1	0	0	0	0	0	0	0	0	0	14
9:00	1	7	7	2	0	0	0	0	0	0	0	0	0	17
10:00	1	6	12	0	0	0	0	0	0	0	0	0	0	19
11:00	0	4	6	2	0	0	0	0	0	0	0	0	0	12
12:00 PM	1	3	8	2	0	0	0	0	0	0	0	0	0	14
1:00	0	10	8	0	0	0	0	0	0	0	0	0	0	18
2:00	1	11	16	2	0	0	0	0	0	0	0	0	0	30
3:00	2	11	12	2	0	0	0	0	0	0	0	0	0	27
4:00	3	18	19	1	0	0	0	0	0	0	0	0	0	41
5:00	4	8	15	2	0	0	0	0	0	0	0	0	0	29
6:00	2	10	4	0	0	0	0	0	0	0	0	0	0	16
7:00	0	3	8	0	0	0	0	0	0	0	0	0	0	11
8:00	1	1	4	1	0	0	0	0	0	0	0	0	0	7
9:00	0	3	1	1	0	0	0	0	0	0	0	0	0	5
10:00	0	1	1	1	0	0	0	0	0	0	0	0	0	3
11:00	0	0	2	0	0	0	0	0	0	0	0	0	0	2
Total	18	111	135	17	0	0	0	0	0	0	0	0	0	281
Grand Total	37	215	246	35	0	0	0	0	0	0	0	0	0	533

Stats	Percentile	15th	50th	85th	95th
Speed	17	20	23	25	
Mean Speed (Average)	19.8				
10 MPH Pace Speed	15-24				
Number in Pace	456				
Percent in Pace	85.6%				
Number > 25 MPH	35				
Percent > 25 MPH	6.6%				



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Mackland Ave Counter
#4

Station ID:
Location 1:
Location 2:
Latitude: 35.090800
Longitude: -106.600270
Direction: B to A, WB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
6:00	1	2	1	0	0	0	0	0	0	0	0	0	0	4
7:00	0	8	5	1	0	0	0	0	0	0	0	0	0	14
8:00	0	12	10	1	0	0	0	0	0	0	0	0	0	23
9:00	4	7	4	1	0	0	0	0	0	0	0	0	0	16
10:00	1	8	3	2	0	0	0	0	0	0	0	0	0	14
11:00	1	7	7	2	0	0	0	0	0	0	0	0	0	17
12:00 PM	3	7	10	1	0	0	0	0	0	0	0	0	0	21
1:00	0	10	6	1	0	0	0	0	0	0	0	0	0	17
2:00	2	7	7	5	0	0	0	0	0	0	0	0	0	21
3:00	2	3	11	0	0	1	0	0	0	0	0	0	0	17
4:00	0	7	10	1	0	0	0	0	0	0	0	0	0	18
5:00	0	2	11	0	0	0	0	0	0	0	0	0	0	13
6:00	0	11	8	0	0	0	0	0	0	0	0	0	0	19
7:00	5	7	5	0	0	0	0	0	0	0	0	0	0	17
8:00	0	3	5	0	0	0	0	0	0	0	0	0	0	8
9:00	0	0	0	0	1	0	0	0	0	0	0	0	0	1
10:00	0	0	2	0	0	0	0	0	0	0	0	0	0	2
11:00	1	0	0	0	0	0	0	0	0	0	0	0	0	1
Total	20	103	105	15	1	1	0	0	0	0	0	0	0	245



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Mackland Ave Counter

#4

Station ID:
Location 1:
Location 2:
Latitude: 35.090800
Longitude: -106.600270
Direction: B to A, WB

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
1:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
5:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
6:00	0	2	1	1	0	0	0	0	0	0	0	0	0	4
7:00	0	3	8	0	0	0	0	0	0	0	0	0	0	11
8:00	0	6	8	2	0	0	0	0	0	0	0	0	0	16
9:00	0	11	7	1	0	0	0	0	0	0	0	0	0	19
10:00	0	3	11	0	0	0	0	0	0	0	0	0	0	14
11:00	1	5	10	2	0	0	0	0	0	0	0	0	0	18
12:00 PM	0	12	9	2	0	0	0	0	0	0	0	0	0	23
1:00	0	4	4	1	0	0	0	0	0	0	0	0	0	9
2:00	1	7	6	0	0	0	0	0	0	0	0	0	0	14
3:00	2	12	7	1	0	0	0	0	0	0	0	0	0	22
4:00	1	17	14	0	0	0	0	0	0	0	0	0	0	32
5:00	2	9	11	0	0	0	0	0	0	0	0	0	0	22
6:00	2	10	9	1	0	0	0	0	0	0	0	0	0	22
7:00	1	5	9	0	0	0	0	0	0	0	0	0	0	15
8:00	0	6	0	0	0	0	0	0	0	0	0	0	0	6
9:00	1	3	1	0	0	0	0	0	0	0	0	0	0	5
10:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
Total	11	119	116	11	0	0	0	0	0	0	0	0	0	257
Grand Total	31	222	221	26	1	1	0	0	0	0	0	0	0	502

Stats	Percentile	15th	50th	85th	95th
Speed	17	20	23	25	
Mean Speed (Average)	19.7				
10 MPH Pace Speed	15-24				
Number in Pace	439				
Percent in Pace	87.5%				
Number > 25 MPH	28				
Percent > 25 MPH	5.6%				



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Mackland Ave Counter
#4

Station ID:
Location 1:
Location 2:
Latitude: 35.090800
Longitude: -106.600270

Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator

Location

Mackland Ave Counter #4


Analysis Dates

Start: 9/21/2022

End: 9/21/2022


Total Percentage of Enforceable Violations

Posted Speed Limit 25 MPH
Enforcement Tolerance 5 MPH
Enforcement Limit Greater than 30 MPH



Percent Speeding: 0%

Rating: Low



Percent Speeding: 0%

Rating: Low



Percent Speeding: 1%

Rating: Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
39	207	216	33	1	1	0	0	0	0	0	0	0

85th Percentile: 23.2

Vehicle Totals - A to B, EB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
19	104	111	18	0	0	0	0	0	0	0	0	0

85th Percentile: 22.9

Vehicle Totals - B to A, WB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
20	103	105	15	1	1	0	0	0	0	0	0	0

85th Percentile: 23.4



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator

Location

Mackland Ave Counter #4


Total Percentage of Enforceable Violations

Analysis Dates

Start: 9/21/2022


End: 9/21/2022

Posted Speed Limit 25 MPH
Enforcement Tolerance 7 MPH
Enforcement Limit Greater than 32 MPH




Percent Speeding: 0%

Rating: Low



Percent Speeding: 0%

Rating: Low



Percent Speeding: 0%

Rating: Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
39	207	216	33	1	1	0	0	0	0	0	0	0

85th Percentile: 23.2

Vehicle Totals - A to B, EB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
19	104	111	18	0	0	0	0	0	0	0	0	0

85th Percentile: 22.9

Vehicle Totals - B to A, WB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
20	103	105	15	1	1	0	0	0	0	0	0	0

85th Percentile: 23.4



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator

Location

Mackland Ave Counter #4


Total Percentage of Enforceable Violations

Analysis Dates

Start: 9/22/2022


End: 9/22/2022

Posted Speed Limit 25 MPH
Enforcement Tolerance 7 MPH
Enforcement Limit Greater than 32 MPH




Percent Speeding: 0%

Rating: Low



Percent Speeding: 0%

Rating: Low



Percent Speeding: 0%

Rating: Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
29	230	251	28	0	0	0	0	0	0	0	0	0

85th Percentile: 23

Vehicle Totals - A to B, EB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
18	111	135	17	0	0	0	0	0	0	0	0	0

85th Percentile: 23.3

Vehicle Totals - B to A, WB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
11	119	116	11	0	0	0	0	0	0	0	0	0

85th Percentile: 22.8



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Montclair Dr Counter #1

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.088916
Longitude: -106.599602

9/19/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB
12:00 AM	*	*	*	*	3	1	0	1	*	*	*	*	*	*	2	1
1:00	*	*	*	*	0	1	1	1	*	*	*	*	*	*	0	1
2:00	*	*	*	*	0	0	0	0	*	*	*	*	*	*	0	0
3:00	*	*	*	*	0	0	0	1	*	*	*	*	*	*	0	0
4:00	*	*	*	*	0	1	0	1	*	*	*	*	*	*	0	1
5:00	*	*	*	*	1	3	3	3	*	*	*	*	*	*	2	3
6:00	*	*	*	*	2	8	1	3	*	*	*	*	*	*	2	6
7:00	*	*	*	*	14	15	15	16	*	*	*	*	*	*	14	16
8:00	*	*	*	*	20	28	12	24	*	*	*	*	*	*	16	26
9:00	*	*	*	*	15	15	18	19	*	*	*	*	*	*	16	17
10:00	*	*	*	*	10	20	12	18	*	*	*	*	*	*	11	19
11:00	*	*	*	*	13	16	10	13	*	*	*	*	*	*	12	14
12:00 PM	*	*	*	*	20	25	12	19	*	*	*	*	*	*	16	22
1:00	*	*	*	*	13	17	20	18	*	*	*	*	*	*	16	18
2:00	*	*	*	*	16	20	26	17	*	*	*	*	*	*	21	18
3:00	*	*	*	*	15	16	21	16	*	*	*	*	*	*	18	16
4:00	*	*	*	*	25	22	30	22	*	*	*	*	*	*	28	22
5:00	*	*	*	*	19	16	34	27	*	*	*	*	*	*	26	22
6:00	*	*	*	*	24	14	11	16	*	*	*	*	*	*	18	15
7:00	*	*	*	*	11	17	13	17	*	*	*	*	*	*	12	17
8:00	*	*	*	*	7	8	8	11	*	*	*	*	*	*	8	10
9:00	*	*	*	*	5	5	5	4	*	*	*	*	*	*	5	4
10:00	*	*	*	*	2	5	2	5	*	*	*	*	*	*	2	5
11:00	*	*	*	*	4	1	2	2	*	*	*	*	*	*	3	2
Total	0	0	0	0	239	274	256	274	0	0	0	0	0	0	248	275
Day	0		0		513		530		0		0		0		523	
AM Peak					8:00	8:00	9:00	8:00							8:00	8:00
Volume					20	28	18	24							16	26
PM Peak					4:00	12:00 PM	5:00	5:00							4:00	12:00 PM
Volume					25	25	34	27							28	22
Comb Total	0		0		513		530		0		0		0		523	
ADT	ADT: 522		AADT: 522													




Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.088916
Longitude: -106.599602

File Name: Montclair Dr Counter #1
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.088916
Longitude: -106.599602
Direction: A to B, NB

File Name: Montclair Dr Counter #1
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	1	1	1	0	0	0	0	0	0	0	0	3
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
6:00	0	0	1	1	0	0	0	0	0	0	0	0	0	2
7:00	0	4	5	3	1	1	0	0	0	0	0	0	0	14
8:00	1	1	10	7	1	0	0	0	0	0	0	0	0	20
9:00	0	2	6	6	1	0	0	0	0	0	0	0	0	15
10:00	0	1	2	6	1	0	0	0	0	0	0	0	0	10
11:00	0	2	4	4	2	1	0	0	0	0	0	0	0	13
12:00 PM	2	4	3	6	5	0	0	0	0	0	0	0	0	20
1:00	2	0	3	5	2	1	0	0	0	0	0	0	0	13
2:00	0	0	8	7	1	0	0	0	0	0	0	0	0	16
3:00	0	1	6	5	3	0	0	0	0	0	0	0	0	15
4:00	0	5	8	8	3	1	0	0	0	0	0	0	0	25
5:00	0	3	7	8	1	0	0	0	0	0	0	0	0	19
6:00	2	3	12	4	3	0	0	0	0	0	0	0	0	24
7:00	0	1	7	3	0	0	0	0	0	0	0	0	0	11
8:00	1	2	2	2	0	0	0	0	0	0	0	0	0	7
9:00	2	0	2	1	0	0	0	0	0	0	0	0	0	5
10:00	1	0	1	0	0	0	0	0	0	0	0	0	0	2
11:00	0	1	0	2	1	0	0	0	0	0	0	0	0	4
Total	11	31	88	79	26	4	0	0	0	0	0	0	0	239



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Montclair Dr Counter #1

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.088916
Longitude: -106.599602
Direction: A to B, NB

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	2	1	0	0	0	0	0	0	0	0	0	0	3
6:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
7:00	2	4	7	2	0	0	0	0	0	0	0	0	0	15
8:00	1	4	2	5	0	0	0	0	0	0	0	0	0	12
9:00	0	6	4	6	2	0	0	0	0	0	0	0	0	18
10:00	1	2	3	6	0	0	0	0	0	0	0	0	0	12
11:00	0	1	3	5	0	0	1	0	0	0	0	0	0	10
12:00 PM	0	3	4	3	2	0	0	0	0	0	0	0	0	12
1:00	0	3	9	7	0	1	0	0	0	0	0	0	0	20
2:00	1	4	7	12	2	0	0	0	0	0	0	0	0	26
3:00	2	3	9	6	1	0	0	0	0	0	0	0	0	21
4:00	3	2	15	8	2	0	0	0	0	0	0	0	0	30
5:00	3	8	10	11	1	1	0	0	0	0	0	0	0	34
6:00	0	2	4	3	2	0	0	0	0	0	0	0	0	11
7:00	0	0	7	6	0	0	0	0	0	0	0	0	0	13
8:00	0	1	4	3	0	0	0	0	0	0	0	0	0	8
9:00	0	1	2	2	0	0	0	0	0	0	0	0	0	5
10:00	0	0	1	1	0	0	0	0	0	0	0	0	0	2
11:00	0	0	1	1	0	0	0	0	0	0	0	0	0	2
Total	13	46	95	87	12	2	1	0	0	0	0	0	0	256
Grand Total	24	77	183	166	38	6	1	0	0	0	0	0	0	495
Stats														
	Percentile			15th	50th	85th	95th							
	Speed			19	24	29	32							
	Mean Speed (Average)			23.7										
	10 MPH Pace Speed			20-29										
	Number in Pace			347										
	Percent in Pace			70.1%										
	Number > 25 MPH			211										
	Percent > 25 MPH			42.6%										



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Montclair Dr Counter #1

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.088916
Longitude: -106.599602
Direction: B to A, SB

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	1	0	0	0	0	0	0	0	0	0	1
1:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	1	0	0	0	0	0	0	0	0	1
5:00	0	1	2	0	0	0	0	0	0	0	0	0	0	3
6:00	1	0	4	3	0	0	0	0	0	0	0	0	0	8
7:00	0	1	7	5	2	0	0	0	0	0	0	0	0	15
8:00	1	2	8	13	3	1	0	0	0	0	0	0	0	28
9:00	1	2	8	2	2	0	0	0	0	0	0	0	0	15
10:00	3	4	6	5	1	1	0	0	0	0	0	0	0	20
11:00	0	4	4	6	1	1	0	0	0	0	0	0	0	16
12:00 PM	1	3	9	9	3	0	0	0	0	0	0	0	0	25
1:00	2	1	8	2	3	1	0	0	0	0	0	0	0	17
2:00	0	1	5	10	3	1	0	0	0	0	0	0	0	20
3:00	2	2	4	5	3	0	0	0	0	0	0	0	0	16
4:00	0	3	3	11	4	1	0	0	0	0	0	0	0	22
5:00	1	1	6	5	3	0	0	0	0	0	0	0	0	16
6:00	2	2	6	4	0	0	0	0	0	0	0	0	0	14
7:00	1	7	6	3	0	0	0	0	0	0	0	0	0	17
8:00	1	0	3	4	0	0	0	0	0	0	0	0	0	8
9:00	1	1	0	3	0	0	0	0	0	0	0	0	0	5
10:00	1	1	0	3	0	0	0	0	0	0	0	0	0	5
11:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Total	18	36	90	95	29	6	0	0	0	0	0	0	0	274



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Montclair Dr Counter #1

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.088916
Longitude: -106.599602
Direction: B to A, SB

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	0	1	0	0	0	0	0	0	0	0	1
1:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
4:00	0	0	0	0	0	1	0	0	0	0	0	0	0	1
5:00	0	2	0	1	0	0	0	0	0	0	0	0	0	3
6:00	0	0	2	0	1	0	0	0	0	0	0	0	0	3
7:00	1	2	5	5	2	1	0	0	0	0	0	0	0	16
8:00	0	2	9	8	4	1	0	0	0	0	0	0	0	24
9:00	2	1	7	5	4	0	0	0	0	0	0	0	0	19
10:00	2	3	4	7	1	1	0	0	0	0	0	0	0	18
11:00	0	2	2	4	4	1	0	0	0	0	0	0	0	13
12:00 PM	1	1	7	7	2	0	1	0	0	0	0	0	0	19
1:00	0	2	5	4	7	0	0	0	0	0	0	0	0	18
2:00	1	3	5	7	0	1	0	0	0	0	0	0	0	17
3:00	0	6	4	2	4	0	0	0	0	0	0	0	0	16
4:00	0	3	10	8	1	0	0	0	0	0	0	0	0	22
5:00	2	3	13	5	3	1	0	0	0	0	0	0	0	27
6:00	1	2	8	4	1	0	0	0	0	0	0	0	0	16
7:00	0	4	9	4	0	0	0	0	0	0	0	0	0	17
8:00	1	1	5	4	0	0	0	0	0	0	0	0	0	11
9:00	0	1	2	1	0	0	0	0	0	0	0	0	0	4
10:00	2	0	2	1	0	0	0	0	0	0	0	0	0	5
11:00	0	0	2	0	0	0	0	0	0	0	0	0	0	2
Total	13	39	102	77	35	7	1	0	0	0	0	0	0	274
Grand Total	31	75	192	172	64	13	1	0	0	0	0	0	0	548

Stats	Percentile	15th	50th	85th	95th
	Speed	19	24	30	32
Mean Speed (Average)		24.1			
10 MPH Pace Speed		20-29			
Number in Pace		362			
Percent in Pace		66.1%			
Number > 25 MPH		250			
Percent > 25 MPH		45.6%			




Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.088916
Longitude: -106.599602

File Name: Montclair Dr Counter #1
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No



85th Percentile: 29.9



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator

Location

Montclair Dr Counter #1


Total Percentage of Enforceable Violations

Analysis Dates

Start: 9/21/2022


End: 9/21/2022

Posted Speed Limit 25 MPH
Enforcement Tolerance 7 MPH
Enforcement Limit Greater than 32 MPH




Percent Speeding: 6%

Rating: Low



Percent Speeding: 5%

Rating: Low



Percent Speeding: 6%

Rating: Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
29	67	178	174	55	10	0	0	0	0	0	0	0

85th Percentile: 29.4

Vehicle Totals - A to B, NB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
11	31	88	79	26	4	0	0	0	0	0	0	0

85th Percentile: 29

Vehicle Totals - B to A, SB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
18	36	90	95	29	6	0	0	0	0	0	0	0

85th Percentile: 29.5



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Montclair Dr Counter #2

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.089655
Longitude: -106.600321

9/19/2022	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB	A to B, NB	B to A, SB
12:00 AM	*	*	*	*	3	1	0	2	*	*	*	*	*	*	2	2
1:00	*	*	*	*	0	1	1	1	*	*	*	*	*	*	0	1
2:00	*	*	*	*	0	0	0	0	*	*	*	*	*	*	0	0
3:00	*	*	*	*	0	0	0	1	*	*	*	*	*	*	0	0
4:00	*	*	*	*	0	1	0	1	*	*	*	*	*	*	0	1
5:00	*	*	*	*	3	2	4	2	*	*	*	*	*	*	4	2
6:00	*	*	*	*	5	8	3	3	*	*	*	*	*	*	4	6
7:00	*	*	*	*	15	14	16	16	*	*	*	*	*	*	16	15
8:00	*	*	*	*	21	27	11	22	*	*	*	*	*	*	16	24
9:00	*	*	*	*	16	14	18	19	*	*	*	*	*	*	17	16
10:00	*	*	*	*	10	18	13	17	*	*	*	*	*	*	12	18
11:00	*	*	*	*	13	17	11	15	*	*	*	*	*	*	12	16
12:00 PM	*	*	*	*	21	26	11	19	*	*	*	*	*	*	16	22
1:00	*	*	*	*	13	15	18	17	*	*	*	*	*	*	16	16
2:00	*	*	*	*	11	20	24	14	*	*	*	*	*	*	18	17
3:00	*	*	*	*	15	17	20	20	*	*	*	*	*	*	18	18
4:00	*	*	*	*	27	24	28	22	*	*	*	*	*	*	28	23
5:00	*	*	*	*	21	17	33	25	*	*	*	*	*	*	27	21
6:00	*	*	*	*	21	15	12	16	*	*	*	*	*	*	16	16
7:00	*	*	*	*	11	17	12	18	*	*	*	*	*	*	12	18
8:00	*	*	*	*	10	11	8	11	*	*	*	*	*	*	9	11
9:00	*	*	*	*	5	6	4	5	*	*	*	*	*	*	4	6
10:00	*	*	*	*	1	6	2	4	*	*	*	*	*	*	2	5
11:00	*	*	*	*	4	1	2	2	*	*	*	*	*	*	3	2
Total	0	0	0	0	246	278	251	272	0	0	0	0	0	0	252	276
Day	0		0		524		523		0		0		0		528	
AM Peak					8:00	8:00	9:00	8:00							9:00	8:00
Volume					21	27	18	22							17	24
PM Peak					4:00	12:00 PM	5:00	5:00							4:00	4:00
Volume					27	26	33	25							28	23
Comb Total	0		0		524		523		0		0		0		528	
ADT	ADT: 524		AADT: 524													




Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.089655
Longitude: -106.600321

File Name: Montclair Dr Counter #2
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Montclair Dr Counter #2

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.089655
Longitude: -106.600321
Direction: A to B, NB

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	1	1	1	0	0	0	0	0	0	0	0	3
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	1	0	2	0	0	0	0	0	0	0	0	0	0	3
6:00	0	2	2	1	0	0	0	0	0	0	0	0	0	5
7:00	0	4	5	4	1	1	0	0	0	0	0	0	0	15
8:00	2	0	10	7	2	0	0	0	0	0	0	0	0	21
9:00	0	1	5	10	0	0	0	0	0	0	0	0	0	16
10:00	0	2	2	5	1	0	0	0	0	0	0	0	0	10
11:00	1	1	4	4	2	1	0	0	0	0	0	0	0	13
12:00 PM	2	2	5	7	4	1	0	0	0	0	0	0	0	21
1:00	0	2	5	5	0	1	0	0	0	0	0	0	0	13
2:00	0	1	4	4	2	0	0	0	0	0	0	0	0	11
3:00	0	1	4	7	3	0	0	0	0	0	0	0	0	15
4:00	0	6	2	11	6	1	1	0	0	0	0	0	0	27
5:00	1	0	4	13	3	0	0	0	0	0	0	0	0	21
6:00	0	1	10	9	1	0	0	0	0	0	0	0	0	21
7:00	1	1	7	2	0	0	0	0	0	0	0	0	0	11
8:00	0	2	5	3	0	0	0	0	0	0	0	0	0	10
9:00	0	1	2	2	0	0	0	0	0	0	0	0	0	5
10:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
11:00	0	0	0	1	3	0	0	0	0	0	0	0	0	4
Total	8	27	80	96	29	5	1	0	0	0	0	0	0	246



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Montclair Dr Counter #2

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.089655
Longitude: -106.600321
Direction: A to B, NB

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	0	3	1	0	0	0	0	0	0	0	0	0	4
6:00	1	1	1	0	0	0	0	0	0	0	0	0	0	3
7:00	0	5	8	3	0	0	0	0	0	0	0	0	0	16
8:00	0	1	5	3	2	0	0	0	0	0	0	0	0	11
9:00	0	2	6	5	5	0	0	0	0	0	0	0	0	18
10:00	0	1	4	6	2	0	0	0	0	0	0	0	0	13
11:00	0	1	4	5	0	0	0	1	0	0	0	0	0	11
12:00 PM	0	1	4	4	2	0	0	0	0	0	0	0	0	11
1:00	0	1	5	6	6	0	0	0	0	0	0	0	0	18
2:00	1	3	8	10	1	1	0	0	0	0	0	0	0	24
3:00	2	2	9	5	1	1	0	0	0	0	0	0	0	20
4:00	1	3	13	10	1	0	0	0	0	0	0	0	0	28
5:00	1	6	10	13	2	1	0	0	0	0	0	0	0	33
6:00	1	1	3	3	3	1	0	0	0	0	0	0	0	12
7:00	0	1	4	6	1	0	0	0	0	0	0	0	0	12
8:00	0	0	5	3	0	0	0	0	0	0	0	0	0	8
9:00	0	0	3	1	0	0	0	0	0	0	0	0	0	4
10:00	0	1	1	0	0	0	0	0	0	0	0	0	0	2
11:00	0	0	1	1	0	0	0	0	0	0	0	0	0	2
Total	7	30	98	85	26	4	0	1	0	0	0	0	0	251
Grand Total	15	57	178	181	55	9	1	1	0	0	0	0	0	497
Stats														
	Percentile			15th	50th	85th	95th							
	Speed			20	25	30	33							
	Mean Speed (Average)			24.8										
	10 MPH Pace Speed			20-29										
	Number in Pace			357										
	Percent in Pace			71.8%										
	Number > 25 MPH			247										
	Percent > 25 MPH			49.7%										



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.089655
Longitude: -106.600321
Direction: B to A, SB

File Name: Montclair Dr Counter #2
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No

9/21/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	1	0	0	0	0	0	0	0	0	0	1
1:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	1	0	0	0	0	0	0	0	0	1
5:00	0	0	2	0	0	0	0	0	0	0	0	0	0	2
6:00	1	2	4	1	0	0	0	0	0	0	0	0	0	8
7:00	0	3	4	6	1	0	0	0	0	0	0	0	0	14
8:00	0	1	11	12	3	0	0	0	0	0	0	0	0	27
9:00	1	2	7	2	2	0	0	0	0	0	0	0	0	14
10:00	1	2	9	4	2	0	0	0	0	0	0	0	0	18
11:00	1	5	4	6	1	0	0	0	0	0	0	0	0	17
12:00 PM	0	8	6	10	2	0	0	0	0	0	0	0	0	26
1:00	0	1	6	6	2	0	0	0	0	0	0	0	0	15
2:00	1	3	3	10	2	1	0	0	0	0	0	0	0	20
3:00	1	4	5	7	0	0	0	0	0	0	0	0	0	17
4:00	0	0	9	12	2	1	0	0	0	0	0	0	0	24
5:00	0	2	4	8	3	0	0	0	0	0	0	0	0	17
6:00	0	3	7	4	0	1	0	0	0	0	0	0	0	15
7:00	0	6	6	4	1	0	0	0	0	0	0	0	0	17
8:00	0	3	6	2	0	0	0	0	0	0	0	0	0	11
9:00	0	2	3	1	0	0	0	0	0	0	0	0	0	6
10:00	0	1	2	3	0	0	0	0	0	0	0	0	0	6
11:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Total	6	48	99	100	22	3	0	0	0	0	0	0	0	278



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

File Name: Montclair Dr Counter #2

Date Printed: 9/26/2022

Start Date: 9/21/2022

End Date: 9/22/2022

GPS Accuracy: 0 ft

Location Verified: No

Station ID:
Location 1:
Location 2:
Latitude: 35.089655
Longitude: -106.600321
Direction: B to A, SB

9/22/2022	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	1	0	1	0	0	0	0	0	0	0	0	2
1:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
4:00	0	0	0	0	1	0	0	0	0	0	0	0	0	1
5:00	1	0	0	1	0	0	0	0	0	0	0	0	0	2
6:00	0	0	1	1	1	0	0	0	0	0	0	0	0	3
7:00	0	4	3	7	2	0	0	0	0	0	0	0	0	16
8:00	0	3	8	9	1	1	0	0	0	0	0	0	0	22
9:00	0	1	6	9	3	0	0	0	0	0	0	0	0	19
10:00	0	4	5	6	2	0	0	0	0	0	0	0	0	17
11:00	0	0	8	5	2	0	0	0	0	0	0	0	0	15
12:00 PM	0	3	7	7	1	0	1	0	0	0	0	0	0	19
1:00	0	1	7	6	3	0	0	0	0	0	0	0	0	17
2:00	0	0	9	4	1	0	0	0	0	0	0	0	0	14
3:00	2	5	5	4	4	0	0	0	0	0	0	0	0	20
4:00	1	3	10	8	0	0	0	0	0	0	0	0	0	22
5:00	0	3	12	7	3	0	0	0	0	0	0	0	0	25
6:00	0	1	9	6	0	0	0	0	0	0	0	0	0	16
7:00	1	5	8	3	1	0	0	0	0	0	0	0	0	18
8:00	0	1	6	4	0	0	0	0	0	0	0	0	0	11
9:00	0	2	2	0	1	0	0	0	0	0	0	0	0	5
10:00	0	0	2	2	0	0	0	0	0	0	0	0	0	4
11:00	0	0	2	0	0	0	0	0	0	0	0	0	0	2
Total	5	37	112	89	27	1	1	0	0	0	0	0	0	272
Grand Total	11	85	211	189	49	4	1	0	0	0	0	0	0	550
Stats														
	Percentile			15th	50th	85th	95th							
	Speed			20	24	29	32							
	Mean Speed (Average)			24.2										
	10 MPH Pace Speed			20-29										
	Number in Pace			398										
	Percent in Pace			72.4%										
	Number > 25 MPH			243										
	Percent > 25 MPH			44.2%										




Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Station ID:
Location 1:
Location 2:
Latitude: 35.089655
Longitude: -106.600321

File Name: Montclair Dr Counter #2
Date Printed: 9/26/2022
Start Date: 9/21/2022
End Date: 9/22/2022
GPS Accuracy: 0 ft
Location Verified: No





Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator

Location

Montclair Dr Counter #2


Total Percentage of Enforceable Violations

Analysis Dates

Start: 9/21/2022


End: 9/21/2022

Posted Speed Limit 25 MPH
Enforcement Tolerance 7 MPH
Enforcement Limit Greater than 32 MPH



Percent Speeding: 6%

Rating: Low



Percent Speeding: 8%

Rating: Low



Percent Speeding: 4%

Rating: Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
14	75	179	196	51	8	1	0	0	0	0	0	0

85th Percentile: 29.3

Vehicle Totals - A to B, NB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
8	27	80	96	29	5	1	0	0	0	0	0	0

85th Percentile: 29.8

Vehicle Totals - B to A, SB

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
6	48	99	100	22	3	0	0	0	0	0	0	0

85th Percentile: 28.8

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO1
Station ID:
Location 1:
Location 2:
Latitude: 35.097237
Longitude: -106.602213

File Name: untitled_0
Date Printed: 5/19/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No


5/15/2023	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB
12:00 AM	*	*	0	1	2	3	*	*	*	*	*	*	*	*	1	2
1:00	*	*	0	0	2	0	*	*	*	*	*	*	*	*	1	0
2:00	*	*	0	0	1	0	*	*	*	*	*	*	*	*	0	0
3:00	*	*	0	0	0	0	*	*	*	*	*	*	*	*	0	0
4:00	*	*	0	0	1	1	*	*	*	*	*	*	*	*	0	0
5:00	*	*	2	1	0	0	*	*	*	*	*	*	*	*	1	0
6:00	*	*	1	2	3	4	*	*	*	*	*	*	*	*	2	3
7:00	*	*	10	15	7	6	*	*	*	*	*	*	*	*	8	10
8:00	*	*	15	19	18	19	*	*	*	*	*	*	*	*	16	19
9:00	*	*	12	9	9	17	*	*	*	*	*	*	*	*	10	13
10:00	*	*	5	12	11	13	*	*	*	*	*	*	*	*	8	12
11:00	*	*	10	13	12	12	*	*	*	*	*	*	*	*	11	12
12:00 PM	*	*	7	5	18	16	*	*	*	*	*	*	*	*	12	10
1:00	*	*	12	7	16	14	*	*	*	*	*	*	*	*	14	10
2:00	*	*	15	11	7	12	*	*	*	*	*	*	*	*	11	12
3:00	*	*	17	16	12	15	*	*	*	*	*	*	*	*	14	16
4:00	*	*	13	17	17	10	*	*	*	*	*	*	*	*	15	14
5:00	*	*	18	14	16	15	*	*	*	*	*	*	*	*	17	14
6:00	*	*	6	13	13	18	*	*	*	*	*	*	*	*	10	16
7:00	*	*	7	8	9	6	*	*	*	*	*	*	*	*	8	7
8:00	*	*	6	5	2	8	*	*	*	*	*	*	*	*	4	6
9:00	*	*	2	9	1	4	*	*	*	*	*	*	*	*	2	6
10:00	*	*	1	4	3	4	*	*	*	*	*	*	*	*	2	4
11:00	*	*	3	1	2	1	*	*	*	*	*	*	*	*	2	1
Total	0	0	162	182	182	198	0	0	0	0	0	0	0	0	169	187
Day	0		344		380		0		0		0		0		356	
AM Peak			8:00	8:00	8:00	8:00									8:00	8:00
Volume			15	19	18	19									16	19
PM Peak			5:00	4:00	12:00 PM	6:00									5:00	3:00
Volume			18	17	18	18									17	16
Comb Total	0		344		380		0		0		0		0		356	
ADT		ADT: 362		AADT: 362												

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO1
Station ID:
Location 1:
Location 2:
Latitude: 35.097237
Longitude: -106.602213

File Name: untitled_0
Date Printed: 5/19/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No



Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO1
Station ID:
Location 1:
Location 2:
Latitude: 35.097237
Longitude: -106.602213
Direction: A to B, SB

File Name: untitled_0
Date Printed: 5/19/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No

5/16/2023	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	1	0	1	0	0	0	0	0	0	0	0	0	0	2
6:00	0	0	0	0	1	0	0	0	0	0	0	0	0	1
7:00	1	0	2	3	3	1	0	0	0	0	0	0	0	10
8:00	1	0	2	7	3	2	0	0	0	0	0	0	0	15
9:00	0	2	4	5	0	0	0	1	0	0	0	0	0	12
10:00	1	1	0	3	0	0	0	0	0	0	0	0	0	5
11:00	0	1	3	5	1	0	0	0	0	0	0	0	0	10
12:00 PM	2	1	2	2	0	0	0	0	0	0	0	0	0	7
1:00	2	1	4	3	2	0	0	0	0	0	0	0	0	12
2:00	2	4	1	4	4	0	0	0	0	0	0	0	0	15
3:00	1	2	4	7	3	0	0	0	0	0	0	0	0	17
4:00	1	0	5	3	4	0	0	0	0	0	0	0	0	13
5:00	1	0	4	8	2	3	0	0	0	0	0	0	0	18
6:00	0	2	2	0	2	0	0	0	0	0	0	0	0	6
7:00	2	1	1	1	2	0	0	0	0	0	0	0	0	7
8:00	1	3	2	0	0	0	0	0	0	0	0	0	0	6
9:00	0	0	1	1	0	0	0	0	0	0	0	0	0	2
10:00	0	0	0	1	0	0	0	0	0	0	0	0	0	1
11:00	0	1	0	2	0	0	0	0	0	0	0	0	0	3
Total	16	19	38	55	27	6	0	1	0	0	0	0	0	162

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO1
Station ID:
Location 1:
Location 2:
Latitude: 35.097237
Longitude: -106.602213
Direction: A to B, SB

File Name: untitled_0
Date Printed: 5/19/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No

5/17/2023	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	2	0	0	0	0	0	0	0	0	0	2
1:00	2	0	0	0	0	0	0	0	0	0	0	0	0	2
2:00	0	0	0	0	0	0	0	1	0	0	0	0	0	1
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
5:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00	0	1	0	1	0	1	0	0	0	0	0	0	0	3
7:00	1	0	1	4	1	0	0	0	0	0	0	0	0	7
8:00	4	2	5	4	2	1	0	0	0	0	0	0	0	18
9:00	0	0	2	2	3	1	1	0	0	0	0	0	0	9
10:00	0	1	5	3	2	0	0	0	0	0	0	0	0	11
11:00	0	1	4	5	2	0	0	0	0	0	0	0	0	12
12:00 PM	5	2	4	6	1	0	0	0	0	0	0	0	0	18
1:00	2	5	3	4	1	1	0	0	0	0	0	0	0	16
2:00	0	0	3	3	1	0	0	0	0	0	0	0	0	7
3:00	1	2	5	1	3	0	0	0	0	0	0	0	0	12
4:00	1	1	8	3	4	0	0	0	0	0	0	0	0	17
5:00	1	1	3	8	3	0	0	0	0	0	0	0	0	16
6:00	2	3	3	4	1	0	0	0	0	0	0	0	0	13
7:00	1	2	5	1	0	0	0	0	0	0	0	0	0	9
8:00	1	0	1	0	0	0	0	0	0	0	0	0	0	2
9:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
10:00	0	1	0	1	1	0	0	0	0	0	0	0	0	3
11:00	0	0	0	2	0	0	0	0	0	0	0	0	0	2
Total	21	23	53	54	25	4	1	1	0	0	0	0	0	182
Grand Total	37	42	91	109	52	10	1	2	0	0	0	0	0	344
Stats	Percentile		15th	50th	85th	95th								
	Speed		17	25	31	34								
	Mean Speed (Average)		24.1											
	10 MPH Pace Speed		20-29											
	Number in Pace		199											
	Percent in Pace		57.8%											
	Number > 25 MPH		174											
	Percent > 25 MPH		50.6%											

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO1
Station ID:
Location 1:
Location 2:
Latitude: 35.097237
Longitude: -106.602213
Direction: B to A, NB

File Name: untitled_0
Date Printed: 5/19/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No

5/16/2023	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	1	0	0	0	0	0	0	0	0	0	0	0	1
6:00	1	0	0	1	0	0	0	0	0	0	0	0	0	2
7:00	2	1	2	6	4	0	0	0	0	0	0	0	0	15
8:00	0	4	4	5	6	0	0	0	0	0	0	0	0	19
9:00	2	2	2	1	1	1	0	0	0	0	0	0	0	9
10:00	1	2	5	3	1	0	0	0	0	0	0	0	0	12
11:00	1	4	3	4	1	0	0	0	0	0	0	0	0	13
12:00 PM	0	1	2	1	1	0	0	0	0	0	0	0	0	5
1:00	1	0	2	4	0	0	0	0	0	0	0	0	0	7
2:00	2	2	5	1	0	1	0	0	0	0	0	0	0	11
3:00	1	2	3	5	4	1	0	0	0	0	0	0	0	16
4:00	2	3	4	6	2	0	0	0	0	0	0	0	0	17
5:00	1	3	2	5	2	1	0	0	0	0	0	0	0	14
6:00	2	1	2	5	3	0	0	0	0	0	0	0	0	13
7:00	2	2	1	1	2	0	0	0	0	0	0	0	0	8
8:00	0	1	2	1	1	0	0	0	0	0	0	0	0	5
9:00	0	0	6	2	1	0	0	0	0	0	0	0	0	9
10:00	0	0	3	1	0	0	0	0	0	0	0	0	0	4
11:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
Total	18	30	49	52	29	4	0	0	0	0	0	0	0	182

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO1
Station ID:
Location 1:
Location 2:
Latitude: 35.097237
Longitude: -106.602213
Direction: B to A, NB

File Name: untitled_0
Date Printed: 5/19/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No

[illegible]

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO1
Station ID:
Location 1:
Location 2:
Latitude: 35.097237
Longitude: -106.602213
Direction: Combined

File Name: untitled_0
Date Printed: 5/19/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No

5/16/2023	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	1	0	0	0	0	0	0	0	0	0	0	0	1
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	1	1	1	0	0	0	0	0	0	0	0	0	0	3
6:00	1	0	0	1	1	0	0	0	0	0	0	0	0	3
7:00	3	1	4	9	7	1	0	0	0	0	0	0	0	25
8:00	1	4	6	12	9	2	0	0	0	0	0	0	0	34
9:00	2	4	6	6	1	1	0	1	0	0	0	0	0	21
10:00	2	3	5	6	1	0	0	0	0	0	0	0	0	17
11:00	1	5	6	9	2	0	0	0	0	0	0	0	0	23
12:00 PM	2	2	4	3	1	0	0	0	0	0	0	0	0	12
1:00	3	1	6	7	2	0	0	0	0	0	0	0	0	19
2:00	4	6	6	5	4	1	0	0	0	0	0	0	0	26
3:00	2	4	7	12	7	1	0	0	0	0	0	0	0	33
4:00	3	3	9	9	6	0	0	0	0	0	0	0	0	30
5:00	2	3	6	13	4	4	0	0	0	0	0	0	0	32
6:00	2	3	4	5	5	0	0	0	0	0	0	0	0	19
7:00	4	3	2	2	4	0	0	0	0	0	0	0	0	15
8:00	1	4	4	1	1	0	0	0	0	0	0	0	0	11
9:00	0	0	7	3	1	0	0	0	0	0	0	0	0	11
10:00	0	0	3	2	0	0	0	0	0	0	0	0	0	5
11:00	0	1	1	2	0	0	0	0	0	0	0	0	0	4
Total	34	49	87	107	56	10	0	1	0	0	0	0	0	344

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO1
Station ID:
Location 1:
Location 2:
Latitude: 35.097237
Longitude: -106.602213
Direction: Combined

File Name: untitled_0
Date Printed: 5/19/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No


5/17/2023	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	1	3	1	0	0	0	0	0	0	0	0	5
1:00	2	0	0	0	0	0	0	0	0	0	0	0	0	2
2:00	0	0	0	0	0	0	0	1	0	0	0	0	0	1
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	1	1	0	0	0	0	0	0	0	0	0	0	2
5:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00	0	2	2	1	1	1	0	0	0	0	0	0	0	7
7:00	1	1	3	5	1	2	0	0	0	0	0	0	0	13
8:00	7	6	10	10	3	1	0	0	0	0	0	0	0	37
9:00	2	0	11	6	4	2	1	0	0	0	0	0	0	26
10:00	3	4	8	5	4	0	0	0	0	0	0	0	0	24
11:00	4	6	5	7	2	0	0	0	0	0	0	0	0	24
12:00 PM	9	2	11	9	3	0	0	0	0	0	0	0	0	34
1:00	5	8	4	9	3	1	0	0	0	0	0	0	0	30
2:00	4	0	9	4	2	0	0	0	0	0	0	0	0	19
3:00	3	2	11	7	3	1	0	0	0	0	0	0	0	27
4:00	2	2	10	8	5	0	0	0	0	0	0	0	0	27
5:00	2	2	9	15	3	0	0	0	0	0	0	0	0	31
6:00	5	8	9	7	2	0	0	0	0	0	0	0	0	31
7:00	1	3	8	3	0	0	0	0	0	0	0	0	0	15
8:00	2	2	1	3	2	0	0	0	0	0	0	0	0	10
9:00	2	2	1	0	0	0	0	0	0	0	0	0	0	5
10:00	0	2	0	2	3	0	0	0	0	0	0	0	0	7
11:00	0	0	0	3	0	0	0	0	0	0	0	0	0	3
Total	54	53	114	107	42	8	1	1	0	0	0	0	0	380
Grand Total	88	102	201	214	98	18	1	2	0	0	0	0	0	724
Stats	Percentile													
	Speed													
	15th													
	50th													
	85th													
	95th													
	16													
	24													
	30													
	34													
	23.3													
	20-29													
	413													
	57.0%													
	333													
	46.0%													

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO1
Station ID:
Location 1:
Location 2:
Latitude: 35.097237
Longitude: -106.602213

File Name: untitled_0
Date Printed: 5/19/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No



4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator


Analysis Dates

Start: 5/16/2023

End: 5/16/2023

Total Percentage of Enforceable Violations

Posted Speed Limit	25 MPH
Enforcement Tolerance	5 MPH
Enforcement Limit	Greater than 30 MPH



Percent Speeding: 19%

Rating: Medium Low



Percent Speeding: 21%

Rating: Medium Low



Percent Speeding: 18%

Rating: Medium Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
34	49	87	107	56	10	0	1	0	0	0	0	0
85th Percentile: 30.8												

85th Percentile: 30.8

Vehicle Totals - A to B, None Specified

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
16	19	38	55	27	6	0	1	0	0	0	0	0

85th Percentile: 30.9

Vehicle Totals - B to A, None Specified

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
18	30	49	52	29	4	0	0	0	0	0	0	0

85th Percentile: 30.6

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator


Analysis Dates

Start: 5/17/2023

End: 5/17/2023

Total Percentage of Enforceable Violations

Posted Speed Limit	25 MPH
Enforcement Tolerance	5 MPH
Enforcement Limit	Greater than 30 MPH



Percent Speeding: 14%

Rating: Medium Low



Percent Speeding: 17%

Rating: Medium Low



Percent Speeding: 11%

Rating: Medium Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
54	53	114	107	42	8	1	1	0	0	0	0	0
85th Percentile: 29.3												

85th Percentile: 29.3

Vehicle Totals - A to B, None Specified

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
21	23	53	54	25	4	1	1	0	0	0	0	0

85th Percentile: 30.4

Vehicle Totals - B to A, None Specified

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
33	30	61	53	17	4	0	0	0	0	0	0	0

85th Percentile: 28.4

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator


Analysis Dates

Start: 5/16/2023

End: 5/16/2023


Total Percentage of Enforceable Violations

Posted Speed Limit	25 MPH
Enforcement Tolerance	7 MPH
Enforcement Limit	Greater than 32 MPH



Percent Speeding: 13%

Rating: Medium Low



Percent Speeding: 14%

Rating: Medium Low



Percent Speeding: 12%

Rating: Medium Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
34	49	87	107	56	10	0	1	0	0	0	0	0
85th Percentile: 30.8												

Vehicle Totals - A to B, None Specified

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
16	19	38	55	27	6	0	1	0	0	0	0	0
85th Percentile: 30.9												

Vehicle Totals - B to A, None Specified

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
18	30	49	52	29	4	0	0	0	0	0	0	0

85th Percentile: 30.6

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator


Analysis Dates

Start: 5/17/2023

End: 5/17/2023


Total Percentage of Enforceable Violations

Posted Speed Limit	25 MPH
Enforcement Tolerance	7 MPH
Enforcement Limit	Greater than 32 MPH



Percent Speeding: 8%

Rating: Low



Percent Speeding: 10%

Rating: Medium Low



Percent Speeding: 5%

Rating: Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
54	53	114	107	42	8	1	1	0	0	0	0	0
85th Percentile: 29.3												

Vehicle Totals - A to B, None Specified

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
21	23	53	54	25	4	1	1	0	0	0	0	0
85th Percentile: 30.4												

Vehicle Totals - B to A, None Specified

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
33	30	61	53	17	4	0	0	0	0	0	0	0
85th Percentile: 28.4												

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO2
Station ID:
Location 1:
Location 2:
Latitude: 35.088317
Longitude: -106.602041

File Name: untitled_0
Date Printed: 6/23/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No

5/15/2023	Monday		Tuesday		Wednesday		Thursday		Friday		Saturday		Sunday		Week Average	
Time	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB	A to B, SB	B to A, NB
12:00 AM	*	*	0	0	0	1	*	*	*	*	*	*	*	*	0	0
1:00	*	*	0	0	0	0	*	*	*	*	*	*	*	*	0	0
2:00	*	*	0	0	0	0	*	*	*	*	*	*	*	*	0	0
3:00	*	*	1	0	1	0	*	*	*	*	*	*	*	*	1	0
4:00	*	*	0	2	0	0	*	*	*	*	*	*	*	*	0	1
5:00	*	*	1	0	1	2	*	*	*	*	*	*	*	*	1	1
6:00	*	*	2	2	4	2	*	*	*	*	*	*	*	*	3	2
7:00	*	*	3	4	3	10	*	*	*	*	*	*	*	*	3	7
8:00	*	*	2	3	3	8	*	*	*	*	*	*	*	*	2	6
9:00	*	*	4	3	4	2	*	*	*	*	*	*	*	*	4	2
10:00	*	*	6	5	3	6	*	*	*	*	*	*	*	*	4	6
11:00	*	*	10	3	6	6	*	*	*	*	*	*	*	*	8	4
12:00 PM	*	*	5	4	5	4	*	*	*	*	*	*	*	*	5	4
1:00	*	*	5	7	5	6	*	*	*	*	*	*	*	*	5	6
2:00	*	*	8	7	8	6	*	*	*	*	*	*	*	*	8	6
3:00	*	*	8	5	10	5	*	*	*	*	*	*	*	*	9	5
4:00	*	*	11	3	12	3	*	*	*	*	*	*	*	*	12	3
5:00	*	*	11	8	6	10	*	*	*	*	*	*	*	*	8	9
6:00	*	*	5	7	7	3	*	*	*	*	*	*	*	*	6	5
7:00	*	*	2	6	3	6	*	*	*	*	*	*	*	*	2	6
8:00	*	*	3	3	0	0	*	*	*	*	*	*	*	*	2	2
9:00	*	*	1	3	2	1	*	*	*	*	*	*	*	*	2	2
10:00	*	*	3	2	2	0	*	*	*	*	*	*	*	*	2	1
11:00	*	*	0	4	0	0	*	*	*	*	*	*	*	*	0	2
Total	0	0	91	81	85	81	0	0	0	0	0	0	0	0	87	80
Day	0		172		166		0		0		0		0		167	
AM Peak			11:00	10:00	11:00	7:00									11:00	7:00
Volume			10	5	6	10									8	7
PM Peak			4:00	5:00	4:00	5:00									4:00	5:00
Volume			11	8	12	10									12	9
Comb Total	0		172		166		0		0		0		0		167	
ADT	ADT: 169		AADT: 169													

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO2
Station ID:
Location 1:
Location 2:
Latitude: 35.088317
Longitude: -106.602041
Direction: A to B, SB

File Name: untitled_0
Date Printed: 6/23/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No

5/16/2023	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	1	0	0	0	0	0	0	0	0	0	0	0	0	1
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
6:00	0	0	2	0	0	0	0	0	0	0	0	0	0	2
7:00	1	1	0	1	0	0	0	0	0	0	0	0	0	3
8:00	0	0	1	1	0	0	0	0	0	0	0	0	0	2
9:00	0	0	3	1	0	0	0	0	0	0	0	0	0	4
10:00	2	0	0	3	1	0	0	0	0	0	0	0	0	6
11:00	1	4	5	0	0	0	0	0	0	0	0	0	0	10
12:00 PM	0	3	1	1	0	0	0	0	0	0	0	0	0	5
1:00	1	1	3	0	0	0	0	0	0	0	0	0	0	5
2:00	1	6	1	0	0	0	0	0	0	0	0	0	0	8
3:00	3	1	2	2	0	0	0	0	0	0	0	0	0	8
4:00	0	2	7	2	0	0	0	0	0	0	0	0	0	11
5:00	4	5	2	0	0	0	0	0	0	0	0	0	0	11
6:00	0	2	1	1	0	1	0	0	0	0	0	0	0	5
7:00	0	1	1	0	0	0	0	0	0	0	0	0	0	2
8:00	0	0	3	0	0	0	0	0	0	0	0	0	0	3
9:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
10:00	1	1	0	1	0	0	0	0	0	0	0	0	0	3
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	15	27	34	13	1	1	0	0	0	0	0	0	0	91

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO2
Station ID:
Location 1:
Location 2:
Latitude: 35.088317
Longitude: -106.602041
Direction: A to B, SB

File Name: untitled_0
Date Printed: 6/23/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No

5/17/2023	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	1	0	0	0	0	0	0	0	0	1
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
6:00	0	2	2	0	0	0	0	0	0	0	0	0	0	4
7:00	0	2	1	0	0	0	0	0	0	0	0	0	0	3
8:00	2	1	0	0	0	0	0	0	0	0	0	0	0	3
9:00	0	1	1	1	1	0	0	0	0	0	0	0	0	4
10:00	0	2	1	0	0	0	0	0	0	0	0	0	0	3
11:00	2	2	1	1	0	0	0	0	0	0	0	0	0	6
12:00 PM	2	1	1	0	1	0	0	0	0	0	0	0	0	5
1:00	0	2	3	0	0	0	0	0	0	0	0	0	0	5
2:00	2	4	2	0	0	0	0	0	0	0	0	0	0	8
3:00	1	2	3	4	0	0	0	0	0	0	0	0	0	10
4:00	1	2	6	3	0	0	0	0	0	0	0	0	0	12
5:00	1	2	2	0	1	0	0	0	0	0	0	0	0	6
6:00	0	4	2	1	0	0	0	0	0	0	0	0	0	7
7:00	0	1	2	0	0	0	0	0	0	0	0	0	0	3
8:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:00	0	1	1	0	0	0	0	0	0	0	0	0	0	2
10:00	0	1	1	0	0	0	0	0	0	0	0	0	0	2
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	11	30	30	10	4	0	0	0	0	0	0	0	0	85
Grand Total	26	57	64	23	5	1	0	0	0	0	0	0	0	176

Stats	Percentile	15th	50th	85th	95th
Speed		15	20	25	29
Mean Speed (Average)		19.7			
10 MPH Pace Speed		15-24			
Number in Pace		120			
Percent in Pace		68.2%			
Number > 25 MPH		29			
Percent > 25 MPH		16.5%			

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO2
Station ID:
Location 1:
Location 2:
Latitude: 35.088317
Longitude: -106.602041
Direction: B to A, NB

File Name: untitled_0
Date Printed: 6/23/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No

5/16/2023	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	Total
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	1	0	0	1	0	0	0	0	0	0	0	0	0	2
5:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
6:00	2	0	0	0	0	0	0	0	0	0	0	0	0	2
7:00	1	1	2	0	0	0	0	0	0	0	0	0	0	4
8:00	0	0	2	1	0	0	0	0	0	0	0	0	0	3
9:00	0	0	2	1	0	0	0	0	0	0	0	0	0	3
10:00	0	2	0	2	1	0	0	0	0	0	0	0	0	5
11:00	1	1	1	0	0	0	0	0	0	0	0	0	0	3
12:00 PM	1	1	2	0	0	0	0	0	0	0	0	0	0	4
1:00	3	3	0	1	0	0	0	0	0	0	0	0	0	7
2:00	3	2	2	0	0	0	0	0	0	0	0	0	0	7
3:00	2	1	2	0	0	0	0	0	0	0	0	0	0	5
4:00	0	0	2	0	1	0	0	0	0	0	0	0	0	3
5:00	3	3	2	0	0	0	0	0	0	0	0	0	0	8
6:00	0	0	6	1	0	0	0	0	0	0	0	0	0	7
7:00	1	1	3	1	0	0	0	0	0	0	0	0	0	6
8:00	0	1	1	1	0	0	0	0	0	0	0	0	0	3
9:00	0	1	0	2	0	0	0	0	0	0	0	0	0	3
10:00	0	0	0	0	1	1	0	0	0	0	0	0	0	2
11:00	3	0	1	0	0	0	0	0	0	0	0	0	0	4
Total	21	17	28	11	3	1	0	0	0	0	0	0	0	81

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO2
Station ID:
Location 1:
Location 2:
Latitude: 35.088317
Longitude: -106.602041
Direction: B to A, NB

File Name: untitled_0
Date Printed: 6/23/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No

5/17/2023	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	1	0	0	0	0	0	0	0	0	0	0	0	0	1
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	1	1	0	0	0	0	0	0	0	0	0	0	2
6:00	1	0	1	0	0	0	0	0	0	0	0	0	0	2
7:00	1	3	5	1	0	0	0	0	0	0	0	0	0	10
8:00	0	2	4	2	0	0	0	0	0	0	0	0	0	8
9:00	0	0	2	0	0	0	0	0	0	0	0	0	0	2
10:00	2	3	0	0	1	0	0	0	0	0	0	0	0	6
11:00	2	1	2	1	0	0	0	0	0	0	0	0	0	6
12:00 PM	1	2	1	0	0	0	0	0	0	0	0	0	0	4
1:00	2	2	0	1	1	0	0	0	0	0	0	0	0	6
2:00	0	4	2	0	0	0	0	0	0	0	0	0	0	6
3:00	2	1	2	0	0	0	0	0	0	0	0	0	0	5
4:00	0	0	2	1	0	0	0	0	0	0	0	0	0	3
5:00	0	2	4	3	1	0	0	0	0	0	0	0	0	10
6:00	0	2	1	0	0	0	0	0	0	0	0	0	0	3
7:00	0	4	1	1	0	0	0	0	0	0	0	0	0	6
8:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:00	0	0	0	0	0	1	0	0	0	0	0	0	0	1
10:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	12	27	28	10	3	1	0	0	0	0	0	0	0	81
Grand Total	33	44	56	21	6	2	0	0	0	0	0	0	0	162
Stats	Percentile													
	Speed													
	15th													
	50th													
	85th													
	95th													
	Speed													
	14													
	21													
	26													
	30													
	Mean Speed (Average)													
	19.3													
	10 MPH Pace Speed													
	15-24													
	Number in Pace													
	99													
	Percent in Pace													
	61.1%													
	Number > 25 MPH													
	29													
	Percent > 25 MPH													
	17.9%													

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO2
Station ID:
Location 1:
Location 2:
Latitude: 35.088317
Longitude: -106.602041
Direction: Combined

File Name: untitled_0
Date Printed: 6/23/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No

5/16/2023	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	0	0	0	0	0	0	0	0	0	0	0	0	0	0
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	1	0	0	0	0	0	0	0	0	0	0	0	0	1
4:00	1	0	0	1	0	0	0	0	0	0	0	0	0	2
5:00	0	0	1	0	0	0	0	0	0	0	0	0	0	1
6:00	2	0	2	0	0	0	0	0	0	0	0	0	0	4
7:00	2	2	2	1	0	0	0	0	0	0	0	0	0	7
8:00	0	0	3	2	0	0	0	0	0	0	0	0	0	5
9:00	0	0	5	2	0	0	0	0	0	0	0	0	0	7
10:00	2	2	0	5	2	0	0	0	0	0	0	0	0	11
11:00	2	5	6	0	0	0	0	0	0	0	0	0	0	13
12:00 PM	1	4	3	1	0	0	0	0	0	0	0	0	0	9
1:00	4	4	3	1	0	0	0	0	0	0	0	0	0	12
2:00	4	8	3	0	0	0	0	0	0	0	0	0	0	15
3:00	5	2	4	2	0	0	0	0	0	0	0	0	0	13
4:00	0	2	9	2	1	0	0	0	0	0	0	0	0	14
5:00	7	8	4	0	0	0	0	0	0	0	0	0	0	19
6:00	0	2	7	2	0	1	0	0	0	0	0	0	0	12
7:00	1	2	4	1	0	0	0	0	0	0	0	0	0	8
8:00	0	1	4	1	0	0	0	0	0	0	0	0	0	6
9:00	0	1	1	2	0	0	0	0	0	0	0	0	0	4
10:00	1	1	0	1	1	1	0	0	0	0	0	0	0	5
11:00	3	0	1	0	0	0	0	0	0	0	0	0	0	4
Total	36	44	62	24	4	2	0	0	0	0	0	0	0	172

Wilson & Company

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Site Code: SO2
Station ID:
Location 1:
Location 2:
Latitude: 35.088317
Longitude: -106.602041
Direction: Combined

File Name: untitled_0
Date Printed: 6/23/2023
Start Date: 5/16/2023
End Date: 5/17/2023
GPS Accuracy: 0 ft
Location Verified: No

5/17/2023	0 - 15	> 15 -	> 20 -	> 25 -	> 30 -	> 35 -	> 40 -	> 45 -	> 50 -	> 55 -	> 60 -	> 65 -	> 70	Total
Time	MPH	20 MPH	25 MPH	30 MPH	35 MPH	40 MPH	45 MPH	50 MPH	55 MPH	60 MPH	65 MPH	70 MPH	MPH	
12:00 AM	1	0	0	0	0	0	0	0	0	0	0	0	0	1
1:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	0	0	0	1	0	0	0	0	0	0	0	0	1
4:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	0	1	2	0	0	0	0	0	0	0	0	0	0	3
6:00	1	2	3	0	0	0	0	0	0	0	0	0	0	6
7:00	1	5	6	1	0	0	0	0	0	0	0	0	0	13
8:00	2	3	4	2	0	0	0	0	0	0	0	0	0	11
9:00	0	1	3	1	1	0	0	0	0	0	0	0	0	6
10:00	2	5	1	0	1	0	0	0	0	0	0	0	0	9
11:00	4	3	3	2	0	0	0	0	0	0	0	0	0	12
12:00 PM	3	3	2	0	1	0	0	0	0	0	0	0	0	9
1:00	2	4	3	1	1	0	0	0	0	0	0	0	0	11
2:00	2	8	4	0	0	0	0	0	0	0	0	0	0	14
3:00	3	3	5	4	0	0	0	0	0	0	0	0	0	15
4:00	1	2	8	4	0	0	0	0	0	0	0	0	0	15
5:00	1	4	6	3	2	0	0	0	0	0	0	0	0	16
6:00	0	6	3	1	0	0	0	0	0	0	0	0	0	10
7:00	0	5	3	1	0	0	0	0	0	0	0	0	0	9
8:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
9:00	0	1	1	0	0	1	0	0	0	0	0	0	0	3
10:00	0	1	1	0	0	0	0	0	0	0	0	0	0	2
11:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	23	57	58	20	7	1	0	0	0	0	0	0	0	166
Grand Total	59	101	120	44	11	3	0	0	0	0	0	0	0	338

Stats	Percentile	15th	50th	85th	95th
Speed		14	20	26	29
Mean Speed (Average)		19.5			
10 MPH Pace Speed		15-24			
Number in Pace		219			
Percent in Pace		64.8%			
Number > 25 MPH		58			
Percent > 25 MPH		17.2%			

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Total Percentage of Enforceable Violations

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator


Analysis Dates

Start: 5/17/2023

End: 5/17/2023


Total Percentage of Enforceable Violations

Posted Speed Limit	25 MPH
Enforcement Tolerance	5 MPH
Enforcement Limit	Greater than 30 MPH



Percent Speeding: 5%

Rating: Low



Percent Speeding: 5%

Rating: Low



Percent Speeding: 5%

Rating: Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
23	57	58	20	7	1	0	0	0	0	0	0	0
85th Percentile: 25.3												

Vehicle Totals - A to B, None Specified

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
11	30	30	10	4	0	0	0	0	0	0	0	0
85th Percentile: 25.2												

Vehicle Totals - B to A, None Specified

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
12	27	28	10	3	1	0	0	0	0	0	0	0

85th Percentile: 25.5

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator


Analysis Dates

Start: 5/16/2023

End: 5/16/2023


Total Percentage of Enforceable Violations

Posted Speed Limit	25 MPH
Enforcement Tolerance	7 MPH
Enforcement Limit	Greater than 32 MPH



Percent Speeding: 2%

Rating: Low



Percent Speeding: 2%

Rating: Low

Percent Speeding: 2%

Rating: Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
36	44	62	24	4	2	0	0	0	0	0	0	0
85th Percentile: 25.7												

Vehicle Totals - A to B, None Specified

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
15	27	34	13	1	1	0	0	0	0	0	0	0
85th Percentile: 25.1												

Vehicle Totals - B to A, None Specified

[illegible]

4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109

Speed Enforcement Evaluator


Analysis Dates

Start: 5/17/2023

End: 5/17/2023


Total Percentage of Enforceable Violations

Posted Speed Limit	25 MPH
Enforcement Tolerance	7 MPH
Enforcement Limit	Greater than 32 MPH



Percent Speeding: 2%

Rating: Low



Percent Speeding: 1%

Rating: Low



Percent Speeding: 2%

Rating: Low

Vehicle Totals - Combined

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
23	57	58	20	7	1	0	0	0	0	0	0	0
85th Percentile: 25.3												

85th Percentile: 25.3

Vehicle Totals - A to B, None Specified

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
11	30	30	10	4	0	0	0	0	0	0	0	0

85th Percentile: 25.2

Vehicle Totals - B to A, None Specified

<= 15	<= 20	<= 25	<= 30	<= 35	<= 40	<= 45	<= 50	<= 55	<= 60	<= 65	<= 70	> 70
12	27	28	10	3	1	0	0	0	0	0	0	0

85th Percentile: 25.5

Appendix B – Crash Data

Appendix C – Public Meeting Summary

Meeting Summary



Meeting Title: McDuffie-Twin Parks Traffic Calming Study – Public Meeting #1

Date: 2/7/2023

Time: 6:00 pm – 7:00 pm

Location: Zoom – City of Albuquerque

Attendees:

See page 3. There were 34 attendees, including City of Albuquerque staff and Wilson & Company staff who attended as Panelists.

I. Introduction and Presentation

Audra Gallegos opened the meeting. She then introduced Councilor Tammy Fiebelkorn on the call. The councilor then described the safety issues within the McDuffie-Twin Parks area and expressed hope that this study would provide solutions to those issues.

Audra Gallegos (Wilson & Company) then began a slideshow presentation.

II. Q&A Session

A question & answer session followed the presentation. The questions and responses are listed below:

Participant Question	Project Team Response
Question, via audio: A member of the Neighborhood Association Board (NAB) had questions related to Solano Drive (between Lomas Boulevard and Mackland Avenue). She mentioned that she has walked the area with Laura Rummier (COA) to identify locations that need traffic calming initiatives implemented and Solano Drive was one of them. Is there a plan for Solano Drive?	Audra: We are planning to have striping recommendations for no parking near the entrances of the park, but let me get with Laura and the rest of the City of Albuquerque Staff and we will get back to you on traffic calming along Solano.
Question, via audio: What is the plan for the pedestrian crosswalk at Mackland Avenue crossing Carlisle Boulevard?	Councilor: The crosswalk has been painted as well as an order has been placed to install a pedestrian rectangular flashing beacons to alert drivers of pedestrians crossing. There is no date set in place at the moment but as soon as the beacons are delivered, they will be placed.
Question, via audio: There is a high number of bicyclists along Constitution Avenue crossing Morningside Drive. The bulbout presented at that intersection seemed to reduce the bike lane for bicyclist.	Audra: The intersection example does show a bulbout and provides a bike ramp for bicyclist to be able to cross the intersection and then it ties back to the existing bike lane. This is the same for other bulbout examples shown.
Comment, via audio: I wanted to clarify that I am really excited that you are going to put something at Mackland Avenue and Montclair Drive because it is such a weird intersection. People do slow down, but there is so many sight problems with bushes and stuff. It is very hard to cross there. I think most of the wide intersections that we have in the area could use something like that.	Audra: Thank you, we appreciate your comment.

Participant Question	Project Team Response
Comment, via audio: I am kind of opposed to the Avenida del Sol example making it one-way.	Audra: That is why we are here. We want to hear from all of you and get your input. And if you do not like something, just let us know.
Comment, via Audio: I wanted to echo this idea of some sort of traffic calming at Solano Drive and Mackland Avenue. We were almost run down one time.	Audra: Thank you, we appreciate your comment.
Comment, via audio: Carlisle Boulevard has become more dangerous in my view. I have seen pedestrians actually running and diving at the intersection north of Constitution Avenue where the streets have stripping and flashing lights. That is a difficult street right now.	Audra: Thank you, we appreciate your comments.
Question, via audio: Do you take out the on-street parking at Washington Street just north of Constitution Avenue in your proposed example?	Audra: The example does show the on-street parking switching to the west side of the roadway, currently placed on the east side. These are just examples. We want to have the conversations with you all and what you want to see and do not see out there. However, to shift the on-street parking on this west side instead. What this does is, it shifts that southbound through lane over so that if somebody is traveling southbound on Washington Street the offset is not as strong.
Question, via audio: Removing the on-street parking of the west side, would become a problem for the people that live on the east side that currently parked at the roadway. Vehicles parking at the other side of the roadway would be somewhat treacherous and difficult for current users to walk across the traffic along Washington Street.	Audra: Thank you, we appreciate your comment.
Comment, via audio: A lot of participants have suggested a traffic circle at the intersection of Washington Street and Constitution Avenue. However, about 15 years ago the City of Albuquerque try to put a traffic circle but it was not big enough and it did not work.	Audra: Yes, that is correct. There is not enough space for a traffic circle to fit.
Question, via chat: Washington Street and Hannett Avenue is a popular crossing for families to walk to the park. Please consider how to make this crossing safer and thank you for including it in the study!	Audra: For that intersection, adding bulbouts will reduced the pedestrian crossing distance. Advanced signing and stripping would also be placed to help make that pedestrian crossing more visible.
Question, via chat: Have you obtained information on how many times the wall at the southwest corner of Washington and Constitution has been knocked down over the last 10 years?	Audra: We recieved the crash data from the 2016 to 2020 data, but we do not have the crash data at this time on how many times it has been hit. However, in the example provided adding a bulbout will move over the vehicular traffic away from that location and it would also help slow down vehicles that are turning.
Question, via chat: Has Councilor secured or approved funding for this project?	Audra: As part of this project, we will look at conceptual costs for these examples that will help

Participant Question	Project Team Response
	Councilor look at what type of funding would be needed for these projects. Councilor: Our district did set aside money to pay for this study so we can come up with some alternatives. If the community wants the different alternatives, then will move forward. The next step is to provide a cost estimate of the alternatives selected moving forward, and then I will find funding for it as well. But just know this is a priority for me.
Question, via chat: Is 48 hours a typical amount of time to collect vehicle data?	Audra: Yes, 48 hours is the typical time period for collecting tube count data.
Question, via chat: The crash data showed no incidences on Morningside Drive between Hannett Avenue and Indian School Road, and we see cars speeding there frequently was the period of time of the study sufficient to get the true picture?	Audra: The crash data that we got provides information related to reported crashes that had a police report done. Therefore, if those incidents occurred outside the time period or do not have a crash report, we would not be able to incorporate that information.
Question, via chat: I noticed that based on the crash study visual (heat map) shared, there were quite a few crash spots directly surrounding Altura Park (especially as compared to Twin Parks) but Hannett Avenue and Aspen Avenue were not included in the study. Can these two roads be added to the study?	Audra: I think that is something we can talk about internally, and then we can provide an answer back for that one.
Question, via chat: What about speed bumps in more areas to look slow traffic like Avenida del Sol?	Audra: Speed bumps are definitely an option. Although, speed bumps cannot be placed on emergency routes. Speed bumps are definitely an option if that is what the neighborhood wants.
Question, via chat: Will traffic calming on some streets cause traffic to shift over to other areas that don not have traffic calming devices?	Audra: This is always a possibility. Traffic calming can help reduce cut through traffic in one neighborhood and detour the traffic onto other streets.
Comment, via chat: We get so much cut through traffic on Montclair Drive (Lomas Boulevard to Carlisle Boulevard), and the stop signs at Montclair and Mackland are frequently ignored.	Audra: If the stop signs are being ignored on Montclair Drive and Mackland Avenue, a traffic circle would really benefit since there will be a physical barrier in the middle of the intersection. Drivers entering the intersection will need to slow down.
Comments, via chat: What about adding flashing lights to the stop signs at Washington Street and Constitution Avenue? This is an extremely dangerous intersection.	Audra: Yes, that is a possibility of adding flashing stop signs to that intersection.
Comment, via chat: I like the idea of moving the southbound lane on Washington Street at Constitution Avenue to move it to the east. Can you clarify if any of the street parking on Washington Street, north of Hannett Avenue will change?	Audra: The only area that we had looked at to potentially change the parking was at this one block of Washington Street, just north of Constitution Avenue, just to shift that lane over. The other parking areas that we looked at restriping did not affect the existing on street parking.
Comment, via chat: There are large communication boxes at the intersection of Washington and Constitution and one that is	Audra: Thank you, we appreciate your comment.

Participant Question	Project Team Response
underground that is accessed by a manhole and it is used regularly.	
Comment, via chat: The lights on Carlisle Boulevard, do they stop traffic?	Audra: This intersection will have rapid flashing beacons that are triggered when someone pushes the button. The lights then flash to alert drivers that a pedestrian is crossing but they do not stop the traffic.
Question, via chat: Is it possible to get a copy of the PowerPoint presentation and the data presented?	Audra: The PowerPoint will be provided in a PDF to the city and the city will post it in their website. Also, once the report is finalized that will also be posted on the City's website.
Comment, via chat: It is hard to see traffic coming west on Lomas because of a utility pole, is there a plan to address it?	Audra: That intersection was not part of the scope of this project, but we can talk internally with the city to see if there are any plans for that intersection in the future.
Comment, via chat: There is a large number of pedestrians crossing at Sunningdale and Washington, I just wanted to make sure that it got included in this conversation.	Audra: Yes, we did show an example of a pedestrian mid-block crossing that would allow pedestrian to cross there.
Question, via audio: Can you remind us of what the next steps are? What happens next?	Audra: We will take the input provided in during this presentation and incorporate the information into the report. Based on the inputs we have received we would determine what improvement would be moving forward and then once we have preliminary recommendations set we will be scheduling another public meeting.
Question, via audio: Will there be a way to get a copy of the report before the public hearing?	Audra: Yes, there is a possibility of placing the draft report onto the city's website prior to the next meeting and notify the meeting attendees when they have been uploaded.

III. Closing and Schedule

Audra: If any additional questions or comments please email them to me. (Audra put the contact info back on the screen.) The presentation from tonight will be placed on the project webpage. The meeting concluded.

IV. Summary of Comments Received after the Public Meeting

Public comments were accepted for a two-week period after the public meeting. A total of 48 emails were received. The following is a summary of the comments received:

- Out of the 48 emails received, majority of commenters were for the traffic circle at Montclair and Mackland and installing the proposed bulbouts.
- Fifteen (15) emails received were specifically for the pedestrian crossings.
- Nine (9) emails received were for speed humps being placed on various streets and two (2) commenters were opposed to any speed humps.
- Five (5) commenters were opposed to the traffic circle.
- Twelve (12) comments received were opposed to the one-way on Avenida del Sol.
- Additional requests received were as follows:
 - Traffic calming on Solano, Aspen, Altura Avenue, and Hannett
 - Traffic circle at Morningside and Avenida de Resolana
 - Traffic circle at Washington Street and Hannett-Sunningdale

- Switch stop signs on Morningside and Avenida de Resolana
- Stop sign at Morningside and Avenida de Resolana
- Stop sign on Avenida del Sol and Morningside
- Stop sign at Mackland and Montclair
- Crosswalk across Mackland at entrance to park
- Stop ahead markings at Constitution Avenue and Washington Street
- Flashing stop signs on Constitution Avenue and Washington Street
- More police enforcement
- Multiway stops or traffic signals
- Speed radar signs
- Speed cameras
- Reflective signing on wall at Washington Street
- Metal posts to protect wall on Washington Street

V. Meeting Attendees

Attendee Name

Kathryn Hildebrand	De McMann
Denise Fligner	Denise Hammer
Margaret Keller	Ed Anlian
Orville Pratt	Eric Jantz
Alex T.	Gundar Peterson
Alexis Tappan	Jenna Hunter
Barry	Jennifer Brower
Bill Keleher	Joyce Kolberg
Carol Morris	Kristin Oreskovich
Cathy Drake	Mary Dickman
Charles Bachechi	Marlene Hubbard
Vicky Kauffman	Paula Dal Santo
TWE	Karla Sampson
Stan Hordes	Helen Hordes
Molly McIntosh	Dee McMann
Rick Gonzales	

Project Team Members in attendance:

Name:

Clr. Tammy Fiebelkorn
Aziza Chavez
Laura Rummler
Tom Menicucci
Tim Brown
Audra Gallegos
Lorenzo Cornejo

Organization:

City of Albuquerque
City of Albuquerque
City of Albuquerque
City of Albuquerque
City of Albuquerque
Wilson & Company
Wilson & Company

Email:

TFiebelkorn@cabq.gov
AzizaChavez@cabq.gov
LRummler@cabq.gov
TMenicucci@cabq.gov
TJBrown@cabq.gov
Audra.Gallegos@wilsonco.com
Lorenzo.Cornejo@wilsonco.com



McDuffie-Twin Parks Traffic Calming Study

Public Meeting

WILSON
& COMPANY

discipline | intensity | collaboration | shared ownership | solutions

Introductions

City of Albuquerque

- Councilor Tammy Fiebelkorn
- Laura Rummler– Council District 7 Policy Analyst
- Tim Brown, PE – Traffic Engineering Manager


Wilson & Company

- Audra Gallegos, PE
- Lorenzo Cornejo, EI



Study Limits

- Study Limits: McDuffie-Twin Parks Neighborhood
 - Washington Street
 - Constitution Avenue
 - Morningside Drive
 - Marble Avenue
 - Montclair Drive
 - Mackland Avenue
 - Avenida del Sol
- Posted Speed Limit: 25-30 mph



Wilson & Company, Inc., Engineers & Architects



Purpose of Tonight's Meeting

- Introduce project
- Introduce potential alternatives
- Public input – we want to hear from you!



Schedule

- Existing Conditions Report – December 2022
- Public Meeting #1 – Tonight's meeting
- Identification of Improvements and Recommendations – Spring 2023
- Public Meeting #2 – Spring 2023
- Final Report – Spring 2023





Existing Conditions

Tube Count Data

- Tube counts (volume, speed)
- 48-hour period
- 15% of vehicles exceeding 5 mph and 7 mph

Location	Speed	Percentage of Vehicles Exceeding Speed Limit			
		Wednesday		Thursday	
		Counter per Direction 1	Counter per Direction 2	Counter per Direction 1	Counter per Direction 2
Morningside Drive (North of Aspen Ave.)	5 mph	0%	0%	0%	0%
Morningside Drive (South of Aspen Ave.)	7 mph	0%	0%	0%	0%
Washington Street (North of Sunningdale Ave.)	5 mph	15%	8%	15%	10%
Washington Street (South of Sunningdale Ave.)	7 mph	8%	2%	10%	3%
Washington Street (South of Avenida Estrellita)	5 mph	14%	41%	16%	45%
Washington Street (South of Avenida Del Sol)	7 mph	7%	24%	7%	27%
Constitution Drive (West of Morningside Ave.)	5 mph	8%	35%	10%	39%
Constitution Drive (East of Morningside Ave.)	7 mph	3%	20%	5%	23%
Avenida Del Sol (West of Mackland Ave.)	5 mph	18%	25%	24%	31%
Avenida Del Sol (East of Mackland Ave.)	7 mph	9%	12%	12%	15%
Morningside Drive (North of Mackland Ave.)	5 mph	6%	13%	6%	18%
Morningside Drive (South of Mackland Ave.)	7 mph	2%	6%	3%	8%
Marble Avenue (South of Mackland Ave.)	5 mph	34%	39%	33%	39%
Mackland Avenue (West of Montclair Dr.)	7 mph	21%	22%	18%	23%
Mackland Avenue (East of Montclair Dr.)	5 mph	73%	30%	73%	31%
Montclair Drive (South of McDuffie Cir.)	7 mph	61%	16%	60%	18%
Montclair Drive (North of Mesa Verde Ave.)	5 mph	7%	25%	2%	20%
Montclair Drive (North of Mesa Verde Ave.)	7 mph	3%	19%	0%	11%
Montclair Drive (North of Mesa Verde Ave.)	5 mph	2%	22%	4%	19%
Montclair Drive (North of Mesa Verde Ave.)	7 mph	1%	14%	2%	13%
Montclair Drive (North of Mesa Verde Ave.)	5 mph	6%	7%	6%	9%
Montclair Drive (North of Mesa Verde Ave.)	7 mph	3%	2%	2%	6%
Montclair Drive (North of Mesa Verde Ave.)	5 mph	7%	7%	6%	7%
Montclair Drive (North of Mesa Verde Ave.)	7 mph	4%	3%	4%	3%
Montclair Drive (North of Mesa Verde Ave.)	5 mph	5%	12%	6%	12%
Montclair Drive (North of Mesa Verde Ave.)	7 mph	3%	7%	2%	8%
Montclair Drive (North of Mesa Verde Ave.)	5 mph	0%	0%	0%	0%
Montclair Drive (North of Mesa Verde Ave.)	7 mph	0%	0%	0%	0%
Montclair Drive (North of Mesa Verde Ave.)	5 mph	13%	13%	6%	16%
Montclair Drive (North of Mesa Verde Ave.)	7 mph	5%	6%	2%	7%
Montclair Drive (North of Mesa Verde Ave.)	5 mph	14%	9%	12%	11%
Montclair Drive (North of Mesa Verde Ave.)	7 mph	8%	4%	7%	5%



Pedestrian Count Data

- Camera (pedestrians, bicyclists)
- 13-hour period


Intersection	Time	Pedestrian 13-hr Volume				Bicyclist 13-hr Volume			
		South Leg	West Leg	North Leg	East Leg	NB	EB	SB	WB
Washington St. and Sunningdale Ave.	AM Peak	15	2	16	3	4	0	3	2
	PM Peak	1	2	9	1	8	3	3	0
	13 Hour Total	53	19	87	13	58	11	48	6
Washington St. and Constitution Ave.	AM Peak	2	2	1	3	0	2	2	4
	PM Peak	2	2	0	0	0	4	3	0
	13 Hour Total	9	8	3	4	17	39	18	36
Morningside Dr. and Constitution Ave.	AM Peak	4	5	1	10	0	2	2	6
	PM Peak	3	12	0	9	1	5	1	0
	13 Hour Total	16	71	12	57	22	37	15	37



Crash Data

- 2016-2020
- 158 total crashes
- 88% of crashes occurred in clear weather conditions
- 72% of crashes occurred in daylight conditions

Year	Crash Severity			Total
	Injury	Fatal	PDO*	
2016	9 (25%)	0 (0%)	27 (75%)	36 (100%)
2017	8 (27%)	0 (0%)	22 (73%)	30 (100%)
2018	11 (42%)	0 (0%)	15 (58%)	26 (100%)
2019	16 (39%)	0 (0%)	25 (61%)	41 (100%)
2020	8 (32%)	0 (0%)	17 (68%)	25 (100%)
Total	52 (33%)	0 (0%)	106 (67%)	158 (100%)



Neighborhood Traffic Management Program (NTMP)

- City of Albuquerque Neighborhood Traffic Management Program Policy Manual
- Nine (9) thresholds, one (1) or more must meet
 1. Over a twenty-four-hour period, 15% of the vehicles traveling in the study area exceeded 7 miles per hour over the speed limit.
 2. Three reported crashes in a 5-year period where the police report identified speed as either a primary or contributing cause of the crash.
 3. A crash involving a pedestrian or cyclist in a school zone in a five-year period.
 4. Over a twenty-four-hour period more than 800 vehicles were counted traveling through the study area and 15% of the vehicles traveling in the study area exceeded 5 miles per hour over the speed limit.
 5. Over a twenty-four-hour period, 15% of the vehicles traveling in the study area exceeded 5 miles per hour over the speed limit and there was at least one reported crash in a 5-year period where the police report identified speed as either a primary or contributing cause of the crash.
 6. Over a twenty-four-hour period, 15% of the vehicles traveling in the study area exceeded 5 miles per hour over the speed limit and a field survey conducted by the Traffic Engineering Division determined that 25% of the peak hour traffic was cut-through traffic.
 7. Over a twenty-four-hour period more than 800 vehicles were counted traveling through the study area and there was at least one reported crash in a 5-year period where the police report identified speed as either a primary or contributing cause of the crash.
 8. Over a twenty-four-hour period more than 800 vehicles were counted traveling through the study area and a field survey conducted by the Traffic Engineering Division determined that 25% of the peak hour traffic was cut-through traffic.
 9. A field survey conducted by the Traffic Engineering Division determined that 25% of the peak hour traffic was cut-through traffic and there was at least one reported crash in 5 years where the police report identified speed as either a primary or contributing cause of the crash.



Traffic Calming Criteria Evaluation Results

Roadway	Meets NTMP Criteria?
Morningside Drive	NO
Washington Street	YES
Constitution Avenue	YES
Mackland Avenue	NO
Avenida del Sol	YES
Montclair Drive	NO





Potential Alternatives

Striping

Benefits

- Low cost to install and modify
- Does not inhibit emergency vehicles

Cons

- Maintenance
- Effectiveness may be low



Traffic Circles

Benefits

- Improves safety
- Lower vehicle speeds
- Reduce conflict points
- Increased access to main street from side street

Cons

- Slows down emergency vehicles
- May eliminate on-street parking
- May require modifications to curb, gutter, and sidewalks



Neckdowns and Bulbouts

Benefits

- Lower vehicle speeds
- Reduces pedestrian crossing distances

Cons

- May reduce on-street parking
- May impact drainage
- May slow right turning emergency vehicles



Lane Narrowing with Center Island/Pedestrian Refuge

Benefits

- Lower vehicle speeds
- Reduces pedestrian crossing distances

Cons

- May reduce on-street parking
- May impact drainage
- May impact driveway access



Speed Humps

Benefits

- Decreases vehicle speeds
- Discourages cut-through traffic
- Low cost to install

Cons

- May increase noise levels as vehicles decelerate and accelerate
- Inhibits emergency vehicles



Examples – Constitution & Washington

- Striping
- Bulbouts



Examples – Washington & Hannett-Sunningdale

- Midblock Crossing
- Bulbout
- Striping



Wilson & Company, Inc., Engineers & Architects



Examples – Constitution & Morningside

- Midblock Crossing
- Bulbout
- Center Island
- Striping



Wilson & Company, Inc., Engineers & Architects



Examples – Mackland & Montclair

- Traffic circle



Wilson & Company, Inc., Engineers & Architects



Examples – Avenida del Sol & Avenida la Resonlana

- Traffic circle



Examples – Avenida del Sol & Morningside

- One-way street
- Bulbout



Wilson & Company, Inc., Engineers & Architects





Public Input

Questions/Comments

- Provide comments tonight
- Email comments to audra.gallegos@wilsonco.com
- Deadline for comments February 21, 2023





Thank you!

Meeting Summary



Meeting Title: McDuffie-Twin Parks Traffic Calming Study – Public Meeting #2

Date: 9/7/2023

Time: 6:00 pm – 7:00 pm

Location: Zoom – City of Albuquerque

Attendees: See page 4. There were 38 attendees, including City of Albuquerque staff and Wilson & Company staff who attended as Panelists.

I. Introduction and Presentation

Audra Gallegos opened the meeting. She then introduced Councilor Tammy Fiebelkorn on the call. The Councilor then described the safety issues within the McDuffie-Twin Parks area and that the meeting would describe the findings of the study.

Audra Gallegos (Wilson & Company) then began a slideshow presentation.

II. Q&A Session

A question & answer session followed the presentation. The questions and responses are listed below:

Participant Question	Project Team Response
Question, via audio: I had a question about the roundabouts. People are basically whipping around the roundabout and there is concern that the cars would then just end up crashing into the houses. Is there going to be any sort of speed calming related to the roundabouts to help prevent those concerns or like bollards along the sides?	Audra: Entering the traffic circle people will slow down due to yield signs, and while entering through them. Then stripping may be included at the approaches to help navigate people through it.
Question, via audio: Crossing the intersection at Mackland and Carlisle that is, I think, the most risk I take every day compared to everything else I do. Was there any discussion or thoughts about how to make it safer?	Councilor: Pedestrian crossing signs have been installed and rapid flashing beacons are expected to be install relatively soon.
Question, via audio: Could someone reiterate what was just said about the Montclair and Mackland intersection?	Audra: An elongated traffic circle is proposed at this intersection. Drivers would have to slow down entering the intersection and then make their way around the traffic circle in order to make their turning movements.
Question, via audio: When I look at the data that was presented, there was not much data to warrant a traffic calming technique. As extreme as that elongated traffic circle, can you enlighten me in the thinking behind this (Montclair and Mackland intersection)?	Audra: At this intersection, we looked at sight distances since it is not a conventional four-legged intersection. Therefore, an elongated traffic circle would help. This would help slow people down entering the intersection, and they would have to go around the traffic circle.
Question, via audio: Are the lanes full size lanes at the traffic circles for big vehicles to make turns? Big vehicles might not be able to	Audra: In the design process, we will model vehicle turning templates based on different vehicles.

Participant Question	Project Team Response
navigate through the traffic circle (Montclair and Mackland intersection).	
Comment, via audio: If you want to slow people down, move the stop sign on Solano at Mackland to Montclair.	Audra: Thank you, we can look at the volumes at this intersection and see if moving the stop sign would be warranted.
Comment, via audio: When approaching pedestrian islands, it seems like drivers feel like it is a bottleneck. And what winds up happening is that drivers wind up merging into the bike lane. Maybe adding delineators would prevent drivers from winding up merging into the bike lanes.	Tim Brown: We will look into adding delineators or some kind of separator. I appreciate that comment very much.
Comment, via audio: I guess delineators would also be needed at the Constitution and Washington intersection. I am assuming from the pictures shown that there is a bulb out for cyclist to ride through it. Cyclist can ride through that. OK, yeah, this is looking amazing. Like I said, I ride down here five days a week. I use Constitution and I see people crossing the street all the time. They are waiting there with their dogs ready to walk to the park. So, this is really good stuff. I appreciate the work here.	Audra: Yes. So, there would essentially be a curb cut through it and the bicyclist could ride through it. Thank you so much.
Question, via chat: Please confirm which park would have the no parking at the entrances?	Audra: That is the McDuffie Hidden Park. No parking signs would be placed at the various entrances around the park.
Comment, via chat: In other cities, I have seen parking curbs used as protected bike lanes, maybe a potential escalation if the flexible delineators do not work well.	
Comment, via audio: I really want to strongly emphasize to the city that they have to do something about speed limits.	Councilor: Thank you. I do think that is one of the main reasons that we are doing this study and looking for alternatives to do traffic calming in these areas because residents are walking to that park, biking to work. I know I might not be able to solve the speeding problem citywide. But you know, these kinds of interventions can calm traffic down and that is the whole hope here. But I definitely hear your frustration and I share it.
Question, via audio: Is there any plans for adding mid-block traffic calming, like speed bumps or other things like that?	Audra: Speed bumps cannot be placed on emergency routes such as arterials which limits where they can be placed. Adding some improvements along Washington at Hannah and Sunningdale hopefully will help reduce speeding.
Question, via chat: For the segment of Washington between Hannett and Constitution,	Audra: We decided not to change the parking lane at this particular intersection.

Participant Question	Project Team Response
did you change the parking lane from the east to the west as previously proposed?	

III. Closing and Schedule

Audra: If any additional questions or comments please email them to me. (Audra put the contact info back on the screen.) The presentation from tonight will be placed on the project webpage. The meeting concluded.

IV. Summary of Comments Received after the Public Meeting

Public comments were accepted for a two-week period after the public meeting. A total of 60 emails were received. The following is a summary of the comments received:

- Out of the 60 emails, twenty-seven (27) emails were in support of all six traffic calming measures proposed.
- Few of the proposed traffic calming measures got additional support such as:
 - For – mid-block crossing, bulbouts, and stripping at Washington and Hannett/Sunningdale (36 emails)
 - For – stripping and bulbouts at Constitution and Washington (32 emails)
 - For – mid-block crossing, bulbouts, and center island at Constitution and Morningside (32 emails)
 - For – speed bumps along Avenida Del Sol (29 emails)
- Two (2) commenters were opposed to the traffic circle at Mackland and Montclair.
 - Additional comments received were as follows:
 - Adding delineators at the intersections with the proposed bulbouts
 - Conduct a speed study along Indian School near the intersection with Washington, look at speed bumps along Indian School
 - Conduct a speed study along Washington near the intersection with Indian School, look at speed bumps for northbound approach
 - Nine (9) emails related to drivers ignoring the stop sign at Aspen and Hannett
 - Six (6) emails mentioned drivers speeding through Altura Park Neighborhood, using it as a cut-through traffic between Carlisle and Washington potentially conducting a speed study in this area
 - Look at the possibility of adding speed cushions on Washington and Constitution
 - Adding striped crosswalks at entrances to McDuffie Park
 - An additional assessment of sidewalk condition and medians to be conducted within the study area
 - Limited visibility for pedestrians crossing Constitution and Morningside
 - Two (2) emails mentioned conducting a safety study at Hannett and Aspen

V. Meeting Attendees

Attendee Name

Luis Sutherlin	iPhone 505-XXX-XXXX
Alexis Tappan	Austin Anaya
Barry	Bryan Dombrowski
Carol Morris	Charles Bachechi
Chris	Connor Boyle
David Esdale	Eric & Mary
Fayenorth	Hilmac
Ian	iPhone
J. Hunter	Jennifer Brower
Justin Carmona	KC Roehl
Keenan Ryan	Keith Stubbs
Klaus	Kristin Oreskovich
Kristine Yamiki	Marlene Hubbard
Martha Hardman	Patrick Martin
Rich Borncamp	Victor Davis



McDuffie-Twin Parks Traffic Calming Study

Public Meeting

WILSON
& COMPANY

discipline | intensity | collaboration | shared ownership | solutions

Introductions

City of Albuquerque

- Councilor Tammy Fiebelkorn
- Aziza Chavez– Council Services
- Tom Menicucci– Council Services
- Justin Carmona – Council Services
- Tim Brown, PE – Traffic Engineering Manager
- Roberto Gallegos – Traffic Engineering
- Manh Tran – Traffic Engineering


Wilson & Company

- Audra Gallegos, PE
- Lorenzo Cornejo, EI



Study Limits

- Study Limits: McDuffie-Twin Parks Neighborhood
 - Washington Street
 - Constitution Avenue
 - Morningside Drive
 - Marble Avenue
 - Montclair Drive
 - Mackland Avenue
 - Avenida del Sol
 - Solano Drive
- Posted Speed Limit: 25-30 mph



Wilson & Company, Inc., Engineers & Architects



Purpose of Tonight's Meeting

- Reintroduce project
- Present alternatives
- Public input – we want to hear from you!



Schedule

- Existing Conditions Report – December 2022
- Public Meeting #1 – February 2023
- Identification of Improvements and Recommendations – Summer 2023
- Public Meeting #2 – Tonight's meeting
- Final Report – Fall 2023





Existing Conditions

Tube Count Data

- Tube counts (volume, speed)
- 48-hour period
- 15% of vehicles exceeding 5 mph and 7 mph

Location	Speed	Percentage of Vehicles Exceeding Speed Limit			
		Wednesday		Thursday	
		Counter per Direction 1	Counter per Direction 2	Counter per Direction 1	Counter per Direction 2
Morningside Drive (North of Aspen Ave.)	5 mph	0%	0%	0%	0%
	7 mph	0%	0%	0%	0%
Morningside Drive (South of Aspen Ave.)	5 mph	15%	8%	15%	10%
	7 mph	8%	2%	10%	3%
Washington Street (North of Sunningdale Ave.)	5 mph	14%	41%	16%	45%
	7 mph	7%	24%	7%	27%
Washington Street (South of Sunningdale Ave.)	5 mph	8%	35%	10%	39%
	7 mph	3%	20%	5%	23%
Washington Street (South of Avenida Estrellita)	5 mph	18%	25%	24%	31%
	7 mph	9%	12%	12%	15%
Washington Street (South of Avenida Del Sol)	5 mph	6%	13%	6%	18%
	7 mph	2%	6%	3%	8%
Constitution Drive (West of Morningside Ave.)	5 mph	34%	39%	33%	39%
	7 mph	21%	22%	18%	23%
Constitution Drive (East of Morningside Ave.)	5 mph	73%	30%	73%	31%
	7 mph	61%	16%	60%	18%
Avenida Del Sol (West of Mackland Ave.)	5 mph	7%	25%	2%	20%
	7 mph	3%	19%	0%	11%
Avenida Del Sol (East of Mackland Ave.)	5 mph	2%	22%	4%	19%
	7 mph	1%	14%	2%	13%
Morningside Drive (North of Mackland Ave.)	5 mph	6%	7%	6%	9%
	7 mph	3%	2%	2%	6%
Marble Avenue (South of Mackland Ave.)	5 mph	7%	7%	6%	7%
	7 mph	4%	3%	4%	3%
Mackland Avenue (West of Montclair Dr.)	5 mph	5%	12%	6%	12%
	7 mph	3%	7%	2%	8%
Mackland Avenue (East of Montclair Dr.)	5 mph	0%	0%	0%	0%
	7 mph	0%	0%	0%	0%
Montclair Drive (South of McDuffie Cir.)	5 mph	13%	13%	6%	16%
	7 mph	5%	6%	2%	7%
Montclair Drive (North of Mesa Verde Ave.)	5 mph	14%	9%	12%	11%
	7 mph	8%	4%	7%	5%



Tube Count Data Solano Drive

- Tube counts (volume, speed)
- 48-hour period
- 15% of vehicles exceeding 5 mph and 7 mph

Location	Speed	Percentage of Vehicles Exceeding Speed Limit			
		Wednesday		Thursday	
		Counter per Direction 1	Counter per Direction 2	Counter per Direction 1	Counter per Direction 2
Solano Drive (North of Aspen Ave.)	5 mph	21%	18%	17%	11%
	7 mph	14%	12%	10%	5%
Solano Drive (North of Lomas Blvd.)	5 mph	2%	5%	5%	5%
	7 mph	2%	2%	1%	2%



Pedestrian Count Data

- Camera (pedestrians, bicyclists)
- 13-hour period

Intersection	Time	Pedestrian 13-hr Volume				Bicyclist 13-hr Volume			
		South Leg	West Leg	North Leg	East Leg	NB	EB	SB	WB
Washington St. and Sunningdale Ave.	AM Peak	15	2	16	3	4	0	3	2
	PM Peak	1	2	9	1	8	3	3	0
	13 Hour Total	53	19	87	13	58	11	48	6
Washington St. and Constitution Ave.	AM Peak	2	2	1	3	0	2	2	4
	PM Peak	2	2	0	0	0	4	3	0
	13 Hour Total	9	8	3	4	17	39	18	36
Morningside Dr. and Constitution Ave.	AM Peak	4	5	1	10	0	2	2	6
	PM Peak	3	12	0	9	1	5	1	0
	13 Hour Total	16	71	12	57	22	37	15	37




Crash Data

- 2016-2020
- 158 total crashes
- 88% of crashes occurred in clear weather conditions
- 72% of crashes occurred in daylight conditions

Year	Crash Severity			Total
	Injury	Fatal	PDO*	
2016	9 (25%)	0 (0%)	27 (75%)	36 (100%)
2017	8 (27%)	0 (0%)	22 (73%)	30 (100%)
2018	11 (42%)	0 (0%)	15 (58%)	26 (100%)
2019	16 (39%)	0 (0%)	25 (61%)	41 (100%)
2020	8 (32%)	0 (0%)	17 (68%)	25 (100%)
Total	52 (33%)	0 (0%)	106 (67%)	158 (100%)

*PDO-Property damage only



Neighborhood Traffic Management Program (NTMP)

- City of Albuquerque Neighborhood Traffic Management Program Policy Manual
- Nine (9) thresholds, one (1) or more must meet
 1. Over a twenty-four-hour period, 15% of the vehicles traveling in the study area exceeded 7 miles per hour over the speed limit.
 2. Three reported crashes in a 5-year period where the police report identified speed as either a primary or contributing cause of the crash.
 3. A crash involving a pedestrian or cyclist in a school zone in a five-year period.
 4. Over a twenty-four-hour period more than 800 vehicles were counted traveling through the study area and 15% of the vehicles traveling in the study area exceeded 5 miles per hour over the speed limit.
 5. Over a twenty-four-hour period, 15% of the vehicles traveling in the study area exceeded 5 miles per hour over the speed limit and there was at least one reported crash in a 5-year period where the police report identified speed as either a primary or contributing cause of the crash.
 6. Over a twenty-four-hour period, 15% of the vehicles traveling in the study area exceeded 5 miles per hour over the speed limit and a field survey conducted by the Traffic Engineering Division determined that 25% of the peak hour traffic was cut-through traffic.
 7. Over a twenty-four-hour period more than 800 vehicles were counted traveling through the study area and there was at least one reported crash in a 5-year period where the police report identified speed as either a primary or contributing cause of the crash.
 8. Over a twenty-four-hour period more than 800 vehicles were counted traveling through the study area and a field survey conducted by the Traffic Engineering Division determined that 25% of the peak hour traffic was cut-through traffic.
 9. A field survey conducted by the Traffic Engineering Division determined that 25% of the peak hour traffic was cut-through traffic and there was at least one reported crash in 5 years where the police report identified speed as either a primary or contributing cause of the crash.



Traffic Calming Criteria Evaluation Results

Roadway	Meets NTMP Criteria?
Morningside Drive	NO
Washington Street	YES
Constitution Avenue	YES
Mackland Avenue	NO
Avenida del Sol	YES
Montclair Drive	NO
Solano Drive	NO





Public Meeting #1 Input

Public Input

Received 48 emails

Most For:

- Traffic circle
- Bulbouts – only if they don't affect bike lanes
- Pedestrian crossings
- Speed humps

Most Opposed:

- One-way on Avenida del Sol

Additional Requests:

- Include Solano Drive – added to study
- Multiway stops – need to meet FHWA requirements





Proposed Alternatives

Constitution & Washington

- Striping
- Bulbouts



Wilson & Company, Inc., Engineers & Architects



Washington & Hannett-Sunningdale

- Midblock Crossing
- Bulbout
- Striping



Wilson & Company, Inc., Engineers & Architects



Constitution & Morningside

- Midblock Crossing
- Bulbout
- Center Island
- Striping



Wilson & Company, Inc., Engineers & Architects



Mackland & Montclair

- Elongated traffic circle



Wilson & Company, Inc., Engineers & Architects



Avenida del Sol

- Not an emergency route
- Speed humps



Wilson & Company, Inc., Engineers & Architects



Park Entrances

- No parking striping at entrances





Public Input

Questions/Comments

- Provide comments tonight
- Email comments to audra.gallegos@wilsonco.com
- Deadline for comments September 21, 2023





Thank you!

Appendix D – Conceptual Cost Estimates

Prepared by



4401 Masthead Street NE, Suite 150
Albuquerque, NM 87109
505-348-4000