PDF ANALYSIS - ISSUES SUMMARY WITH COORDINATES

Issue #1: Confidence: 0.95

Dimension 6'-11' missing inch symbol

Location: [371.1, 219.1] Coordinates: [371.1, 219.1]

Correct to 6'-11"

Issue #2: Confidence: 0.95

Dimension 5'-51' ambiguous Location: [354.8, 223.4] Coordinates: [354.8, 223.4]

Correct to intended value (e.g., 5'-5" or 5'-5 1/2")

Issue #3: Confidence: 0.95

Units note missing Location: [702.3, 460.6] Coordinates: [702.3, 460.6]

Add global units note in title block

Issue #4: Confidence: 0.95

Grid system unclear (numeric stack 1·13) Location: [308.0, 170.0, 352.4, 249.1] Coordinates: [308.0, 170.0, 352.4, 249.1]

Convert to proper grid or remove; provide clear chained dimensions

Issue #5: Confidence: 0.95

Missing overall elevation dimensions Location: [60.0, 150.0, 640.0, 300.0] Coordinates: [60.0, 150.0, 640.0, 300.0] Add overall width/height baselines

Issue #6: Confidence: 0.95

Datum levels not indicated clearly

Location: [165.8, 273.0] Coordinates: [165.8, 273.0]

Add FFL/ceiling/lintel datums on sections

Issue #7: Confidence: 0.95

Detail A missing sheet reference

Location: [637.8, 157.5] Coordinates: [637.8, 157.5]

Add complete reference (e.g., A/INT_LB_LT-xx)

Issue #8: Confidence: 0.95

Detail B (upper) missing sheet reference


Location: [221.7, 114.7] Coordinates: [221.7, 114.7] Add complete reference

Issue #9: Confidence: 0.95

Duplicate Detail B tag (lower) Location: [539.6, 354.8]

Coordinates: [539.6, 354.8]

Rename uniquely (e.g., Detail C) with sheet ref



Issue #10: Confidence: 0.95

Generic ·as/detail· ambiguous Location: [425.7, 282.3] Coordinates: [425.7, 282.3]

Replace with explicit detail reference

Issue #11: Confidence: 0.95

Section B-B- lacks plan cross-ref

Location: [165.8, 273.0] Coordinates: [165.8, 273.0]

Add plan sheet/section cut reference

Issue #12: Confidence: 0.95

Section D-D- lacks plan cross-ref

Location: [190.9, 497.5] Coordinates: [190.9, 497.5]

Add plan sheet/section cut reference

Issue #13: Confidence: 0.95

Legend missing

Location: [700.0, 350.0, 820.0, 410.0] Coordinates: [700.0, 350.0, 820.0, 410.0] Add legend for symbols/abbreviations

Issue #14: Confidence: 0.95

North arrow missing Location: [780.0, 140.0] Coordinates: [780.0, 140.0]

Add north arrow

Issue #15: Confidence: 0.95

Scale unacceptable for working drawing

Location: [702.3, 460.6] Coordinates: [702.3, 460.6]

Provide working scale (e.g., 1:25)

Issue #16: Confidence: 0.95

N.T.S. punctuation nonstandard

Location: [702.3, 460.6] Coordinates: [702.3, 460.6]

Use ·N.T.S.·

Issue #17: Confidence: 0.95

Drawing title content incomplete

Location: [703.9, 421.9] Coordinates: [703.9, 421.9]

Populate with Basement Lobby Wall Elevations and drawing no.

Issue #18: Confidence: 0.95

Date format inconsistent Location: [749.6, 459.7] Coordinates: [749.6, 459.7]

Use ISO or office-standard format consistently

Issue #19: Confidence: 0.95

Revision table empty

Location: [707.3, 280.0], [728.8, 279.8]

Coordinates: [707.3, 280.0] Populate revision entries

Issue #20: Confidence: 0.95

Plotting scale unverifiable Location: [702.3, 460.6] Coordinates: [702.3, 460.6]

Provide scale and graphic scale bar

Issue #21: Confidence: 0.95

Sheet/plot info missing

Location: [680.0, 380.0, 830.0, 590.0] Coordinates: [680.0, 380.0, 830.0, 590.0] Add sheet size and plotting instructions

Issue #22: Confidence: 0.95

Project title verification Location: [710.9, 78.8] Coordinates: [710.9, 78.8] Ensure exact contract title

Issue #23: Confidence: 0.95

Legal note formatting Location: [707.3, 54.5] Coordinates: [707.3, 54.5] Reformat to avoid crowding

Issue #24: Confidence: 0.95

DWG name not populated

Location: [700.0, 430.0, 820.0, 470.0] Coordinates: [700.0, 430.0, 820.0, 470.0] Fill in DWG name per CAD standard