



A



B



C




Figure 4. Variation in the speed of melanization reaction between the resistant and susceptible lines. (A) The images taken at 18h, 24h and 26h after *L. boulardi* G486 infection of lines 437 and lines 892. (B) Proportion of oil droplets with signs of melanization at different time points post injection in the resistant and susceptible lines. Points represent means and error bars the 95% confidence interval.