COMAP - Vane angle vs TOD

Jonas Gahr Sturtzel Lunde (jonassl@astro.uio.no)

July 27, 2020

Relevant code found at https://github.com/jgslunde/comap_general/tree/master/vane_angle





Figure 1 – Normalized TOD power (thin lines) for a handful of feeds of a single level 1 file, together with vane angle (black dots) over a Tsys measurements. The TOD/angle relation should be completely symmetric in time, but a light offset can be seen (the TOD is seemingly lagging behind the vane angle). Another (expected) observed effect is the different widths of feeds TOD top hat, due to their differing physical placements on the feed array.



 $\mathbf{Figure}\ 2-\mathit{Same}\ \mathit{setup}\ \mathit{as}\ \mathit{1.}\ \mathit{Normalized}\ \mathit{TOD}\ \mathit{power}\ \mathit{interpolated}\ \mathit{on}\ \mathit{and}\ \mathit{plotted}\ \mathit{against}\ \mathit{vane}\ \mathit{angle}.$





Figure 3 – Same type of plot as 2, but with all feed 1 obsids from 2020-04. We would expect the TOD/vane relation to be consistent between "vane descending" and "vane ascending", but we see two very distinct TOD/angle curves. This again strongly hints at an offset between the TOD and angle timestamps.



 $\textbf{Figure 4} - \textit{Introducing an offset of 7e-6 MJD (0.6 seconds) solves the problem, and gives us the plot like we expect it to look. \\$




Figure 5 – Same plot as above, but with feed 8, which is the farthest from the calibration vane, and therefore has the "worst" TOD/angle relation. We see that maximum power isn't reached until the vane as descended to at least 70 degrees.




Figure 6 – Plots showing the first 10 (above) and 1 (below) seconds of time stamps of the TOD, vane, and array. The offset we had to be introduced to get consistent results in previous plots is also shown, as a black line.




Figure 7 – Scatter plot showing the power/angle relation of the calibration vane for all feeds, binned to 0.25 degrees. 12 months of level 1 files, from 2019-07 through 2020-06 was used.




Figure 8 - Angles for which the different feeds pass below the 97.5% power threshold, ordered after their physical placement on the array.





Figure 9 – Scatter plot showing the power/angle relation of the calibration vane for the three "worst" feeds, binned to 0.25 degrees. Error bars show $\sigma(x)/\sqrt{N}$, magnified by a power of 10, for clarity.



 $\mathbf{Figure}\ \mathbf{10} - \textit{Difference from previous bin in 0.25 degree binned power/angle relation}.$