





Thick Thinsulate carpet on the floor: room error below 3 kHz 1.408 → 1.277 dB (-0.131)

2026-09-23 · arc vertical · sphere 20 cm back along the axis · 95 tones · 11 calibrated capsules



Hz (3-5 kHz omitted: the sphere is not axisymmetric there). +90° = top, -90° = bottom