






Roll of material on the wall the speaker fires toward (instead of the curtain): room error below 3 kHz 1.472 → 1.403 dB (-0.069, better)

2026-09-25/in-plane-a → 2026-09-25/material-roll · below 3 kHz, 465 of 946 cells moved >0.05 dB toward flat and 395 away from it · 95 tones · 11 calibrated capsules



Hz (3-5 kHz omitted: the sphere is not axisymmetric there). +90° = top, -90° = bottom