




Floor states compared: an evenly laid carpet is the worst of all




wedges + Thinsulate (old tripod) — 1.277 dB below 3 kHz (floor-carpet)




heaped carpet, no wedges (old tripod) — 1.324 dB below 3 kHz (2026-09-24/chaotic-carpet-3)




wedges only (old tripod) — 1.400 dB below 3 kHz (2026-09-24/bare-day2)




carpet laid flat, no wedges (old tripod) — 1.642 dB below 3 kHz (2026-09-24/carpet-added)




bare foam, everything removed (old tripod) — 2.054 dB below 3 kHz (2026-09-24/floor-no-wedges)



heaped carpet, no wedges (new levelled mount) — 1.443 dB below 3 kHz (2026-09-24/center-levelled)



EVEN thick carpet (new levelled mount) — 2.540 dB below 3 kHz (2026-09-24/floor-even-carpet)



Hz (3-5 kHz omitted: the sphere is not axisymmetric there). +90° = top, -90° = bottom