dubizzle cars

English



0097 144501601
Book Inspection Now


Overview | Basic Detail | Exterior Condition | Comments

2017 - Honda Civic

8.1 / 10








Do not solely rely on dubizzle car inspection for your car purchase decision.

Car Details

Test Drive	Done
Model	Civic
Year	2017
Registered Emirates	Dubai
No. of Cylinders	4
Seating Capacity	5 Seater
Interior Color	Tan
Specs	GCC Specs

Fuel Type	Petrol
Service History	Partial
Mortgage	Yes

Make	Honda
Trim	Exi
Odometer Reading (KM/M)	163186
Engine CC	2000
Horsepower (in BHP)	156
Number of Doors	4 Door
Body Type	Sedan
Transmission Type	Automatic
Color	Black
No. of Keys	1
Vehicle Findings	Underneath Fully Covered

Test Drive	Done
Make	Honda
Model	Civic
Trim	Exi
Year	2017
Odometer Reading (KM/M)	163186
Registered Emirates	Dubai

View More

Summary

Car Details 100%	Exterior Body Damage Diagram 50.8%	Front Left Wheel & Tyre 100%
Front Right Wheel & Tyre 100%	Rear Left Wheel & Tyre 100%	Rear Right Wheel & Tyre 100%
Engine & Transmission 94.6%	Steering, Suspension & Brakes 100%	Frame Condition 70%


Interior, Electricals & Air Conditioner 75%

Car Specs 100%

Exterior Condition

* Click or tap on the number(s) to see defect details

View All Faults



Fully Repainted

Partially Repainted

Car Body

Front Windscreen	Chip
Bonnet	Chip +1
Front Bumper	Dent +2
Front Right Fender	Chip +3
Front Right Door	Scratch +3
Back Right Door	Dent +2
Right Running Board	Scratches
Back Right Fender	Chip +2
Car Trunk	Dent
Rear Bumper	Repair +2
Back Left Fender	Repair +2
Back Left Door	Dent +1
Front Left Door	Scratch +2
Front Left Fender	Dent +2
Left Running Board	Scratches

Wheel And Tyre

Front Left

100%

Manufacturer	Date (Year)
Dunlop	24

Tread
5-7.5

Condition
No visible fault

Rims/Alloys
Scratch

Front Right 100%

Manufacturer
Dunlop

Date (Year)
24

Tread
5-7.5

Condition
No visible fault

Rims/Alloys
Scratch

Rear Left 100%

Manufacturer
Dunlop

Date (Year)
24

Tread
5-7.5

Condition
No visible fault

Rims/Alloys
Scratch

Rear Right 100%

Manufacturer
Dunlop

Date (Year)
24

Tread
5-7.5

Condition
No visible fault

Rims/Alloys
Scratch

Spare Wheel Available ✓

Engine & Transmission 94.6%

Steering, Suspension & Brakes 100%

Frame Condition 70%

Interior, Electricals & Air Conditioner 75%

Car Specs 100%

Comments

Door beadings & exterior Weatherstrips are deformed. Minor scratches on the door pads & interior trim panels. RR LH wheel housing repaired. Valve cover resealed. Major scratches, dents & chips on the exterior. Suspension components refitted. Oil wetness on the rear crank seal area.

Report Information

Inspection Date
Jul 14, 2026

Inspection Time
11:15 AM

Reference #
212857

Disclaimer

1. The inspection is strictly limited to the items listed in this Inspection Report and does not cover any other items. 2. The inspection is visual and non-mechanical only. If you wish to complete a mechanical inspection or an inspection of the internal parts of the vehicle, dubizzle encourages you to contact a different service provider who undertakes that type of inspection. 3. dubizzle does not inspect historic service records or accident records for the vehicle, and does not check whether the vehicle is subject to a recall notice. 4. While dubizzle uses accepted methods for inspecting the vehicle, these methods do not necessarily identify all faults with the vehicle. In particular, the inspection does not cover intermittent problems which are not apparent at the time of the inspection. 5. This Inspection Report, and all intellectual property rights therein, will remain the exclusive property of dubizzle. 6. This Inspection Report represents dubizzle's subjective opinion as to the condition of the vehicle (limited to the specific items listed in this Inspection Report), considering the age and condition of the vehicle at the time of inspection and based on the dubizzle inspector's knowledge and experience. This Inspection Report is designed to assist you to make decisions based on the general condition of the vehicle only. dubizzle will not provide a recommendation as to whether to sell or purchase the vehicle. 7. dubizzle can only advise on the condition of the vehicle at the time of the inspection, and this Inspection Report is only current as at the time it is issued. If you are considering purchasing the vehicle, it is your responsibility to conduct a further inspection of the vehicle at the time of purchase. 8. This Inspection Report is provided by dubizzle 'as is' for your information only, without any warranties whatsoever. In particular, dubizzle does not provide any warranty regarding the accuracy or completeness of any information contained in this Inspection Report, or the fitness of the information contained in this Inspection Report for any purpose intended. 9. If this Inspection Report is provided to you directly by dubizzle, only you may rely on the content of this Inspection Report, and dubizzle does not accept any liability whatsoever to any third-party you may choose to share this Inspection Report with. 10. If this Inspection Report is provided to you by someone else than dubizzle, you may not rely on the content of this Inspection Report, and dubizzle does not accept any liability whatsoever to you in connection with this Inspection Report.