VEHICLE INSPECTION

Comprehensive Inspection Report

2024 Nissan Sunny

Prepared for SAMPLE ONLY - Not a real inspection

REPORT NO.	DATE	POINTS
WD-260722-D002	23-JUL-2026	135

WEBSITE
www.thewheelerdealers.com

EMAIL
info@thewheelerdealers.com

Inspection Details

Date	Time	Inspection Type	VIN Number
23-JUL-2026	01:00 PM	135-Point	–

Vehicle Summary

Nissan

Sunny SV



SAMPLE ONLY: 2024 Versa front, not the inspected Sunny. Photo: Deathpallie325 / Wikimedia Commons. CC BY 4.0: https://creativecommons.org/licenses/by/4.0/ Resized.

Make	Nissan
Model	Sunny
Model Year	2024
Trim	SV
Body Type	Sedan
Regional Specs	GCC
Transmission	Automatic
Fuel Type	Petrol
Exterior Colour	Grey
Odometer	55,285 km · Genuine
Number of Keys	2
Spare Tyre	Available
Inspection Location	Al Quoz, Dubai
Inspector	Omar Haddad


Report Overview

RECOMMENDED WITH REPAIRS

135 inspection points checked. 129 passed, 4 need attention, 2 failed.

- Pass — 96%
- Attention — 3%
- Fail — 1%

Overall condition score **8.2**/10



Exterior

26 pass · 2 attention · 0 fail

Front bumper ATTENTION Scuff on lower left corner, cosmetic	**Rear bumper** PASS
Bonnet / hood PASS	**Roof** PASS
Boot / tailgate PASS	**Front-left fender** PASS
Front-right fender PASS	**Rear-left fender** PASS
Rear-right fender PASS	**Front-left door** ATTENTION Small dent, paint intact
Front-right door PASS	**Rear-left door** PASS
Rear-right door PASS	**Front windshield** PASS
Rear windshield PASS	**Left windows** PASS
Right windows PASS	**Left headlight** PASS
Right headlight PASS	**Left taillight** PASS
Right taillight PASS	**Fog lights** PASS
Side mirrors PASS	**Exterior trim & mouldings** PASS
Number plates PASS	**Wiper blades** PASS
Overall paint condition PASS	**Panel gaps & alignment** PASS

Interior

22 pass · 0 attention · 0 fail

Dashboard	PASS	Steering wheel	PASS
Driver seat	PASS	Passenger seat	PASS
Rear seats	PASS	Seatbelts	PASS
Headliner	PASS	Carpets & mats	PASS
Door panels	PASS	Center console	PASS
Glovebox	PASS	A/C cooling	PASS
Heater	PASS	Infotainment / display	PASS
Speakers / audio	PASS	Instrument cluster	PASS
Interior lights	PASS	Sunroof / moonroof	PASS
Cup holders & storage	PASS	Boot interior & tools	PASS
Rear A/C vents	PASS	Cabin odour / cleanliness	PASS

Mechanical

21 pass · 1 attention · 0 fail

Engine start	PASS	Engine idle	PASS
Engine noise	PASS	Engine oil level	PASS
Engine oil condition Dark — service due	ATTENTION	Coolant level	PASS
Coolant leaks	PASS	Brake fluid	PASS

Power steering fluid	PASS	Transmission fluid	PASS
Transmission shifting	PASS	Drive belts	PASS
Hoses	PASS	Radiator	PASS
Water pump	PASS	Engine mounts	PASS
Oil leaks	PASS	Exhaust smoke	PASS
Timing belt / chain	PASS	Air filter	PASS
Throttle body	PASS	Turbo / supercharger	N/A
Clutch (if manual)	N/A	Engine bay cleanliness	PASS

Tyres & Brakes

14 pass · 0 attention · 2 fail

Front-left tyre tread	FAIL Tread 1.8 mm — below legal minimum, replace before use	Front-right tyre tread	PASS
Rear-left tyre tread	PASS	Rear-right tyre tread	PASS
Front-left tyre condition	PASS	Front-right tyre condition	PASS
Rear-left tyre condition	PASS	Rear-right tyre condition	PASS
Spare tyre	PASS	Front brake pads	FAIL Pads ~2 mm remaining, replace soon
Rear brake pads	PASS	Front brake discs	PASS
Rear brake discs	PASS	Handbrake / parking brake	PASS

ABS operation	PASS	Wheel alignment	PASS

Underbody

14 pass · 0 attention · 0 fail

Chassis / frame	PASS	Subframe	PASS
Front suspension	PASS	Rear suspension	PASS
Shock absorbers	PASS	Control arms	PASS
Ball joints	PASS	Steering rack	PASS
CV joints & boots	PASS	Exhaust system	PASS
Fuel tank & lines	PASS	Underbody corrosion	PASS
Engine undertray	PASS	Differential / axles	PASS

Electrical

17 pass · 1 attention · 0 fail

Battery health Tested 11.9V at rest, weak	ATTENTION	Battery terminals	PASS
Alternator charging	PASS	Starter motor	PASS
Headlights operation	PASS	Indicators	PASS
Hazard lights	PASS	Brake lights	PASS
Reverse lights	PASS	Interior lighting	PASS
Power windows operation	PASS	Central locking	PASS
Front wipers	PASS	Rear wiper	PASS

Washer jets	PASS	Sensors & warning lights	PASS
Reverse camera / sensors	PASS	Key fob / remote	PASS

Road Test

15 pass · 0 attention · 0 fail

Cold start	PASS	Acceleration	PASS
Engine power	PASS	Gear shifts	PASS
Clutch engagement	N/A	Braking performance	PASS
Steering response	PASS	Steering noise	PASS
Suspension ride	PASS	Wheel bearing noise	PASS
Cruise control	PASS	Cabin noise (NVH)	PASS
Vibrations	PASS	A/C during drive	PASS
Warning lights during drive	PASS	Parking brake hold	PASS

Inspector's Findings

VERDICT **Recommended with repairs**

2 points failed and need attention

FAIL **Tyres & Brakes:** Front-left tyre tread — Tread 1.8 mm — below legal minimum, replace before use

FAIL **Tyres & Brakes:** Front brake pads — Pads ~2 mm remaining, replace soon

SUMMARY

DEMONSTRATION ONLY - not a real inspection. Ratings, mileage and findings below are fictional sample data. Photos show reference Nissan Versa vehicles, not this Sunny, and do not prove any condition or defect.

Overall the vehicle is in good mechanical and structural condition with no signs of accident repair. Two safety items need immediate attention: the front-left tyre is below legal tread depth and the front brake pads are near end of life. Minor cosmetic wear noted on the front bumper and driver door. Engine oil is due for service and the battery is weak.

RECOMMENDED REPAIRS

1. Replace front-left tyre (below 2 mm)
2. Replace front brake pads
3. Engine oil & filter service
4. Test / replace battery (11.9 V at rest)
5. Optional: cosmetic repair to front bumper and front-left door

Vehicle Photos



SAMPLE ONLY: 2024 Versa rear, not the inspected Sunny. Photo: Deathpallie325 / Wikimedia Commons. CC BY 4.0: https://creativecommons.org/licenses/by/4.0/ Resized.



SAMPLE ONLY: 2024 Versa interior, not the inspected Sunny. Photo: Deathpallie325 / Wikimedia Commons. CC BY 4.0: https://creativecommons.org/licenses/by/4.0/ Resized.

Thank You for Choosing The Wheeler Dealers

www.thewheelerdealers.com

Buy. Sell. Trade. Smarter.

This report reflects the condition of the vehicle at the time and place of inspection, based on a visual and functional check by a Wheeler Dealers inspector. It is not a warranty or guarantee of future performance. Report No. WD-260722-D002.