

INSPECTION REPORT

TEST SIKA Corp

QSP NOT

Overall Status



Overall: POTENTIAL PERMIT VIOLATIONS

Project Information

Project:	TEST SIKA Corp
Location:	14090 Slover Ave, Fontana, CA 92337, USA
WDID#:	502369
Inspector:	Sarina McMann
Date:	11/27/2025
QSP:	Sarina McMann

Summary

overall site looked good

Recommendations

none

Certification and Signature

Inspector: Sarina McMann

Date: 11/27/2025

Credential: 12345

Designation: QSP

NOAA WEATHER REPORT

72-Hour Forecast

Weather Summary

MAX POP
(72H)
0%


TOTAL QPF
(72H)
0 in

Weather Station: Fontana-Arrow Highway


72-Hour Forecast Details

THU 11/27, 11 PM	FRI 11/28, 1 AM	FRI 11/28, 7 AM	FRI 11/28, 1 PM	FRI 11/28, 7 PM	SAT 11/29, 1 AM	SAT 11/29, 7 AM	SAT 11/29, 1 PM	SAT 11/29, 7 PM	SUN 11/30, 1 AM	SUN 11/30, 7 AM	SUN 11/30, 1 PM	SUN 11/30, 7 PM
0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%	0%
0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"	0.00"

Precipitation Chance (%)



Rainfall (inches)



Erosion Control

Soil binders

CORRECTIVE ACTION REQUIRED

Photos



no slope erosion in place

Sediment Control

Site interior linear sediment controls

CORRECTIVE ACTION REQUIRED

Photos



breach of silt fence

Drain inlet protection

POTENTIAL PERMIT VIOLATIONS

Photos



not an approved bmp control

Track-Out Control

Was track out observed leaving the project boundary?

Answer: NO

Wind Erosion Control

Was dust observed leaving the project boundary?

Answer: NO

Non-Storm Water Control

Was water observed to be discharging from the project?

Answer: NO

If yes, was it being pumped or siphoned off site?

Answer: N/A

Good Housekeeping

Concrete washout devices

POTENTIAL PERMIT VIOLATIONS

Photos



washing out directly in dirt, no washout container provided