

Performance cyclonedds

Logfile name b6ad2164-1808-4e4b-9663-e41691e47652.csv Experiment id 31aedb2f-1c41-4ec3-b6fb-5b04804d2a43 ${\bf Communication\ mean\ \ RCLCPP_SINGLE_THREADED_EXECUTOR}$





Resource usage (man getrusage)

test setup

Performance Test Version 2113db4 Publishing rate 100 Topic name PointCloud1m Number of publishers Number of subscribers Maximum runtime (sec) 30 DDS domain id 0 Single participant

| Experiment Status | success |
|----------------------------|--------------|
| T_loop | 1.0001 |
| received | 99.04 |
| sent | 0.0 |
| lost | 0.0 |
| relative_loss | nan |
| data_received | 105115135.24 |
| latency_min (ms) | 0.6244 |
| latency_max (ms) | 1.4782 |
| latency_mean (ms) | 0.6842 |
| latency_variance (ms) | 0.0001 |
| pub_loop_res_min (ms) | \inf |
| pub_loop_res_max (ms) | -inf |
| pub_loop_res_mean (ms) | 0.0 |
| pub_loop_res_variance (ms) | 0.0 |
| sub_loop_res_min (ms) | 0.0 |
| sub_loop_res_max (ms) | 0.0 |
| sub_loop_res_mean (ms) | 0.0 |
| sub_loop_res_variance (ms) | 0.0 |
| cpu_usage (%) | 0.3794 |
| max_ram_usage (MB) | 27.74 |

| Ignore seconds from beginning | 5 |
|-------------------------------|--------------------|
| Memory check enabled | 0 |
| Msg name | PointCloud1m |
| QOS Durability | VOLATILE |
| QOS History depth | 100 |
| QOS History kind | KEEP_LAST |
| QOS Reliability | RELIABLE |
| QOS Sync. pub/sub | C |
| RMW Implementation | rmw_cyclonedds_cpp |
| Roundtrip Mode | NONE |
| With security | C |
| Zero copy transfer | C |
| | |

environment