

Progress Report: DOI-OIA Coral Reef and Natural Resources Initiative
FY2020

Establishment of Self-sustaining Biological Control of Coconut Rhinoceros Beetle Biotype G in Micronesia

Aubrey Moore PhD

University of Guam College of Natural and Applied Sciences

July 30, 2023

Federal ID D20AP00060

Reporting period 2023-01-01 through 2023-06-30

https://github.com/aubreymoore/2020-D0I-CRB-Biocontrol/raw/master/doi_report_202306/doi_report_2023-06.pdf

Contents

1	Objective 1: Survey to Determine Background OrNV Incidence	5
1.1	Previously reported progress	5
1.2	Recent progress	6
2	Objective 2: Establish Sustainable CRB-G Biocontrol by Autodissemination of OrNV	7
2.1	Previously reported progress	7
2.2	Recent progress	8
2.3	Recent Progress	10
3	Objective 3: Establish Island-wide Monitoring Systems for CRB and Coconut Palm Health	11
3.1	Objective 3a: Pheromone Traps	11
3.1.1	Previously reported progress	11
3.1.2	Recent progress	11
3.2	Objective 3b: Roadside Video Surveys	13
3.2.1	Previously reported progress	13
3.2.2	Recent progress	21
3.2.3	Recent progress	24
4	Recent Publications	26
5	References	27

Summary

Project Staff The project's insect pathologist, Dr. James Grasela retired during June 2022. Prior to leaving, he produced 2 presentation posters to document some of his research results [1, 2]. The latter poster was presented at the Annual Meeting of the Entomological Society of America, Vancouver in November 2022. The project currently supports a full time technician, Christian Cayanan and three part time student research assistants. Laura Caser, Raimunt Mesubed and LeahMarie Bukurou. Raimunt and LeahMarie previously worked on CRB research in Palau under Dr. Chris Kitalong.

Laboratory Activities We have established a CRB rearing facility to rear high quality, disease free CRB adults to be used in laboratory bioassays. We have developed a natural larval diet by sterilizing material from dead standing coconuts. Eggs come from weekly collections from pheromone traps. We are currently testing CRB gut samples from Palau to see if they contain Oryctes nudivirus which can be used as an effective biological control agent for CRB-G on Guam.

Field Activities We continue to run island-wide roadside surveys to monitor CRB damage to coconut palms on Guam. We also maintain pheromone traps.

Pacific Ecological Security Conference (PESC) Project resources were used in support of the PESC which was held in Palau during September 2022. The PI participated in preparatory teleconferences and preparation of a strategic action plan for responding to CRB on Pacific Islands. The PI attended the conference in Palau as an invited delegate from Guam during which he helped finalize the CRB strategic action plan. He also attended a meeting convened by the Office of Insular Affairs at which he made a short presentation on the status of invasive species on Guam [3].

Notes for the Reader

- Each objective, as stated in the funded grant proposal [4], is presented in a frame at the start of each of the following sections.
- The University of Guam CRB biological control project is a long-term effort supported by multiple short-term grants.

1 Objective 1: Survey to Determine Background OrNV Incidence

CRB adults collected from breeding sites and pheromone traps throughout Guam will be tested for presence of OrNV using PCR. Laboratory bioassays will be performed on OrNV isolated from these beetles to evaluate potential for biological control.

1.1 Previously reported progress

Our lab currently uses CRB-G adults collected from pheromone traps as test animals in bioassays to evaluate OrNV isolates as biocontrol agents under the assumption that the Guam beetle population contains only the CRB-G biotype and is free from OrNV infection. In 2019 we gained the capacity to perform PCR in our lab and began testing these assumptions. PCR results indicated that untreated, field-collected beetles, used as experimental controls in our bioassays, were all CRB-G, but 18% of these tested positive for OrNV [5, 6].

Based on these results, the PI decided to suspend bioassays until we had conclusive evidence of OrNV infection in the Guam CRB-G population. This decision was made for two reasons:

1. If field-collected CRB insects where already infected with OrNV, these could not be used as test insects in laboratory bioassays designed to evaluate virulence of OrNV isolates.
2. If an OrNV strain was already spreading within the Guam CRB population, it would be prudent to evaluate this strain as an effective biological control agent.

An experimental plan [7] was developed and executed. One hundred beetles were collected from each of two pheromone trapping sites (Leo Palace Resort in Southern Guam and the UOG Ag. Expt. Stn. in northern Guam). Gut samples were obtained from these beetles and tested using PCR in our lab and also in Sean Marshall's lab at AgResearch New Zealand.

In PCR results from both labs all beetles tested positive for CRB-G biotype and negative for OrNV infection [8].

We concluded that previous OrNV positive tests were the result of lab contamination (not false positives).

Current evidence suggests that all CRB on Guam belong to the CRB-G biotype and there is no OrNV infection within this population. In other words, the background OrNV incidence is zero.

1.2 Recent progress

Work on this objective has been completed. All evidence indicates that the OrNV incidence in the Guam CRB population is zero. We concluded that previous OrNV positive tests were the result of contamination in our lab. We have improved protocols to address this problem.

2 Objective 2: Establish Sustainable CRB-G Biocontrol by Autodissemination of OrNV

OrNV biocontrol candidates will be propagated *in vivo* using established methods [9] and released into the Guam CRB-G population by autodissemination. Autodissemination involves infecting healthy CRB adults with OrNV. These infected beetles are then released at points dispersed throughout the island where they vector disease to conspecifics. A permit for field release of OrNV on Guam has already been obtained from USDA-APHIS. All released beetles will be marked by etching unique numbers on their elytra using a computer-controlled laser engraving system already in use for this application at UOG.

Beetles for *in vivo* propagation of OrNV and autodissemination will be field-collected from breeding sites and pheromone traps because this is far more efficient than rearing beetles in the lab at the current time. Impact of virus releases will be monitored using pheromone traps and a novel roadside video analysis system (see Objective 3). A subset of beetles captured in traps will be used to estimate the virus infection rate. Concurrent with virus releases, we will continue to screen OrNV isolates to find candidate biocontrol agents.

2.1 Previously reported progress

We have not made progress on this objective for two reasons:

1. High mortality of untreated insects in experimental control groups and discovery of OrNV in some of these insects, presumably from laboratory contamination, have thrown results of previous bioassays into question. We need to re-test several OrNV isolates we have previously evaluated in laboratory bioassays.
2. We require permission from the US Environmental Protection Agency (USEPA) prior to release of OrNV as a biological control agent. Data demonstrating efficacy of OrNV as a biological control agent is required by USEPA.

We are currently reviewing our lab methods before resuming laboratory bioassays of OrNV isolates. We are considering changes to minimize OrNV contamination of samples in the bioassays and re-establishment of a CRB rearing program to provide high-quality test insects instead of relying on field-collected beetles.

2.2 Recent progress

We have revised our laboratory bioassay protocols. Previously, we used adults collected from pheromone traps as test insects. This source did not produce high quality, standardized adults needed for bioassays because these beetles were of unknown age and some were infected with pathogens or had other health problems. This caused high variability and high experimental control group mortality in our bioassay results. We now rear CRB from egg to adult in a dedicated CRB rearing lab using a natural diet we have developed. Adults produced by this lab are healthy, pathogen free and of a known age.

Development of a natural diet for CRB rearing. Previously, we individually reared CRB from egg to adult by placing them in Mason jars filled with a commercial steer manure/soil blend purchased from local hardware stores. However this is risky because manure may contain persistent pesticides fed to cattle or pesticides applied to the manure for fly control.

We decided to eliminate this risk by making our own rearing diet from dead standing coconut stems which have begun to rot. We preferentially harvested stems naturally infested CRB grubs.

Processing is simple:

1. Dead standing coconut stems are felled and bucked into 4 foot lengths
2. Logs are run through a chipper and chips are loaded into burlap bags.
Bags are placed in a chest freezer until needed.
3. Chip size is reduced in an industrial Waring blender
4. Material is loaded into Mason jars. These filled jars are sterilized using an autoclave

Establishment of a CRB rearing lab. We converted a 40 foot shipping container into a CRB rearing lab. Temperature is maintained at 80°F by two independent air conditioners. Insects are reared individually from egg to adult by placing them in Mason jars filled with a natural rearing medium made from chipped standing dead coconut stems. There is shelf space for more than 2,000 jars (Fig. 1).



Figure 1: Coconut rhinoceros beetle rearing lab at the University of Guam.

Bioassays to determine sublethal effects of OrNV. Sublethal affects of OrNV infection may be much more important for CRB population suppression than direct mortality. A lab bioassay reported by Prasad et al. 2008 [10] showed that a high dosage of OrNV reduced the number of eggs laid per female from a mean of 58.5 to zero (100% reduction in fecundity). Remarkably, when this dosage was reduced by a factor of 1000, the number of eggs laid per female was reduced from a mean of 58.5 to 16.5 (71.8% reduction in fecundity).

We are preparing to repeat this experiment using OrNV isolate V23B against CRB-G adults produced by our rearing lab. Isolate V23B is of particular interest because this isolate has been shown to infect CRB-G by our lab and also by independent research with CRB-G in the Solomon Islands [11].

If the V23B isolate significantly reduces fecundity, we will use the results as evidence of efficacy as required by the US Environmental Protection Agency in support of a field application permit.

Our rearing facility is now starting to produce adults and bioassays will begin soon.

2.3 Recent Progress

During the first part of 2023 we tested OrNV isolates from Palau. The first bioassay tested OrNV delivered in CRB gut tissue provided by Dr. Chris Kitalong of the Palau Community College. And the second bioassay tested purified by Dr. Madoka Nakai of the Tokyo University of Agriculture and Technology. In both cases we observed no significant responses in terms of mortality, feeding activity, flight activity, or reduction in reproductive potential [12], [13], [14], [15]. Work on both bioassays was done with the assistance of Mayuho Yamauchi, a PhD candidate from Dr. Nakai's lab who visited UOG for one month [16].

My lab is currently testing 4 OrNV isolates sourced from AgResearch New Zealand. These were originally collected in the Philippines.

3 Objective 3: Establish Island-wide Monitoring Systems for CRB and Coconut Palm Health

The CRB-G outbreak on Guam is currently unmonitored on an island-wide basis. An island-wide pheromone trapping system, using about 1500 traps, was operated by the University of Guam from 2008 to 2014. This monitoring system was transferred to the Guam Department of Agriculture which abandoned the effort at the end of February, 2016. Currently, many coconut palms are being killed by CRB-G. But, in the absence of a monitoring system, we do not have an estimate of tree mortality or whether or not the damage is increasing or decreasing. Clearly, establishment of a monitoring system is necessary to evaluate success of the proposed biocontrol project, or any other mitigation efforts. We intend to re-establish island-wide trapping and to establish a sustainable roadside video survey which uses artificial intelligence to detect CRB damage in dash-cam videos.

3.1 Objective 3a: Pheromone Traps

3.1.1 Previously reported progress

We have not deployed new pheromone traps. But we continue to maintain trap lines in central Guam, at the Leo Palace Resort, and in northern Guam, at the University of Guam Agricultural Station in Yigo.

3.1.2 Recent progress

We maintain 35 pheromone traps at the Leo Palace Resort Golf Course. These are serviced biweekly. The main purpose of this activity is to provide adult beetles for experiments.

We have decided not to use pheromone traps for island-wide monitoring because we don't know the relationship between trap catch and CRB population density. Mark-release-recapture studies show that the commercially available pheromone, oryzalure, is not highly attractive to CRB-G on Guam [17]. The recapture rate for 567 marked beetles released in the vicinity of pheromone traps was only 11%.

We will continue to use automated roadside image surveys as a cost-effective instead of pheromone traps for island-wide monitoring of CRB on Guam.

3.2 Objective 3b: Roadside Video Surveys

Damage symptoms such as v-shaped cuts to fronds, bore holes, and dead standing coconut palm stems are readily observed during roadside surveys. Survey data will be collected on a smart-phone dash-cam app which georeferences each image. Initially, images of coconut palm damage by CRB-G will be detected, classified and tagged by a technician. When a large number of images have been tagged, these will be used to train an object detector. This work will result in a fully automated CRB damage detection and monitoring system which generates detection alerts and damage maps. This automated system will be useful as an early detection device for CRB. Roadside surveys on Guam will be performed bimonthly and the system will also be tested on Tinian, an island just north of Guam on which CRB has never been detected.

The envisioned system has already been successfully prototyped. A custom object detector for CRB damage has been trained using the TensorFlow implementation of the Faster R-CNN Deep Learning model (Moore, unpublished).

3.2.1 Previously reported progress

Bimonthly automated roadside video surveys for CRB damage are now operational on Guam and the system has been tested on Rota. Videos recorded with a smart phone attached to a vehicle are analyzed using custom-designed artificial intelligence software which recognizes coconut palms and measures CRB damage. A nontechnical description of the survey method is given in the next section.

A presentation on this new CRB survey methodology was made at the December 9 2020 meeting of the CRB-G Action Group conducted as a Zoom webinar. Videos of all presentations at this meeting are available online [18].

Guam Roadside Video Survey 1 The following four images were extracted from a draft of the University of Guam's Western Pacific Tropical Research Center impact report for 2020. They provide a nontechnical overview of the new automated roadside video survey for CRB damage and results from the first Guam survey in October, 2020.




Figure 2: Feature article in the University of Guam's Western Pacific Tropical Research Center impact report for 2020.

Everyone living on Guam has seen damage to coconut palms caused by coconut rhinoceros beetles (CRB). CRB has been on Guam since 2007, however, until recently, the number of palms being damaged and killed on Guam was unknown. Standardized surveys of CRB damage are needed to monitor changes over time and space, especially in response to control activities and for early detection of CRB in new geographic areas.

UOG entomologist Aubrey Moore has developed a highly automated method for routine island-wide monitoring of CRB damage using a cell phone and artificial intelligence (AI).

Methods for monitoring CRB damage have been developed. But these rely on direct observation or image analysis by human experts and are too time-consuming and expensive for routine monitoring over large areas.

Dr. Trevor Jackson, an entomologist working for AgResearch New Zealand, has developed a survey method based on a five-level scale for classifying CRB damage to individual coconut palms. Jackson's method is being used extensively on CRB-infested islands in the South Pacific. Moore decided to develop an island-wide roadside CRB damage survey for Guam based on an automated version of Jackson's method.



A smart phone is attached to a vehicle using a magnetic mount. As the car travels, the phone records videos that are analyzed by open-source software.


In the automated survey, a smart phone mounted on a car or truck records continuous videos while the vehicle is driven along all major roads on Guam. The smart phone uses a couple of free apps: OpenCamera records videos and GPSLogger records GPS coordinates.

Recent technical breakthroughs in AI have made it much easier to train computers to recognize objects in digital images. Moore collaborated with OnePanel Inc., an AI tech



Above: medium to severe CRB damage detected in the Royal Palms area of Dededo.

Below: each dot on the map represents a video frame in which one or more coconut palms was detected. The image at the top is a frame extract from a video with approximate coordinates indicated by the camera icon.



Continue reading →

8

Figure 3: [Continued] Feature article in the University of Guam's Western Pacific Tropical Research Center impact report for 2020.




Figure 4: [Continued] Feature article in the University of Guam's Western Pacific Tropical Research Center impact report for 2020. This interactive web map is publicly available at: <https://aubreymoore.github.io/new-crb-damage-map>

company, to develop and train a couple of object detectors using a technique called “deep learning”.

The first object detector finds all images of coconut palms in the survey videos and classifies each one using Jackson’s damage scale. The second object detector locates and counts v-shaped cuts in the fronds of each coconut palm. Data extracted from the videos by the object detectors are saved in a SpatialLite database.

To visualize survey results, Moore uses Quantum GIS, to make a publicly available, interactive web map. There are links on the web map to download the survey database and QGIS map project for more detailed analysis.

The first operational island-wide survey on Guam, completed during October 2020, indicated that about 19% of Guam’s coconut palms show CRB damage symptoms. The Guam surveys will be conducted bimonthly. An island-wide roadside video survey is also being done on Rota for early detection of CRB damage.

There is interest in use of roadside video surveys for CRB damage elsewhere in the Pacific and Moore plans to evaluate drone imagery for use on islands without extensive roads. The Guam roadside video survey was designed to be adaptable by using only free

open-source software (FOSS) components. Custom-written software for the project as well videos, databases, and GIS projects from surveys will also be made available for download from public repositories hosted on GitHub.

It is interesting to note that this is not the first time that Moore has dabbled with AI. Thirty years ago he trained an artificial neural network to identify free-flying mosquitoes.

Funded by the US Department of the Interior Office of Insular Affairs, US Forest Service, USDA-APHIS

Thanks to UOG entomology technician Christian Cayanan for doing the surveys.

Further reading:

Moore, A. 2018. The Guam Coconut Rhinoceros Beetle Problem: Past, Present and Future. Zenodo. doi.org/10.5281/zendodo.1185371].

Moore, A. 1991. Artificial neural network trained to identify mosquitoes in flight. Journal of Insect Behavior 4, 391–396.

Aubrey Moore
(671) 735-2068
aubreymoore@triton.uog.edu

10



Figure 5: [Continued] Feature article in the University of Guam’s Western Pacific Tropical Research Center impact report for 2020.

Guam Roadside Video Survey 2 The proportion of coconut palms damaged by CRB increased significantly from 19.2% in October 2020 to 21.5% in December 2020 ($p < 0.001$; Fisher's exact test).




Figure 6: Screenshot of an interactive web map of results from a roadside video survey of CRB damage on Guam in December 2020 <https://aubreymoore.github.io/Guam-CRB-damage-map-2020-12/webmap/v1/>.

Rota Roadside Video Survey 1 Rota was invaded by CRB in 2017 and eradication efforts by Rota Department of Land and Natural Resources have successfully kept the population at a very low level, although the population has begun to spread to new areas of the island. In October 2020, a smart phone and associated equipment was sent to Rota-DLNR so that they could do an initial roadside video survey in support of their CRB control efforts. In addition to the equipment, a survey setup guide [19] and a setup video [20] were prepared and sent.

The survey was performed by Mark Mangolana, Rota-DLNR and the phone containing videos from the survey was returned to the University of Guam. Videos were analyzed using the workflow developed for the Guam surveys. The resulting web map contained many false positives for CRB damage, but there is one hit which shows a classic v-shaped cut probably caused by CRB. For convenience, data for this hit (images, date, location) were documented as an iNaturalist observation (Figure 7). If this v-shaped cut was caused by CRB, there will be a bore hole. Rota-DLNR are following up to see if this is the case.




Figure 7: Screenshot of an iNaturalist observation documenting probable coconut rhinoceros beetle damage detected during a roadside video survey performed by Rota DLNR. <https://www.inaturalist.org/observations/69534809>.

3.2.2 Recent progress

We continue to monitor CRB damage on Guam using automated roadside image surveys (Fig. 8 and Fig. 9).

We also continue to improve our survey methods. Processing was simplified by changing our raw data format from videos taken at 15 images per second to georeferenced still images taken at 1 image per second. This reduced data file memory requirements by 93% and we no longer need to rely on a second app to record latitude and longitude.

In addition to using our methods for routine monitoring of CRB damage, they can be used for early detection of CRB. An initial test of this idea was done on Rota and results were reported in a webinar organized by the Department of the Interior - Office of Insular Affairs [21].

Software tools developed for our automated roadside damage monitoring can be used to detect CRB damage in digital images from any source. Recently, an object detector which we trained to find characteristic v-shaped cuts caused by CRB to examine web images was used to find evidence for an unconfirmed report of CRB establishment in Mexico [22]. We were successful (Fig. 10).




Figure 8: Screen capture of an online interactive map of coconut rhinoceros beetle damage on Guam. <https://aubreymoore.github.io/Guam-CRB-Damage-Map-2021-08/webmap>.




Figure 9: Changes in CRB damage over time.



Figure 10: Coconut palm in Mexico with CRB damage symptoms. This image was selected by an automated search of web images using an object detector developed for CRB damage monitoring on Guam. Image source: <https://www.inaturalist.org/observations/76810823>.

3.2.3 Recent progress

To date, we have completed eight island-wide surveys and data for a ninth survey were recorded in June 2023 but have not yet been analyzed. Interactive damage maps and data are available on the web:

1. Survey completed 2020-10-22: [View map](#) | [View GitHub repository](#) | [Download database](#)

2. Survey completed 2020-12-24: [View map](#) | [View GitHub repository](#) | [Download database](#)
3. Survey completed 2021-03-18: [View map](#) | [View GitHub repository](#) | [Download database](#)
4. Survey completed 2021-05-20: [View map](#) | [View GitHub repository](#) | [Download database](#)
5. Survey completed 2021-09-03: [View map](#) | [View GitHub repository](#) | [Download database](#)
6. Survey completed 2022-02-23: [View map](#) | [View GitHub repository](#) | [Download database](#)
7. Survey completed 2022-11-28: [View map](#) | [View GitHub repository](#) | [Download database](#)
8. Survey completed 2023-04-07: [View map](#) | [View GitHub repository](#) | [Download database](#)
9. Survey completed 2023-06-15: Not yet analyzed.

Results of surveys are made available to the Guam public via press releases [23]. Survey results show that one in five (20%) of Guam's coconut palms growing along roadsides are damaged by CRB (Fig. 11).




Figure 11: Percent of coconut palms growing along Guam's roadsides which show visible damage from coconut rhinoceros beetle.

4 Recent Publications

model
PIDL

5 References

- [1] James J. Grasela and Aubrey Moore. “Preliminary Detection of Wolbachia in the Coconut Rhinoceros Beetle *Oryctes Rhinoceros* (Coleoptera: Scarabaeidae) from Guam, Palau, and Taiwan”. June 21, 2022. URL: <https://zenodo.org/record/6672841> (visited on 06/21/2022).
- [2] James J. Grasela and Aubrey Moore. “Preliminary Efforts to Establish a Continuous Cell Line for Coconut Rhinoceros Beetle (*Oryctes Rhinoceros*, Coleoptera: Scarabaeidae)”. June 21, 2022. URL: <https://zenodo.org/record/6672831> (visited on 06/21/2022).
- [3] Aubrey Moore, Roland Quitugua, and Glenn Dulla. “Overview of Invasive Species Issues on Guam, Pacific Ecological Security Conference, Palau, October 6, 2022”. Oct. 6, 2022. URL: <https://zenodo.org/record/7593110> (visited on 02/01/2023).
- [4] Aubrey Moore. *Grant Proposal: DOI-OIA Coral Reef and Natural Resources Initiative FY2020: Establishment of Self-sustaining Biological Control of Coconut Rhinoceros Beetle Biotype G in Micronesia*. Apr. 23, 2020. URL: https://github.com/aubreymoore/2020-DOI-CRB-Biocontrol/blob/master/doi_proposal.pdf (visited on 05/22/2020).
- [5] James J. Grasela and Aubrey Moore. *{Technical Report: Polymerase Chain Reaction (PCR) Analysis of the Coconut Rhinoceros Beetle (CRB), Oryctes Rhinoceros. Part 3..}* 2020. URL: <https://github.com/aubreymoore/FY19-PPA-Report-1/blob/master/pcrdata/PCR-Summary-Part-3.pdf>.
- [6] James J. Grasela and Aubrey Moore. *{Technical Report: Polymerase Chain Reaction (PCR) Analysis of the Coconut Rhinoceros Beetle (CRB), Oryctes Rhinoceros. Part 2..}* 2020. URL: <https://github.com/aubreymoore/FY19-PPA-Report-1/blob/master/pcrdata/PCR-Summary-Part-2.pdf>.

- [7] Aubrey Moore, James J. Grasela, and Sean David Goldie Marshall. *Experimental Plan: Determining Presence of OrNV in the Guam CRB-G Population*. 2020. URL: <https://github.com/aubreymoore/FY19-PPA-Report-1/raw/master/docs/Guam%20rNV%20Experimental%20Plan.pdf>.
- [8] James J. Grasela and Aubrey Moore. *Investigation to Determine the Presence of OrNV in the Guam CRB Population*. 2020. URL: <https://github.com/aubreymoore/FY19-PPA-Report-1/raw/master/docs/Determining%20the%20Presence%20of%20rNV%20in%20the%20Guam%20CRB.pdf>.
- [9] Alois M. Huger. “The *Oryctes* Virus: Its Detection, Identification, and Implementation in Biological Control of the Coconut Palm Rhinoceros Beetle, *Oryctes Rhinoceros* (Coleoptera: Scarabaeidae)”. In: *Journal of Invertebrate Pathology* 89.1 (May 2005), pp. 78–84. DOI: [10.1016/j.jip.2005.02.010](https://doi.org/10.1016/j.jip.2005.02.010). URL: <http://www.guaminsects.net/CRB/docs/Huger2005.pdf>.
- [10] Shyam Prasad, Jayakumar Velusamy, and Tilak Sharma. “Management of Coconut Rhinoceros Beetle (*Oryctes Rhinoceros*) by Augmentation of *Oryctes* Baculovirus (Kerala Isolate) in Little Andaman Islands”. In: *Indian Journal of Agricultural Sciences* 78 (Nov. 1, 2008), pp. 962–965.
- [11] Gloria Barrera et al. *Electron Microscopy Study Confirms Infection of Coconut Rhinoceros Beetle (CRB-G) Gut Cells by OrNV -V23B. (Poster) Abstracts - 2021 International Congress on Invertebrate Pathology and Microbial Control & 53rd Annual Meeting of the Society for Invertebrate Pathology. Le Studium Conference (Virtual), Tours France. p 137*. July 21, 2021. URL: https://www.researchgate.net/publication/353356673_Electron_microscopy_study_confirms_infection_of_coconut_rhinoceros_beetle_CRB-G_gut_cells_by_OrNV_-V23B_Poster_Abstracts_-_2021_International_Congress_on_Invertebrate_Pathology_and_Microbial_Control_5.

- [12] Aubrey Moore and Laura R. Taitano Caser. “Testing Palau Gut Samples”. In: (Dec. 3, 2022). URL: <https://osf.io/9hdvu/> (visited on 07/25/2023).
- [13] Aubrey Moore. *GitHub Repository: Palau-Guts-Experiment*. Dec. 25, 2022. URL: <https://github.com/aubreymoore/palau-guts-experiment> (visited on 07/25/2023).
- [14] Aubrey Moore and Mayuho Yamauchi. “Flight Test”. In: (Mar. 4, 2023). URL: <https://osf.io/cd2gp/> (visited on 07/25/2023).
- [15] Aubrey Moore. *GitHub Repository: Crb-Flight-Test*. May 2, 2023. URL: <https://github.com/aubreymoore/crb-flight-test> (visited on 07/25/2023).
- [16] Jackie Hanson. *UOG, Tokyo University Test a Rhino Beetle Virus from Palau on Guam’s Beetles*. May 4, 2023. URL: <https://www.uog.edu/news-announcements/2022-2023/2023-uog-tokyo-university-test-a-virus-on-guams-rhino-beetles.php> (visited on 05/08/2023).
- [17] Matthew S. Siderhurst et al. “Effects of Ultraviolet Light and Pheromone Release Rate in Trapping Coconut Rhinoceros Beetles, Oryctes Rhinoceros (Coleoptera: Scarabaeidae), on Guam”. In: (Dec. 31, 2021). ISSN: 0073-134X. URL: <http://scholarspace.manoa.hawaii.edu/handle/10125/81413> (visited on 01/02/2022).
- [18] Aubrey Moore. *Video Recording of the CRBG Action Group Meeting: December 9, 2020 [Conducted via Zoom]*. Dec. 9, 2020. URL: <https://aubreymoore.github.io/CRBG-action-group-webinar-20201209/>.
- [19] Aubrey Moore. *Set Up for Automated Roadside Video Surveys for Detecting and Monitoring Coconut Rhinoceros Beetle Damage on Rota*. Oct. 26, 2020. URL: <https://api.zotero.org/groups/511387/items/3X83KK58/file/view>.
- [20] Aubrey Moore. *YouTube Video: Mounting a Smart Phone on a Vehicle for Roadside Video Surveys of Coconut Rhinoceros Beetle Damage*. 2020. URL: <https://www.youtube.com/watch?v=Pa-UslJV6BI>.

- [21] US Department of the Interior - Office of Insular Affairs. *YouTube Video: The Coconut Rhinoceros Beetle in Rota, Commonwealth of the Northern Mariana Islands*. Feb. 23, 2021. URL: <https://www.youtube.com/watch?v=1IqTXrKqGxM>.
- [22] Trevor Jackson et al. “Social Media Posts Suggest That Coconut Rhinoceros Beetle Has Established in the Western Hemisphere”. In: (July 20, 2022). DOI: [10.22541/au.165828152.28371110/v1](https://doi.org/10.22541/au.165828152.28371110/v1).
- [23] Aubrey Moore. “Press Release: Coconut Rhinoceros Beetle Damage Maps”. 2023-04-23. URL: <https://github.com/aubreymoore/Guam-CRB-web-maps/blob/main/press-release-roadside.pdf>.