Coconut Rhinoceros Beetle Biological Control

Aubrey Moore, University of Guam

November 1, 2020

Report ID: AP18PPQFO000C402-PE-Final-20

Report Type: Final Report

Performance Period: August 1, 2018 through July 31, 2020

https://github.com/aubreymoore/FY19-PPA-Report-1/raw/master/PPA18-report-final.pdf

Abstract

CRB Biological Control. The primary objective of this project was to find an isolate of *Oryctes rhinoceros* nudivirus (OrNV) which can be used as an effective biological control agent for the CRB-G biotype of coconut rhinoceros beetle (CRB).

Laboratory bioassays indicated that OrNV from two sources could be considered as potential biocontrol agents for CRB-G: OrNV isolate V23B maintained in insect tissue culture by AgResearch New Zealand and OrNV in bodies of CRB collected in Taiwan for the current project. However, these laboratory studies did not indicate a level of efficacy deemed necessary to justify field release. Search for an effective biocontrol agent for CRB-G continues.

PCR tests of CRB-G adults collected on Guam during 2019 and early 2020 indicated presence of OrNV in this population. Results from a 2020 survey which followed an experimental protocol developed to minimize false positive test results for OrNV infection indicate that the Guam CRB is free from OrNV infection. It is likely that positive PCR tests where the result of laboratory contamination.

CRB Damage Survey. A secondary objective of this project was to develop a CRB damage monitoring system based on automated digital image analysis of roadside video surveys.

Georeferenced videos were recorded using a smart phone mounted on a road vehicle. An object detector was trained to locate and provide a damage index (0 to 4) for all coconut palms in the videos. A second object detector was trained to locate v-shaped cuts, which are characteristic symptoms of CRB damage.

The first island-wide roadside video survey of CRB damage on Guam was performed in early October 2020. This survey yielded a damage index for each of 57,666 coconut palm images detected in 174,944 video frames. Eight-four percent of these palms were damaged. An online interactive map of the survey results is publicly available. The Guam survey will be repeated bimonthly to monitor spatial-temporal changes in CRB damage in response to control activities.

A roadside video survey of Rota Island is currently being performed to test this method for early detection of CRB damage in areas where this pest is not known to be established.

Regional Collaboration. CRB-G invasions are a major problem for Pacific islands. Uncontrolled outbreaks of this highly invasive biotype are damaging and killing palms in Guam, Rota, Hawaii, Palau, Papua New Guinea, and the Solomon Islands. Without effective control of these outbreaks, the problem will spread to other Pacific islands, resulting in a human tragedy when it reaches atolls were islanders still rely on coconut palm as the *tree of life*.

Project resources, time and effort were used to facilitate communication among an ad hoc collaboration of entomologists working on the CRB-G problem throughout the Pacific. Project staff have been active members of the CRB-G Action Group and have participated in annual scientific meetings organized by this group.

This project has provided online resources including a searchable, online bibliography of journal articles and technical reports about CRB and a an online interactive map for visualizing CRB invasion history.

Contents

1	Staffing Biological Control								
2									
3									
	3.1 Laboratory Bioassays of OrNV Isolates								
	3.2	Virus 7	Transmission Experiment	5					
	3.3		Cests for OrNV Detection	6					
	3.4 Survey to Determine Incidence of OrNV Infection in the Guam CRB Pop-								
				6					
	3.5		Rearing	7					
		3.5.1	Urgent Need for a Pathogen-free CRB Laboratory Colony	7					
		3.5.2	Laboratory Information Management System	7					
		3.5.3	Acquisition of a Virus-Susceptible CRB Biotype for Comparative						
		0.010	Bioassays	7					
4	CRB Damage Survey								
	4.1		ds Development	9					
		4.1.1	Proof of Concept	9					
		4.1.2	Object Detectors for CRB Damage	9					
		4.1.3	Survey Protocol	9					
	4.2	Survey	Results	10					
5	Regional Collaboration								
	5.1		pation in Scientific Meetings	11					
	5.2		pment of Online Resources	11					
R	eferer	ices		12					

1 Background

The major goal of this project was to find an effective biological control agent for coconut rhinoceros beetle biotype G (CRB-G).

Prior to arrival of CRB-G on Guam during 2007, coconut rhinoceros beetle infestations of Pacific islands were readily dealt with by classical biological control using *Oryctes* nudivirus (OrNV), a pathogen specific to rhinoceros beetles. Following a lack of response to release of OrNV on Guam, research showed that the Guam CRB population is a genetically distinct virus-resistant biotype which has become known as CRB-G ([8]). This biotype is highly invasive and is causing massive damage to coconut and oil palms after recent invasion of Papua New Guinea and the Solomon Islands. CRB-G has also invaded Oahu and Rota. Eradication attempts have been launched on these two islands.

Additional goals for this project were to establish a CRB damage survey to evaluate efficacy of biocontrol and other tactics, and to maintain and facilitate collaboration with other Pacific island entomologists working to find solutions for CRB-G management.

2 Staffing

Staff for this project comprised of the PI, a post-doc and a technician.

- Funding from the Department of Interior, Office of Island Affairs was used to hire an insect pathologist for a 2 year term. Dr. James Grasela was recruited and started work at UOG on June 24, 2018.
- Funding from this USDA-APHIS project was used to hire Mr. Chris Cayanan as a technician. Mr. Cayanan was hired during December, 2019, as a replacement for Mr. Ian Iriarte who resigned to accept another job.

3 Biological Control

3.1 Laboratory Bioassays of OrNV Isolates

Four isolates of OrNV were evaluated as candidate biological control agents for CRB-G in a series of laboratory bioassays. Virus sample preparations came from Dr. Sean Marshall's lab at AgResearch New Zealand were they are maintained in insect cell culture.

DUG42 Collected from Dumaguete, Negros Island, Philippines in 2017

MALB Collected from Malaysia, details not available.

PNG Collected from Rabaul, Papua New Guinea in 1988

V23B Collected from southern Luzon, Philippines in 1980

During laboratory bioassays, we dosed CRB-G adults with samples of the OrNV islolates, and observed mortality and changes in mass for one month. Each beetle was kept in isolation and individual records were stored in a laboratory information system developed for this application (Section 3.5.2).

Bioassay results, displayed in Table 1, indicate that one of the isolates, V23B, is pathogenic for CRB-G when doses are applied by placing droplets of virus suspension on mouthparts of adult beetles.

Table 1: Oryctes rhinoceros nudivirus (OrNV) bioassay results summary.

OrNV isolate	bioassay	method^1	beetles	replicates	virus mortality $(p)^2$	inactivated virus mortality $(p)^3$
DUG42	DUG42 [16]	injection	30	2	40% (0.65)	40% (0.65)
MALB	MALB [17] MALBperOS [18]	injection per os	30 13	2 1	50% (0.37) -60% (1.00)	0% (1.00) 20% (1.00)
PNG	PNG [19] PNGperOS [20]	injection per os	81 21	4 1	90% (0.00) 0% (1.00)	5% (1.00) 0% (1.00)
V23B	V23B [21] V23BperOS [23] V23-large_bioassay [22] V23_perOSIN [24]	injection per os per os per os	66 32 53 16	4 2 1 1	88% (0.00) 80% (0.07) 42% (0.00) 60% (0.06)	0% (1.00) 20% (0.69) -

¹ Adult beetles were dosed either by direct injection of virus suspension into the haemocoel or by applying a droplet containing virus to mouthparts.

In a separate experiment, macerated guts from OrNV infected beetles from field collections of CRB in Taiwan were fed to CRB-G field-collected on Guam. PCR results indicated that the Taiwanese OrNV propagated in the Guam beetles (See Subsection 3.3).

We now have two isolates of OrNV which can be considered as candidate biocontrol agents for further testing: V23B and Taiwan.

3.2 Virus Transmission Experiment

This experiment was performed to determine if OrNV isolate V23B can be transmitted from a dosed CRB adult to an undosed CRB adult. If a virus is not contagious in the lab, it will probably have no potential as a biocontrol agent.

² Percent mortality in beetles treated with virus, adjusted for untreated control mortality; number in parentheses is the p-value resulting from a Fisher's exact test of significant difference between mortality of treated and untreated beetles.

³ Percent mortality in beetles treated with heat inactivated virus, adjusted for untreated control mortality; number in parentheses is the *p*-value resulting from a Fisher's exact test of significant difference between mortality of treated and untreated beetles.

Unfortunately, the experiment failed due to very high mortality in the experimental control group and results are inconclusive. For details, see [6]. This experiment needs to be repeated using pathogen-free, laboratory-reared adults (See Section 3.5).

3.3 PCR Tests for OrNV Detection

Previously, our laboratory relied on outside collaboration for molecular testing to determine presence of OrNV in CRB tissues. We recently acquired access to equipment and supplies which allow us to use PCR (polymerase chain reaction) techniques for OrNV detection. We tested five different primer pairs for detection of OrNV in reference samples from AgResearch New Zealand and were successful with all five. Identity of DNA fragments was confirmed as OrNV using a commercial DNA sequencing service.

Details of our PCR technique and initial series of tests can be found in [3], [4] and [5]. Results from PCR tests indicate:

- OrNV is present in the Guam adult CRB population: 18% (10 of 47) gut samples dissected from field collected CRB tested positive for OrNV. **Important Note:** A recent field survey did not detect OrNV in the Guam CRB population. Most likely, positive PCR tests were a result of laboratory contamination. See the next section.
- OrNV is present in the adult Taiwanese CRB population: 7% (5 of 67) gut samples dissected from field collected CRB tested positive for OrNV.
- OrNV from Taiwanese adult CRB propagates in Guam adult CRB: 12% (5 of 41) Guam CRB adults dosed with Taiwanese gut preparations tested positive.

3.4 Survey to Determine Incidence of OrNV Infection in the Guam CRB Population

A survey to determine incidence of OrNV infection in the Guam CRB population was performed following positive PCR tests for OrNV infection in 18% (10 of 47) gut samples dissected from locally collected beetles. The survey followed an experimental protocol developed to minimize false positive test results for OrNV infection is detailed in ([26]). Analysis of specimens collected during the survey is not yet complete because of our courier service temporarily lost one package of insects sent to AgResearch New Zealand. To date 104 of 200 CRB specimens collected in pheromone traps on Guam have been genotyped by CO1 DNA barcoding and tested for OrNV infection using PCR. All of these specimens were identified as CRB-G and none of them tested positive for OrNV.

Preliminary survey results ([2] and Marshall 2020, personal communication) indicate that previous PCR tests of field collected beetles on Guam which were positive for OrNV infection were most likely caused by laboratory contamination.

3.5 CRB Rearing

Experimental beetles were field-collected on Guam as prepupae, pupae or adults from breeding sites or as adults from pheromone traps. Each beetle was given a serial number and was reared individually in a Mason jar stored in one of three environmental chambers set for 30 degrees Celsius, 80% relative humidity and 12 hour photoperiod. Each adult beetle was fed weekly with a slice of banana. Detailed information on the CRB rearing facility can be found in a document prepared in support of a USDA-APHIS permit to allow importation of live CRB for laboratory bioassays [9].

3.5.1 Urgent Need for a Pathogen-free CRB Laboratory Colony

To date, CRB used in bioassays and other laboratory experiments were field collected on Guam, rather than reared in a laboratory colony. This was done because a very high population density of rhino beetles on Guam made field collection far more efficient in terms of time and resources than laboratory rearing. However, field collected beetles are often infected with pathogens, especially the fungus, *Anisopliae majus*, which was introduced on Guam as a classical biological control agent. Presence of these pathogens in experimental animals resulted in unpredictable and often high mortality rates in experimental control groups, leading to inconclusive results such as experienced with the recent virus transmission experiment (3.2).

3.5.2 Laboratory Information Management System

We developed an online database which we use as a laboratory information management system for maintaining individual records for beetles in our rearing program [10]. This system was developed using the web2py python web framework and it is available on the web at http://aubreymoore.pythonanywhere.com/rearing3.

3.5.3 Acquisition of a Virus-Susceptible CRB Biotype for Comparative Bioassays

Since discovery of the CRB-G biotype on Guam [8], we have been operating under the hypothesis that this biotype is significantly more tolerant (resistant) to pathogenic effects of OrNV isolates previously used as effective biocontrol agents for CRB invading Pacific Islands. It has also been hypothesized that CRB-G has different behavioral characteristics, such as a significantly reduced attraction to oryctalure. However, comparative laboratory bioassays have not been performed to test these hypotheses.

We applied for and have been granted a USDA-APHIS import permit for live CRB which will allow us to establish a laboratory colony of CRB from presumed non-virus-resistant populations (See [9] and [30]). We have designed custom shipping containers to facilitate secure transport of live CRB [27].

We plan to import CRB from American Samoa with assistance from our collaborator, Dr. Mark Schmaedick, American Samoa Community College. Plans for project staff to visit American Samoa in December 2019 failed because of travel restrictions prompted by a measles outbreak and in March 2020 because of travel restrictions prompted by the corona virus pandemic.

4 CRB Damage Survey

The objective of this component of the project was to develop an automated system to evaluate CRB damage by image analysis of roadside video surveys. Survey results can be used for:

- 1. Monitoring temporal-spatial changes in CRB damage to coconut palms in response to control efforts.
- 2. Early detection of CRB damage in newly invaded areas.




Figure 1: Screenshot of an interactive web map of results from the Guam01 roadside video survey of CRB damage on Guam ([14]) URL: https://aubreymoore.github.io/Guam-CRB-damage-map-2020-10.

4.1 Methods Development

4.1.1 Proof of Concept

We completed a *proof of concept* trial in which deep learning algorithms were used to train an object detector which locates and counts dead and CRB-damaged coconut palms in video streams. Visual results were presented in a YouTube post [15] and technical details were made available in an Open Science Framework Project [12].

4.1.2 Object Detectors for CRB Damage

The core of our automated image analysis software for detecting CRB damage in roadside surveys a pair of object detectors, one which locates coconut palms in video frames and assigns a damage index to each palm, and another which locates v-shaped cuts to fronds in images of detected coconut palms. We use a standardized CRB damage index which is in use elsewhere in the Pacific ([7], [31]).

The object detectors we used were developed by OnePanel Inc. under a contract which specified a scope of work ([29]) submitted in response to a request for interest (RFI) ([13]). The RFI contained two requirements:

- 1. The system must be built using free open-source software (FOSS). Preferred components include Linux, OpenCV, Python, Jupyter and CVAT.
- 2. The system should be designed so that it can be operated locally in early detection mode on remote Pacific Islands which do not have access to modern telecommunications networks.

OnePanel incorporated the object detectors into a data processing pipeline and delivered a manual for its use ([28]).

4.1.3 Survey Protocol

Georeferenced videos were recorded using a smart phone mounted on a road vehicle. The smart phone uses a pair of free apps to record roadside videos using the phone's camera and to record location using the phone's GPS receiver. An island-wide survey is completed by driving all major routes in both directions. For set up details see [1].

4.2 Survey Results

The first island-wide roadside video survey of CRB damage on Guam was performed in early October 2020. This survey yielded a damage index for each of 57,666 coconut palm images detected in 174,944 video frames. Eight-four percent of these palms were damaged. An online interactive map of the survey results is publicly available (Fig. 1) and data are publicly available in a GitHub repository ([11]). The Guam survey will be repeated bimonthly to monitor spatial-temporal changes in CRB damage in response to control activities.

A roadside video survey of Rota Island is currently being performed to test this method for early detection of CRB damage in areas where this pest is not known to be established.

5 Regional Collaboration

An informal collaboration, the CRB-G Action Group, has been formed among Pacific-based entomologists working on the CRB-G problem. Participants from Guam, Hawaii, Palau, Papua New Guinea, Solomon Islands, Fiji, Malaysia, Japan and New Zealand have met several times and future meetings are planned (Table 2). This is an ad hoc group which has been organized by Dr. Trevor Jackson and Sean Marshall of AgResearch New Zealand. AgResearch is recognized as a global center for expertise on biological control of CRB. AgResearch scientists have worked on CRB in the south Pacific for several decades and they maintain a library of OrNV isolates in cell culture. The New Zealand government has recently committed several million dollars to aid response to CRB-G in the south Pacific islands. Although individual institutions working to find a solution to the CRB-G problem on American-affiliated islands in the northern Pacific have secured funding from multiple, short-term grants, attempts to secure funding to support a sustainable well-coordinated regional project have been unsuccessful.

Table 2: Meetings of the CRB-G Action Group

2015 Pacific Entomology Conference, Honolulu, HI, USA

2016 International Congress of Entomology, Orlando, USA

2017 Japanese Society for Insect Pathology, Tokyo, Japan

2018 Society for Invertebrate Pathology, Gold Coast, Australia

 $2019~{\rm XIX}$ International Plant Protection Congress, Hyderabad, India

2020 (tentative): Pacific Plant Protection Organization, Guam

5.1 Participation in Scientific Meetings

Moore and Grasela participated at the XIX International Plant Protection Congress in a symposium entitled *The challenge of coconut rhinoceros beetle, Oryctes rhinoceros, to palm production and prospects for control in a changing world.* Moore made an oral presentation at this meeting [25]. They also participated in a CRB-G Action Group meeting with colleagues from throughout the Pacific and Asia.

5.2 Development of Online Resources

Project resources were used to build and maintain the following:

- CRB Bibliography https://github.com/aubreymoore/CRB-Bibliography
- Interactive CRB Invasion History Map https://aubreymoore.github.io/crbdist/mymap.html
- CRB Wiki Site https://guaminsects.net/CRBG
- CRB-G Facebook Site https://www.facebook.com/groups/crbg07

References

- [1] Aubrey Moore. Set Up for Automated Roadside Video Surveys for Detecting and Monitoring Coconut Rhinoceros Beetle Damage on Rota. Oct. 26, 2020. URL: https://api.zotero.org/groups/511387/items/3X83KK58/file/view.
- [2] James J. Grasela and Aubrey Moore. Investigation to Determine the Presence of OrNV in the Guam CRB Population. 2020. URL: https://github.com/aubreymoore/FY19-PPA-Report-1/raw/master/docs/Determining%20the%20Presence%20of%200rNV%20in%20the%20Guam%20CRB.pdf.
- [3] James J. Grasela and Aubrey Moore. Technical Report: Polymerase Chain Reaction (PCR) Analysis of the Coconut Rhinoceros Beetle (CRB), Oryctes Rhinoceros. Part 1. 2020. URL: https://github.com/aubreymoore/FY19-PPA-Report-1/blob/master/pcrdata/PCR-Summary-Part-1.pdf.
- [4] James J. Grasela and Aubrey Moore. Technical Report: Polymerase Chain Reaction (PCR) Analysis of the Coconut Rhinoceros Beetle (CRB), Oryctes Rhinoceros. Part 2. 2020. URL: https://github.com/aubreymoore/FY19-PPA-Report-1/blob/master/pcrdata/PCR-Summary-Part-2.pdf.
- [5] James J. Grasela and Aubrey Moore. Technical Report: Polymerase Chain Reaction (PCR) Analysis of the Coconut Rhinoceros Beetle (CRB), Oryctes Rhinoceros. Part 3. 2020. URL: https://github.com/aubreymoore/FY19-PPA-Report-1/blob/master/pcrdata/PCR-Summary-Part-3.pdf.
- [6] James Grasela and Aubrey Moore. Guam CRB Biocontrol Project Technical Report: OrNV Transmission Experiment. 2020. URL: https://github.com/aubreymoore/OrNV-Transmission/blob/master/ornv-transmission.pdf.
- [7] Trevor A. Jackson. "Rhinoceros Beetle Damage. Workshop with Kokonas Indastri Koporesen (KIK). Madang, PNG". In: (May 20, 2019). URL: https://api.zotero.org/groups/511387/items/QMD5TZQU/file/view.
- [8] Sean D. G. Marshall, Aubrey Moore, Maclean Vaqalo, Alasdair Noble, and Trevor A. Jackson. "A New Haplotype of the Coconut Rhinoceros Beetle, *Oryctes Rhinoceros*, Has Escaped Biological Control by *Oryctes Rhinoceros* Nudivirus and Is Invading Pacific Islands". In: *Journal of Invertebrate Pathology* 149 (Oct. 1, 2017), pp. 127–134. ISSN: 0022-2011. DOI: 10.1016/j.jip.2017.07.006. URL: http://www.sciencedirect.com/science/article/pii/S0022201117300289 (visited on 08/26/2017).
- [9] Aubrey Moore. Additional Documentation in Support of a Permit Application for Importation of Live Coconut Rhinoceros Beetles to Guam. June 2, 2019. URL: https://github.com/aubreymoore/CRB-Import-Permit/blob/master/CRB-import-permit-request-additional.pdf.
- [10] Aubrey Moore. Coconut Rhinoceros Beetle Rearing Database. Oct. 13, 2019. URL: http://aubreymoore.pythonanywhere.com/rearing.

- [11] Aubrey Moore. GitHub Repository: Guam-CRB-Damage-Map-2020-10. 2020. URL: https://github.com/aubreymoore/Guam-CRB-damage-map-2020-10.
- [12] Aubrey Moore. Open Science Framework: Digital Image Analysis for Detection of CRB Damage in Videos. Oct. 12, 2019. URL: https://osf.io/czr8t/?view_only=cdec7cc47b514b31b33115113193a2d4.
- [13] Aubrey Moore. Request for Interest: Object Detector(s) for Quantification of Coconut Rhinoceros Beetle Damage in Roadside Video Surveys. June 3, 2020. URL: https://api.zotero.org/groups/511387/items/5IYSRCTJ/file/view.
- [14] Aubrey Moore. Web Map: Guam-CRB-Damage-Map-2020-10. 2020. URL: https://aubreymoore.github.io/Guam-CRB-damage-map-2020-10.
- [15] Aubrey Moore. YouTube Video: Training an Object Detector to Locate Coconut Palms Damaged or Killed by Coconut Rhinoceros Beetle. July 26, 2019. URL: https://www.youtube.com/watch?v=zzSorqcmt9U (visited on 10/09/2019).
- [16] Aubrey Moore and James J. Grasela. *Bioassay Report: DUG42*. University of Guam, 2019. URL: https://github.com/aubreymoore/rearing3/raw/master/bioassay-DUG42.pdf.
- [17] Aubrey Moore and James J. Grasela. *Bioassay Report: MALB*. University of Guam, 2019. URL: https://github.com/aubreymoore/rearing3/raw/master/bioassay-MALB.pdf.
- [18] Aubrey Moore and James J. Grasela. *Bioassay Report: MALBperOS*. University of Guam, 2019. URL: https://github.com/aubreymoore/rearing3/raw/master/bioassay-MALBperOS.pdf.
- [19] Aubrey Moore and James J. Grasela. *Bioassay Report: PNG*. University of Guam, 2019. URL: https://github.com/aubreymoore/rearing3/raw/master/bioassay-PNG.pdf.
- [20] Aubrey Moore and James J. Grasela. *Bioassay Report: PNGperOS*. University of Guam, 2019. URL: https://github.com/aubreymoore/rearing3/raw/master/bioassay-PNGperOS.pdf.
- [21] Aubrey Moore and James J. Grasela. *Bioassay Report: V23B*. University of Guam, 2019. URL: https://github.com/aubreymoore/rearing3/raw/master/bioassay-V23B.pdf.
- [22] Aubrey Moore and James J. Grasela. *Bioassay Report: V23B Large Bioassay*. University of Guam, 2019. URL: https://github.com/aubreymoore/rearing3/raw/master/bioassay-V23B%5C_large%5C_bioassay.pdf.
- [23] Aubrey Moore and James J. Grasela. *Bioassay Report: V23BperOS*. University of Guam, 2019. URL: https://github.com/aubreymoore/rearing3/raw/master/bioassay-V23BperOS.pdf.

- [24] Aubrey Moore and James J. Grasela. *Bioassay Report: V23BperOSIN*. University of Guam, 2019. URL: https://github.com/aubreymoore/rearing3/raw/master/bioassay-V23B%5C_perOSIN.pdf.
- [25] Aubrey Moore, James J. Grasela, and Sean D. G. Marshall. Presentation: Status of a Major Outbreak of Coconut Rhinoceros Beetle,. Oryctes Rhinoceros Biotype G, on Guam and Attempts at Establishing Biological Control. XIX International Plant Protection Congress, Hyderabad, India. Nov. 11, 2019. Nov. 11, 2019. URL: https://github.com/aubreymoore/IAPPS-2019-Presentation/raw/master/Moore_IAPPS-2019.odp.
- [26] Aubrey Moore, James J. Grasela, and Sean David Goldie Marshall. Experimental Plan: Determining Presence of OrNV in the Guam CRB-G Population. 2020. URL: https://github.com/aubreymoore/FY19-PPA-Report-1/raw/master/docs/Guam%200rNV%20Experimental%20Plan.pdf.
- [27] Aubrey Moore and Roland Quitugua. Container for Secure Shipment of Live Coconut Rhinoceros Beetle Adults. Guam Coconut Rhinoceros Beetle Project Technical Report CRB-2017-05-27. University of Guam Cooperative Extension Service, June 1, 2017, p. 3. URL: https://github.com/aubreymoore/CRB-Import-Permit/raw/master/CRB_Shipping_Container.pdf.
- [28] OnePanel Inc. AI Pipeline Operations Manual: University of Guam CRB Damage Pipeline v.1.0. July 24, 2020. URL: https://api.zotero.org/groups/511387/items/DXCX92JC/file/view.
- [29] OnePanel Inc. Scope of Work: Object Detector(s) for Quantification of Coconut Rhinoceros Beetle Damage in Roadside Video Surveys V1.1. June 4, 2020. URL: https://api.zotero.org/groups/511387/items/8ZSUF6BX/file/view.
- [30] USDA-APHIS. CRB Import Permit. July 5, 2019. URL: https://github.com/aubreymoore/CRB-Import-Permit/blob/master/2019-CRB-Import-Permit.pdf.
- [31] Maclean Vaqalo, Visoni Timote, Senimili Baiculacula, Gideon Suda, and Frank Kwainarara. The Coconut Rhinoceros Beetle in the Solomon Islands: A Rapid Damage Assessment of Coconut Palms on Guadalcanal. June 2017. URL: https://api.zotero.org/groups/511387/items/LJDIQZYA/file/view.