


PARSE + PATCH + RE-IMPORT + ENGINEERING CHECK

Source SVG



Structural patch: 6 to 8 panels; 21 to 29 members.

FEM re-solve: peak stress 84.38 → 112.50 MPa; equilibrium passes.



Increase hole diameters by 6 mm: edit is faithful; clearance fails.

Recovered edge distance: 15 → 12 mm, below the stated 15 mm minimum.

Edited SVG

