

Report No.:

**248104514-02**

Page 1 of 3

Client:

**CÔNG TY TNHH HCSP**

518 Tô Ngọc Vân, phường Tam Phú, quận Thủ Đức, TP. Hồ Chí Minh, Việt Nam

Test Item(s):

Powder

Identification/  
Model No(s):

SECCO POWDER DESICCANT GLODRIC; MODEL: GLODRIC 1000G;  
MATERIAL: POWDER; COLOR: WHITE

Sample receiving date:

2019-07-02

Test period:

2019-07-02 to 2019-07-27

Test Specification:


Test result:

Test parameter chosen by customer:

1. Water absorption (25 days)

Please refer to page 02

For and on behalf of  
TÜV Rheinland Vietnam Co., Ltd.



Ms. Dao Thuy Khanh Linh/

2019-07-27

Project Manager

Date

Name/Position

Test result is drawn according to the kind and extent of tests performed.

This test report relates to the a. m. test sample. Without permission of the test center this test report is not permitted to be duplicated in extracts. This test report does not entitle to carry any safety mark on this or similar products.

Test Report No.: 248104514-02

Page 2 of 3

**Material List:**

Material No.	Material	Color	Location
M001	Powder	Off white	Powder

**1. Water absorption (25 days)**Test method: Condition: Ambient air,  $26 \pm 2^\circ\text{C}$ ,  $70 \pm 5\%\text{rH}$ , 25 days**Test result:**

Date	Weight (g)	Temperature ( $^\circ\text{C}$ )	Humid (%)	Water absorption (%)
0	1074	26.0	75	0.0
5	1327	26.0	75	23.6
10	1510	26.2	75	40.6
15	1816	26.1	75	69.1
20	2058	26.0	76	91.6
25	2319	26.0	76	115.9

**Summary:**

Material No.	M001				
	Trial	Before testing (g)	After testing (25 days) (g)	Water absorbed (g)	Water absorbed (%)
1	1	1074	2319	1245	115.9

**Abbreviation:** g = gram

% = Percentage

Test Report No.: 248104514-02

Page 3 of 3

Sample photos:



Lab ID.: A000951587-003



Sample before testing



Sample after testing

--- END ---