



Radiation Tests: Diodes (2)

- For the rest of the diodes, the TID tests were performed by reverse biasing them during the beam time
 - During the stop time, the relay board was used to go through the diode array and conduct a forward current and measure the forward voltage for each diode
 - Performed at a flux of 3.6 Gy/h, **TID tests were successful**
- All the diode boards were then annealed, and no significant change were observed in any of the them
- **NIEL tests for all diodes showed no failure or change in parameters**



A diode test board in CC60 facility



A diode test board inside climatic chamber