


Radiation Tests: SI8920 Isolation Amplifier (1)



- **Chips tested for NIEL showed no issues**
- SEE/TID tests performed at a flux of 3.5×10^8 p/cm²/s
 - With an input voltage of 150 mV, test results showed fluctuations in the output voltage of some chips during the beam time
- Another set of SEE/TID tests performed at a flux of 2×10^8 p/cm²/s, but the same behavior were observed



Unstable behavior of SI8920 at input voltage of 150 mV at PIF