


10. HASIL ANALISIS STRUKTUR SHELTER 2

10.1. Rasio Maksimum Baja Struktural


No	Deskripsi	Beam	Profil	Max Ratio	L/C	Ratio < 1
1	Column	234	PIPE3"	0.543	538	OK
2	Rafter Beam - BX1	81	PIPE3"	0.415	542	OK
3	Rafter Beam - BX2	51	PIPE3"	0.666	529	OK
4	Girder Beam - BZ	65	PIPE3"	0.262	541	OK
5	Crane Beam	107	H250X125X6X9	0.686	529	OK
6	Platform Beam X	124	H250X250X9X14	0.452	563	OK
7	Platform Beam Z	208	H250X125X6X9	0.848	563	OK
7	Steel Pipe	281	PIPS120	0.358	526	OK
Maximum Ratio :				<u>0.848</u>		OK



Status Rasio

10.2. Rasio Baja Struktural Saat Lifting

No	Deskripsi	Beam	Profil	Max Ratio	L/C	Ratio < 1
1	Column	225	PIPE3"	0.046	534	OK
2	Rafter Beam - BX1	82	PIPE3"	0.587	527	OK
3	Rafter Beam - BX2	51	PIPE3"	0.639	529	OK
4	Girder Beam - BZ	65	PIPE3"	0.083	529	OK
5	Crane Beam	107	H250X125X6X9	0.686	529	OK
Maximum Ratio :				<u>0.69</u>		OK



Status Rasio Lifting