
3D fan EigenFluid: complete reconstruction audit
Reconstruction convergence
Relative L_2 error
Modes
Disturbance
Full velocity
Spatial error distribution
Disturbance relative L_2
Rotor
Wake
Far wake
Outer
Quarter-turn symmetry
C4 relative defect
6.07e-01
5.47e-05
GT
Reconstruction
Center and eight parameter corners
Scaled Rayleigh loss
5.77e+03
C
0
1
2
3
4
5
6
7