Problem report for:


Grandstander[wght].ttf

sha1:63fec32e145ca5d0b233d711e8fe4eda8bda3947

Family name: Grandstander

Version: Version 1.200


"






'wght=900.0'


proposed fix



midway interpolation







'wght=900.0'

proposed fix

