Problem report for:

Geologica[CRSV,SHRP,sInt,wght].ttf

sha1:509866f158a1e222e40ecbea1c703ad266f5e937

Family name: Geologica

Version: Version 1.010;gftools[0.9.28]

Parameters:

Error tolerance: 0.95


Kink-reporting aggressiveness: 0.5

Legend:


- Contour start point and direction
- Contour start point when the first two points overlap
- ► Contour start point in contours with wrong direction
- Suggested new contour start point
- Point causing kink in the contour
- Kink artifact
- Colored contours: contours with the wrong order

Tolerance: badness; closer to zero the worse


"




'sInt = -12.0'



midway interpolation




proposed fix




"


'SHRP=100.0'




midway interpolation




proposed fix




'SHRP=100.0'




'SHRP=100.0 sInt=-12.0'




midway interpolation




proposed fix




'SHRP=100.0'




'SHRP=100.0 wght=900.0'



midway interpolation




proposed fix




wrong_start_point


'SHRP=100.0'




'SHRP=100.0 sInt=-12.0'



midway interpolation




proposed fix




wrong_start_point


'SHRP=100.0'




'SHRP=100.0 wght=900.0'



midway interpolation





proposed fix



,,

midway interpolation





'sInt = -12.0'

proposed fix

