Problem report for:

NotoSansMalayalamUl[wdth,wght].ttf

sha1: 4e39e6d83a0a66e1ab7389564ec8630cab8d1503

Family name: Noto Sans Malayalam Ul

Version: Version 2.001

Parameters:

Error tolerance: 0.95

Kink-reporting aggressiveness: 0.5


Legend:

- Contour start point and direction
- Contour start point when the first two points overlap
- Contour start point in contours with wrong direction
- Suggested new contour start point
- Point causing kink in the contour
- Kink artifact
- Colored contours: contours with the wrong order


Tolerance: badness; closer to zero the worse

kink


"



'wght=699.9878'



midway interpolation



proposed fix

