Problem report for:


BigShouldersStencilText[wght].ttf

sha1: c69ecc8bfb7560c0a542143921256a138b63aa8f


Family name: Big Shoulders Stencil Text

Version: Version 2.001


'wght=333.6003'



'wght=900.0'



midway interpolation



proposed fix

