## Problem report for:

## Merienda[wght].ttf

sha1: 59d2f81c132526de0b54e560adc5dfa5f5bde9f7

Family name: Merienda Version: Version 2.001


## Legend:

- Contour start point and direction
- Contour start point when the first two points overlap
- ► Contour start point in contours with wrong direction
- Suggested new contour start point
- Colored contours: contours with the wrong order


Tolerance: badness; closer to zero the worse

# wrong\_start\_point


"




'wght=300.0'



midway interpolation




proposed fix




# wrong\_start\_point


"



'wght=699.9878'



midway interpolation



proposed fix

