Problem report for:

Glory[wght].ttf

sha1: 7e8d080b2abc56efd9f316c84da3352f8c628f86

Family name: Glory

Version: Version 1.011

Parameters:

Error tolerance: 0.95

Kink—reporting aggressiveness: 0.5

Legend:

- Contour start point and direction
- Contour start point when the first two points overlap
- Contour start point in contours with wrong direction
- Suggested new contour start point
- Point causing kink in the contour
- Kink artifact
- Colored contours: contours with the wrong order
- Underweight contours

Tolerance: badness; closer to zero the worse

Summary of problems


```
wrong_start_point: 1
  thorn

kink: 5
  R
  d
  germandbls
  six
  thorn
```


Glyph name: thorn

tolerance: 0.34


Problems: kink, wrong_start_point




'wght=800.0'



midway interpolation



proposed fix




Glyph name: six

tolerance: 0.47


Problems: kink

,,


'wght=800.0'



midway interpolation



proposed fix





Glyph name: germandbls

tolerance: 0.63

Problems: kink


midway interpolation






Problems: kink


,,




'wght=800.0'



midway interpolation




proposed fix




Problems: kink


,,




'wght=800.0'



midway interpolation



proposed fix



Index

- 7 R
 6 d
 5 germandbls
 4 six
 3 thorn

Table of contents

- 3 thorn
- 4 six
- 5 germandbls 6 d 7 R