## Problem report for:

## MontaguSlab[opsz,wght].ttf

sha1: a974d2cd01511c9a4099ab674deb56490b266d9c

Family name: Montagu Slab

Version: Version 1.000

#### Parameters:

Error tolerance: 0.95

Kink-reporting aggressiveness: 0.5


## Legend:


- Contour start point and direction
- Contour start point when the first two points overlap
- ► Contour start point in contours with wrong direction
- Suggested new contour start point
- Point causing kink in the contour
- Kink artifact
- Colored contours: contours with the wrong order

Tolerance: badness; closer to zero the worse

'opsz=16.0'


midway interpolation






'opsz=16.0 wght=400.0'


proposed fix



'opsz=16.0 wght=400.0'


midway interpolation





'opsz=16.0 wght=100.0'

proposed fix




midway interpolation



"




proposed fix



"

midway interpolation





'wght=400.0'

proposed fix

