Problem report for:

Merienda[wght].ttf

sha1: 59d2f81c132526de0b54e560adc5dfa5f5bde9f7


Family name: Merienda Version: Version 2.001

Legend:


- Contour start point and direction
- Contour start point when the first two points overlap
- Contour start point in contours with wrong direction
- Suggested new contour start point

wrong_start_point


"




'wght=300.0'



midway interpolation




proposed fix




wrong_start_point


"



'wght=699.9878'



midway interpolation



proposed fix

