
Problem report for:

AdventPro[wdth,wght].ttf


sha1: 0a5232940c0e815fe4119b03ec2f795b58ed3ed0

Family name: Advent Pro Version: Version 3.000




wrong_start_point

midway interpolation




proposed fix



tolerance: 0.06


contour_order

midway interpolation




'wght=900.0'


proposed fix




"




'wght=699.9878'




midway interpolation




proposed fix




'wdth=200.0'




'wdth=200.0 wght=699.9878'



midway interpolation




proposed fix



midway interpolation

'wdth=200.0 wght=699.9878'



'wdth=200.0 wght=900.0'

proposed fix

