Problem report for:

Catamaran[wght].ttf

sha1: 9f96cf6da56303c4f5284291053aab62247f39f6

Family name: Catamaran Version: Version 2.000

Parameters:

Error tolerance: 0.95

Kink-reporting aggressiveness: 0.5


Legend:

- Contour start point and direction
- Contour start point when the first two points overlap
- ► Contour start point in contours with wrong direction
- Suggested new contour start point
- Point causing kink in the contour
- Kink artifact
- Colored contours: contours with the wrong order


Tolerance: badness; closer to zero the worse

wrong_start_point


'wght=500.0'




'wght=700.0'




midway interpolation



proposed fix




wrong_start_point





wrong_start_point

'wght=700.0'

midway interpolation







proposed fix

