Problem report for:


BigShouldersInlineDisplay[wght].ttf

sha1: 38c1a44fec8415902c681fa185274e169162c7b3


Family name: Big Shoulders Inline Display


Version: Version 2.002


midway interpolation




"












midway interpolation



proposed fix







'wght=333.6003'

