### Problem report for:

### Cormorant[wght].ttf

sha1:6c7140d9322af42c415ed88a6609788d9b0b42a0

Family name: Cormorant Version: Version 4.000

#### Parameters:

Error tolerance: 0.95

Kink-reporting aggressiveness: 0.5


#### Legend:

- Contour start point and direction
- Contour start point when the first two points overlap
- ► Contour start point in contours with wrong direction
- Suggested new contour start point
- Point causing kink in the contour
- Kink artifact
- Colored contours: contours with the wrong order
- Underweight contours


Tolerance: badness; closer to zero the worse

# underweight


"




'wght=700.0'




midway interpolation






## contour\_order


"



'wght=700.0'



midway interpolation



proposed fix

