Problem report for:

Cormorant[wght].ttf

sha1:6c7140d9322af42c415ed88a6609788d9b0b42a0

Family name: Cormorant Version: Version 4.000

Parameters:

Error tolerance: 0.95

Kink-reporting aggressiveness: 0.5


Legend:

- Contour start point and direction
- Contour start point when the first two points overlap
- ► Contour start point in contours with wrong direction
- Suggested new contour start point
- Point causing kink in the contour
- Kink artifact
- Colored contours: contours with the wrong order


Tolerance: badness; closer to zero the worse

contour_order


"




'wght=700.0'



midway interpolation




proposed fix




kink


"



'wght=700.0'



midway interpolation



proposed fix

