Problem report for:

ElMessiri[wght].ttf

sha1: c64c5b5df49eb5bf827342ea900e322996f3a215

Family name: El Messiri Version: Version 2.020

Parameters:

Error tolerance: 0.95


Kink-reporting aggressiveness: 0.5

Legend:


- Contour start point and direction
- Contour start point when the first two points overlap
- ► Contour start point in contours with wrong direction
- Suggested new contour start point
- Point causing kink in the contour
- Kink artifact
- Colored contours: contours with the wrong order

Tolerance: badness; closer to zero the worse


wrong_start_point




'wght=700.0'



midway interpolation




proposed fix




wrong_start_point


midway interpolation



'wght=700.0'




proposed fix




kink


"



'wght=700.0'



midway interpolation



proposed fix

