

Banff Visitor Safety

27/03/2025 - 11:30

Co-ord: 51.70984N, -116.47918W

Slope Angle: 0°

Wind Loading:

Time Interval

Stability:

Air Temperature:

Sky Cover: OVC

Precipitation: S1


Wind: Calm

HS:143

Layer Notes:

72-35cm: Problematic layer

35-10cm: Old crusts



Notes:

Form	Crystal Size	Moisture	ρ kg/m ³	Stability tests & Layer comments
+				
+		M		
°°		W		
● (/)		M		
●		D		
□ (^)				← CT25, SC @ 65cm In depth hoar
^		D		35-10cm: Old crusts
^				