

Banff Visitor Safety

26/11/2021 - 12:00

Co-ord: **51.43921N, -116.54191W**

Slope Angle:


Wind Loading:

Figure 2.12

HS:61

31-29cm: Nov 15 crust

31-29cm: Problematic layer



Notes: Sticky Interface between the new snow and the crust in hand shear tests. Whole snowpack somewhat moist.