


Banff Visitor Safety
27/11/2021 - 11:40
 Co-ord:
 Slope Angle: **35°**
 Wind Loading:

Stability: **HS:90**
Air Temperature: **-3.5°C**
Sky Cover: **OVC**
Precipitation: **NO**
Wind: **Calm**

Layer Notes:
45-44cm: Problematic layer



Notes:

Form	Crystal Size	Moisture	ρ kg/m ³	Stability tests & Layer comments
*r	1.5			
/	1			
/	1			← CT15, SP @60cm
□				
⊗⊗				
□				← CT22, SC @45cm
●	-1			
⊖	1-2	M		