


LOC I-BVI	APP CRS	Rwy Ldg	4501
109.3	101°	TDZE	1238
		Apt Elev	1253

LOC RWY 10

BEAVER COUNTY (BVI)

DME or RADAR REQUIRED	MISSED APPROACH: Climb to 2000 then climbing left turn to 3000 direct EWC VOR/DME and hold.
▼ ▲ Rwy 10 helicopter visibility reduction below ¾ SM NA. When local alimeter setting not received, use Pittsburgh Intl alimeter setting and increase all MDAs 60 feet and visibility S-10 Cats C and D ¼ SM. Circling Rwy 28 NA at night.	

ATIS 118.35	PITTSBURGH APP CON 124.75 338.2	BEAVER COUNTY TOWER ★ 120.3 (CTAF) 0	GND CON 121.8
----------------	------------------------------------	---	------------------



One Minute Holding Pattern

JOTMI

EWC 20.8

RADAR

NAMTH

OM

2000

3000

EWC

6000

3000

281°

101°

101°

3000

2.94°

TCH 42

6.5 NM

5.6 NM

101°

1.1% UP

4501 X 100

28

101°

CATEGORY	A	B	C	D
S-10	1640-1	402 (400-1)	1640-1½	402 (400-1½)
CIRCLING	1720-1	467 (500-1)	1720-1½	1820-2
			467 (500-1½)	567 (600-2)

MIRL Rwy 10-28

REIL Rwys 10 and 28

FAF to MAP 5.6 NM

Knots	60	90	120	150	180
Min:Sec	5:36	3:44	2:48	2:14	1:52