

|                                        |                        |                                                   |
|----------------------------------------|------------------------|---------------------------------------------------|
| WAAS<br>CH <b>99424</b><br><b>W23A</b> | APP CRS<br><b>230°</b> | Rwy Ldg<br>TDZE <b>847</b><br>Apt Elev <b>847</b> |
|----------------------------------------|------------------------|---------------------------------------------------|

RNAV (GPS) RWY 23

SHELBY-CLEVELAND COUNTY RGNL (EHO)

RNP APCH.


▼

▲

Baro-VNAV NA when using Charlotte altimeter setting. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -16°C or above 38°C. When local altimeter setting not received, use Charlotte altimeter setting and increase all DA 88 feet and all MDA 100 feet; increase LPV all Cats visibility 1⁄8 SM and LNAV/VNAV all Cats, LNAV Cat C/D visibility 1⁄4 SM.

MISSED APPROACH:  
Climb to 3000 direct ZISUG and hold.

|                          |                                          |                                 |
|--------------------------|------------------------------------------|---------------------------------|
| AWOS-3<br><b>118.425</b> | CHARLOTTE APP CON<br><b>120.05 257.2</b> | UNICOM<br><b>122.8 (CTAF) 0</b> |
|--------------------------|------------------------------------------|---------------------------------|



ELEV 847

TDZE 847

3000

ZISUG

VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 28).

5 NM Holding Pattern

\* LNAV only.

ZIRUL 2500

ZEMRO 2.3 NM to RWY 23

RWY 23

1600\*

2500

LINCO

023° → 4000

← 203°

GP 3.00° TCH 40

2.3 NM

2.8 NM

9.3 NM

| CATEGORY     | A                  | B | C                    | D |
|--------------|--------------------|---|----------------------|---|
| LPV DA       | 1097-1 250 (300-1) |   |                      |   |
| LNAV/VNAV DA | 1123-1 276 (300-1) |   |                      |   |
| LNAV MDA     | 1440-1 593 (600-1) |   | 1440-1¾ 593 (600-1¾) |   |

MIRL Rwy 5-23 0