

SAND POINT, ALASKA


AL-6537 (FAA)

26190


WAAS CH 56245 W14A	APP CRS 121°	Rwy Ldg 4099 TDZE 23 Apt Elev 24
--	------------------------	---

RNAV (GPS) Z RWY 14
SAND POINT (SDP) (PASD)

RNP APCH-GPS.		MISSED APPROACH: Climbing right turn to 5000 on the RNAV missed approach route to DUGAC and hold.	
 Circling NA northeast of Rwy 14-32.			
AWOS-3P 134.85	ANCHORAGE CENTER 125.35 346.3	COLD BAY RADIO 122.3	CTAF 122.3 



ELEV 24	D	TDZE 23
---------	----------	---------



MIRL Rwy 14-32 **L**
REIL Rwys 14 and 32 **L**

Diagram illustrating a non-convexity in a flight path. The path starts at POSAE (2900) and ends at DUGAC. The path is non-convex because the angle at MOORE is greater than 180°. The diagram also shows the VGS and descent angles for each segment, which are not coincident. The VGS angle for the first segment is 3.49° and for the second segment is 3.60°. The descent angles are 2.2 NM to ORPIE and 1.1 NM to ORPIE. The diagram includes a table with categories A, B, C, and D, and a table with categories A, B, C, and D.

CATEGORY	A	B	C	D
LP MDA	660-1	637 (700-1)	660-1¾	637 (700-1¾)
INAV MDA	820-1 797 (800-1)	820-1¼ 797 (800-1¼)	820-2½	797 (800-2½)
CIRCLING	820-1 796 (800-1)	820-1¼ 796 (800-1¼)	1580-3 1556 (1600-3)	2240-3 2216 (2300-3)

SAND POINT, ALASKA
Amdt 2 02DEC21

55°19'N-160°31'W

SAND POINT (SDP) (PASD)
RNAV (GPS) Z RWY 14

AK, 03 SEP 2026 to 29 OCT 2026