





## **CONCRETE PLACEMENT REPORT**

	GENERAL INFORMATION														
ENGL	OBE PR	OJECT NO.:	02102531.095.0100.0101				CLIENT CONTRACT NO.:			F01-113-01-09					
PROJE	ECT NA	ME:	NSPW - F01-113-01-09 HI Summer Street Entrance												
CLIEN	T:	NSPW					CLIENT P.O.:								
ADDRESS:						co	CONTRACTOR:			Dexter					
		1672 Granville St, 3rd Floor					ARRIVAL TIME:			02:30 PM (-3 GMT)					
		PO Box 186 Halifax, NS B3J 3Z8				DE	_ DEPARTURE TIME:			04:30 PM (-3 GMT)					
ATTENTION:		Jessica McNeil													
PHONE:		(902) 237-2	267	CE	LL:		EMAIL:			jessica.mcneil@novascotia.ca					
MIX NO:		E352A2B			RMWORK	<b>(</b> :	Concrete/Wood			DATE PLACED:			2022-10-27		
SUPPLIER: WEATHER:		Quality Con	crete (Halif	ax) FO	FORMWORK CLEA		Yes		ME	METHOD OF PLACING: Chute					
		, ,								METHOD OF CURING: Curing Compound					
		Cloudy			RRATORS		N/A			EQUIPMENT NO.:			87		
		Cloudy		VIBRATORS:			NA			CALIBRATION DATE: 2022/08/08					
									CAL	IBRATION	IDATE:	2022/08/	08		
						SPEC	IFIED PF	ROPERT	IES						
STRENGTH @ 28 DAYS: 35 MPa SLUMP: 80 +/- 20 mm AIR: 6 +/- 1 %															
Load	Ticke	t Truck		Time Record			Air (%)		Ten	ıp (°C)	Volume		No.	Cure	
No.	No.		Batch	Tested	Unload	Elapsed		Slump	Conc	Air	Load	Cum	Cylinders Cast	Туре	
1	11563	44 1104	14:20	14:40	16:10	1:50	5.5	95	25.0	20.0	7.26	7.26	5	Standar d	
SECTION: Sidewalk exposed aggregate															
LOCATION: Half of front sidewalk, south east of entrance.															
COMN:	MENTS														
RECORD NO.: m-3958 STANDBY: ENGLOBE TECH: Brandon Gorman PER: Who Subditional Periods of the Standard															
	Fo	or testing cor constitu						t in accorda or evaluati							

PROJECT MANAGER: Peter Salah










## **SAMPLE PHOTOS**



## **PROJECT LOCATION**



