

## Bikespace Analysis - Damaged Bicycle Parking Reports

Updated October 29 2024

20 BikeSpace damage reports with nearby City bicycle parking features

### NOTES

- Includes relevant BikeSpace reports between and including 2023-01-01 and 2024-08-23
- Coordinate reference system for lat/long values is WGS84 (EPSG:4326)
- For any questions about this sheet, please contact [bikespaceto@gmail.com](mailto:bikespaceto@gmail.com)

### TABS

- MatchesDisplay: display of damaged bicycle parking reports alongside nearby City of Toronto parking features  
Damage reports are ordered by date descending (most recent first)  
Thumbnail maps: orange triangle is location of damage report  
blue dots are locations of nearest City bicycle parking features (max 5)  
Then damage report listed first, followed by data from applicable City features  
Some City features are based on exact matches determined by volunteer site survey  
Otherwise, up to 5 estimated matches are shown within a 30m radius of the report  
The 'match\_type' field indicates whether the matches are surveyed or estimated.
- MatchesTable: display of damaged bicycle parking reports alongside first match from nearby City of Toronto parking features  
Damage reports are ordered by date descending (most recent first)
- DamageReports: data table for damaged bicycle parking reports
- CityFeatures: data table for City of Toronto parking features matched with damage reports  
(Note that the same features may be listed more than once)

### SOURCES

User reports of damaged bicycle parking are from the BikeSpace app ([bikespace.ca](https://bikespace.ca))

BikeSpace damage reports are checked for data quality.

Resolved issues, known test entries, duplicates, and reports not on City property are omitted.

City of Toronto bicycle parking features are from the following datasets:


- Bicycle Parking - High Capacity (Outdoor)
- Bicycle Parking Racks
- Street Furniture - Bicycle Parking

## Bikespace Analysis - Damaged Bicycle Parking Reports

Updated October 29 2024

20 BikeSpace damage reports with nearby City bicycle parking features

### BIKESPACE REPORT #1399 (2024-08-22)



<b>bikespace_id</b>	1399
<b>latitude</b>	43.65991437
<b>longitude</b>	-79.38724666
<b>issues</b>	['damaged']
<b>comments</b>	BP-22556 ring has fallen down; no longer secured
<b>report_date</b>	2024-08-22
<b>report_time</b>	14:55:00
<b>Notes</b>	Shared with City in damage report 2024-08-23; Should be a #teambikespace entry; forgot to add the hashtag
<b>Survey_Date</b>	
<b>Asset</b>	BP-22556
<b>Check_311_Date</b>	2024-08-22
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Loose/unsecured
<b>WARD</b>	University-Rosedale (11)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1399">https://app.bikespace.ca/dashboard?submission_id=1399</a>

<b>match_type</b>	surveyed
<b>distance</b>	3.467457873
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-22556
<b>OBJECTID</b>	38411
<b>ADDRESSNUMBERTEXT</b>	220
<b>ADDRESSSTREET</b>	Elizabeth St
<b>FRONTINGSTREET</b>	Elizabeth St
<b>SIDE</b>	West
<b>FROMSTREET</b>	College St
<b>DIRECTION</b>	South
<b>SITEID</b>	None
<b>WARD</b>	11
<b>BIA</b>	None
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.65994558
<b>longitude</b>	-79.38724564

**BIKESPACE REPORT #1400 (2024-08-22)**


<b>bikespace_id</b>	1400
<b>latitude</b>	43.6587695
<b>longitude</b>	-79.39509485
<b>issues</b>	['damaged']
<b>comments</b>	BP-27452 ring is missing #teambikespace
<b>report_date</b>	2024-08-22
<b>report_time</b>	14:00:00
<b>Notes</b>	Shared with City in damage report 2024-08-23
<b>Survey_Date</b>	
<b>Asset</b>	BP-27452
<b>Check_311_Date</b>	2024-08-22
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Post with no ring
<b>WARD</b>	University-Rosedale (11)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1400">https://app.bikespace.ca/dashboard?submission_id=1400</a>

<b>match_type</b>	surveyed
<b>distance</b>	1.373623558
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-27452
<b>OBJECTID</b>	23565
<b>ADDRESSNUMBERTEXT</b>	197
<b>ADDRESSSTREET</b>	College St
<b>FRONTINGSTREET</b>	College St
<b>SIDE</b>	South
<b>FROMSTREET</b>	Ln E Beverley S College
<b>DIRECTION</b>	East
<b>SITEID</b>	None
<b>WARD</b>	11
<b>BIA</b>	None
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.65877375
<b>longitude</b>	-79.39507885

**BIKESPACE REPORT #1401 (2024-08-22)**


<b>bikespace_id</b>	1401
<b>latitude</b>	43.65500096
<b>longitude</b>	-79.4202044
<b>issues</b>	['damaged']
<b>comments</b>	BP-27742 ring is missing #teambikespace
<b>report_date</b>	2024-08-22
<b>report_time</b>	13:05:00
<b>Notes</b>	Shared with City in damage report 2024-08-23
<b>Survey_Date</b>	BP-27742
<b>Asset</b>	2024-08-22
<b>Check_311_Date</b>	No requests found
<b>Check_311_Notes</b>	Post with no ring
<b>City_Problem_Type</b>	University-Rosedale (11)
<b>WARD</b>	
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1401">https://app.bikespace.ca/dashboard?submission_id=1401</a>

<b>match_type</b>	surveyed
<b>distance</b>	1.975693797
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-27742
<b>OBJECTID</b>	13653
<b>ADDRESSNUMBERTEXT</b>	766
<b>ADDRESSSTREET</b>	College St
<b>FRONTINGSTREET</b>	Shaw St
<b>SIDE</b>	East
<b>FROMSTREET</b>	College St
<b>DIRECTION</b>	North
<b>SITEID</b>	None
<b>WARD</b>	11
<b>BIA</b>	Little Italy
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.6550085
<b>longitude</b>	-79.42022659

**BIKESPACE REPORT #1403 (2024-08-22)**


<b>bikespace_id</b>	1403
<b>latitude</b>	43.69265627
<b>longitude</b>	-79.4410299
<b>issues</b>	['damaged']
<b>comments</b>	BP-32163 ring missing #teambikespace
<b>report_date</b>	2024-08-22
<b>report_time</b>	11:36:00
<b>Notes</b>	Shared with City in damage report 2024-08-23
<b>Survey_Date</b>	BP-32163
<b>Asset</b>	2024-08-22
<b>Check_311_Date</b>	No requests found
<b>Check_311_Notes</b>	Post with no ring
<b>City_Problem_Type</b>	Toronto-St. Paul's (12)
<b>WARD</b>	
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1403">https://app.bikespace.ca/dashboard?submission_id=1403</a>


<b>match_type</b>	surveyed
<b>distance</b>	1.711687959
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-32163
<b>OBJECTID</b>	30883
<b>ADDRESSNUMBERTEXT</b>	626
<b>ADDRESSSTREET</b>	Vaughan Rd
<b>FRONTINGSTREET</b>	Vaughan Rd
<b>SIDE</b>	West
<b>FROMSTREET</b>	Oakwood Ave
<b>DIRECTION</b>	West
<b>SITEID</b>	None
<b>WARD</b>	12
<b>BIA</b>	Oakwood Village
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.69266545
<b>longitude</b>	-79.44101284

**BIKESPACE REPORT #1402 (2024-08-22)**


<b>bikespace_id</b>	1402
<b>latitude</b>	43.69292778
<b>longitude</b>	-79.44087384
<b>issues</b>	['damaged']
<b>comments</b>	BP-32158 bent and missing cap #teambikespace
<b>report_date</b>	2024-08-22
<b>report_time</b>	11:30:00
<b>Notes</b>	Shared with City in damage report 2024-08-23; Bent and missing cap
<b>Survey_Date</b>	
<b>Asset</b>	BP-32158
<b>Check_311_Date</b>	2024-08-22
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Bent
<b>WARD</b>	Toronto-St. Paul's (12)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1402">https://app.bikespace.ca/dashboard?submission_id=1402</a>


<b>match_type</b>	surveyed
<b>distance</b>	0.964376797
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-32158
<b>OBJECTID</b>	20323
<b>ADDRESSNUMBERTEXT</b>	503
<b>ADDRESSSTREET</b>	Oakwood Ave
<b>FRONTINGSTREET</b>	Oakwood Ave
<b>SIDE</b>	East
<b>FROMSTREET</b>	Belvidere Ave
<b>DIRECTION</b>	North
<b>SITEID</b>	None
<b>WARD</b>	12
<b>BIA</b>	Oakwood Village
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.69292114
<b>longitude</b>	-79.44086615

**BIKESPACE REPORT #1398 (2024-08-21)**



<b>bikespace_id</b>	1398
<b>latitude</b>	43.66477305
<b>longitude</b>	-79.38044
<b>issues</b>	['damaged']
<b>comments</b>	Post and Ring BP-36518 is loose and has cap missing #teambikespace
<b>report_date</b>	2024-08-21
<b>report_time</b>	16:30:00
<b>Notes</b>	Shared with City in damage report 2024-08-23
<b>Survey_Date</b>	2024-08-21
<b>Asset</b>	BP-36518
<b>Check_311_Date</b>	2024-08-18
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Loose/unsecured
<b>WARD</b>	Toronto Centre (13)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1398">https://app.bikespace.ca/dashboard?submission_id=1398</a>

<b>match_type</b>	surveyed
<b>distance</b>	1.468349851
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-36518
<b>OBJECTID</b>	24732
<b>ADDRESSNUMBERTEXT</b>	477
<b>ADDRESSSTREET</b>	Church St
<b>FRONTINGSTREET</b>	Church St
<b>SIDE</b>	East
<b>FROMSTREET</b>	Maitland St
<b>DIRECTION</b>	North
<b>SITEID</b>	None
<b>WARD</b>	13
<b>BIA</b>	Church-Wellesley Village
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.66478058
<b>longitude</b>	-79.38045496

**BIKESPACE REPORT #1396 (2024-08-17)**


<b>bikespace_id</b>	1396
<b>latitude</b>	43.66481765
<b>longitude</b>	-79.37982042
<b>issues</b>	['damaged']
<b>comments</b>	Ring not firmly attached to post: top bolt is missing and bottom bolt is loose, so not secure for bike parking. It is the first bike ring located on the north east corner on Church, at Maitland.
<b>report_date</b>	2024-08-17
<b>report_time</b>	12:50:52
<b>Notes</b>	Shared with City in damage report 2024-08-23
<b>Survey_Date</b>	2024-08-21
<b>Asset</b>	BP-36687
<b>Check_311_Date</b>	2024-08-18
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Loose/unsecured
<b>WARD</b>	Toronto Centre (13)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1396">https://app.bikespace.ca/dashboard?submission_id=1396</a>

<b>match_type</b>	surveyed
<b>distance</b>	10.42462545
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-36687
<b>OBJECTID</b>	17841
<b>ADDRESSNUMBERTEXT</b>	84
<b>ADDRESSSTREET</b>	Maitland St
<b>FRONTINGSTREET</b>	Maitland St
<b>SIDE</b>	North
<b>FROMSTREET</b>	Alexander Pl
<b>DIRECTION</b>	West
<b>SITEID</b>	None
<b>WARD</b>	13
<b>BIA</b>	Church-Wellesley Village
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.66481032
<b>longitude</b>	-79.3799493

**BIKESPACE REPORT #1387 (2024-08-04)**



<b>bikespace_id</b>	1387
<b>latitude</b>	43.65913249
<b>longitude</b>	-79.38674894
<b>issues</b>	['damaged']
<b>comments</b>	BP-22469, missing ring, e side of Elizabeth St, <a href="https://flic.kr/p/2q86HtE">https://flic.kr/p/2q86HtE</a> #teambikespace
<b>report_date</b>	2024-08-04
<b>report_time</b>	13:06:46
<b>Notes</b>	Shared with City in damage report 2024-08- 23
<b>Survey_Date</b>	BP-22469
<b>Asset</b>	2024-08-15
<b>Check_311_Date</b>	No requests found
<b>Check_311_Notes</b>	Post with no ring
<b>City_Problem_Type</b>	University-Rosedale (11)
<b>WARD</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1387">https://app.bikespace.ca/dashboard?submission_id=1387</a>
<b>url</b>	

<b>match_type</b>	surveyed
<b>distance</b>	3.12346979
<b>source</b>	street-furniture-bicycle- parking
<b>ID</b>	BP-22469
<b>OBJECTID</b>	18610
<b>ADDRESSNUMBERTEXT</b>	201
<b>ADDRESSSTREET</b>	Elizabeth St
<b>FRONTINGSTREET</b>	Elizabeth St
<b>SIDE</b>	East
<b>FROMSTREET</b>	La Plante Ave
<b>DIRECTION</b>	West
<b>SITEID</b>	None
<b>WARD</b>	11
<b>BIA</b>	None
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.65912499
<b>longitude</b>	-79.38671161

**BIKESPACE REPORT #1382 (2024-07-27)**



<b>bikespace_id</b>	1382
<b>latitude</b>	43.65176589
<b>longitude</b>	-79.47375706
<b>issues</b>	['damaged']
<b>comments</b>	Broken ring and post in front of runnymede tpl branch
<b>report_date</b>	2024-07-27
<b>report_time</b>	16:11:58
<b>Notes</b>	Shared with City in damage report 2024-08-23
<b>Survey_Date</b>	2024-08-19
<b>Asset</b>	BP-22650
<b>Check_311_Date</b>	2024-08-15
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Loose/unsecured
<b>WARD</b>	Parkdale-High Park (4)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1382">https://app.bikespace.ca/dashboard?submission_id=1382</a>

<b>match_type</b>	surveyed
<b>distance</b>	2.777872906
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-22650
<b>OBJECTID</b>	16802
<b>ADDRESSNUMBERTEXT</b>	2178
<b>ADDRESSSTREET</b>	Bloor St W
<b>FRONTINGSTREET</b>	Bloor St W
<b>SIDE</b>	North
<b>FROMSTREET</b>	Glendonwynne Rd
<b>DIRECTION</b>	East
<b>SITEID</b>	None
<b>WARD</b>	04
<b>BIA</b>	Bloor West Village
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.65179089
<b>longitude</b>	-79.47375639

**BIKESPACE REPORT #1369 (2024-07-05)**



<b>bikespace_id</b>	1369
<b>latitude</b>	43.64951657
<b>longitude</b>	-79.42643081
<b>issues</b>	['not_provided', 'damaged']
<b>comments</b>	The one bike ring that is there is loose.
<b>report_date</b>	2024-07-05
<b>report_time</b>	17:00:00
<b>Notes</b>	Shared with City in damage report 2024-08-23
<b>Survey_Date</b>	2024-08-22
<b>Asset</b>	BP-20032
<b>Check_311_Date</b>	2024-08-15
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Loose/unsecured
<b>WARD</b>	Davenport (9)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1369">https://app.bikespace.ca/dashboard?submission_id=1369</a>

<b>match_type</b>	surveyed
<b>distance</b>	13.4039799
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-20032
<b>OBJECTID</b>	17985
<b>ADDRESSNUMBERTEXT</b>	1322
<b>ADDRESSSTREET</b>	Dundas St W
<b>FRONTINGSTREET</b>	Dundas St W
<b>SIDE</b>	North
<b>FROMSTREET</b>	Coolmine Rd
<b>DIRECTION</b>	West
<b>SITEID</b>	None
<b>WARD</b>	09
<b>BIA</b>	Little Portugal
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.64954434
<b>longitude</b>	-79.4262691

**BIKESPACE REPORT #1367 (2024-07-01)**



<b>bikespace_id</b>	1367
<b>latitude</b>	43.69368608
<b>longitude</b>	-79.44127643
<b>issues</b>	['damaged']
<b>comments</b>	
<b>report_date</b>	2024-07-01
<b>report_time</b>	19:56:25
<b>Notes</b>	Shared with City in damage report 2024-08-23
<b>Survey_Date</b>	2024-08-22
<b>Asset</b>	BP-44877
<b>Check_311_Date</b>	2024-08-15
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Bent
<b>WARD</b>	Toronto-St. Paul's(12)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1367">https://app.bikespace.ca/dashboard?submission_id=1367</a>

<b>match_type</b>	surveyed
<b>distance</b>	8.604192805
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-44877
<b>OBJECTID</b>	12017
<b>ADDRESSNUMBERTEXT</b>	529
<b>ADDRESSSTREET</b>	Oakwood Ave
<b>FRONTINGSTREET</b>	Oakwood Ave
<b>SIDE</b>	East
<b>FROMSTREET</b>	Strader Ave
<b>DIRECTION</b>	North
<b>SITEID</b>	None
<b>WARD</b>	12
<b>BIA</b>	Oakwood Village
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.69366103
<b>longitude</b>	-79.44117541

**BIKESPACE REPORT #1345 (2024-05-06)**



<b>bikespace_id</b>	1345
<b>latitude</b>	43.66412305
<b>longitude</b>	-79.3686262
<b>issues</b>	['damaged']
<b>comments</b>	The bike stand is broken
<b>report_date</b>	2024-05-06
<b>report_time</b>	12:19:26
<b>Notes</b>	Shared with City in damage report 2024-08-23; Several bent Post and Rings, but appear to have been spray-tagged orange for fixing. BP-28070 is fully bent over.
<b>Survey_Date</b>	2024-08-21
<b>Asset</b>	BP-28070
<b>Check_311_Date</b>	2024-08-15
<b>Check_311_Notes</b>	Likely 311 request located at 233 Carlton. Another ring post fix request nearby via 311 at 467 parliament.
<b>City_Problem_Type</b>	Bent
<b>WARD</b>	Toronto Centre (13)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1345">https://app.bikespace.ca/dashboard?submission_id=1345</a>

<b>match_type</b>	surveyed
<b>distance</b>	15.68769374
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-28070
<b>OBJECTID</b>	21815
<b>ADDRESSNUMBERTEXT</b>	235
<b>ADDRESSSTREET</b>	Carlton St
<b>FRONTINGSTREET</b>	Carlton St
<b>SIDE</b>	South
<b>FROMSTREET</b>	Parliament St
<b>DIRECTION</b>	West
<b>SITEID</b>	None
<b>WARD</b>	13
<b>BIA</b>	Cabbagetown
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.66410153
<b>longitude</b>	-79.36843394

**BIKESPACE REPORT #1342 (2024-04-28)**


<b>bikespace_id</b>	1342
<b>latitude</b>	43.70293996
<b>longitude</b>	-79.29698819
<b>issues</b>	['damaged']
<b>comments</b>	Ring fallen down on BP-34713. <a href="https://flic.kr/p/2pMYvOg">https://flic.kr/p/2pMYvOg</a> #teambikespace
<b>report_date</b>	2024-04-28
<b>report_time</b>	12:53:57
<b>Notes</b>	Shared with City in damage report 2024-08-23
<b>Survey_Date</b>	
<b>Asset</b>	BP-34713
<b>Check_311_Date</b>	2024-08-15
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Loose/unsecured
<b>WARD</b>	Beaches-East York (19)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1342">https://app.bikespace.ca/dashboard?submission_id=1342</a>

<b>match_type</b>	surveyed
<b>distance</b>	0.717393311
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-34713
<b>OBJECTID</b>	36807
<b>ADDRESSNUMBERTEXT</b>	466A
<b>ADDRESSSTREET</b>	Dawes Rd
<b>FRONTINGSTREET</b>	Dawes Rd
<b>SIDE</b>	West
<b>FROMSTREET</b>	Ln N Gower W Dawes
<b>DIRECTION</b>	West
<b>SITEID</b>	None
<b>WARD</b>	19
<b>BIA</b>	None
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.70294602
<b>longitude</b>	-79.29699125

**BIKESPACE REPORT #1330 (2024-03-23)**


<b>bikespace_id</b>	1330
<b>latitude</b>	43.66883394
<b>longitude</b>	-79.33701189
<b>issues</b>	['damaged']
<b>comments</b>	BP-35952 Ring and post is missing a ring. #TeamBikeSpace
<b>report_date</b>	2024-03-23
<b>report_time</b>	12:16:23
<b>Notes</b>	Shared with City in damage report 2024-08-23
<b>Survey_Date</b>	
<b>Asset</b>	BP-35952
<b>Check_311_Date</b>	2024-08-22
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Post with no ring
<b>WARD</b>	Toronto-Danforth (14)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1330">https://app.bikespace.ca/dashboard?submission_id=1330</a>

<b>match_type</b>	surveyed
<b>distance</b>	4.376360216
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-35952
<b>OBJECTID</b>	25032
<b>ADDRESSNUMBERTEXT</b>	1029
<b>ADDRESSSTREET</b>	Gerrard St E
<b>FRONTINGSTREET</b>	Gerrard St E
<b>SIDE</b>	South
<b>FROMSTREET</b>	Marjory Ave
<b>DIRECTION</b>	East
<b>SITEID</b>	None
<b>WARD</b>	14
<b>BIA</b>	None
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.66882086
<b>longitude</b>	-79.33706309

**BIKESPACE REPORT #1329 (2024-03-23)**


<b>bikespace_id</b>	1329
<b>latitude</b>	43.66905693
<b>longitude</b>	-79.33668736
<b>issues</b>	['damaged']
<b>comments</b>	BP-35870 ring and post broken, ring is missing. #teambikespace
<b>report_date</b>	2024-03-23
<b>report_time</b>	12:04:22
<b>Notes</b>	Shared with City in damage report 2024-08-23
<b>Survey_Date</b>	BP-35870
<b>Asset</b>	2024-08-22
<b>Check_311_Date</b>	No requests found
<b>Check_311_Notes</b>	Post with no ring
<b>City_Problem_Type</b>	
<b>WARD</b>	Toronto-Danforth (14)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1329">https://app.bikespace.ca/dashboard?submission_id=1329</a>

<b>match_type</b>	surveyed
<b>distance</b>	4.466777922
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-35870
<b>OBJECTID</b>	35312
<b>ADDRESSNUMBERTEXT</b>	1040
<b>ADDRESSSTREET</b>	Gerrard St E
<b>FRONTINGSTREET</b>	Gerrard St E
<b>SIDE</b>	North
<b>FROMSTREET</b>	Galt Ave
<b>DIRECTION</b>	West
<b>SITEID</b>	None
<b>WARD</b>	14
<b>BIA</b>	None
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.66903146
<b>longitude</b>	-79.33673023

BIKESPACE REPORT #1328 (2024-03-16)




bikespace_id	1328
latitude	43.69069735
longitude	-79.34930268
issues	['damaged']
comments	Ring has fallen down on post, is no longer attached. Asset ID is BP-24431. #teambikespace
report_date	2024-03-16
report_time	15:39:55
Notes	Shared with City in damage report 2024-08-23
Survey_Date	
Asset	BP-24431
Check_311_Date	2024-08-22
Check_311_Notes	No requests found
City_Problem_Type	Loose/unsecured
WARD	Toronto-Danforth (14)
url	<a href="https://app.bikespace.ca/dashboard?submission_id=1328">https://app.bikespace.ca/dashboard?submission_id=1328</a>

match_type	surveyed
distance	7.518990174
source	street-furniture-bicycle-parking
ID	BP-24431
OBJECTID	18415
ADDRESSNUMBERTEXT	1068-1070
ADDRESSSTREET	Pape Ave
FRONTINGSTREET	Pape Ave
SIDE	West
FROMSTREET	Gamble Ave
DIRECTION	North
SITEID	None
WARD	14
BIA	None
ASSETTYPE	Ring
STATUS	Existing
latitude	43.69067302
longitude	-79.34938972

**BIKESPACE REPORT #1310 (2024-01-12)**


<b>bikespace_id</b>	1310
<b>latitude</b>	43.67215151
<b>longitude</b>	-79.37802315
<b>issues</b>	['damaged']
<b>comments</b>	Ring missing from ring and post
<b>report_date</b>	2024-01-12
<b>report_time</b>	08:16:47
<b>Notes</b>	Shared with City in damage report 2024-08-23. Spray painted for fixing as of 2024-10-06.
<b>Survey_Date</b>	2024-10-06
<b>Asset</b>	BP-35057
<b>Check_311_Date</b>	2024-08-22
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Post with no ring
<b>WARD</b>	University-Rosedale (11)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1310">https://app.bikespace.ca/dashboard?submission_id=1310</a>

<b>match_type</b>	surveyed
<b>distance</b>	8.725058117
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-35057
<b>OBJECTID</b>	20081
<b>ADDRESSNUMBERTEXT</b>	366
<b>ADDRESSSTREET</b>	Bloor St E
<b>FRONTINGSTREET</b>	Bloor St E
<b>SIDE</b>	North
<b>FROMSTREET</b>	Sherbourne St N
<b>DIRECTION</b>	West
<b>SITEID</b>	None
<b>WARD</b>	11
<b>BIA</b>	None
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.67220638
<b>longitude</b>	-79.37794572

**BIKESPACE REPORT #1291 (2023-12-16)**


<b>bikespace_id</b>	1291
<b>latitude</b>	43.67069258
<b>longitude</b>	-79.3930006
<b>issues</b>	['damaged']
<b>comments</b>	Post with missing ring
<b>report_date</b>	2023-12-16
<b>report_time</b>	16:53:21
<b>Notes</b>	Shared with City in damage report 2024-08-23
<b>Survey_Date</b>	2024-08-18
<b>Asset</b>	BP-23818
<b>Check_311_Date</b>	2024-08-22
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Post with no ring
<b>WARD</b>	University-Rosedale (11)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1291">https://app.bikespace.ca/dashboard?submission_id=1291</a>

<b>match_type</b>	surveyed
<b>distance</b>	9.897343562
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-23818
<b>OBJECTID</b>	18632
<b>ADDRESSNUMBERTEXT</b>	119
<b>ADDRESSSTREET</b>	Yorkville Ave
<b>FRONTINGSTREET</b>	Yorkville Ave
<b>SIDE</b>	South
<b>FROMSTREET</b>	Hazelton Ave
<b>DIRECTION</b>	East
<b>SITEID</b>	None
<b>WARD</b>	11
<b>BIA</b>	Bloor-Yorkville
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.67069797
<b>longitude</b>	-79.39312312

**BIKESPACE REPORT #1290 (2023-12-16)**


<b>bikespace_id</b>	1290
<b>latitude</b>	43.66976132
<b>longitude</b>	-79.39375699
<b>issues</b>	['damaged']
<b>comments</b>	Bike ring with missing sleeve
<b>report_date</b>	2023-12-16
<b>report_time</b>	16:29:31
<b>Notes</b>	Shared with City in damage report 2024-08-23
<b>Survey_Date</b>	2024-08-18
<b>Asset</b>	BP-34237
<b>Check_311_Date</b>	2024-08-22
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Post with no ring
<b>WARD</b>	University-Rosedale (11)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=1290">https://app.bikespace.ca/dashboard?submission_id=1290</a>

<b>match_type</b>	surveyed
<b>distance</b>	4.994398598
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-34237
<b>OBJECTID</b>	20231
<b>ADDRESSNUMBERTEXT</b>	164
<b>ADDRESSSTREET</b>	Cumberland St
<b>FRONTINGSTREET</b>	Cumberland St
<b>SIDE</b>	North
<b>FROMSTREET</b>	Avenue Rd
<b>DIRECTION</b>	East
<b>SITEID</b>	None
<b>WARD</b>	11
<b>BIA</b>	Bloor-Yorkville
<b>ASSETTYPE</b>	Ring
<b>STATUS</b>	Existing
<b>latitude</b>	43.66978509
<b>longitude</b>	-79.39370441

## BIKESPACE REPORT #35 (2023-09-27)



<b>bikespace_id</b>	35
<b>latitude</b>	43.65182799
<b>longitude</b>	-79.40798879
<b>issues</b>	['damaged']
<b>comments</b>	Hi, the bike rack in front of 829 Dundas St W is missing the cap cover. It is overflowing with debris like cigarette butts because it is located next to the bar Dundas Video.
<b>report_date</b>	2023-09-27
<b>report_time</b>	16:04:52
<b>Notes</b>	Shared with City in damage report 2024-08-23. Actual post and ring location is about 100m west of report location
<b>Survey_Date</b>	2024-08-22
<b>Asset</b>	BP-25632
<b>Check_311_Date</b>	2024-08-22
<b>Check_311_Notes</b>	No requests found
<b>City_Problem_Type</b>	Cap missing
<b>WARD</b>	Spadina-Fort York (10)
<b>url</b>	<a href="https://app.bikespace.ca/dashboard?submission_id=35">https://app.bikespace.ca/dashboard?submission_id=35</a>

<b>match_type</b>	surveyed
<b>distance</b>	100.9854326
<b>source</b>	street-furniture-bicycle-parking
<b>ID</b>	BP-25632
<b>OBJECTID</b>	34732
<b>ADDRESSNUMBERTEXT</b>	829
<b>ADDRESSSTREET</b>	Dundas St W
<b>FRONTINGSTREET</b>	Dundas St W
<b>SIDE</b>	South
<b>FROMSTREET</b>	Ln W Palmerston S
<b>DIRECTION</b>	Dundas
<b>SITEID</b>	West
<b>WARD</b>	None
<b>BIA</b>	10
<b>ASSETTYPE</b>	Trinity-Bellwoods
<b>STATUS</b>	Ring
<b>latitude</b>	Existing 43.65158793
<b>longitude</b>	-79.40919637



## Bikespace Analysis - Damaged Bicycle Parking Reports

Updated October 29 2024

20 BikeSpace damage reports with nearby City bicycle parking features

bikespace_id	latitude	longitude	issues	parking_duration	comments	report_date	report_time	Notes	Survey_Date
1399	43.65991437	-79.38724666	['damaged']	minutes	BP-22556 ring has fallen down; no longer secured	2024-08-22	14:55:00	Shared with City in damage report 2024-08-23; Should be a #teambikespace entry; forgot to add the hashtag	
1400	43.6587695	-79.39509485	['damaged']	minutes	BP-27452 ring is missing #teambikespace	2024-08-22	14:00:00	Shared with City in damage report 2024-08-23	
1401	43.65500096	-79.4202044	['damaged']	minutes	BP-27742 ring is missing #teambikespace	2024-08-22	13:05:00	Shared with City in damage report 2024-08-23	
1403	43.69265627	-79.4410299	['damaged']	minutes	BP-32163 ring missing #teambikespace	2024-08-22	11:36:00	Shared with City in damage report 2024-08-23	
1402	43.69292778	-79.44087384	['damaged']	minutes	BP-32158 bent and missing cap #teambikespace	2024-08-22	11:30:00	Shared with City in damage report 2024-08-23; Bent and missing cap	
1398	43.66477305	-79.38044	['damaged']	minutes	Post and Ring BP-36518 is loose and has cap missing #teambikespace	2024-08-21	16:30:00	Shared with City in damage report 2024-08-23	2024-08-21
1396	43.66481765	-79.37982042	['damaged']	multiday	Ring not firmly attached to post: top bolt is missing and bottom bolt is loose, so not secure for bike parking. It is the first bike ring located on the north east corner on Church, at Maitland.	2024-08-17	12:50:52	Shared with City in damage report 2024-08-23	2024-08-21
1387	43.65913249	-79.38674894	['damaged']	minutes	BP-22469, missing ring, e side of Elizabeth St, <a href="https://flic.kr/p/2q86HtE">https://flic.kr/p/2q86HtE</a> #teambikespace	2024-08-04	13:06:46	Shared with City in damage report 2024-08-23	
1382	43.65176589	-79.47375706	['damaged']	minutes	Broken ring and post in front of runnymede tpl branch	2024-07-27	16:11:58	Shared with City in damage report 2024-08-23	2024-08-19
1369	43.64951657	-79.42643081	['not_provided', 'damaged']	minutes	The one bike ring that is there is loose.	2024-07-05	17:00:00	Shared with City in damage report 2024-08-23	2024-08-22
1367	43.69368608	-79.44127643	['damaged']	minutes		2024-07-01	19:56:25	Shared with City in damage report 2024-08-23	2024-08-22

Asset	Check_311_Date	Check_311_Notes	City_Problem_Type	WARD	url	Additional Matches	Survey Photo	match_type	distance	source	ID
BP-22556	2024-08-22	No requests found	Loose/unsecured	University-Rosedale (11)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1399.JPG	surveyed		3.467457873	street-furniture-bicycle-parking	BP-22556
BP-27452	2024-08-22	No requests found	Post with no ring	University-Rosedale (11)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1400.JPG	surveyed		1.373623558	street-furniture-bicycle-parking	BP-27452
BP-27742	2024-08-22	No requests found	Post with no ring	University-Rosedale (11)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1401.JPG	surveyed		1.975693797	street-furniture-bicycle-parking	BP-27742
BP-32163	2024-08-22	No requests found	Post with no ring	Toronto-St. Paul's (12)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1403.JPG	surveyed		1.711687959	street-furniture-bicycle-parking	BP-32163
BP-32158	2024-08-22	No requests found	Bent	Toronto-St. Paul's (12)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1402.JPG	surveyed		0.964376797	street-furniture-bicycle-parking	BP-32158
BP-36518	2024-08-18	No requests found	Loose/unsecured	Toronto Centre (13)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1398.jpg	surveyed		1.468349851	street-furniture-bicycle-parking	BP-36518
BP-36687	2024-08-18	No requests found	Loose/unsecured	Toronto Centre (13)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1396.jpg	surveyed		10.42462545	street-furniture-bicycle-parking	BP-36687
BP-22469	2024-08-15	No requests found	Post with no ring	University-Rosedale (11)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1387.jpg	surveyed		3.12346979	street-furniture-bicycle-parking	BP-22469
BP-22650	2024-08-15	No requests found	Loose/unsecured	Parkdale-High Park (4)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1382.JPG	surveyed		2.777872906	street-furniture-bicycle-parking	BP-22650
BP-20032	2024-08-15	No requests found	Loose/unsecured	Davenport (9)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1369.JPG	surveyed		13.4039799	street-furniture-bicycle-parking	BP-20032
BP-44877	2024-08-15	No requests found	Bent	Toronto-St. Paul's (12)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1367.JPG	surveyed		8.604192805	street-furniture-bicycle-parking	BP-44877

OBJECTID	ADDRESSNUMBERT		FRONTINGSTREET	SIDE	FROMSTREET	DIRECTION	SITEID	BIA	ASSETTYPE	STATUS	SDE_STATE_ID
	EXT	ADDRESSSTREET									
38411 220	Elizabeth St	Elizabeth St	West	College St	South	None	None	Ring	Existing	0	
23565 197	College St	College St	South	Ln E Beverley S College	East	None	None	Ring	Existing	0	
13653 766	College St	Shaw St	East	College St	North	None	Little Italy	Ring	Existing	0	
30883 626	Vaughan Rd	Vaughan Rd	West	Oakwood Ave	West	None	Oakwood Village	Ring	Existing	0	
20323 503	Oakwood Ave	Oakwood Ave	East	Belvidere Ave	North	None	Oakwood Village	Ring	Existing	0	
24732 477	Church St	Church St	East	Maitland St	North	None	Church-Wellesley Village	Ring	Existing	0	
17841 84	Maitland St	Maitland St	North	Alexander Pl	West	None	Church-Wellesley Village	Ring	Existing	0	
18610 201	Elizabeth St	Elizabeth St	East	La Plante Ave	West	None	None	Ring	Existing	0	
16802 2178	Bloor St W	Bloor St W	North	Glendonwynne Rd	East	None	Bloor West Village	Ring	Existing	0	
17985 1322	Dundas St W	Dundas St W	North	Coolmine Rd	West	None	Little Portugal	Ring	Existing	0	
12017 529	Oakwood Ave	Oakwood Ave	East	Strader Ave	North	None	Oakwood Village	Ring	Existing	0	

### Bikespace Analysis - Damaged Bicycle Parking Reports

Updated October 29 2024

20 BikeSpace damage reports with nearby City bicycle parking features

bikespace_id	latitude	longitude	issues	parking_duration	comments	report_date	report_time	Notes	Survey_Date
1345	43.66412305	-79.3686262	['damaged']	minutes	The bike stand is broken	2024-05-06	12:19:26	Shared with City in damage report 2024-08-23; Several bent Post and Rings, but appear to have been spray-tagged orange for fixing. BP-28070 is fully bent over.	2024-08-21
1342	43.70293996	-79.29698819	['damaged']	hours	Ring fallen down on BP-34713. <a href="https://flic.kr/p/2pMYvQg">https://flic.kr/p/2pMYvQg</a> #teambikespace	2024-04-28	12:53:57	Shared with City in damage report 2024-08-23	
1330	43.66883394	-79.33701189	['damaged']	minutes	BP-35952 Ring and post is missing a ring. #TeamBikeSpace	2024-03-23	12:16:23	Shared with City in damage report 2024-08-23	
1329	43.66905693	-79.33668736	['damaged']	minutes	BP-35870 ring and post broken, ring is missing. #teambikespace	2024-03-23	12:04:22	Shared with City in damage report 2024-08-23	
1328	43.69069735	-79.34930268	['damaged']	minutes	Ring has fallen down on post, is no longer attached. Asset ID is BP-24431. #teambikespace	2024-03-16	15:39:55	Shared with City in damage report 2024-08-23	
1310	43.67215151	-79.37802315	['damaged']	hours	Ring missing from ring and post	2024-01-12	08:16:47	Shared with City in damage report 2024-08-23. Spray painted for fixing as of 2024-10-06.	2024-10-06
1291	43.67069258	-79.3930006	['damaged']	hours	Post with missing ring	2023-12-16	16:53:21	Shared with City in damage report 2024-08-23	2024-08-18
1290	43.66976132	-79.39375699	['damaged']	hours	Bike ring with missing sleeve	2023-12-16	16:29:31	Shared with City in damage report 2024-08-23	2024-08-18
35	43.65182799	-79.40798879	['damaged']	minutes	Hi, the bike rack in front of 829 Dundas St W is missing the cap cover. It is overflowing with debris like cigarette butts because it is located next to the bar Dundas Video.	2023-09-27	16:04:52	Shared with City in damage report 2024-08-23. Actual post and ring location is about 100m west of report location	2024-08-22

Asset	Check_311_Date	Check_311_Notes	City_Problem_Type	WARD	url	Additional Matches	Survey Photo	match_type	distance	source	ID
BP-28070	2024-08-15	Likely 311 request located at 233 Carlton. Another ring post fix request nearby via 311 at 467 parliament.	Bent	Toronto Centre (13)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1345.jpg	surveyed		15.68769374	street-furniture-bicycle-parking	BP-28070
BP-34713	2024-08-15	No requests found	Loose/unsecured	Beaches-East York (19)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1342.jpg	surveyed		0.717393311	street-furniture-bicycle-parking	BP-34713
BP-35952	2024-08-22	No requests found	Post with no ring	Toronto-Danforth (14)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0	surveyed		4.376360216	street-furniture-bicycle-parking	BP-35952
BP-35870	2024-08-22	No requests found	Post with no ring	Toronto-Danforth (14)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0	surveyed		4.466777922	street-furniture-bicycle-parking	BP-35870
BP-24431	2024-08-22	No requests found	Loose/unsecured	Toronto-Danforth (14)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0	surveyed		7.518990174	street-furniture-bicycle-parking	BP-24431
BP-35057	2024-08-22	No requests found	Post with no ring	University-Rosedale (11)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1310.jpg	surveyed		8.725058117	street-furniture-bicycle-parking	BP-35057
BP-23818	2024-08-22	No requests found	Post with no ring	University-Rosedale (11)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1291.jpg	surveyed		9.897343562	street-furniture-bicycle-parking	BP-23818
BP-34237	2024-08-22	No requests found	Post with no ring	University-Rosedale (11)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 1290.jpg	surveyed		4.994398598	street-furniture-bicycle-parking	BP-34237
BP-25632	2024-08-22	No requests found	Cap missing	Spadina-Fort York (10)	<a href="https://app.bikespac.com">https://app.bikespac.com</a>	0 35.JPG	surveyed		100.9854326	street-furniture-bicycle-parking	BP-25632

OBJECTID	ADDRESSNUMBERT		FRONTINGSTREET	SIDE	FROMSTREET	DIRECTION	SITEID	BIA	ASSETTYPE	STATUS	SDE_STATE_ID
	EXT	ADDRESSSTREET									
21815 235	Carlton St	Carlton St	South	Parliament St	West	None	Cabbagetown	Ring	Existing	0	
36807 466A	Dawes Rd	Dawes Rd	West	Ln N Gower W Dawes	West	None	None	Ring	Existing	0	
25032 1029	Gerrard St E	Gerrard St E	South	Marjory Ave	East	None	None	Ring	Existing	0	
35312 1040	Gerrard St E	Gerrard St E	North	Galt Ave	West	None	None	Ring	Existing	0	
18415 1068-1070	Pape Ave	Pape Ave	West	Gamble Ave	North	None	None	Ring	Existing	0	
20081 366	Bloor St E	Bloor St E	North	Sherbourne St N	West	None	None	Ring	Existing	0	
18632 119	Yorkville Ave	Yorkville Ave	South	Hazelton Ave	East	None	Bloor-Yorkville	Ring	Existing	0	
20231 164	Cumberland St	Cumberland St	North	Avenue Rd	East	None	Bloor-Yorkville	Ring	Existing	0	
34732 829	Dundas St W	Dundas St W	South	Ln W Palmerston S Dundas	West	None	Trinity-Bellwoods	Ring	Existing	0	