⚠ SYNTHETIC FIXTURE DATA: not real satellite results

Preliminary Observation Report: DB-0004

Report generated: 2026-10-12 16:26 UTC

Location

Site	Site C
Centroid (lon, lat)	114.03305, 22.46277
Zoning (indicative)	Other zoning (Indicative overlay only, not a zoning determination.)
Area	1.15 ha
First detected	2025-02-01
Persistence	6 of 6 months
Confidence	High

Satellite metrics

Measure	Baseline	Current	Change
Radar backscatter VV (dB)	-18.9 dB	-12.4 dB	+6.5 dB vs baseline
NDWI (water index)	0.27	-0.09	-0.36 vs baseline

Before and after



Before (baseline) (synthetic test image)



After (current) (synthetic test image)

Preliminary brief

Brief status: Cited

Preliminary Observation: Possible Wetland Loss at Site C

Summary

A 1.15 ha area outside the Wetland Conservation and Buffer Areas (indicative zoning) shows a persistent transition from water-covered to dry or filled surface, first observed in February 2025 and present in 6 of the

Satellite-derived indicator for screening purposes only. This is not a legal determination of unauthorised development. Findings require site verification by the relevant authority.

last 6 months.

Evidence

- Affected area: 1.15 ha
- Radar backscatter rose +6.5 dB above the 2023-2024 baseline for the same month
- NDWI changed by -0.36 against the same-month baseline
- First detected 2025-02, persistent in 6 of 6 recent months

Statutory basis

1. Synthetic test claim used to check that statutory claims and their citations render correctly. [1] [2]

Recommended action

Refer for site inspection and zoning confirmation by the relevant authority.

Limitations

Satellite-derived indicator for screening purposes only. This is not a legal determination of unauthorised development. Findings require site verification by the relevant authority.

Generated 2026-10-01 00:00 UTC • model fixture-generator (no LLM)

Citations

[1] Synthetic Test Document A (fixture) • Page 3 • Section: Test section 1

"Synthetic placeholder text for interface testing only; not quoted from any real document."

https://example.invalid/fixture-document-a

[2] Synthetic Test Document B (fixture) • Page 11 • Section: Test section 2

"Second synthetic placeholder passage used to check multi-citation layout."

https://example.invalid/fixture-document-b

Disclaimer

Satellite-derived indicator for screening purposes only. This is not a legal determination of unauthorised development. Findings require site verification by the relevant authority.