



Route comparison: rectangles=20, panel=2440 x 1220 mm

shared-edge cut collinear chain travel safe lift stability event
near-shared cut single edge detour penalized travel


Path-LS: runtime=295.2 ms, cost=5026.7, machining=22909.7, stability=4, safe_lift=1, detour=25




Process-aware: runtime=217.5 ms, cost=12752.8, machining=30635.8, stability=0, safe_lift=2, detour=9



Multi-start process LS: runtime=806.0 ms, cost=12752.8, machining=30635.8, stability=0, safe_lift=2, detour=9



Process-aware beam: runtime=581.5 ms, cost=7144.1, machining=25027.1, stability=0, safe_lift=0, detour=10



Beam+process LS: runtime=494.8 ms, cost=7018.4, machining=24901.4, stability=0, safe_lift=0, detour=0

