


### Route comparison: rectangles=9, panel=20 x 20 mm

— shared-edge cut — collinear chain — travel — safe lift × stability event  
— near-shared cut — single edge — detour — penalized travel

Full: runtime=95.8 ms, cost=32.0, machining=182.0, stability=0, safe\_lift=0, detour=0



Single edges: runtime=152.8 ms, cost=40.0, machining=276.0, stability=0, safe\_lift=0, detour=0

