



Route comparison: rectangles=30, panel=2440 x 1220 mm

— shared-edge cut — collinear chain - - travel - - safe lift × stability event
— near-shared cut — single edge - - detour - - penalized travel

Full: runtime=972.8 ms, cost=12145.4, machining=33470.5, stability=0, safe_lift=1, detour=0



No stability: runtime=1761.3 ms, cost=7806.4, machining=29131.5, stability=12, safe_lift=1, detour=0



Path-LS: runtime=365.0 ms, cost=6814.6, machining=28139.7, stability=3, safe_lift=2, detour=0

