



Route comparison: rectangles=20, panel=2440 x 1220 mm

- shared-edge cut collinear chain travel safe lift stability event
near-shared cut single edge detour penalized travel


Greedy: runtime=8.4 ms, cost=5227.2, stability=4, safe_lift=1, detour=25



Path-LS: runtime=296.5 ms, cost=5026.7, stability=4, safe_lift=1, detour=25



Process-aware: runtime=223.0 ms, cost=12752.8, stability=0, safe_lift=2, detour=9



Process-aware beam: runtime=597.3 ms, cost=7144.1, stability=0, safe_lift=0, detour=10

