

A1466 Minor water inflow maintenance

"Faulty model"

A1466

[Fault
phenomeno
n] Do not
start up

"Maintenance process"

After receiving an A1466, the customer said that it would not be turned on, but it would not trigger after being tested by hand, and the current had not been charged yet.



After removing the back cover, it was found that the screen interface was corroded. Looks like there is water in the motherboard.




After the main board was removed, there were two places with water on the back. After cleaning, it was found that it was good.



The screen interface is also easy to handle.

After processing, the power-on does not trigger automatically, but the upper battery has a slight current of 100MA, which seems to be charging, so after waiting for a while, the current jumps to 3A and seems to be charging

Electricity is normal.



When the battery is charged for a while, press boot again, which has started normally.

[Maintenance Results]

A1466 is not turned on, the screen interface is corroded by water, and the battery is dead. After treatment, the maintenance is successful.