



Temperature In A Heated Room
Radiator (Left) And Window (Right)



Uniform Mesh
512 Cells, $h_{\max}/h_{\min} = 1$, L^2 Error $2.3\text{e-}02$



Mesh Graded Towards Both Features
3775 Cells, $h_{\max}/h_{\min} = 32$, L^2 Error $7.3\text{e-}04$

